

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Md Ishak, Mohd Imran

Date: 05 Mar 2019

Preliminary Advice

Vehicle No	: SKB1508E	Accident Date	: 25/02/2019
Make	: AUDI A1	Policy No.	: 2100301745-06
Assignment Date	: 01/03/2019	Excess	: S\$600.00
Date of Inspection	: 27/02/2019	Est. Duration of Repair	: 10.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,929.00
Revised Amount	:S\$	13,470.00
Check Items (Estimated)	:S\$	12,945.00
Total	:S\$	26,415.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	36,889.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,111.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer asking for Lump Sum \$11,000/-