

# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: AIG	DATE	: 26-Feb-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<b>VEHICLE DETAILS</b>			
VEHICLE NO	: SLK8200L		AGH300026986
MODEL	: TOYOTA ALPHA 2.5		Poh kin
CHASSIS NO			
<b>ACCIDENT DETAILS</b>		DATE	: 26-Feb-19
		TIME	: 21:35HRS
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

**CLAIM DETAIL : PARTS**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,100.60	\$ <del>2,100.60</del> 1718
2	TAILGATE EMBLEM "ALPHA" <i>Ne</i>	1	\$ 90.00	\$ 90.00 ✓
3	TAILGATE LOCK <i>ng.</i>	1	\$ 480.90	\$ 480.90 ✓
4	TAILGATE WEATHERSTRIP <i>new</i>	1	\$ 330.50	\$ 330.50 +
5	TAILGATE ANTENINA <i>Crack'd</i>	1	\$ 180.90	\$ 180.90 ✓
6	TAYLGATE BUZZLE <i>ng</i>	1	\$ 130.00	\$ 130.00 ✓
7	REAR WINDSCREEN MOULDING <i>ne</i>	1	\$ 250.90	\$ 250.90 ✓
8	TAYLGATE INNER BOARD <i>Crack'd</i>	1	\$ 980.50	\$ <del>980.50</del> 549.40
9	REAR BUMPER <i>Rehond</i>	1	\$ 1,890.50	\$ <del>1,890.50</del> 1575
10	REAR BUMPER SIDE RETAINER <i>Ne</i>	1	\$ 98.30	\$ 98.30 ✓
11	REAR END PANEL <i>Dented</i>	1	\$ 820.00	\$ <del>820.00</del> 685
12	REAR END PANEL TOP GARNISH <i>Rehond</i>	1	\$ 244.90	\$ 244.90 ✓
13	REVERSE SENSOR <i>ng</i>	2	\$ 498.00	\$ <del>996.00</del> 498

6501.30  
 4875.97  
 TOTAL PRICE \$ 8,594.00  
 LESS 25% \$ 2,148.50  
**SUB TOTAL PRICE \$ 6,445.50**

**SPECIAL NETT ITEMS**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Ne</i>	1	\$ 50.00	\$ 50.00

2	TAILGATE WINDSCREEN SEALANT <i>Jan</i>	1	\$ 100.00	\$ <del>100.00</del> <i>40</i>
3	TAILGATE WINDSCREEN INNER SEAL	1	\$ 120.00	\$ <del>120.00</del> <i>40</i>
4	REAR BUMPER CLIP (SET) <i>Mc</i>	1	\$ 20.00	\$ 20.00 <i>1</i>
5	REAR END PANEL GARNISH CLIP (SET) <i>Mc</i>	1	\$ 20.00	\$ <del>20.00</del> <i>10</i>
6	REAR END PANEL SEALANT <i>Mc</i>	1	\$ 100.00	\$ <del>100.00</del> <i>60</i>
			<i>170</i> TOTAL	\$ 410.00

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)**

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ <del>1,200.00</del> <i>80</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ <del>1,200.00</del> <i>80</i>	
3	TO TRANSFER TAIL GATE MECHNISM	\$ <del>250.00</del> <i>80</i>	
4	LABOUR TO REMOVE AND REFIT WINDSCREEN	\$ <del>120.00</del> ✓	
5	TUFF COAT	\$ <del>180.00</del> <i>60</i>	
6	TO CONDUCT WATER LEAKAGE TEST	\$ 250.00	<i>+</i>
7	WIRING CHECK	\$ <del>150.00</del> <i>30</i>	
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ <del>100.00</del> <i>60</i>	
TOTAL		\$3,450.00	<i>1950</i>

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 6,855.50  
 TOTAL LABOUR COST : \$ 3,450.00  
 TOTAL REPAIR COST : \$ 10,305.50

**APPROVED DETAILS**

EXCESS :  
 NO. OF WORKING DAYS :  
 RE-SURVEY :  
 PART BY PART OR LUMP SUM :  
 DATE & TIME OF SURVEY :  
 SURVEYED BY :  
 CONTACT NUMBER :  
 FAX NUMBER :

*Adrian Lj*  
*01/03/19*  
*h/s . 06 days .*  
*total: 6995.97*  
*4/s: 56K*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: