L 19003828/Tod3@pecial Instruction: 22/00/9/2002 ASS. REC. BY: ASSIGNMENT (Office) SULVEYOR WOI Dute/Time: 82115 From (Person): Bill to: 7828 Estimated Cost: OD/TP/WS/TPRES/ SEL 13659 Insured: To Inspect Vehicle No: 9116 5779 Tel: at Workshop m/s Road 303 Alexandm of MOMIZOD 1318 1501 Claim No: Policy No: 500 .00 Excess: Sum Insured: D.O.A. Make of Veh: 43119 (Client's Record) H.O.D. Endorsement: CA / REV / REP. / REV 24 HRS Date Time 10 11amo 1/3 19 Person Contacted: Estimate Date/Time Action/Instruction SKL 1365 Y 05/03/19

Sicono Tayth REF: UC	CONTRACTOR
	ASSIGNMENT
iom Date:	Volt No. SKL 15654 Yr Regn 2013, Sep.
Etimaled Cost	Type: MCRr (M.Cycle / Bus / Van / Lony / Taxi / Prime Mover /
O) TP / WS / TP RES / OD RES / EVA / INV / MY	Truck / Trailer or
o Impect Vehicle No. 9KL 1365Y	Make: 15 MW 3/6 = 1598
Workshop mis Personnea Motor	Colour white A/C Insured/Std/NI/NA
303 Alexandra Rd.	Sp.Reading 4808 Z TRadio Insured / Std / NI / NA
and	Eng/No:
oficy No	CINO WBA 3/A/2040572/426
	Gen. Cond. Good Fair / Poor / Burnt
laima No.	V 6
un Insured Excess: AS	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	
take of Veh:	Tyro Size F: 225 SORIT
<b>X</b>	
(Policy Condition)	R: 7:
emark. The veh had commenced its N/S	
repair at the time of inspection.	TOYOTYOKO OF Confinence
at or Market Value: 964K	Front Rear
DAC Accident Rport: Consistent? Yes or No	Pr/Bal. C mm R/Bal. C mm
HA / PR Seen: Consistent? Yes or No	L/Bal 6 mm L/Bal 6 mm
st Repairs: 3 days Res.: Yes or No	D.O.A D.O.I 4/3/19
um Sum: % 3 Val.: Yes or No	Survey held at PML
	Des. of Damages . Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS	TUDINI THE TUDINI
zate: Person Contacted Gam	
Date / Time   Action / Instruction	220
Oplozing Continued P/P 1 Cf 5.419.70_ Red RECEIVED 2 9 MAI	/ VMVPQ ~ I
RECEIVED 2 9 MAI	29 Z9
RECEIVED 2 9 MAI	29 Z9
RECEIVED 2 9 MAI	Days Of Repair: 3 Resurvey No. of Trip: / Survey Fee: 250+25
RECEIVED 2 9 MAI	Days Of Repair: 3 Resurvey No. of Trip: / Survey Fee: 250+25
RECEIVED 2 9 MAI	Days Of Repair: 3 Resurvey No. of Trip: / Survey Fee: 250+25  Add Fee: Site Imap 15  Solvey Fee: 250+25  Add Fee: 80

11.11

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	3054Z	
Vehicle No.:	5KL1365Y	
Vehicle to be Exported:	No	
Intended Deregistration Date:	04 Mar 2019	
Vehicle Make:	B.M.W.	
Vehicle Model:	316I 1.6 AT D/AB 4DR ABS HID	
Primary Colour:	White	
Manufacturing Year:	2013	
Engine No.:	A415J558N13B16A	
Chassis No.:	WBA3A12040J721426	
Maximum Power Output:	100.0 kW (134 bhp)	
Open Market Value:	\$34,648.00	
Original Registration Date:	30 Sep 2013	
First Registration Date:	30 Sep 2013	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$30,508.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	29 Sep 2023	
PARF Rebate Amount: Intended COE Rebate Details	\$21,355.00	
COE Expiry Date:	29 Sep 2023	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
QP Paid:	\$83,751.00	
COE Rebate Amount:	\$38,269.00	
Total Rebate Amount:	\$59,624.00	

The information contained herein is correct as at 04 Mar 2019

OK

# Shirley Hiew (LKK Auto)

From:

Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Sent:

Friday, 29 March 2019 10:25 AM

To:

'PBSP'

Cc:

Shirley Hiew (LKK Auto)

Subject:

RE: FINAL REPORT / SKL1365Y

Hi Caroline,

COR \$5960.90, 3 days.

Regards Taufikh Lkk Auto

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Thursday, 28 March 2019 4:51 PM

To: taufikh@lkkauto.com; SUR Subject: FINAL REPORT / SKL1365Y

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour: 2,422.00 Total Parts: 3,538.90

Total Labour & Parts: 5,960.90

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

# Shirley Hiew (LKK Auto)

From:

Gary Poh Chai Hoon <gary.poh.chaihoon@simedarby.com.sg>

Sent:

Tuesday, 5 March 2019 11:58 AM

To:

Shirley Hiew (LKK Auto)

Cc:

SUR

Subject:

RE: SKL 1365Y OD (UOI)

Dear Shirley

noted with thanks

Thank you.

Best Regards,

# Gary Poh

Customer Service Advisor | Body and Paint Performance Motors Limited 303 Alexandra Road Sime Darby Performance Centre Singapore 159941

Hp (+65) 9116 5779 | Fax (+65) 6479 4601 gary.poh.chai.hoon@simedarby.com.sq



http://www.pml.com.sq/7series/

Please consider the environment before printing this e-mail.

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Tuesday, March 05, 2019 10:29 AM

To: Gary Poh Chai Hoon

Cc: SUR

Subject: RE: SKL 1365Y OD (UOI)

Dear Gary,

Enclose the discharge voucher for client due execution.

As instructed by our client, please proceed at repair cost not exceeding \$7,000.00 (inclusive supplementary) to repair the insured vehicle

# SKL 1365Y (Excess \$ 500/-) on part by part basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Gary Poh Chai Hoon [mailto:gary.poh.chaihoon@simedarby.com.sg]

Sent: Tuesday, 5 March 2019 8:53 AM

To: Shirley Hiew (LKK Auto) < Shirley Hiew@lkkauto.com>

Cc: SUR < sur@lkkauto.com > Subject: RE: SKL 1365Y OD (UOI)

Dear Shirley,

we accept the offer @7,000.00 . kindly revert .

Thank you.

Best Regards,

### Gary Poh

Customer Service Advisor | Body and Paint Performance Motors Limited 303 Alexandra Road Sime Darby Performance Centre Singapore 159941 Hp (+65) 9116 5779 | Fax (+65) 6479 4601 gary.poh.choi.hoon@simedarby.com.sq



http://www.pml.com.sq/7series/

Please consider the environment before printing this e-mail.

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Monday, March 04, 2019 5:34 PM

To: Gary Poh Chai Hoon

Cc: SUR

Subject: RE: SKL 1365Y OD (UOI)

Dear Gary,

According to our surveyor Taufikh, kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 7,000.00 on part by part basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# Shirley Hiew (LKK Auto)

From:

LEW JENNY < jennylew@uoi.com.sg>

Sent:

Tuesday, 5 March 2019 10:10 AM

To:

Shirley Hiew (LKK Auto)

Cc:

SUR

Subject:

RE: PRELIMINARY REVISED OF SKL 1365Y

Attachments:

OD Template.zip

Dear Shirley,

Please proceed with the repair authorisation up to S\$7,000.00

Excess: S\$500.00

Enclose the discharge voucher for client due execution.

Thank You.

Warmest Regards

Jenny Lew

Claims Department

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909

Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

#### UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Tuesday, 5 March, 2019 9:07 AM To: LEW JENNY <jennylew@uoi.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: PRELIMINARY REVISED OF SKL 1365Y

Dear Jenny,

Enclosed preliminary revised of vehicle SKL 1365Y

Date of survey: 04/03/2019 Number of days: 3-4 days

Repairer able to undertake the repair cost not exceeding \$ 7,000.00 on part by part basis.

We have Not authorise repair.

Kindly let us have your approval please.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

# LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DHOM120013181501

Date: 05 March 2019

Our Ref: CS/UOI19003828/T1sd3

The Motor Claims Department UNITED OVERSEAS INSURANCE LTD

Dear Sir/Madam.


# INITIAL INSPECTION REPORT OF VEHICLE NO. SKL 1365Y .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/03/2019 at the premises of M/s Performance Motors Limited and have the following to report:-

Workshop Estimate Amount	: SS	11,370.50	
Revised Estimate Amount	: S\$	5,604.95	
"Check" Items Amount	: S\$	4,715.55	
Total	: S\$	10,320.50	_,
Market Value	: SS	67,000.00	
LTA Reimbursement Value	: S\$	59,624.00	
Nett Value	: SS	7,376.00	_

#### Description of Damage:

The vehicle sustained damages at the front n/s portion



#### Comments/ Present Status:

Damages Consistent.

Repair cost economical, we have not authorise repair

Repairer able to undertake the repair cost not exceeding \$ 7,000.00 on part by part basis.

Repair days: 3-4 Days

Yours faithfully, Mohamad Taufikh Automotive Assessor

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and <u>accurate</u> as possible. Any wilful misrepresentation or wilholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for arctiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available
  aforesaid.

ACCI	CTA	T-17	<b>ICNIT</b>
AUU	DIA		

Date Of Report 21/02/2019 19:44

Date Of Accident 20/02/2019 17:50

Exact Location Of Accident ALONG ALEXANDRA ROAD TOWARDS AYE

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKL1365Y

Insured/Policyholder

Name Of Registered Owner OOI BOON PENG

NRIC No \$1563054Z

Email Address BPEC911@SINGNET.COM.SG

 Mobile Phone No
 (LOCAL) +65-98391100

 Alternative Phone No
 OTHERS-98370028

Vehicle Particulars

Manufacturer BMW

Model 316I 1.6 AT D/AB 4DR ABS HID

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company UNITED OVERSEAS INSURANCE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number DHOM120013181501

Cover Note Number N.A

Driver

Name of Driver QUEK ENG CHIEW

 NRIC No
 \$1560803Z

 Date Of Birth
 08/10/1962

 Occupation
 INDOOR

 Date Of Driving Pass
 01/06/1985

Driving Experience 33 YEARS AND 8 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-98370028

Fax Number

Contact Number

EMail Address QUEK\_ENG\_CHIEW@MOE.EDU.SG

Address

NA

Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

#### General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

#### Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

ELAINE TAY

GENDER:

FEMALE

#### Details of Police Action

Was the accident reported to the police?

YES

If Yes Please state which Police Station

POLICE STATION NAME [OTHER]

CHOA CHU KANG NPC

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT: ON THE ABOVE MENTIONED DATE, TIME AND LOCATION, I WAS MAKING A U-TURN ALONG ALEXANDRA ROAD, JUST AFTER MALAN ROAD, I WAS WAITING IN THE YELLOW BOX FOR THE TRAFFIC TO MOVE, A SMRT BUS, BEARING PLATE NUMBER SMB5080X, BUS SERVICE 61, REFUSE TO GIVE WAY, AS IT MOVED PAST MY VEHICLE, IT HIT THE FRONT OF MY CAR'S FRONT LEFT HEADLIGHTS, DAMAGING BOTH THE HEADLIGHTS AND THE BUMPER. THE BUS SUBSEQUENTLY STOPPED AND THE DRIVER ALIGHTED. WE EXCHANGED PARTICULARS. NO ONE COMPLAINT OF ANY INJURIES AND AS SUCH, AMBULANCE AND TRAFFIC POLICE WAS NOT CALLED. WE THEN MADE OUR SEPARATE WAYS.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SMB5080X

Vehicle Make/Model/Colour

ALEXANDER DENNIS / ENVIRO500

**Details Of Properties** 

N.A

Vehicle Category

Name of Driver

MUHAMMAD RAHIMIN BIN MD SHAH

NRIC/Passport Number

S9429774E

Contact Number

96174674

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)


#### Sketch Plan

Present record decreasing the contents of the investment to speed up the authority by the postment of the process of the

The granteering has been applied by the process of the process of representation by the process of religious to real, which include interroge as an expension of the statements of the process of religious to real, which include interroge as an expension of the statement of the s

VERIFIED BY AJAX MARS REPORTING OFFICER MOHAMMAD SULHANDI BIN MOHD AFFANDI

June 1







3.01%

Report No. 1/20190220/2213

Police Station Of Origin Chos Chu Kang N.P.C 20 Chos Chu Kang Street 52 #01-02 SINGAPORE 689250 Tel No. 1800-7659999

Date/Te	me Report 019 21:33	Made.	Vide Report No.	Station Diary No 214
Informs	orte Partic	ariers .	AND REAL PROPERTY.	
The second second second	Informant		Address 103 CASHEW ROAD #05-04	SINGAPORE 679674
ID Type	A STATE OF THE PARTY OF THE PAR	12231201510	Contact No: Home/Office	Mobile: 98370028
Nationali			Email	Market Comments
Sex Female	Age: 56	Date of Birth: 08/10/1962	Type of Informant Driver	
Race: Chinese			Language English	Institution / School Name
Occupatio		No. 10 East	Driving Licence Information: Class: 3	Date of Expiry:

Type of Accident	CAT CHARLES THE COLUMN TO THE		Date/Time of Accident 20/02/2019 17:50	Type of Location Straight Road	
Location Along Road 1 ALEXANDRA TOWARDS A)					
Veather: Clear	A Hamel	Road Surface: Dry		Road Speed Limit	
CONTRACTOR ON CO.		Traffic Control:	The second	Traffic Volume: Heavy	
The state of the s		Not Controlled		Heavy	

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKL1365Y					Slightly Damaged	1
SMB5080X	Bus/Coach/Mi				- Mariana Maria	0

Datails of Person Involved	THE RESERVE TO THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW
Any Pedestrian Involved; No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Palce Station Of Origin Choa Chu Kang N.P.C. 20 Choa Chu Kang Street 52 #01-02 SINGAPORE 689286 Tel No 1800-7659999



243

Report No. 1/20190220/2213

# CONTINUATION OF REPORT

Name QUEK ENG CHIEV  Related Vehicle SKL1365Y (Car)  Hospital/Clinic NIL Class of Driving Licence & Expiry Date  Date Treatment NIL Date Discharge NIL No. of Days granted Medical Leave NIL Degree of Injury NIL.  Delver Name MUHAMMAD RAHIMIN BIN MD ID No.	Dover			ID No.	S1560803Z
Related Vehicle SKL1365Y (Car)  Hospital/Clinic NIL Class of Driving Licence & Expiry Date  Date Treatment NIL Date Discharge NIL Degree of Injury NIL No. of Days granted Medical Leave NIL Degree of Injury NIL Delver Name MUHAMMAD RAHIMIN BIN MD ID No.  Related Vehicle SMB5080X (Bus/Coach/Minibus) Contact No.  Class of Driving Licence & Driving Licence & Driving Licence & Class of Driving Licence		QUEK ENG CHIEW		Contact No.	98370028
Hospital/Clinic NIL Class of Driving Licence & Expiry Date  Date Treatment NIL Date Discharge NIL Degree of injury NIL  No. of Days granted Medical Leave NIL Degree of injury NIL  Delve Name MUHAMMAD RAHIMIN BIN MD ID No.  Related Vehicle SMB5080X (Bus/Coach/Minibus) Contact No.  Class of Driving Licence & Driving Licence &	Related Vehicle	SKI_1365Y (Car)			Service Control of the Control of th
Date Treatment NIL Degree of injury NIL No. of Days granted Medical Leave NIL Degree of injury NIL Delver Name MUHAMMAD RAHIMIN BIN MD ID No.  Seleted Vehicle SMB5080X (Bus/Coach/Minibus) Contact No.  Class of Driving Licence &	CALCULATIVE	NIL		Driving Licence &	Class: 3 Date of Expiry: NIL
Name MUHAMMAD RAHIMIN BIN MD ID No.  Itelated Vehicle SMB5080X (Bus/Coach/Minibus) Contact No.  Class of Driving Licence &	Date Treatment	NIL ted Medical Leave NIL	Date Disci Degree of	injury NIL	
elated Vehicle SMB5080X (Bus/Coact/Williams)  Spital/Clinic NIL Class of Driving Licence &	river	THE RESERVE OF THE PERSON NAMED IN COLUMN		ID No.	S9429774E
Driving Licence &	elated Vehicle	SMB5080X (Bus/Coach/Minibus)		Contact No	NIL NIL
temper y server	ospital/Clinic	NIL		Driving Licence &	Class NIL Date of Expiry: NIL
ate Treatment NIL Date Discharge NIL Degree of Injury NIL	te Treatment	NIL		charge NIL	The second and a second

### Brief Details.

On the above mentioned date, time and location, I was making a U-turn along Alexandra Road, just after Malan Road. I was waiting in the yellow box for the traffic to move. A SMRT Bus, bearing plate number SMB5080X, bus service 61, refused to give way. As it moved past my vehicle, it hit the front of my car's front left headlights, damaging both the headlights and the bumper. The bus subsequently stopped and the driver alighted. We exchanged particulars. No one complaint of any injuries and as such, Ambulance and Traffic Police was not called. We then made our separate ways.

- FERNAUSE



Contact No.: 65478151

Authentication Stamp

NF1158

Police Station Of Origin Choa Chu Kang N P C 23 Choa Chu Kang Street 52 #01-02 SINGAPORE 689286


Tel No: 1800-7659999

Sketch Plan Informant is not able to provide sketch plan

Report No. 1/20190220/2215

CONTINUATION OF REPORT


IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certainer with you now, please fax a copy to 85474885 stating the report number as reference Signature Of Informant er Recording The Report STAN SOL MO FORMAD PLASIF BIN KAMAR Date/Time: Signal Printerpreter 20/02/2019 21:33 Not applicable Officer in Charge Of Case Classification Of Case TP/GIA/ Staff Sgt WONG SIEU LUI















United Oversess Insurance Limited

3 Anson Road #28-01 Springlest Tower Singapore 079909 Tet (65) 6222 7733

Fax (65) 6327 3869 / 6327 3870 Email: ContactUs@uol.com sg. MOLICOTTI SA

Co. Reg. No. 197100152R

#### Certificate of Insurance

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE NO.

DH0M120013181501

Excess:

\$500/-NAMED DRIVERS

COMPREHENSIVE

\$1500/-OTHERS

Vehicle Number SKL1365Y

\$3000/-APPL TO <25 YRS & OR <3YRS EXP \$100/-WINDSCREEN DAMAGE CLAIM

Name of Insured

Type of Cover

**DOI BOON PENG** 

Restricted Driver(s)

NOT APPLICABLE

Period of Insurance

30 September 2017 to 29 September 2019

Engine#

A415J558N13B16A

Hire Purchase

BMW FINANCIAL SERVICES SINGAPORE PTE LTD

Chassis#

WBA3A12040J721426

PRIVATE CAR - INDIVIDUAL OWNERSHIP [MX 1] AUTHORISED DRIVER

(1) The Insured

(2) Any other person who is driving on the Insured's order or with his permission

(3) In the event of the death of the Insured

(a) any member of the Insured's family or a paid driver who has been driving the car during the lifetime of the Insured and permission to drive had not been withdrawn prior to the death of Insured and

(b) any other person who has been given permission to drive the vehicle prior to the death and such permission had not been withdrawn by the Insured

LIMITATIONS AS TO USE

Use only for social domestic and pleasure purposes and for the Insured's business THE POLICY DOES NOT COVER

Use for hire or reward or racing pace-making reliability trial or speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purposes in connection with the Motor Trade

The carriage of passengers pursuant to car pooling arrangements and payments or any of them made by the passengers thereunder towards the running expenses of any vehicle described in the Schedule shall not be deemed to constitute use for hire or reward

Provided that the person is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor

\*Limitation rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles(Third-Party Risks and Compensation) Act (Chapter 189) and part Iv of the Road Transport Act, 1987 (Malaysia).

UNITED OVERSEAS INSURANCE LTD

For the Company

FCTTS

Date: 04/09/2017


# Performance Motors Limited

The two to the line bett done on Million

LH TELESCOPING NOZZLE

BMW BLUE XENON BULBS (2xD1S)

BMW BLUE HALOGEN BULBS 2 X H8



280 Tamping King Cont East Cont (motion Simpageor & 1418) Tel (198888 Minoriales) Ten (144893) Tip Areabdy Took

Sime Party Supiness restor

Sime Party Supiness restor

Sime Party Supiness Afrechales

Opinions Afrechales

Opinions Afrechales

Afrechales

Afrechales

Afrechales

Afrechales



159 85

799.45

100.15

159 85

799 45

100.15

1

1

1

GST REG. NO : M2 - 0020081 - X

#### ESTIMATE

Estimate No. Date Estimate Prepared By	: b1 50305 : 27/02/2019 : Gary Poh 0	Control of the contro			Page No. :	1 of 5
- ESTIMATE REPAIR FOR - Oci Boon Peng 103 Cashew Road #05-04 Singapore 679674		3		seas :	115 Insurance L -01 Springle	
REGN NO	CHASSIS NO.	REGN. DATE 30/09/2013	MODEL 3161A/4			MILEAGE 0
To	ECET PTION replace front bumper and se by the accident					950 1,700.0
pair	nting front bumper					934 1.034.0
	check electrical wiring sys					150 177.0
	replace left headlight.					408 481.0
Sur	ndries.					7 150.0
				Tot	al Labour 1:	3,542.0
	SCRIPTION			QTY	PRIC	VALU
1,7,57	ONT SHOCK ABSORBER			1	43.00 378.10	7 378.1
17.577	BUMPER TOP MOUNT	n.			97 90	979
175.555	ERT AIR INTAKE CENTE LH DEFORMATION ELE			1	101.80	7 101 8
	LH LOWER DEFORMAT			1	86 40	? 86
	SUPPORT FOGLAMP	TOTAL ELEMENT		1	41 85	7 41 8
	SHER ROD CENTER (SE	PORTI		1	41.85	, 7 41.8
	BUMPER PANEL TRIM			1	1,027.25	de-1.027
	COVER SPRAY NOZZLE			1	43.25	7 22
( ), Expendit of	SHER ROD LH (SPORT)			1	22 45	7 22
	SED GRID LH (LINES SI	PORT)		1	85.05	3 85.0
FRT	LH GRILLE (SPORT)			1	128.00	128 (
	DMMET	1742		2	0.75	2 122
	BUMPER LOWER MOU	NT		1	133.80	133.
1077514517	COVER BOTTOM			1	116.55	7116
	LECTOR LIP LH			1	55 95 71 25	A41 - 71
(0.000)	QUE 82MM	TANING OVETEN		1	87 00	7 87
HO	SE LINE HEADLIGHT CLI	EANING STSTEM		- 1	150 85	7 150

# Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 18748)35598 GBT Neg. No H2-8020081-x

303, Alexandra Boad Sime Darby Performance Centre Singapore 159941 Tel. 61190100 (Sales & Admin) 63190111 (AfterBales) Fam. 64747770

280. Keepooy Arang Road East Coast Centre Bingapore 438180 Tel. 63150868 (AfterSales) Fax. 5344977)

315. Alexandra Road Sime Darmy Business Centre Singapore 15994 Tel. 63190536 (AfterSales) 6319033/530 (Motograd) Fam. 64796601 (AfterSales) 64796624 (Motograd)



GST REG. NO : M2 - 0020081 - X

### ESTIMATE

Estimate No. : b1 50305

Date Estimated : 27/02/2019

Prepared By : Gary Poh Chai Hoon Page No. : 2 of 5

REGN. NO. SKL1365Y

CHASSIS NO.

J721426

REGN. DATE 30/09/2013

MODEL 316iA/4 MILEAGE

0

QTY

DESCRIPTION DRIVER MODULE HEADLIGHTS CONTROL UNIT XENON LIGHT LH HEADLIGHT (XENON) LED MODULE LH FOG LIGHT

763.70 867.85 2,119.70 162.05 292.80

? 867.85 Cu4-2,119.70 7 162.05 7 292.80

VALUE

7 763.70

Total Parts

PRIC

7,828.50



Labour 1 3,542.00 Parts 7,828.50 Labour 2 0.00 Excess 0.00 Total GST @ 7% 795.94 Grand Total 12,166.44

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

<sup>\*\*</sup> PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

NOW Dealer

# Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197451559W GST Reg. No Mi-0015091-x

303. Alexandra Road Sime Darby Performance Centre Bingapore 159541 Tel. 63190100 (Bales & Admin) 63190111 (AfterBales) Fax. 64747770

160, Empong Arang Road East Coast Centre Singapore 438380 Tel 63190888 (AfterSales) FAX 63449773

Dit, Alexandra Hoad Sime Darty Business Centre Singapore 199944 Tel. 6119528 (AfterSales) 6119553/530 (Motorrad) Fas. 64796601 (AfterSales) 6479624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

### ESTIMATE

Estimate No.

: b1 50305 Page No. : 1 of 5

Date Estimated

: 27/02/2019

Prepared By

: Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -

Ooi Boon Peng 103 Cashew Road

#05-04

- ACCOUNT -115

United Overseas Insurance Ltd

3 Anson Road #28-01 Springleaf Tower

Singapore 079909

Singapore 679674

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SKL1365Y

J721426

30/09/2013

316iA/4

0

DESCRIPTION VALUE To replace front bumper and aatachment include knocking 1,700.00 cause by the accident ... 93 1,034.00 painting front bumper 177.00 To check electrical wiring systems at the front section for proper function including adjustments of headlights.

To replace left headlight.

481.00

Sundries.

Total Labour 1:

3,542.00

150.00

DESCRIPTION	QTY	PRIC	VALUE
FRONT SHOCK ABSORBER	1	43.00 V	/'× ? 43.00
FRT BUMPER TOP MOUNT	1	378.10	√ ₹ 378.10
INSERT AIR INTAKE CENTER	1	97.90	~ 2 97.90
FRT LH DEFORMATION ELEMENT	1	101.80	A 2 101.80
FRT LH LOWER DEFORMATION ELEMENT	1	86.40	7 4 ? 86.40
LH SUPPORT FOGLAMP	1	41.85	X 7 41.85
FINISHER ROD CENTER (SPORT)	4	41.85	7 41.85
FRT BUMPER PANEL TRIM (LINES SRA)	1	1,027.25	06-1,027.25
LH COVER SPRAY NOZZLE PRIMED	1	43.25	7/3/43.25
FINISHER ROD LH (SPORT)	1	22.45	de 7 22.45
CLOSED GRID LH (LINES SPORT)	1	85.05	85.05
FRT LH GRILLE (SPORT)	1	128.00	wn ≤ ? 128.00
GROMMET	2	0.75	X/nn 1.50
FRT BUMPER LOWER MOUNT	1	133.80	¥ (× 133.80
LH COVER BOTTOM	1	116.55	(no ) × 7116.55
DEFLECTOR LIP LH	1	55.95	× ? 55.95
PLAQUE 82MM	1	71.25	14 -71.25
HOSE LINE HEADLIGHT CLEANING SYSTEM	1	87.00	nv ₹ 87.00
LH TELESCOPING NOZZLE	-1	159.85	JUS V ? 159.85
BMW BLUE XENON BULBS (2xD1S)	1	799.45	√viX 7 799.45
BMW BLUE HALOGEN BULBS 2 X H8	1	100.15	Vm X.7 100.15



BOW Dealer

# Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 1974011559W GST Reg. No M2-0020081-X

303, Alexandra Road Sime Datby Performance Centre Singapote 189941 Tel 62190100 (Bales a Admin) 62190111 (AfterBales) Fax. 64747770

280, Kampong Arang Moad East Chast Centre Singapore 438180

Tel: 63190888 (AfterSales) Fax: 63649773

315, Alexandra Road Sime Darby Business Centre Singapore 155944 Tel. 63180528 (Afterdale 63180533/538 (Motorrad)

(Afterdales) (AfterSales) (Motorrad)



GST REG. NO : M2 - 0020081 - X

### ESTIMATE

Estimate No.

: b1 50305

Date Estimated

: 27/02/2019

Prepared By

: Gary Poh Chai Hoon

REGN. NO.

CHASSIS NO.

REGN, DATE

MODEL

MILEAGE

Page No. : 2 of 5

SKL1365Y

J721426

30/09/2013

316iA/4

0

DESCRIPTION DRIVER MODULE HEADLIGHTS CONTROL UNIT XENON LIGHT LH HEADLIGHT (XENON) LED MODULE LH FOG LIGHT

PRIC QTY 763.70 867.85 2,119.70 162.05 292.80

AM X 2 763.70 .- ×? 867.85 Cu4 -2,119.70 \* X 7 162.05 NA: X7 292.80

VALUE

Total Parts

7,828.50

500 43192 1140 taufille e (Manote von

11380.60

Labour 1 3,542.00 Parts 7,828.50 4 Labour 2 0.00 Excess 0.00 Total GST @ 7% 795.94 Grand Total 12,166.44

<sup>\*\*</sup> THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

<sup>\*\*</sup> PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A mamber of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



### SUPPLEMENTARY

Estimate No.

: b1 50305

Date Estimated : 27/02/2019

Prepared By

: Gary Poh Chai Hoon

REPAIR FOR -

Ooi Boon Peng

103 Cashew Road

#05-04

- ACCOUNT -

Page No. :

United Overseas Insurance Ltd

3 Anson Road #28-01 Springleaf Tower

Singapore 079909

Singapore 679674

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

M LEAGE

SKL1365Y

J721426

30/09/2013

3161A/4

0

DISC. % NETT DESCRIPTION ORIGINAL PRICE

DISC. % NETT DESCRIPTION UNIT PRICE QTY 10.10 Per # LH HEADLIGHT BRACKET \* 10.10 1.00

Total Labour:

Total Parts:

10.10

Total Labour & Parts:

10.10

8090 Dealer

# Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020881-x

303. Alexandra Road Sime Durby Performance Centre Bingapore 189941

Tel. 63180100 (Sales & Admin) 82180111 (AfterSales) Fax. 84747770 180. Eampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63448773 815, Alexandra Road Sime Darry Susiness Centre Simpapore 159944 Tel: 63190528 (AfterSales) 63190531/538 (Motorrad) Fex: 64796601 (AfterSales) 64796602 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50305 Page No. : 3 of 5

Date Estimated : 27/02/2019

Prepared By : Gary Poh Chai Hoon

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE

SKL1365Y J721426 30/09/2013 316iA/4 0

#### Terms & Conditions of Service

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- 2. The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements. ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- 3 Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed. PML's estimate shall prevail.
- 4 The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- 6. PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above. PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be
  liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- 6. Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- 9. The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- 10. If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- 11. If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- 12. PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- 13. These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- 14. If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.

# Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197:01559W GST Reg. No M2-0626881-W

303. Alexandrs Boad Sime Darby Performance Centre Singapore 189941

Tel. #3190100 (Hales & Admin) #3190111 (AfterSales) Fax. #4747770

380. Kampong Arang Boad Bast Coast Centre Singapore 438180

63190880 (AfterSales) 63449773

F15, Alexandra Road Sime Darty Business Bingapore 159944 Tel 61190529 (A 61190517/530 () Centire

AfterGales Motorrad Fax. Afterfales)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50305 Page No. : 4 of 5

Date Estimated : 27/02/2019

Prepared By : Gary Poh Chai Hoon

REGN. NO. REGN: DATE MODEL MILEAGE CHASSIS NO.

SKL1365Y J721426 30/09/2013 316iA/4 0

- 15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
- 16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
- 17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
  - The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to
    - (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority.
    - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer.
    - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
    - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle.
    - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides, and
    - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore
  - The Vendor shall also disclose the Customer's personal data:
    - (a) to its service providers, for example, providers of web hosting or maintenance services. for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
    - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides:
    - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
    - (d) to the Vendor's business partners for the purpose of carrying out product promotions:
    - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
    - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
    - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
  - The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later
  - If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
  - 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
  - 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
    - (a) but his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
    - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
    - (c) specify the personal data he wants access to, including any account or reference numbers where applicable

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.

SMW Dealer

# Performance Motors Limited

A member of the Sime Darby Group Co. Neg. No. 197401559W GET Beg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Pax. 64747770

280, Kampong Arang Road East Coast Centre Hingapore 438180

Tel. 63190888 |AfterSales| Fax. 63449773

SIS. Alexandra Road Sine Darry Musiness Centre Singapore 159944 Tel 63190528 (AfterSale 63190533/530 (Mucorrad)

Afterdales Pax. 64796601 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

Prepared By

: b1

50305

Page No. : 5 of 5

Date Estimated

: 27/02/2019

: Gary Poh Chai Hoon

MODEL

MILEAGE

REGN. NO.

CHASSIS NO.

REGN. DATE

SKL1365Y

J721426

30/09/2013

316iA/4

0

- The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.
- The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
  - (a) but his request in writing
  - (b) provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
  - (c) specify the information that is incorrect and what it should be replaced with

The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.

- The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovernentioned purposes set out in Clauses 17.1 and 17.2 If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or.
  - (a) put his request in writing by way of an email sent to the Vendor;
  - (b) provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer, and
  - (c) If the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer Performance Motors Limited

Address: Sime Darby Performance Centre 303 Alexandra Road Singapore 159941

Email address: dataprotection@pml com.sg

# Performance Motors Limited

A member of the Sine Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



# FINAL REPORT

Estimate No.

: b1 50305

Page No. :

Dat e Est i mat ed : 27/02/2019

Prepared By

: Gary Poh Chai Hoon

REPAIR FOR -

- ACCOUNT -

Oci Boon Peng

United Overseas Insurance Ltd

103 Cashew Road

3 Anson Road #28-01 Springleaf Tower

#05-04

Singapore 079909

Singapore 679674

REGN. NO.

CHASSIS NO.

REGN DATE

MODEL

M LEAGE

SKL1365Y	J721426	30/09/2013	316iA/4	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT
	it bumper and attachn escoping nozzle includ	nents, LH headlight de knocking caused by	850,00		850.00
To spray paint	front bumper		934.00		934.00
To check elect for proper func	rical wiring systems at tion	t the front section	150.00		150.00
	xenon headlight inclui ts for proper function		408.00		408.00
Sundries			80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER PANEL TRIM (LINES SRA)	1,027.25	1.00		1,027.25
LH COVER SPRAY NOZZLE PRIMED	43.25	1.00		43.25
FINISHER ROD LH (SPORT)	22.45	1.00		22.45
CLOSED GRID LH (LINES SPORT)	85.05	1.00		85.05
# LH HEADLIGHT BRACKET *	10.10	1.00		10.10
PLAQUE 82MM	71.25	1.00		71.25
LH TELESCOPING NOZZLE	159.85	1.00		159.85
LH HEADLIGHT (XENON)	2,119.70	1.00		2,119,70

# SUPPLEMENTARY ITEMS

Total Labour :	2,422.00
Total Parts:	3,538.90
Total Labour & Parts :	5,960.90
Deduction for Excess:	500.00
Total Repair Costs less Excess:	5,460.90
GST @7%:	382.26
Grand Total:	5,843.16



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

			nationale Des Experts En Autom	
UNIT	ED OVERSEAS I	NSURANCE LTD	Ref : CS/UOI190038	28/T1sd3e2
	SON ROAD #28-0 NGLEAF TOWER	01 R SINGAPORE 079909	Date: 15-04-2019 Code: UOI2	
1.		Policy Parti	culars :- OWN DAMAGE	
	Insured Veh.		Veh. Inspected	SKL 1365Y
	Policy No.	DHOM120013181501	Coverage (\$)	0.00
	Claim No.		Excess (\$)	500.00
	Assign From	FELIS	Assign Date	01/03/2019
2.		Vehicle Pa	articulars & Condition	
	Make & Model	B.M.W. 316I	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WBA3A12040J721426	Colour	WHITE
	Odometer	48082	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	CONTINENTAL	6 mm
	L/H Front Tyre	225/50 R17	CONTINENTAL	6 mm
	R/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm
	L/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm
4.			iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	FRONT N/S PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	
	Accident Date	20/02/2019	Inspection Date	04/03/2019
	Survey held at	PERFORMANCE MOTORS	LTD	
		303 ALEXANDRA ROAD SINGAPORE 159941		
5a.	Toron In		Remarks	
		ALUE IS \$\$67,000.00(EST. A		EPAIRS.
5b.			ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Day	8



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 1365Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
1	FRONT SHOCK ABSORBER (SN)	NOT NECESSARY	43.00	
1	FRT BUMPER TOP MOUNT (SN)	NOT NECESSARY	378.10	
1	INSERT AIR INTAKE CENTER (SN)	NOT NECESSARY	97.90	
1	FRT LH DEFORMATION ELEMENT (SN)	NOT NECESSARY	101.80	
1	FRT LH LOWER DEFORMATION ELEMENT (SN)	NOT NECESSARY	86.40	
1	LH SUPPORT FOGLAMP (SN)	NOT NECESSARY	41.85	
1	FINISHER ROD CENTER (SPORT) (SN)	NOT NECESSARY	41.85	
1	FRT BUMPER PANEL TRIM (LINES SRA) (SN)	DEFORMED	1,027.25	1,027.25
1	LH COVER SPRAY NOZZLE PRIMED (SN)	MISSING	43.25	43.25
1	FINISHER ROD LH (SPORT( (SN)	DEFORMED	22.45	22.45
1	CLOSED GRID LH (LINES SPORT) (SN)	DEFORMED	85.05	85.05
1	FRT LH GRILLE (SPORT) (SN)	NOT NECESSARY	128.00	
2	GROMMET (SN)	NOT NECESSARY	1.50	
1	FRT BUMPER LOWER MOUNT (SN)	NOT NECESSARY	133.80	
1	LH COVER BOTTOM (SN)	NOT NECESSARY	116.55	
1	DEFLECTOR LIP LH (SN)	NOT NECESSARY	55.95	
1	PLAQUE 82MM (SN)	NECESSARY	71.25	71.25
1	HOSE LINE HEADLIGHT CLEANING SYSTEM (SN)	NOT NECESSARY	87.00	-
1	LH TELESCOPING NOZZLE (SN)	DISTORTED	159.85	159.85
1	BMW BLUE XENON BULBS (2XD1S) (SN)	NOT NECESSARY	799.45	
1	BMW BLUE HALOGEN BULBS 2 X H8 (SN)	NOT NECESSARY	100.15	
1	DRIVER MODULE HEADLIGHTS (SN)	NOT NECESSARY	763.70	
1	CONTROL UNIT XENON LIGHT (SN)	NOT NECESSARY	867.85	
1	LH HEADLIGHT (XENON) (SN)	CRACKED	2,119.70	2,119.70
1	LED MODULE (SN)	NOT NECESSARY	162.05	
1	LH FOG LIGHT (SN)	NOT NECESSARY	292.80	
1	LH HEADLIGHT BRACKET (SN) (ADDITIONAL)	NECESSARY	10.10	10.10
			7,988.60	3,618.90
	LABOUR			
	TO REPLACE FRONT BUMPER AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT.		1,700.00	850.00
	PAINTING FRONT BUMPER.		1,034.00	934.00

Report Ref No. CS/UOI19003828/T1sd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.			177.00	150.00
	REPLACE LEFT HEADLIGHT.		481.00	408.00
			3,392.00	2,342.00
	GRAND TOTAL		11,380.60	5,960.90

RECOMMENDED COST OF REPAIRS	5,960.90
LESS EXCESS	-500.00
NETT LIABILITY	5,460.90

Report Ref No. CS/UOI19003828/T1sd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.