

ASSIGNMENT

Vehicle

Person

Estimated Cost

OD

To Inspect Vehicle

at Workshop

Policy No

Sum Insured

Make of Vely

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time

Date/Time

Action/Instruction

(✓) Estimate

Warp agreed Steve Sunny

SMD 71104

YMGS33A - CCC / III 17012861 / Aka 342

Don: 29/6/17

Steve

Chong Boon Sen

CS/CT119003829 / Etd3

ASSIGNMENT (Office)

CT1

Bill to

Date/Time

1/3/19 @ 11:14am

5024
NPR85

SMD 71104

Insured

YM 6533A

8K Automobile

Tel

6266 0555

48 Joh Guan Rd East # 01-121

Claim No

Remarks

D.O.A

25/02/19

H.O.D. Endorsement

Vehicle

IN/OUT

lup!

Person Contacted

Yvonne

11:41am @ 1/3/19

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum insured: _____ Excess: _____
 (Client's Record)
 Make of Vntr: _____

Vntr No: SMD 71104 Vt Regn: 31/08/18
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai Elantra cc: 1.6
 Colour: slvr A/C: Insured / Std / NI / NA
 Sp. Reading: 9969 T/Ratio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KM H10841CMJU 745374
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: _____

(Policy Condition)
 Remark: The voh had commenced its
 repair at the time of inspection.

X	X	X
N/S	O/S	

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or NEXEN

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Vol.: Yes or No

Front: _____ Rear: _____
 R/Bal: 8 mm R/Bal: 8 mm
 L/Bal: 8 mm L/Bal: 8 mm
 D.O.A: 25/2/19 D.O.I: 1/3/19
 Survey held at SK Automobile

CA / REV / REP. / 24 HRS

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time : _____ Action / Instruction

MV - 75,000
 PV - 41,507
 NV - 33,493

Stamp

Pis 200 me.

- Parts prices

3/4/19 Confir. Finest 13,800 92, 12 chs
 (Red. 9274.75: 40%)

RECEIVED 06 APR 2019

Date/Time: File Pass to?

☐ : Proff. Report
☒ : Final Report

Days Of Repair: 12

Resurvey No. of Trip: _____

Survey Fee: _____
 Transportation: _____

Date/Time: File Return to?

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		01 Mar 2019 11:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:				
Main Claimant:	LOH WEI KIAT, ID: 56932016C			
Vehicle Reg. No.:	SMD7110U	Date of Loss:	25/02/2019 14:00 - :59	
Claim Type:	TP	Policy/Cover Note No.:		
Vehicle Reg. No. (Insured):	YM6533A	Policy No. (Claimant):	CN011694	
		Excess:	S\$0.00	
Repairer:	SK Automobile Pte Ltd (Toh Guan) 48 Toh Guan Road East #01-121, Enterprise Hub, 608586 Toa Payoh - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/03/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Friday, 1 March 2019 11:18 AM
To: assignments
Subject: FW: Arrange for Pre-repair Inspection for SMD7110U (YOUR Insured: YM6533A) DOA 25 Feb 2019

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 1 March 2019 11:15 AM
To: Pioneer Workshop <pioneer@skauto.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Arrange for Pre-repair Inspection for SMD7110U (YOUR Insured: YM6533A) DOA 25 Feb 2019

Without Prejudice

Dear Sir,

We appoint LKK.

Dear LKK,

Pls pri.

We merimened.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Pioneer Workshop [mailto:pioneer@skauto.com.sg]
Sent: Friday, 1 March, 2019 10:52 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: Arrange for Pre-repair Inspection for SMD7110U (YOUR Insured: YM6533A) DOA 25 Feb 2019

Dear Boon Sen,

Please help assist arrange ADRIAN LING survey above vehicle.

On Fri, Mar 1, 2019 at 10:30 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Pioneer Workshop [<mailto:pioneer@skauto.com.sg>]

Sent: Friday, 1 March, 2019 10:26 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Fwd: Arrange for Pre-repair Inspection for SMD7110U (YOUR Insured: YM6533A) DOA 25 Feb 2019

Dear Boon Sen,

Kindly Arrange survey for below vehicle:

TP Survey Before Repair:

Our vehicle No.: SMD7110U

Your Vehicle No.: YM6533A

D.O.A : 25/02/2019

Location: 48 Toh Guan Road East #01-121 Enterpriser Hub Singapore 608586

----- Forwarded message -----

From: **Pioneer Workshop** <pioneer@skauto.com.sg>

Date: Thu, Feb 28, 2019 at 4:33 PM

Subject: Fwd: Arrange for Pre-repair Inspection for SMD7110U (YOUR Insured: YM6533A) DOA 25 Feb 2019

To: <claimsdept@sg.cntaiping.com>

Resend_Reminder

----- Forwarded message -----

From: **Pioneer Workshop** <pioneer@skauto.com.sg>

Date: Wed, Feb 27, 2019 at 4:58 PM

Subject: Fwd: Arrange for Pre-repair Inspection for SMD7110U (YOUR Insured: YM6533A) DOA 25 Feb 2019

To: <claimsdept@sg.cntaiping.com>

Resend_Reminder

----- Forwarded message -----

From: **Pioneer Workshop** <pioneer@skauto.com.sg>

Date: Wed, Feb 27, 2019 at 11:16 AM

Subject: Arrange for Pre-repair Inspection for SMD7110U (YOUR Insured: YM6533A) DOA 25 Feb 2019

To: <claimsdept@sg.cntaiping.com>

Dear Motor Claim Department

Kindly Arrange survey for below vehicle:

TP Survey Before Repair:

Our vehicle No.: SMD7110U

Your Vehicle No.: YM6533A

D.O.A : 25/02/2019

Location: 48 Toh Guan Road East #01-121 Enterpriser Hub Singapore 608586

--

Thanks & Regards,

Yvonne

SK Automobile Pte Ltd
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: pioneer@skauto.com.sg

--

Thanks & Regards,

Yvonne

SK Automobile Pte Ltd
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: pioneer@skauto.com.sg

--

Thanks & Regards,

Yvonne

SK Automobile Pte Ltd
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555

Fax: +65-6266 3155
Email: pioneer@skauto.com.sg

--

Thanks & Regards,

Yvonne

SK Automobile Pte Ltd
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: pioneer@skauto.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--

Thanks & Regards,

Yvonne

SK Automobile Pte Ltd
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: pioneer@skauto.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Steve Chen (LKK Auto)

From: Pioneer Workshop <pioneer@skauto.com.sg>
Sent: Wednesday, April 03, 2019 9:53 AM
To: Steve Chen (LKK Auto)
Subject: Re: SMD7110U Finalize

Dear Steve,

Confirm finalized @ \$13,860.92. And 12 days

On Tue, Apr 2, 2019 at 5:33 PM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Sir,

We have come out with the finalize \$13,860.92. And 12 days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2016C
Vehicle Details	
Vehicle No.:	SMD7110U
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Mar 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT (AMS)
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	G4FGJU254481
Chassis No.:	KMHD841CMJU745374
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$12,570.00
Original Registration Date:	31 Aug 2018
First Registration Date:	31 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$12,570.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2028
PARF Rebate Amount:	\$9,427.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,798.00
COE Rebate Amount:	\$32,080.00
Total Rebate Amount:	\$41,507.00

The information contained herein is correct as at 02 Mar 2019

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

23 Jun 2014 Porsche Cayenne Diesel 3.0A @ \$181,800



Agent Unit! 5 Years Warranty
From Agent! As Good As New
Condition Come (Down New)
Cars & Yachts Stock!



Lake View Credit Pte Ltd

[view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

Hyundai Elantra

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Hyundai Elantra	Any	Any	2018	Any	Any	Any	Availabl
	Hyundai Elantra 1.6A GLS	\$76,800	\$7,540 /yr	13-Jul-2018	1,591 cc	9,500 km	Sedan	Availabl
Lowest Depreciation! Buy This Low Mileage Unit With A Peace Of Mind With Full Agent Warranty. The Perfect Fuel Efficient Model. High Loans Up To 80% With Lowest Interest Rates From 2.18%. Trade In Wel...								
Posted: 01-Mar-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								
	Hyundai Elantra 1.6A GLS	\$68,800	\$6,930 /yr	31-Mar-2018	1,591 cc	36,000 km	Sedan	Availabl
Buy At The Best Depreciation! Still Under Agent Warranty. Well Maintained. The Perfect Family Car With Fuel Efficiency. Loan Available With Lowest Interest Rates From 2.18%. Trade In Welcome. Call Now...								
Posted: 25-Feb-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								
	Hyundai Elantra 1.6A GLS	\$70,000	\$7,040 /yr	11-Apr-2018	1,591 cc	20,000 km	Sedan	Availabl
Keyless Entry And Push/Start, Servicing Fully Maintained And Well Taken Care By Komoco Motors Since Day One, Accident-Free 5 Years Engine Unlimited Mileage With 5 Years Warranty Included Major Part Se...								
360 VR Cars								
Posted: 17-Feb-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								
	Hyundai Elantra 1.6A GLS	\$80,800	\$8,030 /yr	18-Jun-2018	1,591 cc	-	Sedan	Availabl
1 Owner, Low Mileage Done, Like New Interior, Agent Maintained.								
Posted: 12-Feb-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								
	LED Scuff Plate							
Hyundai Elantra LED Scuff Plate.								
More info about this product								
	Hyundai Elantra 1.6A GLS	\$72,800	\$7,500 /yr	14-Mar-2018	1,591 cc	9,963 km	Sedan	Availabl
Superb Condition.Low Mileage.Like New.Agent Warranty And Maintained.Up To 100% Flexible Loan.We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivaed Warr...								
Classic Credit Pte Ltd								
Posted: 19-Jan-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								

Compare

Save this search criteria, to get email alerts whenever a match is found.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/02/2019 11:48
Date Of Accident	25/02/2019 14:50
Exact Location Of Accident	CLEMENTI AVE 1 CASA CLEMENTI CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD7110U
Insured/Policyholder	
Name Of Registered Owner	LOH WEI KIAT
NRIC No	S6932016C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94308885
Alternative Phone No	OTHERS-94308885

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA AD 1.6 GLS AT (AMS)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN011694
Cover Note Number	

Driver

Name of Driver	LOH WEI KIAT
NRIC No	S6932016C
Date Of Birth	19/09/1969
Occupation	INDOOR
Date Of Driving Pass	05/09/1987
Driving Experience	31 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94308885
Fax Number	
Contact Number	OTHERS-94308885
Email Address	NOEMAIL

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SMD7110U

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25/02/2019 at around 14:50 Hours, just like any other school day where I waited in my vehicle, SMD711011, to fetch my daughter from school. I'm early and therefore decided to switch off my vehicle engine. I waited for a while and out of sudden, the lorry in front reversed. Immediately I sound my horn but was too late as the lorry reversed very quickly and hit onto my vehicle's front portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Kennedy John
 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name: *[Signature]*
 APOL/PRD No.: 182423728

8322 8813

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)

48 Toh Guan Road Esat #01-121

Enterprise Hub S(608586)

Tel: 6266 0555 Fax: 6266 3155

Store (LKK)

w/ L. Rajendran

1/3/19

12 pm

Rajendran

4/3/19

2/4/2019

TO	: CHINA TAIPING	DATE	: 26-Feb-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT :			
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	:	VEHICLE NO.	: SMD7110U
ADDRESS	:	MODEL / MAKE	: HYUNDAI ELANTRA
TEL. NO.	:	CHASSIS NO.	: KMHD841CMJU745374
OWNER INSURANCE	: AXA	ACCIDENT DETAIL	
POLICY NO.	: CN011694	DATE	: 25-Feb-19
		TIME	: 16:30hrs
PERSON INCHARGE :			

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BONNET / DD	1	\$ 1,526.00	\$ 1,526.00
2	FRONT BONNET HINGES LH/RH LH / RH / BT	2	\$ 88.60	\$ 177.20
3	FRONT BONNET INSULATOR MAT TN /	1	\$ 221.00	\$ 221.00
4	FRONT BONNET MECHANISM LOCK / BT	1	\$ 129.90	\$ 129.90
5	FRONT BONNET RUBBER GUIDE STOPPER LH/RH LH / RH / BT	1	\$ 10.10	\$ 40.40
6	FRONT BONNET CABLE ? CRU /	1	\$ 42.30	\$ 42.30
7	FRONT BONNET CABLE EXTENSION ? X MV	1	\$ 38.90	\$ 38.90
8	FRONT GRILLE / BR	1	\$ 461.00	\$ 461.00
9	FRONT GRILLE LOGO EMBLEM / BR	1	\$ 56.90	\$ 56.90
10	FRONT GRILLE MOULDING / CUT (C/w Item 8)	1	\$ 156.20	\$ 156.20
11	FRONT HEADLAMP LH/RH LH / RH / BR	2	\$ 1,199.80	\$ 2,399.60
12	FRONT HEADLAMP LOWER BRACKET LH/RH ? LH / RH / BT	2	\$ 98.60	\$ 197.20
13	FRONT HEADLAMP LOWER SUPPORT FRAME LH/RH ? LH / RH / BT	2	\$ 950.11	\$ 1,900.22
14	FRONT FENDER LH/RH LH / RH / DD	1	\$ 968.10	\$ 1,936.20
15	FRONT FENDER MUDFLAP LH/RH LH / RH / NN	2	\$ 72.80	\$ 145.60
16	FRONT FENDER INNER SHIELD LH/RH RH / LH / TN	2	\$ 159.34	\$ 318.68
17	FRONT BUMPER / BR	1	\$ 675.94	\$ 675.94
18	FRONT BUMPER LOWER DIFFUSER X / CRU	1	\$ 617.35	\$ 617.35
19	FRONT BUMPER REINFORCEMENT ? / DD	1	\$ 498.20	\$ 498.20
20	FRONT BUMPER TOP RUBBER SEAL / TN	1	\$ 65.30	\$ 65.30
21	FRONT BUMPER SIDE RETAINER LH/RH RH / LH / BR	2	\$ 43.61	\$ 87.22
22	FRONT BUMPER CORNER RETAINER LH/RH RH / LH / BR	2	\$ 86.70	\$ 173.40
23	FRONT BUMPER INNE SPONGE / BR	1	\$ 212.83	\$ 212.83
24	FRONT BUMPER TOP BRACKET RH / LH / BT	2	\$ 86.70	\$ 173.40
25	FRONT BUMPER DAY LAMP LH/RH X NN RH / LH / BR	2	\$ 218.40	\$ 436.80
26	FRONT BUMPER FOG LAMP LH/RH X NN	2	\$ 398.20	\$ 796.40
27	FRONT BUMPER FOG LAMP GARNISH LH/RH X NN	2	\$ 145.30	\$ 290.60

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	FRONT BUMPER NUMBER PLATE GARNISH X NN	1	\$ 189.50	\$ 189.50
29	FRONT BUMPER LOWER BEAM ? CR4	1	\$ 81.00	\$ 81.00
30	FRONT SUPPORT PANEL / CR4	1	\$ 1,159.70	\$ 1,159.70
31	FRONT SUPPORT PANEL TOP GARNISH / DP	1	\$ 179.50	\$ 179.50
32	AIRCON CONDENSER / BT	1	\$ 1,325.50	\$ 1,325.50
33	AIRCON CONDENSER AIR GUIDE LH/RH RP / LFI / CR4	2	\$ 38.90	\$ 77.80
34	AIRCON DISCHARGE PIPE ? (Small) DD	1	\$ 154.90	\$ 154.90
35	AIRCON LIQUID PIPE ? (Big) DD	1	\$ 636.50	\$ 636.50
36	AIRCON COOLING PIPE ? X NN	1	\$ 596.40	\$ 596.40
37	RADIATOR ? DD	1	\$ 1,610.30	\$ 1,610.30
38	RADIATOR TOP BRACKET LH/RH ? N/A X	2	\$ 41.50	\$ 83.00
39	RADIATOR TOP HOSE / CR4	1	\$ 148.60	\$ 148.60
40	RADIATOR NECK ? / CR4	1	\$ 101.45	\$ 101.45
41	RADIATOR NECK HOSE ? / CR4	1	\$ 90.65	\$ 90.65
42	RADIATOR FAN MOTOR WITH COWLING ? / CR4	1	\$ 596.20	\$ 596.20
43	HORN / BT	1	\$ 85.00	\$ 85.00
44	FRONT AIR DUCT NECK / CR	1	\$ 38.00	\$ 38.00
45	WASHER TANK / CR4	1	\$ 65.30	\$ 65.30
46	WASHER TANK MOTOR X NN	2	\$ 89.20	\$ 178.40
47	ENGINE LOWER UNDER COVER X / CR4	1	\$ 138.60	\$ 138.60
48	ENGINE INTAKE MANIFOLD / CR4	1	\$ 1,144.30	\$ 1,144.30
49	AIR RESONATOR BOX ASSY ? X NN	1	\$ 490.60	\$ 490.60
50	AIR CLEANER BOX ASSY ? / CR4	1	\$ 199.30	\$ 199.30
51	FRONT WIPER GRILLE X NN	1	\$ 196.40	\$ 196.40
52	FRONT WIPER GRILLE GARNISH LH/RH NN X	2	\$ 76.50	\$ 153.00

14,344.96
- 20%
11,475.96

TOTAL PRICE \$ 23,494.64
LESS -20% \$ (4,698.93)
SUB TOTAL PRICE \$ 18,795.71

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BONNET INSULATOR MAT CLIPS SET	1	\$ 50.00	\$ 50.00
2	FRONT BONNET R-134a STICKER	1	\$ 80.00	\$ 80.00
3	FRONT BONNET VEHICLE EMISSION STICKER	1	\$ 80.00	\$ 80.00
4	FRONT BONNET BELT ANCHORAGES STICKER	1	\$ 80.00	\$ 80.00
5	FRONT GRILLE CLIPS SET	1	\$ 30.00	\$ 30.00
6	FRONT BUMPER CLIPS SET	1	\$ 60.00	\$ 60.00
7	FRONT BUMPER RIVETS SET new	1	\$ 50.00	\$ 50.00
8	FRONT BUMPER NUMBER PLATE WITH CASING SET	1	\$ 65.00	\$ 65.00
9	FRONT SUPPORT PANEL TOP GARNISH CLIPS SET	1	\$ 20.00	\$ 20.00
10	FRONT FENDER INNER SHIELD CLIPS SET LH	1	\$ 60.00	\$ 60.00
11	RADIATOR COOLANT	1	\$ 80.00	\$ 80.00
12	FRONT WIPER GRILLE CLIPS SET	1	\$ 20.00	\$ 20.00
13	FRONT AIR DUCT CLIPS SET	1	\$ 10.00	\$ 10.00

TOTAL \$ 685.00

X
/
949.30/
/
789/
/
/
250.80/
X
768/
X
108.10/
/
/
/
/
/
/
X
/
/
X
/
X
X
20/
30/
30/
30
20
30
130
X NN
10
90
30
19
270

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$	1,200.00	750	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$	1,200.00	800	
TO APPLY ANTI-RUST & TUFF KOTE	\$	80.00	50	
TO PERFORM LIGHTING & WIRING CHECK	\$	80.00	30	
TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS	\$	120.00	100	
TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST	\$	120.00	60	
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$	250.00	? X	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$	280.00	120	
TO DISMANTLE & REPLACED ENGINE INTAKE MANIFOLD WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$	250.00	150	

TOTAL

\$ 3,580.00

2040

P - 11,475.96

M - 270

L - 2040

13,785.96

Supp - 74.96

13,860.92 ✓

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	19,480.71
TOTAL LABOUR COST	:	\$	3,580.00
TOTAL REPAIR COST	:	\$	23,060.71

23135-67

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS :
RE-SURVEY :
P / P OR L / S :

DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel: 6266 0555 Fax : 6266 3155

TO	: CHINA TAIPING	DATE	: 5-Mar-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT :			
<u>OWNER PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO.	: SMD7110U
ADDRESS	:	MODEL / MAKE	: HYUNDAI ELANTRA
TEL. NO.	:	CHASSIS NO.	: KMHD841CMJU745374
OWNER INSUANCE	: AXA	<u>ACCIDENT DETAIL</u>	
POLICY NO.	: CN011694	DATE	: 25-Feb-19
		TIME	: 16:30hrs
PERSON INCHARGE :			

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

SUPPLEMENTARY ITEMS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	ALAM CENTRE LOCK BUZZLE / <i>UK</i>	1	\$ 93.70	\$ 93.70
TOTAL PRICE				\$ 93.70
LESS -20%				\$ (18.74)
SUB TOTAL PRICE				<u>\$ 74.96</u>

APPROVED DETAILS

DATE / TIME OF RESURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

SK Automobile Pte. Ltd.
 (Co Reg. No. 201500047H)
 48 Toh Guan Road Esat #01-121
 Enterprise Hub S(608586)
 Tel: 6266 0555 Fax : 6266 3155

TO	: CHINA TAIPING	DATE	: 5-Mar-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	:		
<u>OWNER PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO.	: SMD7110U
ADDRESS	:	MODEL / MAKE	: HYUNDAI ELANTRA
TEL. NO.	:	CHASSIS NO.	: KMHD841CMJU745374
OWNER INSUANCE	: AXA	<u>ACCIDENT DETAIL</u>	
POLICY NO.	: CN011694	DATE	: 25-Feb-19
		TIME	: 16:30hrs
PERSON INCHARGE	:		

QUOTATION SUMMARY PAGE 01
 CLAIMS DETAIL : PARTS LIST SUPPLEMENTARY ITEMS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	ALAM CENTRE LOCK BUZZLE	1	\$ 93.70	\$ 93.70
TOTAL PRICE				\$ 93.70
LESS -20%				\$ (18.74)
SUB TOTAL PRICE				<u>\$ 74.96</u>

APPROVED DETAILS

DATE / TIME OF RESURVEY :
 SURVEYED BY / FROM :
 CONTACT NUMBER :
 FAX NUMBER :
 EMAIL ADDRESS :

LIS / P/P ? 8322 8813 Steve (LKK)
 SK Automobile Pte. Ltd. with signature
 (Co Reg. No. 201500047H) 1/3/19
 48 Toh Guan Road Esat #01-121 12 pm 12 1 chgs
 Enterprise Hub S(608586)
 Tel: 6266 0555 Fax: 6266 3155

TO	: CHINA TAIPING	DATE	: 26-Feb-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	:		
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	:	VEHICLE NO.	: SMD7110U
ADDRESS	:	MODEL / MAKE	: HYUNDAI ELANTRA
TEL. NO.	:	CHASSIS NO.	: KMHD841CMJU745374
OWNER INSURANCE	: AXA	ACCIDENT DETAIL	
POLICY NO.	: CN011694	DATE	: 25-Feb-19
PERSON INCHARGE	:	TIME	: 16:30hrs

QUOTATION SUMMARY PAGE 01
 CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BONNET / DD	1	\$ 1,526.00	\$ 1,526.00
2	FRONT BONNET HINGES LH/RH LH / RH / BT	2	\$ 88.60	\$ 177.20
3	FRONT BONNET INSULATOR MAT TN /	1	\$ 221.00	\$ 221.00
4	FRONT BONNET MECHANISM LOCK / BT	1	\$ 129.90	\$ 129.90
5	FRONT BONNET RUBBER GUIDE STOPPER LH/RH LH / RH / PH	4	\$ 10.10	\$ 40.40
6	FRONT BONNET CABLE	1	\$ 42.30	\$ 42.30
7	FRONT BONNET CABLE EXTENSION	1	\$ 38.90	\$ 38.90
8	FRONT GRILLE / BR	1	\$ 461.00	\$ 461.00
9	FRONT GRILLE LOGO EMBLEM / BR	1	\$ 56.90	\$ 56.90
10	FRONT GRILLE MOULDING / CUT	1	\$ 156.20	\$ 156.20
11	FRONT HEADLAMP LH/RH LH / RH / BR	2	\$ 1,199.80	\$ 2,399.60
12	FRONT HEADLAMP LOWER BRACKET LH/RH LH / RH / PH	2	\$ 98.60	\$ 197.20
13	FRONT HEADLAMP LOWER SUPPORT FRAME LH/RH RH / LH / PH	2	\$ 950.11	\$ 1,900.22
14	FRONT FENDER LH/RH LH x RH x	2	\$ 968.10	\$ 1,936.20
15	FRONT FENDER MUDFLAP LH/RH LH x RH x PH	2	\$ 72.80	\$ 145.60
16	FRONT FENDER INNER SHIELD LH/RH RH / LH x TN	2	\$ 159.34	\$ 318.68
17	FRONT BUMPER / BR	1	\$ 675.94	\$ 675.94
18	FRONT BUMPER LOWER DIFFUSER	1	\$ 617.35	\$ 617.35
19	FRONT BUMPER REINFORCEMENT	1	\$ 498.20	\$ 498.20
20	FRONT BUMPER TOP RUBBER SEAL / TN	1	\$ 65.30	\$ 65.30
21	FRONT BUMPER SIDE RETAINER LH/RH RH / LH / BR	2	\$ 43.61	\$ 87.22
22	FRONT BUMPER CORNER RETAINER LH/RH RH / LH /	2	\$ 86.70	\$ 173.40
23	FRONT BUMPER INNE SPONGE / BR	1	\$ 212.83	\$ 212.83
24	FRONT BUMPER TOP BRACKET RH / LH /	2	\$ 86.70	\$ 173.40
25	FRONT BUMPER DAY LAMP LH/RH x RH / RH /	2	\$ 218.40	\$ 436.80
26	FRONT BUMPER FOG LAMP LH/RH x TN	2	\$ 398.20	\$ 796.40
27	FRONT BUMPER FOG LAMP GARNISH LH/RH x TN	2	\$ 145.30	\$ 290.60

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	FRONT BUMPER NUMBER PLATE GARNISH Y <i>NN</i>	1	\$ 180.50	\$ 180.50
29	FRONT BUMPER LOWER BEAM 2 / <i>CRV</i>	1	\$ 81.00	\$ 81.00
30	FRONT SUPPORT PANEL / <i>CRV</i>	1	\$ 1,159.70	\$ 1,159.70
31	FRONT SUPPORT PANEL TOP GARNISH / <i>DP</i>	1	\$ 179.50	\$ 179.50
32	AIRCON CONDENSER / <i>BT</i>	1	\$ 1,325.50	\$ 1,325.50
33	AIRCON CONDENSER AIR GUIDE LH/RH <i>RH / LH</i>	2	\$ 38.90	\$ 77.80
34	AIRCON DISCHARGE PIPE 2 / <i>(2nd)</i>	1	\$ 154.90	\$ 154.90
35	AIRCON LIQUID PIPE 2 / <i>(1st)</i>	1	\$ 636.50	\$ 636.50
36	AIRCON COOLING PIPE 2 <i>X</i>	1	\$ 596.40	\$ 596.40
37	RADIATOR 2 / <i>1</i>	1	\$ 1,610.30	\$ 1,610.30
38	RADIATOR TOP BRACKET LH/RH 2 <i>X</i>	2	\$ 41.50	\$ 83.00
39	RADIATOR TOP HOSE / <i>CRV</i>	1	\$ 148.60	\$ 148.60
40	RADIATOR NECK 2 / <i>1</i>	1	\$ 101.45	\$ 101.45
41	RADIATOR NECK HOSE 2 <i>CRV</i> 2 / <i>1</i>	1	\$ 90.65	\$ 90.65
42	RADIATOR FAN MOTOR WITH COWLING 2 / <i>1</i>	1	\$ 596.20	\$ 596.20
43	HORN / <i>BT</i>	1	\$ 85.00	\$ 85.00
44	FRONT AIR DUCT NECK / <i>DP</i>	1	\$ 38.00	\$ 38.00
45	WASHER TANK / <i>CRV</i>	1	\$ 65.30	\$ 65.30
46	WASHER TANK MOTOR 2 <i>X</i>	2	\$ 80.20	\$ 178.40
47	ENGINE LOWER UNDER COVER 2 / <i>1</i>	1	\$ 138.60	\$ 138.60
48	ENGINE INTAKE MANIFOLD / <i>CRA</i>	1	\$ 1,144.30	\$ 1,144.30
49	AIR RESONATOR BOX ASSY 2 <i>X</i>	1	\$ 490.60	\$ 490.60
50	AIR CLEANER BOX ASSY 2 / <i>1</i>	1	\$ 199.30	\$ 199.30
51	FRONT WIPER GRILLE 2 <i>NN</i>	1	\$ 196.40	\$ 196.40
52	FRONT WIPER GRILLE GARNISH LH/RH 2 <i>NN X</i>	2	\$ 76.50	\$ 153.00

TOTAL PRICE \$ 23,494.64 \$19,168.00
 LESS -20% \$ (4,698.93) \$(3,833.60)
 SUB TOTAL PRICE \$ 18,795.71 \$15,334.40

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BONNET INSULATOR MAT CLIPS SET	1	\$ 50.00	\$ 50.00 <i>20</i>
2	FRONT BONNET R-134a STICKER	1	\$ 80.00	\$ 80.00 <i>30</i>
3	FRONT BONNET VEHICLE EMISSION STICKER	1	\$ 80.00	\$ 80.00 <i>30</i>
4	FRONT BONNET BELT ANCHORAGES STICKER	1	\$ 80.00	\$ 80.00 <i>30</i>
5	FRONT GRILLE CLIPS SET	1	\$ 30.00	\$ 30.00 <i>20</i>
6	FRONT BUMPER CLIPS SET	1	\$ 60.00	\$ 60.00 <i>30</i>
7	FRONT BUMPER RIVETS SET	1	\$ 50.00	\$ 50.00 <i>30</i>
8	FRONT BUMPER NUMBER PLATE WITH CASING SET	1	\$ 65.00	\$ 65.00 <i>X</i>
9	FRONT SUPPORT PANEL TOP GARNISH CLIPS SET	1	\$ 20.00	\$ 20.00 <i>10</i>
10	FRONT FENDER INNER SHIELD CLIPS SET LH	1	\$ 60.00	\$ 60.00 <i>30</i>
11	RADIATOR COOLANT	1	\$ 80.00	\$ 80.00 <i>30</i>
12	FRONT WIPER GRILLE CLIPS SET	1	\$ 20.00	\$ 20.00 <i>10</i>
13	FRONT AIR DUCT CLIPS SET	1	\$ 10.00	\$ 10.00 <i>1</i>

TOTAL \$ 685.00 \$270.00

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,200.00	75 ⁰	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,200.00	800	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 80.00	50	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS	\$ 120.00	100	
TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST	\$ 120.00	60	
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 250.00	2X	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 280.00	100	
TO DISMANTLE & REPLACED ENGINE INTAKE MANIFOLD WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 250.00	150	

TOTAL \$ 3,580.00 \$2,040.00

QUOTATION SUMMARY

PAGE 04

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	19,480.71
TOTAL LABOUR COST	:	\$	3,580.00
TOTAL REPAIR COST	:	\$	<u>23,060.71</u>

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS :
RE-SURVEY :
P / P OR L / S :

DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

Parts	\$	19,168.00
Supplementary	\$	93.70
	\$	19,261.70
Less 20%	\$	3,852.34
	\$	1,5409.36
SN	\$	270.00
	\$	15,679.36
Labour	\$	2,040.00
	\$	17,719.36

8322 8813
 L15 / P/P ?
 SK Automobile Pte. Ltd.
 (Co Reg. No. 201500047H)
 48 Toh Guan Road Esat #01-121
 Enterprise Hub S(608586)
 Tel: 6266 0555 Fax : 6266 3155
 Steve (LKK)
 with prejudice
 1/3/19
 12 pm 12 4 chgs
 Re b6 & A-87

TO	: CHINA TAIPING	DATE	: 26-Feb-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	:		
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	:	VEHICLE NO.	: SMD7110U
ADDRESS	:	MODEL / MAKE	: HYUNDAI ELANTRA
TEL. NO.	:	CHASSIS NO.	: KMHD841CMJU745374
OWNER INSURANCE	: AXA	ACCIDENT DETAIL	
POLICY NO.	: CN011694	DATE	: 25-Feb-19
PERSON INCHARGE	:	TIME	: 16:30hrs

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BONNET / DD	1	\$ 1,526.00	\$ 1,526.00
2	FRONT BONNET HINGES LH/RH LH / RH / BT	2	\$ 88.60	\$ 177.20
3	FRONT BONNET INSULATOR MAT TN /	1	\$ 221.00	\$ 221.00
4	FRONT BONNET MECHANISM LOCK / BT	1	\$ 129.90	\$ 129.90
5	FRONT BONNET RUBBER GUIDE STOPPER LH/RH LH / RH / RHP	4	\$ 10.10	\$ 40.40
6	FRONT BONNET CABLE / CR	1	\$ 42.30	\$ 42.30
7	FRONT BONNET CABLE EXTENSION / X NN	1	\$ 38.90	\$ 38.90
8	FRONT GRILLE / BR	1	\$ 461.00	\$ 461.00
9	FRONT GRILLE LOGO EMBLEM / BR	1	\$ 56.90	\$ 56.90
10	FRONT GRILLE MOULDING / CUT	1	\$ 156.20	\$ 156.20
11	FRONT HEADLAMP LH/RH LH / RH / BR	2	\$ 1,199.80	\$ 2,399.60
12	FRONT HEADLAMP LOWER BRACKET LH/RH / LH / RH /	2	\$ 98.60	\$ 197.20
13	FRONT HEADLAMP LOWER SUPPORT FRAME LH/RH / RH / LH /	2	\$ 950.11	\$ 1,900.22
14	FRONT FENDER LH/RH LH x RH /	2	\$ 968.10	\$ 1,936.20
15	FRONT FENDER MUDFLAP LH/RH LH x RH x NN	2	\$ 72.80	\$ 145.60
16	FRONT FENDER INNER SHIELD LH/RH RH / LH x TN	2	\$ 159.34	\$ 318.68
17	FRONT BUMPER / BR	1	\$ 675.94	\$ 675.94
18	FRONT BUMPER LOWER DIFFUSER /	1	\$ 617.35	\$ 617.35
19	FRONT BUMPER REINFORCEMENT / DD	1	\$ 498.20	\$ 498.20
20	FRONT BUMPER TOP RUBBER SEAL / TN	1	\$ 65.30	\$ 65.30
21	FRONT BUMPER SIDE RETAINER LH/RH RH / LH / BR	2	\$ 43.61	\$ 87.22
22	FRONT BUMPER CORNER RETAINER LH/RH RH / LH /	2	\$ 86.70	\$ 173.40
23	FRONT BUMPER INNE SPONGE / BR	1	\$ 212.83	\$ 212.83
24	FRONT BUMPER TOP BRACKET RH / LH /	2	\$ 86.70	\$ 173.40
25	FRONT BUMPER DAY LAMP LH/RH / RH / RLH /	2	\$ 218.40	\$ 436.80
26	FRONT BUMPER FOG LAMP LH/RH x NN	2	\$ 398.20	\$ 796.40
27	FRONT BUMPER FOG LAMP GARNISH LH/RH x NN	2	\$ 145.30	\$ 290.60

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	FRONT BUMPER NUMBER PLATE GARNISH X NN	1	\$ 189.50	\$ 189.50 X
29	FRONT BUMPER LOWER BEAM 2 / CRU	1	\$ 81.00	\$ 81.00 /
30	FRONT SUPPORT PANEL / CRU	1	\$ 1,159.70	\$ 1,159.70 949.30 /
31	FRONT SUPPORT PANEL TOP GARNISH / DP	1	\$ 179.50	\$ 179.50 /
32	AIRCON CONDENSER / DT	1	\$ 1,325.50	\$ 1,325.50 789 /
33	AIRCON CONDENSER AIR GUIDE LH/RH RFI / LFI /	2	\$ 38.90	\$ 77.80 /
34	AIRCON DISCHARGE PIPE 2 / (mm) DO	1	\$ 154.90	\$ 154.90 /
35	AIRCON LIQUID PIPE 2 (mm) / DO	1	\$ 636.50	\$ 636.50 250.50 /
36	AIRCON COOLING PIPE 2 X NN	1	\$ 596.40	\$ 596.40 X
37	RADIATOR 2 / DO	1	\$ 1,610.30	\$ 1,610.30 768 /
38	RADIATOR TOP BRACKET LH/RH 1 X NN	2	\$ 41.50	\$ 83.00 X
39	RADIATOR TOP HOSE / CRU	1	\$ 148.60	\$ 148.60 108.10 /
40	RADIATOR NECK 2 / CRU	1	\$ 101.45	\$ 101.45 /
41	RADIATOR NECK HOSE 2 / CRU	1	\$ 90.65	\$ 90.65 /
42	RADIATOR FAN MOTOR WITH COWLING 2 / CRU	1	\$ 596.20	\$ 596.20 /
43	HORN / DT	1	\$ 85.00	\$ 85.00 /
44	FRONT AIR DUCT NECK / DP	1	\$ 38.00	\$ 38.00 /
45	WASHER TANK / CRU	1	\$ 65.30	\$ 65.30 /
46	WASHER TANK MOTOR X NN	2	\$ 89.20	\$ 178.40 X
47	ENGINE LOWER UNDER COVER 2 / CRU	1	\$ 138.60	\$ 138.60 /
48	ENGINE INTAKE MANIFOLD / CRA	1	\$ 1,144.30	\$ 1,144.30 958.10 /
49	AIR RESONATOR BOX ASSY 2 X NN	1	\$ 490.60	\$ 490.60 X
50	AIR CLEANER BOX ASSY 2 / CRU	1	\$ 199.30	\$ 199.30 /
51	FRONT WIPER GRILLE X NN	1	\$ 196.40	\$ 196.40 X
52	FRONT WIPER GRILLE GARNISH LH/RH NN X	2	\$ 76.50	\$ 153.00 X
TOTAL PRICE				\$ 23,494.64
LESS -20%				\$ (4,698.93)
SUB TOTAL PRICE				\$ 18,795.71

14,295.16

- 20%

11,436.12

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BONNET INSULATOR MAT CLIPS SET	1	\$ 50.00	\$ 50.00 20 /
2	FRONT BONNET R-134a STICKER	1	\$ 80.00	\$ 80.00 30 /
3	FRONT BONNET VEHICLE EMISSION STICKER	1	\$ 80.00	\$ 80.00 30 /
4	FRONT BONNET BELT ANCHORAGES STICKER	1	\$ 80.00	\$ 80.00 30 /
5	FRONT GRILLE CLIPS SET	1	\$ 30.00	\$ 30.00 20 /
6	FRONT BUMPER CLIPS SET	1	\$ 60.00	\$ 60.00 30 /
7	FRONT BUMPER RIVETS SET	1	\$ 50.00	\$ 50.00 30 /
8	FRONT BUMPER NUMBER PLATE WITH CASING SET	1	\$ 65.00	\$ 65.00 X
9	FRONT SUPPORT PANEL TOP GARNISH CLIPS SET	1	\$ 20.00	\$ 20.00 10 /
10	FRONT FENDER INNER SHIELD CLIPS SET LH	1	\$ 60.00	\$ 60.00 20 /
11	RADIATOR COOLANT	1	\$ 80.00	\$ 80.00 30 /
12	FRONT WIPER GRILLE CLIPS SET	1	\$ 20.00	\$ 20.00 10 /
13	FRONT AIR DUCT CLIPS SET	1	\$ 10.00	\$ 10.00 /

TOTAL

\$ 685.00

279

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,200.00	750	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,200.00	800	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 80.00	50	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS	\$ 120.00	100	
TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST	\$ 120.00	60	
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 250.00	2X	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 280.00	100	
TO DISMANTLE & REPLACED ENGINE INTAKE MANIFOLD WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 250.00	150	

TOTAL

\$ 3,580.00

2049

Total - 13,746.12
 Supp - 9379
 13,839.82

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	19,480.71
TOTAL LABOUR COST	:	\$	3,580.00
TOTAL REPAIR COST	:	\$	<u>23,060.71</u>

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS :
RE-SURVEY :
P / P OR L / S :

DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Apr 2019 16:29		01 Mar 2019 11:14 Edit Adj Rpt	S\$13,860.93 Edit Estimates	S\$13,860.93 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	ID: -								
Main Claimant:	LOH WEI KIAT, ID: S6932016C								
Vehicle Reg. No.:	SMD7110U	Date of Loss:	25/02/2019 14:00 - :59 [5 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	YM6533A	Policy No. (Claimant):	CN011694						
		Excess:	S\$0.00						
Repairer:	SK Automobile Pte Ltd (Toh Guan) 48 Toh Guan Road East #01-121, Enterprise Hub, 608586 Jurong East - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 12/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMD7110U
[YM6533A]
TP
LOH WEI KIAT
Feb 25 2019 2:00PM
[-]
SK Automobile Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	☒	
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print
1	26/02/19 11:56	Accident Statement		Load HTML	
Photos/Images			3 per page	☒	
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print
1	26/02/19 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	26/02/19 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	26/02/19 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	26/02/19 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	26/02/19 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	26/02/19 11:56	Driving License [Linked Accident Report Documents]		Load JPG	☒
7	26/02/19 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	26/02/19 11:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	26/02/19 11:56	Driving License [Linked Accident Report Documents]		Load JPG	☒
10	26/02/19 11:56	Insurance policy [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/03/19 11:34	General View		Load JPG	☒
2	02/03/19 11:34	General View		Load JPG	☒
3	02/03/19 11:34	General View		Load JPG	☒
4	02/03/19 11:34	General View		Load JPG	☒
5	02/03/19 11:34	General View		Load JPG	☒
6	02/03/19 11:34	General View		Load JPG	☒
7	02/03/19 11:34	General View		Load JPG	☒
8	02/03/19 11:34	General View		Load JPG	☒
9	02/03/19 11:34	General View		Load JPG	☒
10	02/03/19 11:34	General View		Load JPG	☒
11	02/03/19 11:34	General View		Load JPG	☒
12	02/03/19 11:34	General View		Load JPG	☒
13	02/03/19 11:34	General View		Load JPG	☒
14	02/03/19 11:34	General View		Load JPG	☒
15	02/03/19 11:34	General View		Load JPG	☒
16	02/03/19 11:34	General View		Load JPG	☒
17	02/03/19 11:34	General View		Load JPG	☒
18	02/03/19 11:34	General View		Load JPG	☒
19	02/03/19 11:34	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail Print
20	02/03/19 11:34	General View		☒
21	02/03/19 11:34	General View		☒
22	02/03/19 11:34	General View		☒
23	02/03/19 11:34	General View		☒
24	02/03/19 11:34	General View		☒
25	02/03/19 11:34	General View		☒
26	02/03/19 11:34	General View		☒
27	02/03/19 11:34	General View		☒
28	02/03/19 11:34	General View		☒
29	02/03/19 11:34	General View		☒
30	02/03/19 11:34	General View		☒
31	02/03/19 11:34	General View		☒
32	02/03/19 11:34	General View		☒
33	02/03/19 11:34	General View		☒
34	02/03/19 11:34	General View		☒
35	02/03/19 11:34	General View		☒
36	02/03/19 11:34	General View		☒
37	02/03/19 11:34	General View		☒
38	02/03/19 11:34	General View		☒
39	02/03/19 11:34	General View		☒
40	02/03/19 11:34	General View		☒
41	02/03/19 11:34	Odometer Reading		☒
42	02/03/19 11:34	Chassis Number		☒
43	02/03/19 11:34	General View		☒
44	02/03/19 11:34	General View		☒
45	02/03/19 11:34	General View		☒
46	02/03/19 11:34	General View		☒
47	02/03/19 11:34	General View		☒
48	02/03/19 11:34	General View		☒
49	02/03/19 11:34	General View		☒
50	02/03/19 11:34	General View		☒
51	02/03/19 11:34	General View		☒
52	02/03/19 11:34	General View		☒
53	02/03/19 11:34	General View		☒
54	02/03/19 11:34	General View		☒
55	02/03/19 11:34	General View		☒
56	02/03/19 11:34	General View		☒
57	02/03/19 11:34	General View		☒
58	02/03/19 11:34	General View		☒
59	02/03/19 11:34	General View		☒
60	02/03/19 11:34	General View		☒
61	02/03/19 11:34	General View		☒
62	02/03/19 11:34	General View		☒
63	02/03/19 11:34	General View		☒
64	02/03/19 11:34	General View		☒
65	02/03/19 11:34	General View		☒
66	02/03/19 11:34	General View		☒
67	02/03/19 11:34	General View		☒
68	02/03/19 11:34	General View		☒
69	02/03/19 11:34	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
70	02/03/19 11:34	General View	 Load JPG	☒
71	02/03/19 11:34	General View	 Load JPG	☒
72	02/03/19 11:34	General View	 Load JPG	☒
73	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
74	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
75	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
76	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
77	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
78	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
79	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
80	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
81	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
82	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
83	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
84	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
85	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
86	05/04/19 17:26	Reinspection Photo	 Load JPG	☒
87	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
88	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
89	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
90	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
91	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
92	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
93	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
94	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
95	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
96	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
97	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
98	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
99	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
100	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
101	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
102	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
103	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
104	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
105	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
106	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
107	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
108	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
109	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
110	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
111	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
112	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
113	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
114	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
115	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
116	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
117	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
118	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
119	05/04/19 17:27	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)		
120	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
121	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
122	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
123	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
124	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
125	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
126	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
127	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
128	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
129	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
130	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
131	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
132	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
133	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
134	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
135	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
136	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
137	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
138	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
139	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
140	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
141	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
142	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
143	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
144	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
145	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
146	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
147	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
148	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
149	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
150	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
151	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
152	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
153	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
154	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
155	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
156	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
157	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
158	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
159	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
160	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
161	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
162	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
163	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
164	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
165	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
166	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
167	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
168	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
169	05/04/19 17:27	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
170	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
171	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
172	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
173	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
174	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
175	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
176	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
177	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
178	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
179	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
180	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
181	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
182	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
183	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
184	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
185	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
186	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
187	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
188	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
189	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
190	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
191	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
192	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
193	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
194	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
195	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
196	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
197	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
198	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
199	05/04/19 17:27	Reinspection Photo	 Load JPG	☒
200	05/04/19 17:27	Photo After Spray	 Load JPG	☒
201	05/04/19 17:27	Photo After Spray	 Load JPG	☒
202	05/04/19 17:27	Photo After Spray	 Load JPG	☒
203	05/04/19 17:27	Photo After Spray	 Load JPG	☒
204	05/04/19 17:27	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/03/19 11:14	PRI CONTACT	 Load PDF	
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	26/02/19 11:56	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	26/02/19 11:56	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	26/02/19 11:56	Accident Statement	 Load HTML	

Assessment Reports			1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
Photos/Images			3 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	26/02/19 11:56	Accident Photo		☒
2	26/02/19 11:56	Accident Photo		☒
3	26/02/19 11:56	Accident Photo		☒
4	26/02/19 11:56	Accident Photo		☒
5	26/02/19 11:56	Accident Photo		☒
6	26/02/19 11:56	Driving License		☒
7	26/02/19 11:56	Accident Photo		☒
8	26/02/19 11:56	Accident Photo		☒
9	26/02/19 11:56	Driving License		☒
10	26/02/19 11:56	Insurance policy		☒
Documentation			1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	26/02/19 11:56	Sketch Plan		☒
2	26/02/19 11:56	Sketch Plan #2		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119003829/ETD3Q2

Date: 23/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle No: SMD7110U

Insured Vehicle No: YM6533A

Date of Loss: 25/02/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD7110U

Make & Model: HYUNDAI ELANTRA, 1.6 (A)

Engine No: G4FGJU254481

Reg. Date: 31/08/2018 (Man. Year: 2018)

Chassis No: KMHD841CMJU745374

Colour: Silver

Odometer: 9969 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Nexen 8 mm

Rear Left Side: Nexen 8 mm

Front Right Side: Nexen 8 mm

Rear Right Side: Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,555.67	11,820.93	7,734.74	39.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	2,040.00	1,540.00	43.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,135.67	13,860.93	9,274.74	40.09
+ GST 7.00/7.00% (S\$)	1,619.50	970.27	649.23	40.09
Nett Amount (S\$)	24,755.17	14,831.20	9,923.97	40.09

INSPECTION

Date of Assignment: 01/03/2019

Date Inspected: 01/03/2019 Inspected At:

SK Automobile Pte Ltd (Toh Guan)
48 Toh Guan Road East #01-121,
Enterprise Hub
Singapore 608586

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$13,860.92

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2019)	
Parts: 143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMD7110U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET	Dented	1,526.00 FL	*1,526.00 FL
2	2	*FRONT BONNET HINGES LH/RH	Bent	177.20 FL	*177.20 FL
3	1	*FRONT BONNET INSULATOR MAT	Torn	221.00 FL	*221.00 FL
4	1	*FRONT BONNET MECHANISM LOCK	Bent	129.90 FL	*129.90 FL
5	4	*FRONT BONNET RUBBER GUIDE STOPPER LH/RH	Not Necessary	40.40 FL	*- FL
6	1	*FRONT BONNET CABLE	Cracked	42.30 FL	*42.30 FL
7	1	*FRONT BONNET CABLE EXTENSION	Not Necessary	38.90 FL	*- FL
8	1	*FRONT GRILLE LOGO EMBLEM	Broken	56.90 FL	*56.90 FL
9	1	*FRONT GRILLE }	Broken	461.00 FL	*461.00 FL
10	1	*FRONT GRILLE MOULDING)	Cut	156.20 FL	*- FL
11	2	*FRONT HEADLAMP LH/RH	Broken	2,399.60 FL	*2,399.60 FL
12	2	*FRONT HEADLAMP LOWER BRACKET LH/RH	Broken	197.20 FL	*44.00 FL
13	2	*FRONT HEADLAMP LOWER SUPPORT FRAME LH/RH	Broken	1,900.22 FL	*70.00 FL
14	1	*FRONT FENDER LH/RH	O/S Dented	1,936.20 FL	*968.10 FL
15	2	*FRONT FENDER MUDFLAP LH/RH	Not Necessary	145.60 FL	*- FL
16	1	*FRONT FENDER INNER SHIELD LH/RH	O/S Torn	318.68 FL	*159.34 FL
17	1	*FRONT BUMPER	Broken	675.94 FL	*494.40 FL
18	1	*FRONT BUMPER LOWER DIFFUSER	Cracked	617.35 FL	*225.00 FL
19	1	*FRONT BUMPER REINFORCEMENT	Dented	498.20 FL	*498.20 FL
20	1	*FRONT BUMPER TOP RUBBER SEAL	Torn	65.30 FL	*65.30 FL
21	2	*FRONT BUMPER SIDE RETAINER LH/RH	Broken	87.22 FL	*87.22 FL
22	2	*FRONT BUMPER CORNER RETAINER LH/RH	Broken	173.40 FL	*173.40 FL
23	1	*FRONT BUMPER INNER SPONGE	Broken	212.83 FL	*118.70 FL
24	2	*FRONT BUMPER TOP BRACKET	Bent	173.40 FL	*173.40 FL
25	2	*FRONT BUMPER DAY LAMP LH/RH	Broken	436.80 FL	*436.80 FL
26	2	*FRONT BUMPER FOG LAMP LH/RH	Not Necessary	796.40 FL	*- FL
27	2	*FRONT BUMPER FOG LAMP GARNISH LH/RH	Not Necessary	290.60 FL	*- FL
28	1	*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	189.50 FL	*- FL
29	1	*FRONT BUMPER LOWER BEAM	Crushed	81.00 FL	*81.00 FL
30	1	*FRONT SUPPORT PANEL	Crushed	1,159.70 FL	*949.30 FL
31	1	*FRONT SUPPORT PANEL TOP GARNISH	Broken	179.50 FL	*179.50 FL
32	1	*AIRCON CONDENSER	Bent	1,325.50 FL	*789.00 FL
33	2	*AIRCON CONDENSER AIR GUIDE LH/RH	Crushed	77.80 FL	*77.80 FL
34	1	*AIRCON DISCHARGE PIPE (SMALL)	Dented	154.90 FL	*154.90 FL
35	1	*AIRCON LIQUID PIPE (BIG)	Dented	636.50 FL	*250.80 FL
36	1	*AIRCON COOLING PIPE	Not Necessary	596.40 FL	*- FL
37	1	*RADIATOR	Dented	1,610.30 FL	*768.00 FL
38	2	*RADIATOR TOP BRACKET LH/RH	Not Necessary	83.00 FL	*- FL
39	1	*RADIATOR TOP HOSE	Crushed	148.60 FL	*108.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*RADIATOR NECK	Crushed	101.45 FL	*101.45 FL
41	1		*RADIATOR NECK HOSE	Crushed	90.65 FL	*90.65 FL
42	1		*RADIATOR FAN MOTOR WITH COWLING	Crushed	596.20 FL	*596.20 FL
43	1		*HORN	Bent	85.00 FL	*85.00 FL
44	1		*FRONT AIR DUCT NECK	Broken	38.00 FL	*38.00 FL
45	1		*WASHER TANK	Crushed	65.30 FL	*65.30 FL
46	2		*WASHER TANK MOTOR	Not Necessary	178.40 FL	*- FL
47	1		*ENGINE LOWER UNDER COVER	Crushed	138.60 FL	*138.60 FL
48	1		*ENGINE INTAKE MANIFOLD	Cracked	1,144.30 FL	*1,144.30 FL
49	1		*AIR RESONATOR BOX ASSY	Not Necessary	490.60 FL	*- FL
50	1		*AIR CLEANER BOX ASSY	Crushed	199.30 FL	*199.30 FL
51	1		*FRONT WIPER GRILLE	Not Necessary	196.40 FL	*- FL
52	2		*FRONT WIPER GRILLE GARNISH LH/RH	Not Necessary	153.00 FL	*- FL
53	1		*SET FRONT BONNET INSULATOR MAT CLIPS	Necessary	50.00 FS	*20.00 FS
54	1		*FRONT BONNET R-134a STICKER	Necessary	80.00 FS	*30.00 FS
55	1		*FRONT BONNET VEHICLE EMISSION STICKER	Necessary	80.00 FS	*30.00 FS
56	1		*FRONT BONNET BELT ANCHORAGES STICKER	Necessary	80.00 FS	*30.00 FS
57	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
58	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
59	1		*SET FRONT BUMPER RIVETS	Necessary	50.00 FS	*30.00 FS
60	1		*SET FRONT BUMPER NUMBER PLATE WITH CASING	Not Necessary	65.00 FS	*- FS
61	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
62	1		*SET FRONT FENDER INNER SHIELD CLIPS LH	Necessary	60.00 FS	*20.00 FS
63	1		*RADIATOR COOLANT	Necessary	80.00 FS	*30.00 FS
64	1		*SET FRONT WIPER GRILLE CLIPS	Necessary	20.00 FS	*10.00 FS
65	1		*SET FRONT AIR DUCT CLIPS	Necessary	10.00 FS	*10.00 FS
66	1		*ALAM CENTRE LOCK BUZZLE	Broken	93.70 FL	*93.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	24,273.34	14,708.66
- List Item Discount on L Items 20.00/20.00% (S\$)	4,717.67	2,887.73
Total Parts (S\$)	19,555.67	11,820.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,200.00	750.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,200.00	800.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	80.00	50.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS	New	120.00	100.00
6	TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST	New	120.00	60.00
7	TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	New	250.00	0.00
8	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	280.00	100.00
9	TO DISMANTLE & REPLACED ENGINE INTAKE MANIFOLD WITH OTHER ATTACHMENT PARTS COMPONENTS TO FACILITATE REPAIR	New	250.00	150.00
Gross Labour Cost (S\$)			3,580.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >