

TwinCar AUTOMOTIVE PTE LTD

Kay Pak Antolub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@nd1.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

68416315.
→ Mr. Quo Quing
25/3/19

COMBI GALLERY PTE LTD
SINGAPORE

Contact : 98002975 - 85253471

ESTIMATE

Repair Code : CLM14432
Date in : 28/12/2018
Vehicle Num. : GBD1835T
Model : NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Chassis/Eng# : JNISC2F24Z0856515/ZD30342098K

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER / Cut	1	945.10	945.10
FRONT HEADLAMP LOWER GARNISH - BR.	1	75.00	75.00
FRONT LH CORNER PANEL - Blue	1	389.90	389.90
FRONT LH DOOR X Repair	1	1396.50	1,396.50
FRONT LH DOOR HINGE X	1	56.10	56.10
FRONT LH DOOR STEP GARNISH X SNN	1	139.40	139.40
FRONT LH HEADLAMP / Cut	1	473.40	473.40
FRONT LH SIDE MIRROR X	1	171.80	171.80
FRONT LH UPPER CORNER GARNISH X SNN	1	111.30	111.30
FRONT PANEL 'CABSTAR' EMBLEM X SNN	1	30.00	30.00
Subtotal before discount			3,788.50
Percentage discount 10%			378.85
Sub-total 1			3,409.65
FRONT BUMPER CLIPS - SET X SNN	1	50.00	50.00
FRONT GRILLE CLIPS - SET X	1	30.00	30.00
FRONT LH DOOR ART STICKER / MC	1	300.00	300.00
FRONT LH DOOR COMPANY DETAIL STICKER / MC	1	40.00	40.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET X SNN	1	50.00	50.00

*** This is a computer-generated document which requires no signature ***

TyvinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

COMBI GALLERY PTE LTD
SINGAPORE

Contact : 98002975 - 55253471

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE Acknowledged by Repairer

Repair Code : CLM14432

Date in : 28/12/2018

Vehicle Num. : GBD3835T

Model : NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5

Chassis/Eng# : JN1SC2F24Z0856515/ZD30342098K

FRONT PANEL ART STICKER - SET

Percentage discount : 0%

Subtotal before discount

Sub-total 2

Parts-total

200.00 50 200.00

670.00

0.00

670.00

4,079.65

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove, reinstall window glass, (to FR)

To transfer door glass, regulator gear, motor, railing, chazinel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

30 50.00

50.00

100.00

800.00

700.00

80.00

1,780.00

5,859.65

*** This is a computer-generated document which requires no signature.***

page 2

2196.47 2557.06 2747.06
20% : 1750 2050 2200

4 Days.