



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



PORSCHE

Sompo Insurance		NAME : Mr Sunil Nair	WIP : 43077
05-01/06 Land Tower, Raffles Place, Singapore Land Tower, Singapore 048623		ADDRESS : 56 Tung Po Avenue Singapore 787187	EXCESS :
ATTN. : MOTOR CLAIM DEPT		TEL :	DATE: 27.02.2019
FAX :			
VEH NO :	SLD2000Z	DATE IN :	CONTACT PERSON : EVA 63310683
CHASSIS NO :	WP1ZZZ92ZGKA36208	MILEAGE :	TYPE OF CLAIM : TP
MODEL :	Cayenne	DATE REG.: 10.06.2016	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description		QTY	REVISED	PRICES
1	REAR BUMPER		1	\$ 1,085.20	\$ 1,085.20
2	REAR BUMPER LOWER COVER		1	\$ -	\$ 996.60
3	TAIL PIPE TRIM COVER LH		1	\$ 143.10	\$ 143.10
4	TAIL PIPE TRIM COVER RH		1	\$ 143.10	\$ 143.10
5	U-CLAMP		1	\$ 2.20	\$ 8.00
6	BLIND RIVET		6	\$ 9.00	\$ 9.00
7	TAILGATE		1	\$ -	\$ 3,115.10
8	BLIND RIVET		8	\$ -	\$ 44.00
9	SEALING RUBBER		2	\$ -	\$ 5.00
10	CAVITY PRESERVATION		1	\$ -	\$ 75.30
11	BLIND RIVET NUT		6	\$ -	\$ 25.80
12	CLAMP		2	\$ -	\$ 13.00
13	VELCRO STRIP		1	\$ -	\$ 8.70
14	SUPPORT		2	\$ -	\$ 15.80
15	LOGO PORSCHE CHROME		1	\$ 210.50	\$ 210.50
16	GASKET REAR WINDOW LOWER		1	\$ -	\$ 165.30
SUPPLEMENTARY PARTS					
1	U CLAMP,F/PROTECTION	CX) not /	3	\$ 6.60	
TOTAL PARTS				\$ 1,599.70	\$ 6,063.50
LESS 10%				\$ 159.97	\$ 606.35
TOTAL PARTS COST				\$ 1,439.73	\$ 5,457.15
Labour Description					
1	TO REPLACE TAILGATE, REAR BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 3,120.00	\$ 3,900.00
2	TO RESPRAY TAILGATE, REAR BUMPER & PORSCHE (BLACK).			\$ 2,400.00	\$ 2,600.00
3	TO TRANSFER THE TAILGATE MECHANISM.			\$ -	\$ 780.00
4	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.			\$ -	\$ 560.00
5	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.			\$ -	\$ 195.00