



UCB Engineering Pte Ltd

GST Registration Number: 19-9501338-G

Business Reg. No. 199501338G

Our ref: 190206.Sky (PA7923X)

27 February 2019

Sky Island Transport & Trading
Blk 535 Bukit Panjang Ring Road
#11-817
Singapore 670535

QUOTATION
without Prejudice

Dear Sir,

COST OF REPAIR FOR PA 7923 X

QTY	DESCRIPTIONS	PRICE S\$
1 pc	Rear bumper <i>BT</i>	2,482.18
1 pc	Rear bumper lamp ?	205.00
1 pc	Rear bumper bracket <i>BT</i>	125.00
1 pc	Number plate <i>CRA</i>	32.00
1 pc	Rear door <i>repair</i>	3,650.00
1 pc	Rear lamp <i>X</i>	185.00
1 pc	Exhaust pipe <i>BT</i>	380.00
	Labour charges for remove & replace the above damaged parts checking alignment and repair affected damaged areas	1,600.00 <i>600 700</i>
	To putty & spray painting onto complete rear body Affected areas	1,050.00 <i>500 600</i>
	Artwork	180.00 <i>100</i>
Total		9,889.18

(SGD: Nine Thousand Eight Hundred Eighty-Nine And Cents Eighteen Only)

Price quoted above is subjected to 7% GST

Yours faithfully,
Tan Tiong Chia

RASUL
HP 90010068
5 days
4/5
06/03/19 @ 1510
Resurvey after repair

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2C Jalan Pesawat, Jurong, Singapore 619359
Tel: 6268 1281 Fax: 6268 1282
E-mail: unitedcb@singnet.com.sg