

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 07 Mar 2019

**Preliminary Advice**

Insured Vehicle No	:	SDT7335K			
TP Vehicle No	:	SGH5705S	Accident Date	:	25/02/2019
Make	:	NISSAN LATIO	Assignment Date	:	28/02/2019
Date of Inspection	:	06/03/2019	Est. Duration of Repair	:	8 days
Inspection At	:	Rong Sheng Auto Engineering Trading (Toh Guan Rd East) No 42 Toh Guan Road East, #01-79 Enterprise Hub Singapore 608583			

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 5,610.63
Revised Amount	:	S\$ 3,205.99
Check Items (Estimated)	:	S\$ 0.00
Total	:	S\$ 3,205.99
Lump Sum Repair :S\$		

**Total Loss Consideration**

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

**Remarks**

- (      ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.  
Kindly let us have your authorisation.
- (      ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : TP : WP