



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX :		NAME : Mr Lee Xu Heng Leon ADDRESS : 14 Jalan Lempeng #08-02 Singapore 128799 TEL : 93624998	WIP : 36183 EXCESS : DATE: 28-Feb-19
VEH NO :	SLP7405T	DATE IN :	CONTACT PERSON : Eva 63310683
CHASSIS NO :	JM6BN22A8H0154729	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.: 16-Jun-17	POLICY NO. :

NATURE OF WORKS

Parts Description				REVISED	PRICES
NO	DESCRIPTION	QTY	PART NO		
1	REAR BUMPER <i>DE</i>	1	MBHN1-50-221ABB		\$ 1,074.80
2	RETAINER RHS <i>me</i>	1	MBHN1-50-2H1A		\$ 36.10
3	BRACKET RHS <i>me</i>	1	MBHN9-51-067B		\$ 45.60
4	BRACKET CENTER <i>?</i>	1	MKD53-50-251		\$ 5.10
5	REFLECTOR RHS <i>BRW</i>	1	MD350-51-5M0E		\$ 50.40
6	TOWING COVER RHS <i>X</i>	1	MBHN1-50-EK1 BB		\$ 16.20
7	REAR REINFORCEMENT <i>?</i>	1	MB45A-50-260		\$ 537.30
8	SHIELD SPLASH RHS <i>?</i>	1	MBHN1-50-340B		\$ 71.10
9	GROMMET, REAR BUMPER <i>me</i>	2	M9991-00-501		\$ 5.60
10	RIVET, REAR BUMPER <i>me</i>	4	MBBM4-50-355		\$ 16.80
11	GROMMET, REAR BUMPER <i>me</i>	4	MBHN1-50-0Z1A		\$ 10.00
12	FASTENER, REAR BUMPER <i>me</i>	4	MB45A-56-146A		\$ 11.20
13	PANEL LWR RHS, REAR FENDER <i>repair</i>	1	MB4YA-70-40X		\$ 355.40
14	EXTRACTOR VENT RHS <i>?</i>	1	MD350-51-920A		\$ 71.30
15	GASKET LHS, TAILLAMP <i>me</i>	1	MBHN1-51-163		\$ 20.90
16	GASKET RHS, TAILLAMP <i>me</i>	1	MBHN1-51-153		\$ 20.90
TOTAL PARTS					\$ 2,348.70
LESS 10%					\$ 234.87
TOTAL PARTS COST					\$ 2,113.83

Labour Description

NO	DESCRIPTION	QTY	PRICE
1	MZ-BR-REAR01 TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND PANEL LWR RH. TO REPAIR REAR END PANEL, REAR FENDER LH AND ALL AREAS AFFECTED BY THE ACCIDENT.	<i>660</i>	\$ 2,970.00
2	MZ-SP-SFRT01 TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, PANEL LWR RH, REAR END PANEL, REAR FENDER LH.	<i>1200</i>	\$ 2,520.00
3	MZ-BR-REVSSEN TO TRANSFER REVERSE SENSORS.	NETT	\$ 330.00

4	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	X	\$ 660.00
5	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	X	\$ 350.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
8	MZ-BR-SUNDRI	SUNDRIES.	20	\$ 100.00

* To reprogramme \$180.00

TOTAL LABOUR	\$ -	\$ 7,430.00
TOTAL PARTS	\$ -	\$ 2,113.83
TOTAL	\$ -	\$ 9,543.83
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorized Signature

Resul
Hp 90010068
4 days
7/P
01/03/19 @ 1150
Resul by paint