



Rico 60 Auto Services Pte Ltd. Blk 8, Kaki Bukit Avenue 4, #02-24
 Premier @ Kaki Bukit Singapore 115875, Email: claims@rico60.com
 Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:	PC 3049 K
MAKE & MODEL:	TOYOTA HIACE
MILEAGE:	
TYRE:	
CHASSIS NUM:	JTFST22P200020909

not Add
 1/3/19
 L/S 3550
 Hd
 the photo

ATTN: Loke Poh Hin

L/S 3550

NO.	DESCRIPTION - PARTS	QTY	PRICE
1	FRONT WINDSCREEN MOULDING <i>11 X</i>	1	\$215.00 X
2	FRONT BONNET <i>2 X</i>	1	\$1898.00 X
3	FRONT BONNET LOGO <i>1cc ✓</i>	1	\$68.00 ✓
4	FRONT BONNET CORNER RUBBER LH <i>11 X</i>	1	\$127.80 X
5	FRONT BONNET HINGE LH <i>11 X</i>	1	\$112.30 X
6	FRONT BONNET WEATHER STRIP LH <i>11 X</i>	1	\$76.70 X
7	FRONT HEADLAMP LH <i>CM ✓</i>	1	\$598 ✓
8	FRONT BUMPER <i>Dis ✓</i>	1	\$545 ✓
9	FRONT BUMPER SIDE RETAINER L+R <i>1/5cm 1/c 149.60</i>	2	\$299.20 ✓
10	FRONT BUMPER BRACKET L+R <i>11 X</i>	2	\$165.20 X
11	FRONT BUMPER GRILLE TOP <i>11 X</i>	1	\$267.80 X
12	FRONT BUMPER GRILLE BOTTOM <i>11 X</i>	1	\$276.30 X
13	FRONT BUMPER GRILLE BASE <i>11 X</i>	1	\$393.00 X
14	FRONT BUMPER FOG LAMP COVER LH <i>11 X</i>	1	\$185.00 X
15	FRONT BUMPER TOW COVER <i>11 X</i>	1	\$78.00 X
16	FRONT BUMPER REINFORCEMENT BAR <i>11 X</i>	1	\$258.00 X
17	FRONT QUARTER PANEL LH <i>20/24 ✓</i>	1	\$485.00 ✓
18	FRONT QUARTER PANEL TOP RUBBER LH <i>11 X</i>	1	\$110.00 X
19	FRONT DOOR LH <i>20/24 ✓</i>	1	\$1445.00 ✓
20	FRONT DOOR SIDE MIRROR ASSY LH <i>11 X</i>	1	\$45.90 X
21	FRONT DOOR HANDLE LH <i>11 X</i>	1	\$79.90 X
22	FRONT DOOR KEY LOCK LH <i>11 X</i>	1	\$816.40 X
23	FRONT DOOR HINGE UP AND DOWN LH <i>11 X</i>	2	\$248.40 X
24	FRONT DOOR CHECKER LH <i>11 X</i>	1	\$164.20 ✓
25	FRONT DOOR INNER TRIM LH <i>11 X</i>	1	\$489.00 X
26	FRONT DOOR INNER TRIM SWITCH LH <i>11 X</i>	1	\$78.00 X
27	FRONT DOOR WINDOW CHANNEL LH <i>11 X</i>	1	\$46.00 X
28	FRONT DOOR POWER MOTOR LH <i>11 X</i>	1	\$75.00 X
29	FRONT DOOR REGULATOR LH <i>11 X</i>	1	\$320.00 X
30	FRONT DOOR WEATHERSTRIP LH <i>11 X</i>	1	\$185.20 ✓
31	FRONT DOOR LOWER STEP PANEL LH <i>11 X</i>	1	\$42.00 X
32	FRONT DOOR LOWER STEP PANEL GARNISH LH <i>11 X</i>	1	\$256.00 ✓
33	FRONT DOOR PILLAR LH <i>11 X</i>	1	\$913.20 X
34	FRONT SUPPORT PANEL <i>11 X</i>	1	\$78.00 X
35	FRONT BRACE PANEL COMPLETE SET <i>11 X</i>	1	\$220.00 X
36	FRONT WASHER TANK <i>11 X</i>	1	\$198.00 X
37	FRONT WIREHARNES <i>11 X</i>	1	\$1268.00 X
38	FRONT DASHBOARD ASSY COMPLETE SET <i>11 X</i>	1	\$258.00 X
39	FRONT DASHBOARD CENTER SUPPORT <i>11 X</i>	1	\$175.00 X

40	FRONT LOWER ARM LH	1 1 X	1	\$ 150.00	X
41	FRONT UPPER ARM LH	1 1 X	1	\$ 270.00	X
42	FRONT ABSORBER LH	1 1 X	1	\$ 130.00	X
43	FRONT KNUCKLE ARM LH	1 1 X	1	\$ 270.00	X
44	FRONT WHEEL BEARING LH	1 1 X	1	\$ 170.00	X
45	FRONT BEARING HUB LH	1 1 X	1	\$ 250.00	X
46	FRONT STABILISER LINK LH	1 1 X	1	\$ 180.00	X
47	FRONT STEERING RACK AND PINION ASSY	1 1 X	1	\$ 2149.00	X

P = ~~53896~~ 3796
 LESS 25% = ~~13474~~ 2847

SUBTOTAL \$ -
 LESS 25% \$ -
 PARTS TOTAL \$ -

SPECIAL NETT		QTY	PRICE		
1	FRONT WINDSCREEN SEALANT	1 1 X	1	\$ 120.00	X
2	FRONT HEADLAMP CHROME LH	1 1 180	1	\$ 600.00	180
3	FRONT DOOR BOARD CLIPS LH	10 50	10	\$ 100.00	50
3	FRONT DOOR PILLAR SEALANT	1 1 X	1	\$ 120.00	X
2	FRONT DOOR WINDOW MOULDING CHROME STRIP LH	1 1 1 X	1	\$ 300.00	X
3	FRONT DOOR WINDOW VISOR LH	1 1 100	1	\$ 200.00	100
4	FRONT BUMPER CLIPS	10 50	10	\$ 100.00	50
5	FRONT RIM CAP LH	1 1 1 C X	1	\$ 200.00	X
6	FRONT RIM LH	1 1 X	1	\$ 450.00	X
7	FRONT TYRE LH	1 1 X	1	\$ 350.00	X

S/N = \$380

SPECIAL NETT TOTAL \$ 2,420.00

LABOUR		QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	1 500	\$ 1,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1 600	\$ 1,000.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	1 50	\$ 120.00
4	TO RNR FRONT DOOR MECHANISM	1 60	\$ 120.00
5	TO RNR FRONT WINDSCREEN	1 1 X	\$ 400.00
6	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	1 20	\$ 120.00
7	TO RNR UNDERCARRAIGE SYSTEM	1 1 X	\$ 250.00
8	TO CHECK WHEEL ALIGNMENT	1 1 X	\$ 120.00

LABOUR = \$1,280
 TOTAL = \$4,532
 LESS 25% = \$3,680

4487
 3565

LABOUR TOTAL \$ 3,130.00
 GRAND TOTAL COST \$ 5,550.00