

ASSIGNMENT (Office)

CWS May chun

of FCI

Date/Time: 4:01pm @ 28/2/19

Estimated Cost

Bill to

OD (P) WST/TP RES / OD RES / EVA / INV / MVTC3

To Inspect Vehicle No.

SGG 5246E

Insured

SHA 5430)

at Workshop no.

Cheng Hoe Motor

Tel.

6755 6142

of

Blk 1019 Yishun Ind. park A #01-374

Policy No.

Claim No.

D1900/473 MFSH

Sum Insured

Excess

Make of Veh.

D.O.A

28/2/19

(Client's Record)

CA / REV / REP / REV 24 HRS

1up

H.O.D. Endorsement

Date/Time

10:25am @ 1/3/19

Person Contacted

effeeder

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGG 5246E-X

SHA 5430) - MS/INC 16016349 / H/Hbn2

DoA: 30/8/16

1/3/19 @ 3:36pm revised to May chun by email.

ASS. REC. BY:

REF:

1021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGG 5246E

Yr Regn: 05, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota

c.c. 1598

Colour:

N.L. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

254198

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR0538EC107117382

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

185/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

25/2/19

Rear

R/Bal.

8

mm

L/Bal.

8

mm

D.O.I.


6/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S 1st

The UIC / Chassis frame / Body Structure affected due to collision.



Date / Time

Action / Instruction

12/3/19 File pass to
 11/3/19 11/3/19 8500h email @ confirmed with Efrade.
 (LSD 6170.85, 26%)
 MV: 838K6H; 7A: 837885; NV: 85115

RECEIVED 13 MAR 2019

12/3/2019

Date/Time, File Pass to?

11/3/19 11/3/19

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) TP 500

☐

Prell. Report

☐

Final Report

Days Of Repair: 2

Resurvey No. of Trlp:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

90
50
10
150

MOTOR SURVEY ASSIGNMENT

Date	28-02-2019	Our Ref No. D19001473MFSH
Accident Date	25-02-2019	Claim Type. Third Party
Insured Vehicle	SHA5430J	Third Party Vehicle. SGG5246E
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001473MFSH

Date: 12 March 2019

Our Ref: CS/FCI19003850/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGG 5246E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/03/2019 at the premises of M/s CHENG HOE MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>678.85</u> .
Revised Estimate Amount	: S\$ <u>500.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the o/s front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 12 March 2019 3:36 PM
To: 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001473MFSH/1
Attachments: CSFCI19003850Kqd3.pdf

Dear May,

Enclosed herewith preliminary advice of SGG 5246E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 1 March 2019 10:25 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001473MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 28 February 2019 4:00 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001473MFSH/1

Dear Sir/Mdm,

> Back to OneMotoring

SGG5246E

TP/7C

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4583H
Vehicle Details	
Vehicle No.:	SGG5246E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA 1.6
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	3ZZ4559336
Chassis No.:	MR053ZEC107117382
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,950.00
Original Registration Date:	16 May 2006
First Registration Date:	16 May 2006
Transfer Count:	0
Actual ARF Paid:	\$17,545.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 May 2026
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$45,578.00
COE Rebate Amount:	\$32,885.00
Total Rebate Amount:	\$32,885.00

The information contained herein is correct as at 27 Feb 2019

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848
 ATTN: Motor Claim Department

FAX: 65073849

WS Ref: TP/FC
 Claim Type: Third Party
 Accident Date: 25/02/2019
 TP Veh Reg No: SHA5430J

Not Authorised
11Lm @ 500k
Re-spray After Paint
2 days

Estimate No: ES1991239/YISHUN
Date: 06 Mar 2019
Policy No: 0100638169
Veh Reg No: SGG5246E
Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO
Chassis No: MR053ZEC107117382
Engine No: 3ZZ4559336
Reg. Date: 16/05/2006

Estimate Repair Cost to Vehicle No :SGG5246E

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 FRONT R/H SIDE MIRROR	371.8000	1 PC	371.80	✓
		Less 25%	92.95	278.85
Labour				
2 REMOVE & REFIX FRONT R/H SIDE MIRROR AND CHECK SYSTEM	100.0000	1 LA	100.00	✓
3 PUTTY & RESPRAY ON FRONT R/H SIDE MIRROR AND FRONT R/H DOOR	300.0000	1 LA	300.00	260
			400.00	400.00
			Total	SS 678.85
			Add GST @ 7%	47.52
			Total Amount Payable	SS 726.37

For Cheng Hoe Motor Pte Ltd

og

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003850/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-03-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 5430J	Veh. Inspected	SGG 5246E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001473MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	28/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	MR053ZEC107117382	Colour	METALLIC LIGHT BLUE	
Odometer	254198	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	LING LONG	8 mm	
L/H Front Tyre	185/70 R14	LING LONG	8 mm	
R/H Rear Tyre	185/70 R14	LING LONG	8 mm	
L/H Rear Tyre	185/70 R14	LING LONG	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/02/2019	Inspection Date	06/03/2019	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 5246E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	BROKEN		
	FRONT R/H SIDE MIRROR		371.80	371.80
	LESS 25% DISCOUNT		-92.95	-92.95
			278.85	278.85
	LABOUR			
	REMOVE & REFIX FRONT R/H SIDE MIRROR AND CHECK SYSTEM.		100.00	100.00
	PUTTY & RESPRAY ON FRONT R/H SIDE MIRROR AND FRONT R/H DOOR.		300.00	260.00
			400.00	360.00
GRAND TOTAL			678.85	638.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				500.00

Report Ref No. CS/FCI19003850/Kqd3n2

MARKET VALUE: \$38,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$32,885.00=NETT VALUE: \$5,115.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.