

INSURANCE CASE OWNER:

CC 3, ALH 1900 3852, JK A3Y

LKK IDAC

Surveyor: DHJ DOI: 23/11/19 Date / Time: 27/11/19
 Registered in Merimen: 1/3/19

Pre-assign / CCU / FTE

SIM 2320C



Insured Vehicle No. : _____ Claim No. : _____
 Name of Insured : My chery Hee Policy No. : _____
 Insured Tel No. : _____ HP: _____ Make / Model : _____
 Excess Sec II :SS _____ D.O.A. : 13/11/19 Place of Accident : _____
 Is driver the owner? (YES / NO) Nature of Accident : _____
 If NO, Driver Name / Age : _____ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Driver Tel No. : _____ (VL: YES / NO) Insured Liability : _____ % Final ? Yes / No

SHD 6128K



INSRS: _____
 WSP: SMRT, Inc
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____

Date/ Time	STAGE	DATE / PIC
<u>11/3</u>	Non-Reporting ltr (1st):	
<u>11/3</u>	Non-Reporting ltr (2nd):	
<u>11/3</u>	Non-Reporting ltr (Final):	
<u>11/3</u>	Notification ltr (if non-pickup):	
<u>11/3</u>	Call OI:	<u>15/11/19 chad</u>
<u>11/3</u>	After call ltr to OI:	<u>e-mail ltr</u>
<u>11/3</u>	Documentation Check List:	Handler Typist
<u>11/3</u>	Notification ltr (if non-pickup)	<input type="checkbox"/>
<u>11/3</u>	After call ltr to OI:	<input checked="" type="checkbox"/>
<u>11/3</u>	Authorisation To Act:	<input checked="" type="checkbox"/>
<u>11/3</u>	Release Voucher:	<input checked="" type="checkbox"/>
<u>11/3</u>	Final Repair Bill:	<input checked="" type="checkbox"/>
<u>11/3</u>	Car Rental Invoice:	<input checked="" type="checkbox"/>
<u>11/3</u>	Towing Invoice:	<input type="checkbox"/>
<u>11/3</u>	LTA / GIA :	<input checked="" type="checkbox"/>
<u>11/3</u>	Medical Bill:	<input type="checkbox"/>
<u>11/3</u>	PIR:	<input type="checkbox"/>
<u>11/3</u>	Mandate/Reject Instruction:	<input type="checkbox"/>
<u>11/3</u>	LOD:	<input checked="" type="checkbox"/>
<u>11/3</u>	Payment Breakdown Form:	<input type="checkbox"/>
<u>11/3</u>	Post-Repair Photos:	<input type="checkbox"/>
<u>11/3</u>	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	\$S _____ (_____ days) Reduction: _____ %	Confirm by: Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>20/12/19</u>	Confirm with: <u>Tan Lee Goh</u>
Final Liability:	% <u>100</u> (Agreed / Assessed) BOLA S/N No. : <u>NIL</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Repair Cost:	\$S <u>10350.00</u> (PIR AGAINST OI)	If NO or B 28, Ass. Lia : _____
Loss of Rental (LOR):	\$S <u>2175.31</u> (<u>19</u> days) x \$114.49	(OI appeal on PIR against him)
Loss of Use (LOU):	\$S - (<u>5</u> x days)	
Loss of Income (LOI):	\$S - (<u>5</u> x days)	
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	\$S <u>7.00</u>	
Medical:	\$S -	1) Claim status: <u>Normal/Reject/Private Settle</u>
Disbursement:	\$S - (e.g. Tow/ Independent)	2) Report Format: <u>FF</u>
Legal Cost:	\$S -	3) Survey fee: <u>\$320</u>
Total:	\$S <u>12532.31</u>	Global Sum \$S: <u>12500.00</u>
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$S <u>12500.00</u>	Name 1: <u>SMRT Taxis Pte Ltd</u>
Payee 2: (Strike if N.A.)	\$S _____	Name 2: _____
Payee 3: (Strike if N.A.)	\$S _____	Name 3: _____

COPY SENT 23/11/19

Huee Jie


REF: A16

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 8 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD6128K Yr Regn: 6 Nov/2015
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Print c.c. 1799
 Colour: maroon A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKN36U8057666K1
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Insured / Jammed / Leaked / Burnt or _____
 Brake: Insured / Jammed / Leaked / Burnt or _____
 Modi: NIT / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: -
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Achilles

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>13/2/19</u>	D.O.A. <u>27/2/19</u>



 Survey held at Smart
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	02/19/2015
	L/S - \$10350 (Red \$38732.20 / 797.)
	SLM 2320c
	SGE 1658L

On/Time, File Pass to? : Proli. Report
 : Final Report
 Date/Time, File Return to?
 Days Of Repair:
 Resurvey No. of Trip:
 Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)
 Report Format :
 Lump Sum / I.B.I: (\$)
 Survey Fee:
 Transportation
) \$ + PG. \$
) Photos
) Others
)
 TOTAL

Section A - Accident Details

Registration Number	SHD6128K
Case Reference Number	TAX/02/19/2081
Registration Date	8/11/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	GANDARUBAN
Type of Accident	Side Swipe
Accident Date and Time	13/2/2019 8:20 PM
Accident Reported Date and Time	15/2/2019 3:32 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100145
Special instruction to ARC, if any	TP/TOWED TP COMPOUND /AIG - LKK
Prepared Date and Time	25/2/2019 3:43 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



3/2/19

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,197.00	\$1,200.00
Total Spray Cost	\$4,086.00	\$1,400.00
Total Spare Part Cost	\$25,674.91	\$7,297.18
Total Other Cost	\$2,236.00	\$470.00
TOTAL COST	\$34,193.91 49,083.20	\$10,367.18
Lump Sum Total	\$31,450.00	\$10,350.00 (L/S)
Number of Repair Days	18.0	6.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	28/02/2019 8:41 AM	27/02/2019 3:48 PM
Signature		
Remarks	Supplementary = 2 days	L/S REPAIR_PHOTO AFTER REPAIR.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0290	Invoice Number	
Quotation Date	18.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$1,352.00	\$800.00
TO REPAIR RH PORTION	\$845.00	\$400.00
Total Labour	\$2,197.00	\$1,200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY RADIATOR SUPPORT LOWER	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRT MEMBER LH	\$180.00	\$0.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$0.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY RIM	\$360.00	\$100.00
Total Spray Painting & Panel Beating	\$4,086.00	\$1,400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$125.00	\$90.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$50.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$80.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$240.00	\$50.00
TO ALIGN CHASSIS	\$350.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$100.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$100.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park 24, Singapore 737708
 FAX Number: 63665562
 Estimator Telephone Number: 68662623
 Accident Reporting Number: 58662072

Date Generated: 20090219
 User ID: PehBun

TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$2,236.00	\$470.00

Part 4 - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace	DEF
		52161-16010	BUMPER CLIPS	10.00	\$1.51 16.10	25.00	\$12.08	Replace	Replace	NEL
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.90	25.00	\$59.10	Replace	Replace	CRA
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check	X NN
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Check	X NN
		57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Check	X NN
		52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.88	Replace	Replace	MIS
		52127-47903	COVER, FR BUMPER HOLE RH	0.00	\$18.50	0.00	\$0.00	Replace	Check	X NN
		52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Check	X NN
			NUMBER PLATE	0.00	\$16.00	0.00	\$0.00	Replace	Not Given	X NN
			NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Check	X NN
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	CRA
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Check	X NN
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace	SCR
		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Check	X NN
		81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Check	X NN
		76851-47020	BUMPER LIP FRT	1.00	\$139.60	25.00	\$104.70	Replace	Replace	MIS
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check	X NN
		53113-47040	GRILLE RADIATOR LOWER NO 2	0.00	\$94.60	0.00	\$0.00	Replace	Check	X NN
		53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check	X NN
		75310-47010	EMBLEM FRONT	1.00	\$66.90	25.00	\$64.88	Replace	Replace	MIS
		82113-47180	WIRE, ENGINE ROOM NO 3	0.00	\$242.00	0.00	\$0.00	Replace	Check	X NN
		81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	X NN
		81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check	X NN
		81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	X NN
		81521-47050	LENS & BODY, FR TURN LH	1.00	\$511.80	10.00	\$460.62	Replace	Replace	CRA
		81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	X NN
		81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check	X NN
		81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	X NN
		81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	X NN
		88790-22131	THERMISTOR ASSY	0.00	\$107.00	0.00	\$0.00	Replace	Not Given	X NN
		53301-47060	HOOD PANEL	1.00	\$748.10	25.00	\$561.08	Replace	Replace	DEF
		53395-47020	HOOD END PANEL SEAL	0.00	\$35.50	0.00	\$0.00	Replace	Check	X NN
		53420-47070	HOOD HINGE LH	0.00	\$55.90	0.00	\$0.00	Replace	Check	X NN
		53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Check	X NN
		53510-47102	HOOD LOCK	0.00	\$128.90	0.00	\$0.00	Replace	Check	X NN

6162.80



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 80 Woodlands Industrial Park E4, Singapore 757100
 FAX Number : 63655582
 Estimator Telephone Number : 68602023
 Accident Reporting Number : 9892072

Date Generated : 26/09/2018

User ID : Panduan

53614-47030	CLAMP, HOOD LOCK	0.00	\$5.90	0.00	\$0.00	Replace	Check	X
53341-47020	HOOD PANEL INSULATOR	0.00	\$390.50	0.00	\$0.00	Replace	Check	X
55084-47011	WIPER GARNISH COVER, LH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given	X
55083-47011	WIPER GARNISH COVER, RH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given	X
55708-47101	WIPER GARNISH	0.00	\$614.00	0.00	\$0.00	Replace	Check	X
53201-47902	SUPPORT SUB-ASSY	0.00	\$1,450.40	0.00	\$0.00	Replace	Check	X
53289-47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Check	X
81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	X
81130-47500	HEAD LAMP RH	0.00	\$945.20	0.00	\$0.00	Replace	Check	X
82111-47772	WIRE, ENGINE ROOM	0.00	\$5,587.10	0.00	\$0.00	Replace	Not Given	X
82863-47060	FUSE BLOCK, COVER LOWER	0.00	\$18.50	0.00	\$0.00	Replace	Check	X
82862-47110	FUSE BLOCK, TOP COVER	0.00	\$82.30	0.00	\$0.00	Replace	Check	X
53294-47030	DEFLECTOR, RADIATOR LH	0.00	\$77.00	0.00	\$0.00	Replace	Check	X
53293-47040	DEFLECTOR, RADIATOR RH	0.00	\$83.50	0.00	\$0.00	Replace	Check	X
88460-47150	A/C CONDENSER	0.00	\$1,181.90	0.00	\$0.00	Replace	Check	X
88710-47150	TUBE & ACCESSORY	0.00	\$631.90	0.00	\$0.00	Replace	Check	X
88703-47040	HOSE SUB-ASSY, DISCHARGE COOLANT	0.00	\$386.90	0.00	\$0.00	Replace	Check	X
16400-37230	RADIATOR ASSY	0.00	\$1,498.90	0.00	\$0.00	Replace	Check	X
G9010-47031	RADIATOR ASSY, UPPER	0.00	\$679.50	0.00	\$0.00	Replace	Check	X
57104-47020	RADIATOR LOWER SUPPORT	0.00	\$878.30	0.00	\$0.00	Replace	Check	X
16534-37010	SUPPORT, RADIATOR, LH	0.00	\$17.70	0.00	\$0.00	Replace	Check	X
16533-28051	SUPPORT, RADIATOR, RH	0.00	\$54.50	0.00	\$0.00	Replace	Check	X
18711-37040	FAN SHROUD	0.00	\$244.50	0.00	\$0.00	Replace	Check	X
16712-37030	FAN SHROUD TOP	0.00	\$99.60	0.00	\$0.00	Replace	Check	X
16572-37120	RADIATOR HOSE LOWER	0.00	\$42.40	0.00	\$0.00	Replace	Check	X
16571-37140	RADIATOR TOP HOSE NO 1	0.00	\$42.40	0.00	\$0.00	Replace	Check	X
G9225-47021	HOSE, INVERTER NO.1	0.00	\$80.00	0.00	\$0.00	Replace	Check	X
G9229-47020	HOSE, INVERTER COOLING NO.5	0.00	\$125.30	0.00	\$0.00	Replace	Check	X
53802-47060	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	X
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	X
53878-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	X
53852-47020	FENDER LINER PAD, FR WHEEL, LH	0.00	\$49.30	0.00	\$0.00	Replace	Check	X
53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Check	X
53828-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Check	X
53702-47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Check	X
51444-12050	UNDER COVER SIDE/LH	0.00	\$46.10	0.00	\$0.00	Replace	Check	X
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
42611-47140 (Frt)	WHEEL DISC, FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	R
87002-47070	DOOR FRT/LH	0.00	\$894.40	0.00	\$0.00	Replace	Check	X
	STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X

Handwritten notes on the right side of the table:

- MM (next to rows 53614-47030 to 53289-47032)
- CKA (next to row 81170-47500)
- NN (next to rows 88710-47150 to 51444-12050)
- SVC (next to row 53802-47060)
- NEC (next to row 75374-47051)
- DEF (next to row 53878-47030)
- NN (next to rows 53828-47010 to 51444-12050)
- NN (next to row 87002-47070)
- NN (next to row 51444-12050)



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 85 Woodlands Industrial Park East, Singapore 757105
 FAX Number: 63985532
 E-mail: Telephone Number: 63985533
 Accident Reporting Number: 68852610

Date Generated: 20082019
 User ID: Purbhan

Part Number	Description	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	Notes
53801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	DEF
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	NEC
53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Check	X NN
53851-47040	FENDER LINER PAD, FR WHEEL RH	0.00	\$49.30	0.00	\$0.00	Replace	Check	X NN
	TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	CUF
42611-47140 (Frt)	WHEEL DISC, FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	RC
67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace	BUC
	STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	NEC
69030-47070	DOOR LOCK FRT/RH	0.00	\$575.80	0.00	\$0.00	Replace	Check	X NN
69410-33010	DOOR LOCK STRIKER	0.00	\$40.50	0.00	\$0.00	Replace	Check	X NN
69210-74030	DOOR OUTER HANDLE FRT/RH	1.00	\$370.80	100.00	\$0.00	Replace	Repair	RC
69205-47050	DOOR INNER HANDLE FRT/RH	0.00	\$84.70	0.00	\$0.00	Replace	Check	X
85710-47120F	DOOR REGULATOR MOTOR FRONT RH	0.00	\$947.80	0.00	\$0.00	Replace	Check	X NN
69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Check	X
67861-47030	DOOR WEATHER STRIP FRT/RH	0.00	\$171.20	0.00	\$0.00	Replace	Check	X NN
75851-47900	MOULDING BODY, RH	1.00	\$873.60	100.00	\$0.00	Replace	Repair	RC
61311-47030	PILLAR, CTR BODY	0.00	\$307.70	0.00	\$0.00	Replace	Check	X NN
67003-47080	DOOR RR/RH	1.00	\$854.50	25.00	\$715.88	Replace	Replace	BUC
	PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	NEC
68750-20121	DOOR HINGE UPPER RR/RH	0.00	\$81.70	0.00	\$0.00	Replace	Check	X NN
68740-12120	DOOR HINGE LOWER RR/RH	0.00	\$90.10	0.00	\$0.00	Replace	Check	X NN
68630-47031	CHECK ASSY, RR DOOR	0.00	\$150.30	0.00	\$0.00	Replace	Check	X NN
5702812020	MEMBER SUB-ASSY, FR LH	0.00	\$810.70	0.00	\$0.00	Replace	Check	X NN
Total			\$35,992.51		\$5,704.31			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	Notes
		18400-37230	RADIATOR ASSY	1.00	\$1,495.90	25.00	\$1,122.68	Replace	Replace	BT
		53294-47030	DEFLECTOR, RADIATOR LH	1.00	\$77.00	25.00	\$57.75	Replace	Replace	CRA
6505786		G9010-47031	RADIATOR ASSY, UPPER	1.00	\$679.60	25.00	\$509.70	Replace	Replace	BT
		57104-47020	RADIATOR LOWER SUPPORT	1.00	\$676.30	25.00	\$507.23	Replace	Replace	BT
		16711-37040	FAN SHROUD	1.00	\$244.50	25.00	\$183.38	Replace	Replace	CRA
		88460-47150	A/C CONDENSER	1.00	\$1,181.90	25.00	\$886.43	Replace	Replace	DD
Total					4,866.20		3,417.17			


13,662.04

9121.48
 - 20%

4S \$10,350/-

7297.18
 + 1200.00
 + 1870.00

 10,367.18



LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

SMRT Accident Vehicle Repair Estimate Item(s) must be resurveyed
 subject to final approval from Insurance Company



Accepted by Repairer

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park EA, Singapore 757708	
UEN	
CAS Number : 8065082	
Estimator Telephone Number : 69803023	
Accident Reporting Number : 69802672	

Date Generated : 28/02/2019


User ID : ZhiYangPhua

Section A - Accident Details	
Registration Number	SH-06128K
Case Reference Number	TAXIGD782081
Registration Date	01/12/18
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PROJIS
Name of Driver	GANDARUSAN
Type of Accident	Side Swipe
Accident Date and Time	13/02/19 8:20 PM
Accident Reported Date and Time	15/02/2019 3:32 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24100148
Special Instruction to ARC, if any	TRY TO MED TP COMPOUND JAG - LKK
Prepared Date and Time	25/02/2019 3:43 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,187.00	\$1,200.00
Total Spray Cost	\$4,088.00	\$1,400.00
Total Spare Part Cost	\$22,541.18	\$5,704.38
Total Other Cost	\$3,238.00	\$470.00
TOTAL COST	\$31,485.18	\$8,774.38
Lump Sum Total	\$31,485.18	\$8,774.38
Number of Repair Days	18.0	0.0
Prepared / Adjusted By	Tuck Fook Koh	Hwee Jie
ARC / Surveyor Sign Off Date	28/02/2019 8:41 AM	27/02/2019 3:48 PM
Signature		
Remarks		L/S REPAIR, PHOTO AFTER REPAIR.

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park East, Singapore 757705
FAX Number : 63665582
Estimator Telephone Number : 6860221
Accident Reporting Number : 6860272

Date Generated : 28/02/2016

User ID : ZNYangPlus

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$400.00
TO REPAIR FRONT LH PORTION	\$1,352.00	\$600.00
Total Labour	\$2,197.00	\$1,000.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$0.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRNT MEMBER LH	\$180.00	\$0.00
TO RESPRAY RADIATOR SUPPORT LOWER	\$180.00	\$0.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY RM	\$360.00	\$100.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$4,086.00	\$1,400.00


Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO ALIGN CHASSIS	\$350.00	\$0.00
TO APPLY RUST PROOFING ON AFFECTED AREA	\$300.00	\$00.00
TO CHECK & RESET SYSTEM FUNCTION	\$360.00	\$100.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$60.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$240.00	\$60.00
TO REMOVE AND REFIT WIRE HARNESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$100.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$126.00	\$80.00
Total Other Costs	\$2,256.00	\$470.00

Part 4 - Spare Parts / Material Usage

Part Number	Partion	Stock Number	Part Name	Quantity	Unit Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		81521-47080	LENS & BODY, FR TURN LH	0.00	\$011.80	0.00	\$0.00	Replace	Not Given
		81220-12230	FOG LAMP LH	0.00	\$290.10	0.00	\$0.00	Replace	Check
		81301-47080	HOOD PANEL	1.00	\$748.10	28.00	\$531.88	Replace	Replace
		87013-47000	ARM SUB-ASSY, FR BUMPER RH	0.00	\$290.40	0.00	\$0.00	Replace	Check
		81130-47000	HEAD LAMP RH	0.00	\$948.20	0.00	\$0.00	Replace	Check
		88790-22131	THERMISTOR ASSY	0.00	\$107.00	0.00	\$0.00	Replace	Not Given
		88830-47021	CHECK ASSY, RH DOOR	0.00	\$190.30	0.00	\$0.00	Replace	Check

W M X
 X AMI
 DEF ✓
 X AMI
 X AMI
 W M X
 X AMI




SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
90 Woodlands Industrial Park EA, Singapore 757705
FAX Number : 63655502
Estimator Telephone Number : 68620003
Accident Reporting Number : 5862572

Date Generated : 28/02/2019

User ID : ZHYeng@hua

Part A - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		3310-47102	HOOD LOCK	0.00	\$128.90	0.00	\$0.00	Replace	Check	OK NAI
		57103-47060	FENDER APRON SUB FRTLH	0.00	\$637.80	0.00	\$0.00	Replace	Check	X NAI
		18400-37230	RADIATOR ASSY	0.00	\$1,406.90	0.00	\$0.00	Replace	Check	X NAI
		52165-18010	BUMPER CLIPS	10.00	\$1.81	25.00	\$13.08	Replace	Replace	NCL ✓
		33878-47000	FENDER LINER FRTLH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	DEP ✓
		91526-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	X NAI
		6601-62070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.90	0.00	\$0.00	Replace	Check	X NAI
		91521-47050	LENS & BODY, FR TURN LH	1.00	\$511.80	10.00	\$460.62	Replace	Replace	CRB ✓
		33263-47040	DEFLECTOR, RADIATOR RH	0.00	\$83.50	0.00	\$0.00	Replace	Check	X NAI
		33861-47040	FENDER LINER PAD, FR WHEEL, RH	0.00	\$48.30	0.00	\$0.00	Replace	Check	X NAI
		33363-47011	WIPER GARNISH COVER, RH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given	un X
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check	OK NAI
		18333-28001	SUPPORT, RADIATOR, RH	0.00	\$54.50	0.00	\$0.00	Replace	Check	X NAI
		33803-47050	FENDER FRTLH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	DEP ✓
		18571-37140	RADIATOR TOP HOSE NO 1	0.00	\$42.40	0.00	\$0.00	Replace	Check	X NAI
		52019-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check	X NAI
		98703-47040	HOSE SUB-ASSY, DISCHARGE	0.00	\$386.90	0.00	\$0.00	Replace	Check	X NAI
		50395-47020	HOOD END PANEL SEAL	0.00	\$25.50	0.00	\$0.00	Replace	Check	X NN
		53206-47010	FENDER PROTECTOR FRTLH UPPER	0.00	\$48.10	0.00	\$0.00	Replace	Check	X NAI
		53341-47020	HOOD PANEL INSULATOR	0.00	\$390.50	0.00	\$0.00	Replace	Check	X NAI
		53294-47030	DEFLECTOR, RADIATOR LH	0.00	\$77.00	0.00	\$0.00	Replace	Check	X NAI
		53103-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace	SCR ✓
		50284-47011	WIPER GARNISH COVER, LH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given	un X
		98710-47190	TUBE & ACCESSORY	0.00	\$631.90	0.00	\$0.00	Replace	Check	
		76851-47020	BUMPER LIP FRT	1.00	\$138.60	25.00	\$103.95	Replace	Replace	MI ✓
		82115-47772	WIRE, ENGINE ROOM	0.00	\$5,567.10	0.00	\$0.00	Replace	Not Given	un X
		53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Check	X NAI
		09010-47031	RADIATOR ASSY, UPPER	0.00	\$879.60	0.00	\$0.00	Replace	Check	X NN
		33801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	DEP ✓
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$290.40	0.00	\$0.00	Replace	Check	X NO
		33862-47020	FENDER LINER PAD, FR WHEEL, LH	0.00	\$49.30	0.00	\$0.00	Replace	Check	X NAI
		81170-47300	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	CRB ✓
		91526-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	X NAI
		66005-47070	DOOR LOCK FRT/RH	0.00	\$575.80	0.00	\$0.00	Replace	Check	X NAI
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Check	X NN
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	25.00	\$59.10	Replace	Replace	CRB ✓
		53420-47070	HOOD HINGE LH	0.00	\$55.90	0.00	\$0.00	Replace	Check	X NAI
		91526-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	X NAI



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park EA, Singapore 757706
FAX Number : 63625532
Estimator Telephone Number : 69626223
Accident Reporting Number : 6002072

Date Generated : 28/02/2018

User ID : ZHYangPhua

Part 4 - Spare Parts / Material Usage										
Part Number	Partno	Stock Number	Part Name	Quantity	List Price (S)	Discount (%)	Final Price (S)	Estimator Approved	Surveyor Approved	
		87001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace	Bun /
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	CUT /
		82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Check	X NAI
		08025-47020	HOSE, INVERTER COOLING NO.5	0.00	\$125.30	0.00	\$0.00	Replace	Check	X NAI
		52128-47900	COVER, FR BUMPER HOLE, LH	1.00	\$18.90	25.00	\$14.18	Replace	Replace	MIS /
		75310-47010	EMBLEM FRONT	1.00	\$88.50	25.00	\$66.38	Replace	Replace	MIS /
		57104-47020	RADIATOR LOWER SUPPORT	0.00	\$878.30	0.00	\$0.00	Replace	Check	X NAI
		79881-47900	MOULDING BODY, RH	1.00	\$673.80	100.00	\$0.00	Replace	Repair	X R
		32114-47040	GRILLE, RADIATOR	0.00	\$210.80	0.00	\$0.00	Replace	Check	X NAI
			NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Check	X NAI
		91444-12030	UNDER COVER SIDE, LH	0.00	\$48.10	0.00	\$0.00	Replace	Check	X NAI
		91829-47040	BRACKET, FR TURN UPPER, LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	X NAI
		42611-47140 (FR)	WHEEL DISC, FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	X R
		76374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	REU /
		52127-47800	COVER, FR BUMPER HOLE, RH	0.00	\$18.50	0.00	\$0.00	Replace	Check	X NAI
		98740-12120	DOOR HINGE LOWER R/RH	0.00	\$90.10	0.00	\$0.00	Replace	Check	X NAI
		18711-37040	FAN SHROUD	0.00	\$244.50	0.00	\$0.00	Replace	Check	X NAI
		55826-47060	PROTECTOR, FRONT FENDER SIDE PANEL, LH	0.00	\$114.50	0.00	\$0.00	Replace	Check	X NAI
		53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$84.00	0.00	\$0.00	Replace	Check	X NAI
		52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Check	X NAI
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	REU /
		53014-47030	CLAMP, HOOD LOCK	0.00	\$5.90	0.00	\$0.00	Replace	Check	X NAI
			STICKER DECAL SMRT (DOOR)	1.00	\$90.00	0.00	\$90.00	Replace	Replace	REU /
		85110-47120F	DOOR REGULATOR MOTOR FRONT RH	0.00	\$947.80	0.00	\$0.00	Replace	Check	X NAI
		18712-37000	FAN SHROUD TOP	0.00	\$99.00	0.00	\$0.00	Replace	Check	X NAI
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Check	REU /
		53251-47962	SUPPORT SUB-ASSY	0.00	\$1,492.40	0.00	\$0.00	Replace	Check	REU /
		87602-47070	DOOR FRT, LH	0.00	\$894.40	0.00	\$0.00	Replace	Check	X NAI
		53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Check	X NN
		81311-47030	PILLAR, CTR BODY	0.00	\$307.70	0.00	\$0.00	Replace	Check	X NN
		89410-83010	DOOR LOCK STRIKER	0.00	\$45.90	0.00	\$0.00	Replace	Check	X NN
		98025-47050	DOOR INNER HANDLE FRT/RH	0.00	\$84.70	0.00	\$0.00	Replace	Check	X NN
		52116-47040	BUMPER SUPPORT, FLH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	CRB /
		82963-47110	FUSE BLOCK, TOP COVER	0.00	\$82.30	0.00	\$0.00	Replace	Check	X NN
			NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	~ X
		5710912000	MEMBER SUB-ASSY, FR LH	0.00	\$810.70	0.00	\$0.00	Replace	Check	X NAI
		18972-37120	RADIATOR HOSE LOWER	0.00	\$42.40	0.00	\$0.00	Replace	Check	X NAI
			PANEL, STICKER	1.00	\$90.00	0.00	\$90.00	Replace	Replace	REU /
		18934-37010	SUPPORT, RADIATOR, LH	0.00	\$17.70	0.00	\$0.00	Replace	Check	X NAI
		98210-14000	DOOR OUTER HANDLE FRT/RH	1.00	\$370.80	100.00	\$0.00	Replace	Repair	X R



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
8C Woodlands Industrial Park 8A, Singapore 737702
FAX Number : 63685582
Estimator Telephone Number : 68923223
Accident Reporting Number : 68952572

Date Generated : 26/02/2019

User ID : ZNYangPhua

Part 4 - Spare Parts / Material Usage

Part Number	Partcode	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		8750-20121	DOOR HINGE UPPER RR/RH	0.00	\$81.70	0.00	\$0.00	Replace	Check
		53289-47082	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Check
			STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given
		42811-47140 (FR)	WHEEL DISC FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair
		87003-47080	DOOR RR/RH	1.00	\$364.50	25.00	\$273.38	Replace	Replace
		55708-47101	WIPER GARNISH	0.00	\$814.00	0.00	\$0.00	Replace	Check
		81129-47080	BRACKET, FR TURN LOWER LH	0.00	\$28.00	0.00	\$0.00	Replace	Check
		88480-47130	A/C CONDENSER	0.00	\$1,181.90	0.00	\$0.00	Replace	Check
		87981-47030	DOOR WEATHER STRIP (FR/RR)	0.00	\$171.20	0.00	\$0.00	Replace	Check
		81329-47080	BRACKET, FR TURN LOWER LH	0.00	\$28.00	0.00	\$0.00	Replace	Check
		52119-47830	BUMPER FR/RT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		81215-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Check
			COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Check
		80963-47080	FUSE BLOCK, COVER LOWER	0.00	\$18.50	0.00	\$0.00	Replace	Check
		08225-47021	HOSE, INVERTER NO 1	0.00	\$80.00	0.00	\$0.00	Replace	Check
Total					\$35,992.91		\$5,794.28		

X NAI
 X NAI
 X NAI
 X R
 Buy
 X NAI
 X NAI
 X NAI
 X NI
 X NI
 DEP
 X NI
 X NI
 X NI
 X NI

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Partcode	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TRX / 02 / 19 / 2019	Date of Collection	28 / 2 / 19
Vehicle No	SHD 6128 K	Date of Request	5 / 3 / 19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	2 / 3 DAYS

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	7625, 26, 27	Radiator Assy		\$1496.90
2	7630, 31	Deflector Radiator LH		\$77.00
3	7624, 23, 24	Radiator Assy Upper		\$679.60
4	7619, 20, 21	Radiator Lower Support		\$876.30
5	7632, 33, 34	Fan Shroud		\$244.50
6	7628, 29	A/C Condenser		\$1181.90
7				
8				

BT \$172.08
 CRA \$57.75
 BT \$509.70
 BT \$657.23
 CRA \$183.50
 DD \$886.43

<<<Please submit photographs for damaged parts>>>

13/3/19

I, (Name) CHIA
 (Position) ADVISOR

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 737705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/02/2019

User ID : ZhiYangPhua

Section A - Accident Details	
Registration Number	BHD6128K
Case Reference Number	TAX/02/19/2081
Registration Date	6/11/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	GANDARUBAN
Type of Accident	Side Swipe
Accident Date and Time	13/2/2019 9:20 PM
Accident Reported Date and Time	15/2/2019 3:32 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100148
Special Instruction to ARC, if any	TRYTOWED TP COMPOUND /AIG - LKK
Prepared Date and Time	25/2/2019 3:43 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,197.00	\$1,200.00
Total Spray Cost	\$4,086.00	\$1,400.00
Total Spare Part Cost	\$22,841.18	\$5,704.28
Total Other Cost	\$2,236.00	\$470.00
TOTAL COST	\$31,460.18	\$8,774.28
Lump Sum Total	\$31,450.00	\$8,700.00
Number of Repair Days	10.0	8.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie
ARC / Surveyor Sign Off Date	28/02/2019 8:41 AM	27/02/2019 3:48 PM
Signature		
Remarks		L/S REPAIR, PHOTO AFTER REPAIR.

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 65685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 28/02/2019

User ID : ZhiYangPhua

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$400.00
TO REPAIR FRONT LH PORTION	\$1,352.00	\$800.00
Total Labour	\$2,197.00	\$1,200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO REPSRAY APRON PANEL LH	\$180.00	\$0.00
TO REPSRAY FRONT DOOR LH	\$378.00	\$0.00
TO REPSRAY FRONT DOOR RH	\$378.00	\$200.00
TO REPSRAY FRONT FENDER LH	\$378.00	\$200.00
TO REPSRAY FRONT FENDER RH	\$378.00	\$200.00
TO REPSRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO REPSRAY FRNT MEMBER LH	\$180.00	\$0.00
TO REPSRAY RADIATOR SUPPORT LOWER	\$180.00	\$0.00
TO REPSRAY RH REAR DOOR	\$378.00	\$200.00
TO REPSRAY RIM	\$300.00	\$100.00
TO REPSRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$4,068.00	\$1,400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO ALIGN CHASSIS	\$300.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$50.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$100.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$80.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$240.00	\$80.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$100.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$128.00	\$80.00
Total Other Costs	\$2,238.00	\$470.00

Part 4 - Spare Parts / Material Usage

Part Number	Partion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		81821-47050	LENS & BOOY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given
		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Check
		53301-47060	HOOD PANEL	1.00	\$748.10	25.00	\$561.08	Replace	Replace
		57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Check
		81130-47500	HEAD LAMP RH	0.00	\$945.20	0.00	\$0.00	Replace	Check
		88790-22131	THERMISTOR ASSY	0.00	\$107.00	0.00	\$0.00	Replace	Not Given
		98830-47031	CHECK ASSY, RR DOOR	0.00	\$150.30	0.00	\$0.00	Replace	Check

WV

DEF

WV



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park EA, Singapore 757705
FAX Number : 63665582
Estimator Telephone Number : 68662523
Accident Reporting Number : 68662672

Date Generated : 28/02/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53510-47102	HOOD LOCK	0.00	\$128.90	0.00	\$0.00	Replace	Check
		53702-47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Check
		16400-37230	RADIATOR ASSY	0.00	\$1,496.90	0.00	\$0.00	Replace	Check
		52161-18010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		53675-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.77	Replace	Replace
		81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check
		69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Check
		81521-47050	LENS & BODY, FR TURN LH	1.00	\$511.80	10.00	\$460.62	Replace	Replace
		53293-47040	DEFLECTOR, RADIATOR RH	0.00	\$83.90	0.00	\$0.00	Replace	Check
		53851-47040	FENDER LINER PAD, FR WHEEL RH	0.00	\$49.30	0.00	\$0.00	Replace	Check
		55083-47011	WPER GARNISH COVER, RH	0.00	\$23.90	0.00	\$0.00	Replace	Not Given
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check
		16533-28051	SUPPORT, RADIATOR, RH	0.00	\$54.90	0.00	\$0.00	Replace	Check
		53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace
		16571-37140	RADIATOR TOP HOSE NO 1	0.00	\$42.40	0.00	\$0.00	Replace	Check
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check
		88703-47040	HOSE SUB-ASSY, DISCHARGE	0.00	\$386.90	0.00	\$0.00	Replace	Check
		53395-47020	HOOD END PANEL SEAL	0.00	\$35.90	0.00	\$0.00	Replace	Check
		53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Check
		53341-47020	HOOD PANEL INSULATOR	0.00	\$390.50	0.00	\$0.00	Replace	Check
		53294-47030	DEFLECTOR, RADIATOR LH	0.00	\$77.00	0.00	\$0.00	Replace	Check
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace
		55084-47011	WPER GARNISH COVER, LH	0.00	\$23.90	0.00	\$0.00	Replace	Not Given
		88710-47150	TUBE & ACCESSORY	0.00	\$631.90	0.00	\$0.00	Replace	Check
		76851-47020	BUMPER LIP FRT	1.00	\$138.60	25.00	\$104.70	Replace	Replace
		82111-47772	WRE, ENGINE ROOM	0.00	\$5,567.10	0.00	\$0.00	Replace	Not Given
		53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Check
		G9010-47031	RADIATOR ASSY, UPPER	0.00	\$879.60	0.00	\$0.00	Replace	Check
		53801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Check
		53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Check
		81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace
		81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check
		69030-47070	DOOR LOCK FRT/RH	0.00	\$575.80	0.00	\$0.00	Replace	Check
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$78.40	0.00	\$0.00	Replace	Check
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.90	25.00	\$59.10	Replace	Replace
		53420-47070	HOOD HINGE LH	0.00	\$55.90	0.00	\$0.00	Replace	Check
		81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check

NCC
DCP

CAA

AN

BVC

SCR

AN

UN

DRP

CAA

CAA



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
90 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685552
Estimator Telephone Number : 68952523
Accident Reporting Number : 68662672

Date Generated : 28/02/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace	BVC
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	CUT
		82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Check	
		69029-47020	HOSE, INVERTER COOLING NO.5	0.00	\$125.30	0.00	\$0.00	Replace	Check	
		52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.88	Replace	Replace	MIS
		75310-47010	EMBLEM FRONT	1.00	\$66.50	25.00	\$49.88	Replace	Replace	MIS
		57104-47020	RADIATOR LOWER SUPPORT	0.00	\$876.30	0.00	\$0.00	Replace	Check	
		75851-47900	MOULDING BODY, RH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	
		53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check	
			NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Check	
		51444-12050	UNDER COVER SIDE/LH	0.00	\$46.10	0.00	\$0.00	Replace	Check	
		81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	
		42811-47140 (Frt)	WHEEL DISC, FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.92	Replace	Replace	REC
		52127-47903	COVER, FR BUMPER HOLE RH	0.00	\$18.50	0.00	\$0.00	Replace	Check	
		68740-12120	DOOR HINGE LOWER RR/RH	0.00	\$90.10	0.00	\$0.00	Replace	Check	
		18711-37040	FAN SHROUD	0.00	\$244.50	0.00	\$0.00	Replace	Check	
		53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Check	
		53113-47040	GRILLE RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Check	
		52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Check	
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.92	Replace	Replace	REC
		53814-47030	CLAMP, HOOD LOCK	0.00	\$5.90	0.00	\$0.00	Replace	Check	
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	REC
		85710-47120F	DOOR REGULATOR MOTOR FRONT RH	0.00	\$947.80	0.00	\$0.00	Replace	Check	
		18712-37030	FAN SHROUD TOP	0.00	\$99.60	0.00	\$0.00	Replace	Check	
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	KN
		53201-47902	SUPPORT SUB-ASSY	0.00	\$1,480.40	0.00	\$0.00	Replace	Check	
		67002-47070	DOOR FRT/LH	0.00	\$894.40	0.00	\$0.00	Replace	Check	
		53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Check	
		61311-47030	PILLAR, CTR BODY	0.00	\$307.70	0.00	\$0.00	Replace	Check	
		68410-33010	DOOR LOCK STRIKER	0.00	\$40.50	0.00	\$0.00	Replace	Check	
		68205-47050	DOOR INNER HANDLE FRT/RH	0.00	\$84.70	0.00	\$0.00	Replace	Check	
		52116-47040	BUMPER SUPPORT FLH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	CRJ
		82662-47110	FUSE BLOCK, TOP COVER	0.00	\$82.30	0.00	\$0.00	Replace	Check	
			NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	KN
		5702812020	MEMBER SUB-ASSY, FR LH	0.00	\$810.70	0.00	\$0.00	Replace	Check	
		18672-37120	RADIATOR HOSE LOWER	0.00	\$42.40	0.00	\$0.00	Replace	Check	
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	KN
		18534-37010	SUPPORT, RADIATOR, LH	0.00	\$17.70	0.00	\$0.00	Replace	Check	
		68210-74030	DOOR OUTER HANDLE FRT/RH	1.00	\$370.80	100.00	\$0.00	Replace	Repair	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park EA, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68602823	
Accident Reporting Number : 68602872	

Date Generated : 28/02/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		68750-20121	DOOR HINGE UPPER R/R/RH	0.00	\$81.70	0.00	\$0.00	Replace	Check
		53289- 47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Check
			STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given
		42811- 47140 (Fr)	WHEEL DISC, FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair
		67003-47080	DOOR R/R/RH	1.00	\$954.50	25.00	\$715.88	Replace	Replace
		55708- 47101	WIPER GARNISH	0.00	\$614.00	0.00	\$0.00	Replace	Check
		81528- 47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check
		88460- 47150	A/C CONDENSER	0.00	\$1,181.90	0.00	\$0.00	Replace	Check
		67861-47030	DOOR WEATHER STRIP FRT/RH	0.00	\$171.20	0.00	\$0.00	Replace	Check
		81528- 47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check
		62119- 47930	BUMPER FRT	1.00	\$462.00	25.00	\$346.50	Replace	Replace
		81210- 12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Check
			COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Check
		82663- 47060	FUSE BLOCK, COVER LOWER	0.00	\$18.50	0.00	\$0.00	Replace	Check
		G8225- 47021	HOSE, INVERTER NO.1	0.00	\$80.00	0.00	\$0.00	Replace	Check
Total					\$35,992.51		\$5,704.28		

BUL

DEP

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

View Received Message

This mail is associated with :

***SHD6128K (94168960425G)
[SLM2320C]**

TP
SMRT TAXIS PTE LTD
Feb 13 2019 8:00PM
[NG CHENG HEE]
SMRT Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 19/12/2019 13:29 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12530.00) - SHD6128K - Claim Handler: Syed-Yusoff, Saliha

Approved:12530.00:Pls do your utmost the settle the matter not exceeding \$12,530.00 approval is subject to final repair bill & ATA. breakdown of approval (for internal reference only): COR- \$10,350 LOR-\$1144.90 [19 DAYS- 8 days (surveyor reco

DOCUMENTS SUMMARY

There are no documents.

Date	Day	Taxi at workshop / traffic police compound	Surveyor's recommendation
13/2/2019	Wed	0 day	
14/2/2019	Thurs	1 day	
15/2/2019	Fri	1 day	
16/2/2019	Sat	1 day	
17/2/2019	Sun	1 day	
18/2/2019	Mon	1 day	
19/2/2019	Tues	1 day	
20/2/2019	Wed	1 day	
21/2/2019	Thurs	1 day	
		Accident occurred at 8.20pm & taxi was towed to traffic police compound (please refer to the attachment)	
		taxi at traffic police compound	
		"	
		"	
		"	
		"	
		"	
		"	
		taxi was towed back to workshop at 9.55am (please refer to the towing receipt)	
		<i>not done, only</i>	
		<i>not done, only</i>	
		notified your office of PRS	
		<i>PRS</i>	
		our taxi was surveyed at 3.27pm	
			repair day 1
			repair day 2
			repair day 3
			repair day 4
			repair day 5
			repair day 6
			repair day 7
			repair day 8
		23 days	<u>8 days for repair</u>

View Received Message

This mail is associated with :

***SHD6128K (9416896042SG)
[SLM2320C]**

TP
SMRT TAXIS PTE LTD
Feb 13 2019 8:00PM
[NG CHENG HEE]
SMRT Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 07/11/2019 15:42 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11501.90) - SHD6128K - Claim Handler: Syed-Yusoff, Saliha

Approved:11501.90:approval is subject to final repair bill & ATA. breakdown of approval: COR- \$10,350 LOR-\$1144.90 [10 DAYS] LTA-\$7.00

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Feb 2019 Edit Reg		27 Feb 2019 00:00 Edit Adj Rpt	S\$10,350.00 Edit Estimates	S\$10,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	NG CHENG HEE, ID: 575727251		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHD6128K	Date of Loss:	13/02/2019 20:00 - :59 [39 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9416896042SG	Policy/Cover Note No.:	2100504571 (Comprehensive) Coverage: 24/03/2018 - 23/03/2019
Vehicle Reg. No. (Insured):	SLM2320C	Policy No. (Claimant):	D-18090213MFSH
Excess:			
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 12/03/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG_EXPRESS (19/12/2019): Alert - Adj Mandate Approved (S\$12530.00) - SHD6128K - Claim Handler: Syed-Yusof... AIG_SG_EXPRESS (07/11/2019): Alert - Adj Mandate Approved (S\$11501.90) - SHD6128K - Claim Handler: Syed-Yusof... AIG_SG (04/03/2019): TP GIA REPORT 			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*SHD6128K (9416896042SG)
[SLM2320C]
TP
SMRT TAXIS PTE LTD
Feb 13 2019 8:00PM
[NG CHENG HEE]
SMRT Automotive Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Video															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	04/11/19 17:04	Video - Accident (TP)											Load MP4				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print				
1	07/11/19 15:46	Video - Accident from OI											Load MP4				
Letters/Correspondences															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit				
Photos/Images															3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
2	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
3	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
4	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
5	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
6	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
7	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
8	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
9	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
10	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
11	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
12	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
13	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
14	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
15	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
16	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
17	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
18	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
19	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
20	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
21	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
22	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
23	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
24	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
25	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
26	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
27	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
28	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
29	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
30	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
31	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
32	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
33	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
34	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			
35	04/03/19 10:26	General View											Load JPG	<input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
36	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
37	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
38	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
44	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
47	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
48	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
49	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
50	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
51	04/03/19 10:26	General View	 Load JPG	<input checked="" type="checkbox"/>
52	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	13/03/19 10:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	25/09/19 08:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
69	25/09/19 08:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
70	25/09/19 08:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
71	25/09/19 08:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
72	25/09/19 08:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/03/19 16:44	TP ESTIMATE - MARKED	 Load PDF	
2	15/03/19 16:44	TP GIA REPORT.	 Load PDF	
3	15/05/19 09:38	LETTER TO OI	 Load PDF	
4	01/11/19 11:18	RENTAL RECEIPT	 Load PDF	
5	01/11/19 11:18	RENTAL MILEAGE	 Load PDF	
6	01/11/19 11:18	LTA SEARCH	 Load PDF	
7	01/11/19 11:18	LOD	 Load PDF	
8	04/11/19 16:38	TP_ESTIMATE-MARKED-FINAL	 Load PDF	
9	18/12/19 10:00	TOWING INV	 Load PDF	
10	18/12/19 10:00	TP COMPOUND LETTER	 Load PDF	
11	19/12/19 13:52	supplementary	 Load PDF	
12	19/12/19 13:52	Copy of breakdown of no of days	 Load XLSX	
13	27/12/19 14:18	WORKSHOP INVOICE	 Load PDF	
14	27/12/19 14:18	AUTHORISATION TO ACT FORM	 Load PDF	
15	27/12/19 14:18	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/03/19 12:15	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLM2320C (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHD6128K (TP veh)		
Date of Accident:	13/02/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	49,082.10
Final Repair Cost	:	\$	12,500.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	19 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	12,500.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	SMRT Taxis Pte Ltd	:	\$ 12,500.00
2)		:	\$
3)		:	\$

 JOANNE LEE KHANG MIN
 LKK Auto Consultants Pte Ltd

 27 Dec
 2019
 Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19003852/JDA3Q2

Date: 27/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100504571
 Claimant SHD6128K Insured Vehicle No : SLM2320C
 Vehicle No : SHD6128K
 Date of Loss: 13/02/2019 Nature of Claim: TP Claim No: 9416896042SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD6128K
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR6551643
 Reg. Date: 06/11/2015 (Man. Year: 2015) Chassis No: JTDKN36U805766681
 Colour: Maroon Odometer: 0 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Achilles 6 mm Rear Left Side: Achilles 6 mm
 Front Right Side: Achilles 6 mm Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,563.10	9,121.48	31,441.62	77.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,519.00	3,070.00	5,449.00	63.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	49,082.10	12,191.48	36,890.62	75.16
Approved Total (Overridden) (S\$)		10,350.00		
Nett Amount (S\$)	49,082.10	10,350.00	38,732.10	78.91
+ Car Rental (19.0 x S\$114.49/day) (S\$)		2,175.31		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		12,532.31		
Global Sum Settlement (S\$)		12,500.00		

INSPECTION

Date of Assignment: 27/02/2019
 Date Inspected: 27/02/2019 Inspected At: SMRT Automotive Services Pte Ltd
 (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705
 Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRT (DISC 25%)	Deformed	482.00 F	*361.50 F
2	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.00 F	*12.08 F
3	1		*BUMPER ENERGY ABSORBER FRT (DISC 25%)	Cracked	78.80 F	*59.10 F
4	1		*COVER ,FR BUMPER HOLE LH (DISC 25%)	Missing	18.50 F	*13.88 F
5	1		*BUMPER SUPPORT F/LH (DISC 25%)	Cracked	76.40 F	*57.30 F
6	1		*BUMPER GRILLE SUB-ASSY ,LOWER (DISC 25%)	Scratched	311.10 F	*233.33 F
7	1		*BUMPER LIP FRT (DISC 25%)	Missing	139.60 F	*104.70 F
8	1		*EMBLEM FRONT (DISC 25%)	Missing	86.50 F	*64.88 F
9	1		*HOOD PANEL (DISC 25%)	Deformed	748.10 F	*561.08 F
10	1		*FENDER FRT/LH (DISC 25%)	Buckled	723.40 F	*542.55 F
11	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
12	1		*FENDER LINER FRT/LH (DISC 25%)	Deformed	171.70 F	*128.78 F
13	1		*FENDER FRT/RH (DISC 25%)	Deformed	723.40 F	*542.55 F
14	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
15	1		*DOOR FRT/RH (DISC 25%)	Buckled	894.40 F	*670.80 F
16	1		*DOOR RR/RH (DISC 25%)	Buckled	954.50 F	*715.88 F
17	1		*RADIATOR ASSY (DISC 25%)	Bent	1,496.90 F	*1,122.68 F
18	1		*DEFLECTOR ,RADIATOR LH (DISC 25%)	Cracked	77.00 F	*57.75 F
19	1		*RADIATOR ASSY ,UPPER (DISC 25%)	Bent	679.60 F	*509.70 F
20	1		*RADIATOR LOWER SUPPORT (DISC 25%)	Bent	876.30 F	*657.23 F
21	1		*FAN SHROUD (DISC 25%)	Cracked	244.50 F	*183.38 F
22	1		*A/C CONDENSER (DISC 25%)	Dented	1,181.90 F	*886.43 F
23	1		*LENS & BODY ,FR TURN LH (DISC 10%)	Cracked	511.80 F	*460.62 F
24	1		*HEAD LAMP LH (DISC 10%)	Cracked	945.20 F	*850.68 F
25	1		*TYRE (SN)	Cut	126.74 F	*126.74 F
26	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
27	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
28	1		*WHEEL DISC ,FRONT	Repair	1,484.20 F	*- F
29	1		*WHEEL DISC ,FRONT	Repair	1,484.20 F	*- F
30	1		*DOOR OUTER HANDLE FRT/RH	Repair	370.80 F	*- F
31	1		*MOULDING BODY RH	Repair	673.60 F	*- F
32	1		*BUMPER REINFORCEMENT FRT	Not Necessary	498.40 F	*- F
33	1		*ARM SUB-ASSY ,FR BUMPER LH	Not Necessary	250.40 F	*- F
34	1		*ARM SUB-ASSY ,FR BUMPER RH	Not Necessary	250.40 F	*- F
35	1		*COVER ,FR BUMPER HOLE RH	Not Necessary	18.50 F	*- F
36	1		*BRACKET ,FR BUMPER	Not Necessary	110.40 F	*- F
37	1		*NUMBER PLATE	Not Necessary	15.00 F	*- F
38	1		*NUMBER PLATE FRAME	Not Necessary	12.00 F	*- F
39	1		*BUMPER SUPPOT F/RH	Not Necessary	76.40 F	*- F
40	1		*FOG LAMP LH	Not Necessary	280.10 F	*- F
41	1		*FOG LAMP RH	Not Necessary	295.20 F	*- F
42	1		*BUMPER FRT ABSORBER LOWER	Not Necessary	127.70 F	*- F
43	1		*GRILLE RADIATOR LOWER NO.2	Not Necessary	94.60 F	*- F
44	1		*GRILLE ,RADIATOR	Not Necessary	310.60 F	*- F
45	1		*WIRE ,ENGINE ROOM, NO.3	Not Necessary	242.00 F	*- F
46	1		*BRACKET ,FR TURN CENTER LH	Not Necessary	58.20 F	*- F
47	1		*BRACKET ,FR TURN LOWER LH	Not Necessary	26.00 F	*- F
48	1		*BRACKET ,FR TURN UPPER LH	Not Necessary	24.40 F	*- F
49	1		*BRACKET ,FR TURN CENTER LH	Not Necessary	58.20 F	*- F
50	1		*BRACKET ,FR TURN LOWER LH	Not Necessary	26.00 F	*- F
51	1		*BRACKET ,FR TURN UPPER LH	Not Necessary	24.40 F	*- F
52	1		*LENS & BODY ,FR TURN LH	Not Necessary	511.80 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
53	1		*THERMISTOR ASSY	Not Necessary	107.00 F	*-F
54	1		*HOOD END PANEL SEAL	Not Necessary	35.50 F	*-F
55	1		*HOOD HINGE LH	Not Necessary	55.90 F	*-F
56	1		*HOOD HINGE RH	Not Necessary	55.90 F	*-F
57	1		*HOOD LOCK	Not Necessary	128.90 F	*-F
58	1		*CLAMP ,HOOD LOCK	Not Necessary	5.90 F	*-F
59	1		*HOOD PANEL INSULATOR	Not Necessary	390.50 F	*-F
60	1		*WIPER GARNISH COVER ,LH	Not Necessary	23.80 F	*-F
61	1		*WIPER GARNISH COVER ,RH	Not Necessary	23.80 F	*-F
62	1		*WIPER GARNISH	Not Necessary	614.00 F	*-F
63	1		*SUPPORT SUB-ASSY	Not Necessary	1,460.40 F	*-F
64	1		*COVER ,RADIATOR	Not Necessary	122.80 F	*-F
65	1		*HEAD LAMP RH	Not Necessary	945.20 F	*-F
66	1		*WIRE ,ENGINE ROOM	Not Necessary	5,567.10 F	*-F
67	1		*FUSE BLOCK ,COVER LOWER	Not Necessary	18.50 F	*-F
68	1		*FUSE BLOCK ,TOP COVER	Not Necessary	82.30 F	*-F
69	1		*DEFLECTOR ,RADIATOR LH	Not Necessary	77.00 F	*-F
70	1		*DEFLECTOR ,RADIATOR RH	Not Necessary	83.50 F	*-F
71	1		*A/C CONDENSER	Not Necessary	1,181.90 F	*-F
72	1		*TUBE & ACCESSORY	Not Necessary	631.90 F	*-F
73	1		*HOSE SUB-ASSY ,DISCHARGE	Not Necessary	386.90 F	*-F
74	1		*COOLANT	Not Necessary	12.32 F	*-F
75	1		*RADIATOR ASSY	Not Necessary	1,496.90 F	*-F
76	1		*RADIATOR ASSY ,UPPER	Not Necessary	679.60 F	*-F
77	1		*RADIATOR LOWER SUPPORT	Not Necessary	876.30 F	*-F
78	1		*SUPPORT ,RADIATOR ,LH	Not Necessary	17.70 F	*-F
79	1		*SUPPORT ,RADIATOR ,RH	Not Necessary	54.50 F	*-F
80	1		*FAN SHROUD	Not Necessary	244.50 F	*-F
81	1		*FAN SHROUD TOP	Not Necessary	99.60 F	*-F
82	1		*RADIATOR HOSE LOWER	Not Necessary	42.40 F	*-F
83	1		*RADIATOR TOP HOSE NO 1	Not Necessary	42.40 F	*-F
84	1		*HOSE ,INVERTER NO1	Not Necessary	80.00 F	*-F
85	1		*HOSE INVERTER COOLING NO.5	Not Necessary	125.30 F	*-F
86	1		*FENDER LINER PAD ,FR WHEEL LH	Not Necessary	49.30 F	*-F
87	1		*PROTECTOR ,FRONT FENDER SIDE PANEL LH	Not Necessary	114.50 F	*-F
88	1		*FENDER PROTECTOR FRT/LH UPPER	Not Necessary	46.10 F	*-F
89	1		*FENDER APRON SUB FRT/LH	Not Necessary	637.80 F	*-F
90	1		*UNDER COVER SIDE /LH	Not Necessary	46.10 F	*-F
91	1		*TYRE	Not Necessary	126.74 F	*-F
92	1		*DOOR FRT/LH	Not Necessary	894.40 F	*-F
93	1		*STICKER DECAL SMRT (DOOR)	Not Necessary	60.00 F	*-F
94	1		*FENDER LINER FRT/RH	Not Necessary	171.70 F	*-F
95	1		*FENDER LINER PAD ,FR WHEEL RH	Not Necessary	49.30 F	*-F
96	1		*DOOR LOCK FRT/RH	Not Necessary	575.80 F	*-F
97	1		*DOOR LOCK STRIKER	Not Necessary	40.50 F	*-F
98	1		*DOOR INNER HANDLE FRT/RH	Not Necessary	84.70 F	*-F
99	1		*DOOR REGULATOR MOTOR FRONT RH	Not Necessary	947.80 F	*-F
100	1		*DOOR REGULATOR SUB ASSY ,FRT/ REAR RH	Not Necessary	224.80 F	*-F
101	1		*DOOR WEATHER STRIP FRT/RH	Not Necessary	171.20 F	*-F
102	1		*PILLAR ,CTR BODY	Not Necessary	307.70 F	*-F
103	1		*DOOR HINGE UPPER RR/RH	Not Necessary	81.70 F	*-F
104	1		*DOOR HINGE LOWER RR/RH	Not Necessary	90.10 F	*-F
105	1		*CHECK ASSY ,RR DOOR	Not Necessary	150.30 F	*-F
106	1		*MEMBER SUB-ASSY ,FR LH	Not Necessary	810.70 F	*-F

F=Franchise part.

Total Parts (\$) **40,563.10** **9,121.48**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	2,197.00	1,200.00
2	SPRAY PAINT	New	4,086.00	1,400.00
3	TOWING CHARGE	New	126.00	90.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	50.00
6	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
7	TO TOP UP A/C GAS	New	120.00	0.00
8	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	240.00	50.00
9	TO ALIGN CHASSIS	New	350.00	0.00
10	TO TRANSFER DOOR MECHANISM	New	240.00	100.00
11	TO REMOVE AND REFIT WIRE HARDESS	New	250.00	0.00
12	TO CHECK & RESET SYSTEM FUNCTION	New	350.00	100.00
13	TO REPLACE SUNDRY PARTS	New	100.00	0.00
14	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			8,519.00	3,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >