





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 28/02/2019

User ID : ZhiYangPhua

Section A - Accident Details	
Registration Number	SHD6128K
Case Reference Number	TAX/02/19/2081
Registration Date	6/11/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	GANDARUBAN
Type of Accident	Side Swipe
Accident Date and Time	13/2/2019 8:20 PM
Accident Reported Date and Time	15/2/2019 3:32 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100145
Special Instruction to ARC, if any	TP/TOWED TP COMPOUND /AIG - LKK
Prepared Date and Time	25/2/2019 3:43 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Toyota Prius

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,197.00	\$1,200.00
Total Spray Cost	\$4,086.00	\$1,400.00
Total Spare Part Cost	\$22,941.18	\$5,704.28
Total Other Cost	\$2,236.00	\$470.00
TOTAL COST	\$31,460.18	\$8,774.28
Lump Sum Total	\$31,450.00	\$8,700.00
Number of Repair Days	16.0	6.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee jie
ARC / Surveyor Sign Off Date	28/02/2019 8:41 AM	27/02/2019 3:48 PM
Signature		
Remarks		L/S REPAIR, PHOTO AFTER REPAIR.

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63885592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/02/2019

User ID : ZhiYangPhua

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR			Adjusted by Surveyor, if applicable				
TO REPAIR RH PORTION		\$845.00			\$400.00				
TO REPAIR FRONT LH PORTION		\$1,352.00			\$800.00				
Total Labour		\$2,197.00			\$1,200.00				
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
TO REPSRAY FRONT BUMPER		\$378.00			\$200.00				
TO REPSRAY FRONT HOOD		\$378.00			\$200.00				
TO RESPRAY APRON PANEL LH		\$180.00			\$0.00				
TO RESPRAY FRONT DOOR LH		\$378.00			\$0.00				
TO RESPRAY FRONT DOOR RH		\$378.00			\$200.00				
TO RESPRAY FRONT FENDER LH		\$378.00			\$200.00				
TO RESPRAY FRONT FENDER RH		\$378.00			\$200.00				
TO RESPRAY FRONT SUPPORT PANEL		\$180.00			\$0.00				
TO RESPRAY FRT MEMBER,LH		\$180.00			\$0.00				
TO RESPRAY RADIATOR SUPPORT LOWER		\$180.00			\$0.00				
TO RESPRAY RH REAR DOOR		\$378.00			\$200.00				
TO RESPRAY RIM		\$360.00			\$100.00				
TO RESPRAY ROCKER PANEL MOULDING		\$180.00			\$100.00				
TO SPRAY FRONT BUMPER LOWER SUB GRILLE		\$180.00			\$0.00				
Total Spray Painting & Panel Beating		\$4,086.00			\$1,400.00				
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
TO ALIGN CHASSIS		\$350.00			\$0.00				
TO APPLY RUST-PROOFING ON AFFECTED AREA		\$200.00			\$50.00				
TO CHECK & RESET SYSTEM FUNCTION		\$350.00			\$100.00				
TO CHECK WIRING AND SYSTEM FUNCTION		\$80.00			\$20.00				
TO DO WHEEL ALIGNMENT / TYRE BALANCING		\$120.00			\$60.00				
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)		\$240.00			\$50.00				
TO REMOVE AND REFIT WIRE HARDESS		\$250.00			\$0.00				
TO REPLACE SUNDRY PARTS		\$100.00			\$0.00				
TO TOP UP A/C GAS		\$120.00			\$0.00				
TO TRANSFER DOOR MECHANISM		\$240.00			\$100.00				
TO WASH AND VACUUM		\$60.00			\$0.00				
TOWING CHARGE		\$126.00			\$90.00				
Total Other Costs		\$2,236.00			\$470.00				
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		81521- 47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given
		81220- 12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Check
		53301- 47080	HOOD PANEL	1.00	\$748.10	25.00	\$561.08	Replace	Replace
		57013- 47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Check
		81130- 47500	HEAD LAMP RH	0.00	\$945.20	0.00	\$0.00	Replace	Check
		88790- 22131	THERMISTOR ASSY	0.00	\$107.00	0.00	\$0.00	Replace	Not Given
		68630-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Check

Wⁿ

DRF

Wⁿ



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/02/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		53510- 47102	HOOD LOCK	0.00	\$128.90	0.00	\$0.00	Replace	Check	
		53702- 47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Check	
		16400- 37230	RADIATOR ASSY	0.00	\$1,496.90	0.00	\$0.00	Replace	Check	
		52161- 16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	NEC
		53876- 47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.77	Replace	Replace	DEF
		81529- 47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	
		69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Check	
		81521- 47050	LENS & BODY, FR TURN LH	1.00	\$511.80	10.00	\$460.62	Replace	Replace	CFA
		53293- 47040	DEFLECTOR, RADIATOR RH	0.00	\$83.50	0.00	\$0.00	Replace	Check	
		53851- 47040	FENDER LINER PAD, FR WHEEL RH	0.00	\$49.30	0.00	\$0.00	Replace	Check	
		55083- 47011	WIPER GARNISH COVER, RH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given	un
		52021- 47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check	
		16533- 28051	SUPPORT, RADIATOR, RH	0.00	\$54.50	0.00	\$0.00	Replace	Check	
		53802- 47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	BUC
		16571- 37140	RADIATOR TOP HOSE NO 1	0.00	\$42.40	0.00	\$0.00	Replace	Check	
		52618- 47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check	
		88703- 47040	HOSE SUB-ASSY, DISCHARGE	0.00	\$386.90	0.00	\$0.00	Replace	Check	
		53395- 47020	HOOD END PANEL SEAL	0.00	\$35.50	0.00	\$0.00	Replace	Check	
		53826- 47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Check	
		53341- 47020	HOOD PANEL INSULATOR	0.00	\$390.50	0.00	\$0.00	Replace	Check	
		53294- 47030	DEFLECTOR, RADIATOR LH	0.00	\$77.00	0.00	\$0.00	Replace	Check	
		53102- 47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace	SCR
		55084- 47011	WIPER GARNISH COVER, LH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given	un
		88710- 47150	TUBE & ACCESSORY	0.00	\$631.90	0.00	\$0.00	Replace	Check	
		76851- 47020	BUMPER LIP FRT	1.00	\$139.60	25.00	\$104.70	Replace	Replace	
		82111- 47772	WIRE, ENGINE ROOM	0.00	\$5,567.10	0.00	\$0.00	Replace	Not Given	un
		53410- 47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Check	
		G9010- 47031	RADIATOR ASSY, UPPER	0.00	\$679.60	0.00	\$0.00	Replace	Check	
		53801- 47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	DEF
		57014- 47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Check	
		53852- 47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Check	
		81170- 47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	CFA
		81529- 47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	
		69030-47070	DOOR LOCK FRT/RH	0.00	\$575.80	0.00	\$0.00	Replace	Check	
		52115- 47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Check	
		52611- 47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	25.00	\$59.10	Replace	Replace	CRA
		53420- 47070	HOOD HINGE LH	0.00	\$55.90	0.00	\$0.00	Replace	Check	
		81529- 47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/02/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace	BUC
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	CUT
		82113- 47180	WRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Check	
		G9229- 47020	HOSE, INVERTER COOLING NO.5	0.00	\$125.30	0.00	\$0.00	Replace	Check	
		52128- 47903	COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.88	Replace	Replace	MIS
		75310- 47010	EMBLEM FRONT	1.00	\$86.50	25.00	\$64.88	Replace	Replace	MIS
		57104- 47020	RADIATOR LOWER SUPPORT	0.00	\$878.30	0.00	\$0.00	Replace	Check	
		75851-47900	MOULDING BODY, RH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	
		53111- 47040	GRILLE, RADIATOR	0.00	\$310.80	0.00	\$0.00	Replace	Check	
			NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Check	
		51444- 12050	UNDER COVER SIDE/LH	0.00	\$46.10	0.00	\$0.00	Replace	Check	
		81529- 47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	
		42611- 47140 (Frt)	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	
		75374- 47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.92	Replace	Replace	nee
		52127- 47903	COVER, FR BUMPER HOLE RH	0.00	\$18.50	0.00	\$0.00	Replace	Check	
		68740-12120	DOOR HINGE LOWER RR/RH	0.00	\$90.10	0.00	\$0.00	Replace	Check	
		16711- 37040	FAN SHROUD	0.00	\$244.50	0.00	\$0.00	Replace	Check	
		53828- 47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Check	
		53113 - 47040	GRILLE RADIATOR LOWER NO.2	0.00	\$94.80	0.00	\$0.00	Replace	Check	
		52114- 47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Check	
		75374- 47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.92	Replace	Replace	nee
		53614- 47030	CLAMP, HOOD LOCK	0.00	\$5.90	0.00	\$0.00	Replace	Check	
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	nee
		85710-47120F	DOOR REGULATOR MOTOR FRONT RH	0.00	\$947.80	0.00	\$0.00	Replace	Check	
		16712- 37030	FAN SHROUD TOP	0.00	\$99.80	0.00	\$0.00	Replace	Check	
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	un
		53201- 47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Check	
		67002- 47070	DOOR FRT/LH	0.00	\$894.40	0.00	\$0.00	Replace	Check	
		53875- 47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Check	
		61311-47030	PILLAR, CTR BODY	0.00	\$307.70	0.00	\$0.00	Replace	Check	
		69410-33010	DOOR LOCK STRIKER	0.00	\$40.50	0.00	\$0.00	Replace	Check	
		69205-47050	DOOR INNER HANDLE FRT/RH	0.00	\$84.70	0.00	\$0.00	Replace	Check	
		52116- 47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	CRA
		82862- 47110	FUSE BLOCK, TOP COVER	0.00	\$82.30	0.00	\$0.00	Replace	Check	
			NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	un
		5702812020	MEMBER SUB-ASSY, FR LH	0.00	\$810.70	0.00	\$0.00	Replace	Check	
		16572- 37120	RADIATOR HOSE LOWER	0.00	\$42.40	0.00	\$0.00	Replace	Check	
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	nee
		16534- 37010	SUPPORT, RADIATOR, LH	0.00	\$17.70	0.00	\$0.00	Replace	Check	
		69210-74030	DOOR OUTER HANDLE FRT/RH	1.00	\$370.80	100.00	\$0.00	Replace	Repair	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/02/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		68750-20121	DOOR HINGE UPPER RR/RH	0.00	\$81.70	0.00	\$0.00	Replace	Check
		53289- 47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Check
			STICKER DECAL SMRT (DOOR)	0.00	\$80.00	0.00	\$0.00	Replace	Not Given
		42611- 47140 (Frt)	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair
		67003-47080	DOOR RR/RH	1.00	\$954.50	25.00	\$715.88	Replace	Replace
		55708- 47101	WIPER GARNISH	0.00	\$614.00	0.00	\$0.00	Replace	Check
		81529- 47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check
		88460- 47150	A/C CONDENSER	0.00	\$1,181.90	0.00	\$0.00	Replace	Check
		67861-47030	DOOR WEATHER STRIP FRT/RH	0.00	\$171.20	0.00	\$0.00	Replace	Check
		81529- 47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check
		52119- 47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		81210- 12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Check
			COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Check
		82663- 47060	FUSE BLOCK, COVER LOWER	0.00	\$18.50	0.00	\$0.00	Replace	Check
		G9225- 47021	HOSE, INVERTER NO.1	0.00	\$80.00	0.00	\$0.00	Replace	Check
Total					\$35,992.51		\$5,704.28		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

B4L
DEP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: