



Section A - Accident Details	
Registration Number	SHD6128K
Case Reference Number	TAX/02/19/2081
Registration Date	6/11/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	GANDARUBAN
Type of Accident	Side Swipe
Accident Date and Time	13/2/2019 8:20 PM
Accident Reported Date and Time	15/2/2019 3:32 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100145
Special Instruction to ARC,if any	TP/TOWED TP COMPOUND /AIG - LKK
Prepared Date and Time	25/2/2019 3:43 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,197.00	\$1,200.00
Total Spray Cost	\$4,086.00	\$1,400.00
Total Spare Part Cost	\$25,674.91	\$7,297.18
Total Other Cost	\$2,236.00	\$470.00
TOTAL COST	\$34,193.91 <i>49,083.20</i>	\$10,367.18
Lump Sum Total	\$31,450.00	\$10,350.00 (L/S)
Number of Repair Days	18.0	8.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	28/02/2019 8:41 AM	27/02/2019 3:48 PM
Signature		
Remarks	Supplementary = 2 days	L/S REPAIR, PHOTO AFTER REPAIR.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685502
Estimator Telephone Number : 68662023
Accident Reporting Number : 6662672

Date Generated : 20/09/2019
User ID : PohSuan

Section C - Quotation and Accident Invoice Details
Table with 4 columns: Quotation Number, Invoice Number, Quotation Date, Invoice Date, Invoice Amount, Prepared Date.

Section D - Details of Repair Estimates
Part 1 - Labour Works
Table with 3 columns: Job Scope, Quotation from AR, Adjusted by Surveyor, if applicable.

Part 2 - Spray Painting & Panel Beating Related Works
Table with 3 columns: Job Scope, Quotation from ARC, Adjusted by Surveyor, if applicable.

Part 3 - Other Costs - Accident and Accident Repair Related Expense
Table with 3 columns: Job Scope, Quotation from ARC, Adjusted by Surveyor, if applicable.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number: 63685582
 Estimator Telephone Number: 68662823
 Accident Reporting Number: 68662872

Date Generated: 2009/2019
 User ID: PohSuan

TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$2,236.00	\$470.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61 <i>16.10</i>	25.00	\$12.08	Replace	Replace ✓
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	25.00	\$59.10	Replace	Replace ✓
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check ✗
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Check ✗
		57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Check ✗
		52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.88	Replace	Replace ✓
		52127-47903	COVER, FR BUMPER HOLE RH	0.00	\$18.50	0.00	\$0.00	Replace	Check ✗
		52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Check ✗
			NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given ✗
			NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Check ✗
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace ✓
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Check ✗
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace ✓
		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Check ✗
		81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Check ✗
		76851-47020	BUMPER LIP FRT	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check ✗
		53113-47040	GRILLE RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Check ✗
		53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check ✗
		75310-47010	EMBLEM FRONT	1.00	\$86.50	25.00	\$64.88	Replace	Replace ✓
		82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Check ✗
		81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check ✗
		81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check ✗
		81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check ✗
		81521-47050	LENS & BODY, FR TURN LH	1.00	\$511.80	10.00	\$460.62	Replace	Replace ✓
		81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check ✗
		81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check ✗
		81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check ✗
		81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given ✗
		88790-22131	THERMISTOR ASSY	0.00	\$107.00	0.00	\$0.00	Replace	Not Given ✗
		53301-47060	HOOD PANEL	1.00	\$748.10	25.00	\$561.08	Replace	Replace ✓
		53395-47020	HOOD END PANEL SEAL	0.00	\$35.50	0.00	\$0.00	Replace	Check ✗
		53420-47070	HOOD HINGE LH	0.00	\$55.90	0.00	\$0.00	Replace	Check ✗
		53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Check ✗
		53510-47102	HOOD LOCK	0.00	\$128.90	0.00	\$0.00	Replace	Check ✗

662.80



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park EA, Singapore 757705
 FAX Number : 63685592
 Estimator Telephone Number : 68662623
 Accident Reporting Number : 68662672

Date Generated : 20/09/2019
 User ID : PohSuan

	53614-47030	CLAMP, HOOD LOCK	0.00	\$5.90	0.00	\$0.00	Replace	Check	X
	53341-47020	HOOD PANEL INSULATOR	0.00	\$390.50	0.00	\$0.00	Replace	Check	X
	55084-47011	WIPER GARNISH COVER, LH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given	X
	55083-47011	WIPER GARNISH COVER, RH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given	X
	55708-47101	WIPER GARNISH	0.00	\$614.00	0.00	\$0.00	Replace	Check	X
	53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Check	X
	53289-47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Check	X
	81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	✓
	81130-47500	HEAD LAMP RH	0.00	\$945.20	0.00	\$0.00	Replace	Check	X
	82111-47772	WIRE, ENGINE ROOM	0.00	\$5,567.10	0.00	\$0.00	Replace	Not Given	X
	82663-47060	FUSE BLOCK, COVER LOWER	0.00	\$18.50	0.00	\$0.00	Replace	Check	X
	82662-47110	FUSE BLOCK, TOP COVER	0.00	\$82.30	0.00	\$0.00	Replace	Check	X
	53294-47030	DEFLECTOR, RADIATOR LH	0.00	\$77.00	0.00	\$0.00	Replace	Check	X
	53293-47040	DEFLECTOR, RADIATOR RH	0.00	\$83.50	0.00	\$0.00	Replace	Check	X
	88460-47150	A/C CONDENSER	0.00	\$1,181.90	0.00	\$0.00	Replace	Check	X
	88710-47150	TUBE & ACCESSORY	0.00	\$631.90	0.00	\$0.00	Replace	Check	X
	88703-47040	HOSE SUB-ASSY, DISCHARGE	0.00	\$386.90	0.00	\$0.00	Replace	Check	X
		COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Check	X
	16400-37230	RADIATOR ASSY	0.00	\$1,496.90	0.00	\$0.00	Replace	Check	X
	G9010-47031	RADIATOR ASSY, UPPER	0.00	\$679.60	0.00	\$0.00	Replace	Check	X
	57104-47020	RADIATOR LOWER SUPPORT	0.00	\$876.30	0.00	\$0.00	Replace	Check	X
	16534-37010	SUPPORT, RADIATOR, LH	0.00	\$17.70	0.00	\$0.00	Replace	Check	X
	16533-28051	SUPPORT, RADIATOR, RH	0.00	\$54.50	0.00	\$0.00	Replace	Check	X
	16711-37040	FAN SHROUD	0.00	\$244.50	0.00	\$0.00	Replace	Check	X
	16712-37030	FAN SHROUD TOP	0.00	\$99.60	0.00	\$0.00	Replace	Check	X
	16572-37120	RADIATOR HOSE LOWER	0.00	\$42.40	0.00	\$0.00	Replace	Check	X
	16571-37140	RADIATOR TOP HOSE NO 1	0.00	\$42.40	0.00	\$0.00	Replace	Check	X
	G9225-47021	HOSE, INVERTER NO.1	0.00	\$80.00	0.00	\$0.00	Replace	Check	X
	G9229-47020	HOSE, INVERTER COOLING NO.5	0.00	\$125.30	0.00	\$0.00	Replace	Check	X
	53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	✓
	75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓
	53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	✓
	53852-47020	FENDER LINER PAD, FR WHEEL, LH	0.00	\$49.30	0.00	\$0.00	Replace	Check	X
	53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Check	X
	53828-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Check	X
	53702-47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Check	X
	51444-12050	UNDER COVER SIDE/LH	0.00	\$46.10	0.00	\$0.00	Replace	Check	X
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	42611-47140 (Fr)	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	R
	67002-47070	DOOR FRT/LH	0.00	\$894.40	0.00	\$0.00	Replace	Check	X
		STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 80 Woodlands Industrial Park E4, Singapore 757706
 FAX Number : 82665592
 Estimator Telephone Number : 88662633
 Accident Reporting Number : 88662672

Date Generated : 2008/2019
 User ID : PohSuan

	53801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	✓
	75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓
	53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Check	X
	53851-47040	FENDER LINER PAD, FR WHEEL, RH	0.00	\$49.30	0.00	\$0.00	Replace	Check	X
		TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	✓
	42611-47140 (Frt)	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	✓
	67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace	✓
		STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓
	69030-47070	DOOR LOCK FRT/RH	0.00	\$575.80	0.00	\$0.00	Replace	Check	X
	69410-33010	DOOR LOCK STRIKER	0.00	\$40.50	0.00	\$0.00	Replace	Check	X
	69210-74030	DOOR OUTER HANDLE FRT/RH	1.00	\$370.80	100.00	\$0.00	Replace	Repair	✓
	69205-47050	DOOR INNER HANDLE FRT/RH	0.00	\$84.70	0.00	\$0.00	Replace	Check	X
	85710-47120F	DOOR REGULATOR MOTOR FRONT RH	0.00	\$947.80	0.00	\$0.00	Replace	Check	X
	69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Check	X
	67861-47030	DOOR WEATHER STRIP FRT/RH	0.00	\$171.20	0.00	\$0.00	Replace	Check	X
	75851-47900	MOULDING BODY, RH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	✓
	61311-47030	PILLAR, CTR BODY	0.00	\$307.70	0.00	\$0.00	Replace	Check	X
	67003-47080	DOOR RR/RH	1.00	\$954.50	25.00	\$715.88	Replace	Replace	✓
		PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓
	68750-20121	DOOR HINGE UPPER RR/RH	0.00	\$81.70	0.00	\$0.00	Replace	Check	X
	68740-12120	DOOR HINGE LOWER RR/RH	0.00	\$90.10	0.00	\$0.00	Replace	Check	X
	68630-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Check	X
	5702812020	MEMBER SUB-ASSY, FR LH	0.00	\$810.70	0.00	\$0.00	Replace	Check	X
Total				\$35,992.51		\$5,704.31			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		16400-37230	RADIATOR ASSY	1.00	\$1,496.90	25.00	\$1,122.68	Replace	Replace
		53294-47030	DEFLECTOR, RADIATOR LH	1.00	\$77.00	25.00	\$57.75	Replace	Replace
6505786		G9010-47031	RADIATOR ASSY, UPPER	1.00	\$679.60	25.00	\$509.70	Replace	Replace
		57104-47020	RADIATOR LOWER SUPPORT	1.00	\$876.30	25.00	\$657.23	Replace	Replace
		16711-37040	FAN SHROUD	1.00	\$244.50	25.00	\$183.38	Replace	Replace
		88460-47150	A/C CONDENSER	1.00	\$1,181.90	25.00	\$886.43	Replace	Replace
Total					4,556.20		3,417.17		

13,662.04

9121.48
 - 202

4/5 \$10,350/-

7297.18
 + 1200.00
 + 1870.00

 10,367.18





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/02/2019

User ID : ZhiYangPhua

Registration Number	SHD612BK
Case Reference Number	TAX/02/19/2061
Registration Date	6/11/2015
Company Type	SMRT Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	GANDARUBAN
Type of Accident	Side Swipe
Accident Date and Time	13/2/2019 8 20 PM
Accident Reported Date and Time	15/2/2019 3 32 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100145
Special Instruction to ARC, if any	TP/TOWED TP COMPOUND /AIG - LJK
Prepared Date and Time	25/2/2019 3 43 PM
Chassis Number	
Message	
Work Shop	
Repair Completion Date and Time	



	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,197.00	\$1,200.00
Total Spray Cost	\$4,086.00	\$1,400.00
Total Spare Part Cost	\$22,941.18	\$6,704.28
Total Other Cost	\$2,236.00	\$470.00
TOTAL COST	\$31,460.18	\$8,774.28
Lump Sum Total	\$31,460.00	\$8,700.00
Number of Repair Days	16.0	6.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie
ARC / Surveyor Sign Off Date	28/02/2019 8:41 AM	27/02/2019 3:48 PM
Signature		
Remarks		L/S REPAIR, PHOTO AFTER REPAIR

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757708
FAX Number : 63685592
Estimator Telephone Number : 68662923
Accident Reporting Number : 68662972

Date Generated : 28/02/2019
User ID : ZHYangPhua

Section D - Details of Repair Estimate			Quantity	Unit Price	Total Price	Estimate	Actual			
TO REPAIR RH PORTION			\$845.00		\$400.00					
TO REPAIR FRONT LH PORTION			\$1,352.00		\$800.00					
Total Labour			\$2,197.00		\$1,200.00					
TO REPSRAY FRONT BUMPER			\$378.00		\$200.00					
TO REPSRAY FRONT HOOD			\$378.00		\$200.00					
TO REPSRAY APRON PANEL LH			\$180.00		\$0.00					
TO REPSRAY FRONT DOOR LH			\$378.00		\$0.00					
TO REPSRAY FRONT DOOR RH			\$378.00		\$200.00					
TO REPSRAY FRONT FENDER LH			\$378.00		\$200.00					
TO REPSRAY FRONT FENDER RH			\$378.00		\$200.00					
TO REPSRAY FRONT SUPPORT PANEL			\$180.00		\$0.00					
TO REPSRAY FRT MEMBER LH			\$180.00		\$0.00					
TO REPSRAY RADIATOR SUPPORT LOWER			\$180.00		\$0.00					
TO REPSRAY RH REAR DOOR			\$378.00		\$200.00					
TO REPSRAY RIM			\$360.00		\$100.00					
TO REPSRAY ROCKER PANEL MOULDING			\$180.00		\$100.00					
TO SPRAY FRONT BUMPER LOWER SUB GRILLE			\$180.00		\$0.00					
Total Spray Painting & Panel Beating			\$4,086.00		\$1,400.00					
TO ALIGN CHASSIS			\$350.00		\$0.00					
TO APPLY RUST-PROOFING ON AFFECTED AREA			\$200.00		\$50.00					
TO CHECK & RESET SYSTEM FUNCTION			\$350.00		\$100.00					
TO CHECK WIRING AND SYSTEM FUNCTION			\$80.00		\$20.00					
TO DO WHEEL ALIGNMENT / TYRE BALANCING			\$120.00		\$60.00					
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)			\$240.00		\$50.00					
TO REMOVE AND REFIT WIRE HARDESS			\$250.00		\$0.00					
TO REPLACE SUNDRY PARTS			\$100.00		\$0.00					
TO TOP UP A/C GAS			\$120.00		\$0.00					
TO TRANSFER DOOR MECHANISM			\$240.00		\$100.00					
TO WASH AND VACUUM			\$80.00		\$0.00					
TOWING CHARGE			\$126.00		\$90.00					
Total Other Costs			\$2,236.00		\$470.00					
Part Number	Portion	Stock Number	Part Name	Quantity	Unit Price	Estimate (Net)	Estimate (Gross)	Estimate (Tax)	Actual	
		81521-47080	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00		Replace	Not Given
		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00		Replace	Check
		53301-47080	HOOD PANEL	1.00	\$746.10	25.00	\$561.08		Replace	Replace
		57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00		Replace	Check
		81130-47500	HEAD LAMP RH	0.00	\$945.20	0.00	\$0.00		Replace	Check
		86780-22131	THERMISTOR ASSY	0.00	\$107.00	0.00	\$0.00		Replace	Not Given
		68630-47031	CHECK ASSY, RR DOOR	0.00	\$150.30	0.00	\$0.00		Replace	Check

W h x
 x AMI
 DEF ✓
 x AMI
 x AMI
 W h x
 x AMI



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63985542
Estimator Telephone Number : 68962623
Accident Reporting Number : 68962672

Date Generated : 28/02/2018

User ID : ZhYangPhua

Part No	Part Name	QTY	UNIT PRICE	AMOUNT	PAID	REMARKS	STATUS
08750-20121	DOOR HINGE UPPER R/R/RH	0.00	\$81.70	0.00	\$0.00	Replace	Check
53289-47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Check
	STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given
42611-47140 (FR)	WHEEL DISC. FRONT	1.00	\$1,464.20	100.00	\$0.00	Replace	Repair
67003-47080	DOOR R/R/RH	1.00	\$954.50	25.00	\$715.88	Replace	Replace
55708-47101	WIPER GARMISH	0.00	\$814.00	0.00	\$0.00	Replace	Check
81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check
86460-47150	A/C CONDENSER	0.00	\$1,181.80	0.00	\$0.00	Replace	Check
87881-47030	DOOR WEATHER STRIP FRT/RH	0.00	\$171.20	0.00	\$0.00	Replace	Check
81529-47060	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check
52119-47830	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Check
	COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Check
82663-47060	FUSE BLOCK, COVER LOWER	0.00	\$18.50	0.00	\$0.00	Replace	Check
G9225-47021	HOSE, INVERTER NO 1	0.00	\$60.00	0.00	\$0.00	Replace	Check
Total				\$35,992.51		\$4,704.28	

X NAI
X NAI
X NAI
X R
BUL ✓
X NAI
X NAI
X NAI
X NAI
X NAI
DEP ✓
X NN
X NN
X NN
X NAI

Part No	Part Name	QTY	UNIT PRICE	AMOUNT	PAID	REMARKS	STATUS
Total							

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TRX / 02 / 19 / 2081	Date of Collection	28 / 2 / 19
Vehicle No	SHD 6128K	Date of Request	5 / 3 / 19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	2 / 3 DAYS

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	7625, 26, 27	Radiator Assy		\$1496.90
2	7630, 31	Deflector Radiator LH		\$77.00
3	7622, 23, 24	Radiator Assy Upper		\$679.60
4	7619, 20, 21	Radiator Lower Support		\$876.30
5	7632, 33, 34	Fan Shroud		\$244.50
6	7628, 24	A/C Condenser		\$1181.90
7				
8				

BT \$172.68
 CRA \$57.75
 BT \$509.70
 BT \$657.23
 CRA \$183.5
 DD \$886.43

<<<Please submit photographs for damaged parts>>>

13/3/19

I. (Name) CHIA
 (Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA ..	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff