

Ah Tee Motor Pte Ltd 3 Pioneer Road North,

1-18,

28457

Claim Reference:

Assessment number: SGV4139J- OD AXA

Version: 1810

Date calculated: 02/28/2019 11:20 AM

Full Report

Registration: SGV4139J - OD AXA

Printed: 28/02/2019 11:21 AM

Material Cost - Paint

New Part Painting	108.37
New Part Painting - Plastic K1R	55.60
Surface-/Blend Paint	16.43
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	218.00

Price SGD
108.37
55.60
16.43
28.60
9.00
218.00

Spare Parts

prices as at 2015-06-01

Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	Part <i>Part</i>		0.00
0283	FRONT BUMPER COVER	6400A143WA	CRA	400.00
0350	FRT BUMPER MNTG KIT	MR288150	<i>Ne</i>	20.00
0471	BONNET	5900A138	CRA	320.00
0475	LEFT BONNET HINGE	MN126933	X	32.00
0476	RIGHT BONNET HINGE	MN126934	X	32.00
0493	BONNET LOCK	MN181406	<i>Part</i>	28.00
0575	L/F HEADLAMP	MN169787	CRA	280.00
0576	R/F HEADLAMP	MN169788	CRA	280.00
0741	L/F WING	MN150623	<i>True</i>	260.00
0742	R/F WING	MN150624	<i>True</i>	260.00
0841	L/F SPLASH PANEL	MN161707	?	65.00
0842	R/F SPLASH PANEL	MN161708	?	65.00
0009	FRONT PANEL CPL	MN150613	<i>Part</i>	280.00
0465	CONDENSER	MN151100		0.00
0761	RADIATOR	MR497745	<i>Part</i>	400.00
0767	RADIATOR SHROUD	MR497769	?	80.00
0769	L/UPP RADIATOR BRKT	MR450244	?	10.00
0770	R/UPP RADIATOR BRKT	MR450244	?	10.00
0787	EXPANSION TANK	MR450237	X	45.00
0798	R/FAN MOTOR	MR312898	X	130.00
0388	AIR INTAKE MANIFOLD	MR497518	X	65.00
0000	L/R BUMPER SIDE	RETAINER	<i>Ne</i>	26.00
0001	R/F BUMPER SIDE	RETAINER	<i>Ne</i>	26.00
0002	L/F BUMPER	BRACKET	<i>Ne</i>	15.00
0003	R/F BUMPER	BRACKET	<i>Ne</i>	15.00
0004	L/F HEADLAMP	CLIP	<i>Ne</i>	3.00
0005	R/F HEADLAMP	CLIP	<i>Ne</i>	3.00
0006	AIR DUCT	CLIPS(2PCS)	<i>Ne</i>	5.00
0007	RADIATOR FAN	COWLING	?	40.00

OEM Parts
Non-OEM Parts
Used parts

Savings

0.00

Ah Tee Motor Pte Ltd
Unit 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
 Assessment number: SGV4139J- OD AXA
 Version: 1810
 Date calculated: 02/28/2019 11:20 AM

Full Report
 Registration: SGV4139J - OD AXA
 Printed: 28/02/2019 11:21 AM

Subtotal	3,195.00
Addition(+10.00%)	319.50
Total	3,514.50

Extras Code	Description	Price SGD
1008	COOLANT COOLANT <i>new ✓</i>	40.00*
1009	FRT NUMBER PLATE <i>SA ✓</i>	35.00*
Total Extras		75.00

Final Calculation

	SGD	SGD
Parts	3,195.00	
Addition(+10.00%)	319.50	
Total Parts		3,514.50
Labour Time Base 10 WU/h		
Total 121.0 WU X 45.00 SGD/h	544.50	
Total of Labour		544.50
Total Of Extras		75.00
Paint Work Time Base 10 WU/h		
Labour Cost 91.0 WU X 45.00 SGD/h	409.50	
Material Cost	218.00	
Total Paint Including Material		627.50
Repair Cost Excludes GST		4,761.50
GST (+7.0%)		333.31
Repair Cost Included GST		5,094.81

Ng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:

Assessment number: SGV4139J- OD AXA

Version: 1810

Date calculated: 02/28/2019 11:20 AM

Full Report

Registration: SGV4139J - OD AXA

Printed: 28/02/2019 11:21 AM

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CASUAL

H/ 90010068

8 days

P/P

01/03/19 @ 1450

EXCESS: 500

REVERT

Resurvey before paint