

TPALG
Xiao Tony
Tony

Subject: SGN4623U

Date:

Hyundai Elantra.

KMH D841CMJU729023

\$

Rees Bumper	2x	559.40	✓	
Rees Bumper Lips	~	30	✓	
Rees Bumper Side Holder	x 2	38 x 2 = 76	x	
Rees Bumper lower Garnish	cut	272.60	✓	
Rees Bumper Reinforcement	cut	328	✓	
Reverse Sensor	2 days	280 (sent) 200 (SN)		
Bootlid	} NIP NEE	1602	x	
Bootlid Lock		105	x	
Hyundai Logo		1150	36	x
Elantra Wording		952	38.50	x
Elite Emblem		S.N: 200	38	x

Panel Bending	400	200
Spray Painting	600	200
Wiring	50	30
To remove reverse sensor	400	50

480

total: 1632
L/S: 1.3K
02 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: