

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GZ4411B
 TP/AG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

Estimate No: ES1991396/YISHUN
 Date: 15 Apr 2019
 Policy No: 5093697589-01
 Veh Reg No: GZ4411B
 Make/Model: NISSAN CABSTAR G
 Chassis No: JN1SF4F23Z0861256
 Engine No: QD32224606
 Reg. Date: 18/04/2006

TEL: 64193000 FAX: 64153727

ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 18/02/2019

TP Veh Reg No: SLR1566R

Not Authorized
11 Reg 87
Resurvey After Paint

4 days

Estimate Repair Cost to Vehicle No :GZ4411B

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 TAILLAMPS	248.60	2 PCS	497.20	497.20
		Less 10%	49.72	447.48
Special Net				
2 REAR NUMBER PLATE	18.00	1 PC	18.00	18.00
3 REVERSE SENSOR	200.00	1 SET	200.00	200.00
			218.00	218.00
Labour				
4 REMOVE & REFIX REAR NUMBER PLATE, TAILLAMPS, STRAIGHTEN, KNOCK & REPAIR REAR END PANEL, TAILLAMP PANELS, REAR NUMBER PLATE PANEL, REAR LH CORNAL PANEL & REALIGN THE SAME	500.00	1 LA	500.00	400
5 REMOVE & REFIX TAILGATE ASSY, KNOCK & REPAIR REAR BOTH TAILGATE & REALIGN THE SAME	580.00	1 LA	580.00	450
6 PUTTY & RESPRAY PAINT	200.00	1 LA	200.00	150
			1,280.00	1,280.00
Total				SS 1,945.48
Add GST @ 7%				136.18
Total Amount Payable				SS 2,081.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE