



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 3225U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	912.00	-
1	REAR RETAINER	NOT NECESSARY	79.00	-
			991.00	-
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	CLIPS / RETAINERS (SN)	NOT NECESSARY	25.00	-
			25.00	-
	<b><u>LABOUR</u></b>			
	DISMANTLE / ASSEMBLY OF BUMPER. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		200.00	150.00
	SPRAY PAINTING OF REAR BUMPER (PEARL WHITE).		260.00	200.00
			460.00	350.00
	<b>GRAND TOTAL</b>		<b>1,476.00</b>	<b>350.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>350.00</b>

Report Ref No. CC4/EQI19003862/Gha3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.