

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email:ben@allswellmotor.com.sg

(3rd party claim against EQ Insured SGM1773U)

Estimate repair

Vehicle No. : SLG3225U
Make & Model : AXIO hybrid
Chassis No. : 1.5G CVT

Submitted by :
COE expiry :
Engine No. :

Ben
26-09-2026

Date of survey : _____

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01.	Rear bumper X Repair.	01	\$912.00		
02	RH retainers X NN	01	\$79.00		
01	Special net Chips / retainers X NN \$25 / pct.	01	\$25.00		
01	Labour Description Dismantle / Assembly of bumper	01	\$200.00	150	
02	Spray painting of rear bumper (Pearl white)	01	\$260.00	200	
			\$1,476.00	350	
	2 Days. put by pct. After the paint photos Gma Corp 11/3/19				
<div> <div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company </div> <div> <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div> </div>					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.