



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKL8885S

EQ INSURANCE COMPANY LIMITED

MOTOR CLAIM DEPARTMENT
5 MAXWELL ROAD #17-00
TOWER BLOCK, MND COMPLEX
SINGAPORE 069110
62239433

Vehicle & Document Information

WIP No **31206**
Reg No/Reg Date **SKL8885S / 17/07/2013**
Date In/Mileage **/ 0**
Chassis No **WDD2120342A818885**
Engine No **27492030071509**
Make/Model **MB/E 200 2.0 CGI SEDAN (W212)**
Colour/Trim **028 890 Cavansit B1/ 042 258 Basalt Grey**

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|--------|-------------------|-----|-------------------|
| WE000058 | Credit | 27/02/2019/ 18:33 | CH | 371 / Go Chee Han |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|--|------|------------|-------|-------------|
| Z REQUEST | | | | |
| Customer Request | | | | |
| M BPNSUN | | | | |
| POLICY NO/ACC DATE : D18MTPV01012170 // 25-2-2019 | | | | |
| DRIVE IN/TP VEH : 25-2-2019 // SJJ4810G - EQ | | | | |
| DATE IN/DATE SURVEY: | | | | |
| BY/AUTHORIZED ON : | | | | |
| A BPILAB | | | | 960 1200.00 |
| DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. | | | | |
| A BPIRES | | | | 600 720.00 |
| RESPRAY REAR BUMPER | | | | |
| A BPILAB | | | 0.10 | 380.00 |
| USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT | | | | |
| A BPILAB | | | | 120.00 |
| CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT | | | | |
| M REAR TRIM BUMPER | 1.00 | 1663.18 | 00.00 | 1663.18 |
| M REAR BOTTOM TRIM BUMPER | 1.00 | 234.98 | 00.00 | 234.98 |
| M LH/BUMPER CHROME MOULDING | 1.00 | 132.65 | 00.00 | 132.65 |
| M RH/BUMPER CHROME MOULDING | 1.00 | 132.65 | 00.00 | 132.65 |
| M DISTANCE SENSOR | 2.00 | 177.22 | 00.00 | 354.44 |
| M SPACER RING | 2.00 | 6.42 | 00.00 | 12.84 |

ESTIMATE

RASUL
Hp 90010068
3 days
08/03/19 @1420
Respray before paint

Confirmed & accepted by

7% GST on **Nett 4,950.74** **8,950.74**
346.55

Total Payable 5,297.29

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg