

15/02/2019

INS. CASE OWNER:

CC6 /EQI1900

LKK:

IDAC:

Surveyor:

marcus

DOI:

ASSIGNMENT

1/2/19

Date / Time:

1/2/18

Registered in Merimen:

Pre-assign / CCU / FTE

1/2 28900



Insured Vehicle No.:

Name of Insured:

LSP Tekbing

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

27/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: sim n hurng hart

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

 impn018-00xx70.
 MITSUBISHI
 271 NBI AVE 1 CP.

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SYG 57190


 INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:

 1st
 Auto

 INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:

 INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:

 INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:

Date/ Time

1/3/2019

 SYG 57190 - 0 4/28900 - 8
 file review, collided into parked vehicle 100% send
 letter to OI.
 pending finalize 602.

 PIC call in and mention received letter, informed TP claim
 and they agree to settle and waive Feb issue.

 3/10 - file pass RT type report.
 6/12 - pending mandate approval
 12/12 - offer to settle @ \$18,239.01. (pending acceptance)
 2/12 - settle @ \$18,239.01. NO DV required. file
 pass (h) to close.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 11/3/2019

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

marcus

PRELIMINARY ADVICE

Date/Time:

4/5/2019

Sent By:

LSP

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

R/R

SS 16,745.80

(5

days) Reduction:

\$6271.90 % 28

Email

Call

FINAL SETTLEMENT

Date/Time:

2/1/2019

Confirm with:

Kongie

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(w/57)

SS 17,383.00

(8

days)

x \$107

Loss of Rental (LOR):

SS

856.00

(5

x days)

Loss of Use (LOU):

SS

-

(5

x days)

Loss of Income (LOI):

SS

-

(5

x days)

LOR only

LOU only

LOR + LOU

LOR + LO

LOR + LO

[Tick only one]

GIA/LTA Search

SS

-

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow / Independent)

Legal Cost

SS

-

Total:

SS

18,239.01

Global Sum SS:

FINAL PAYMENT

Date/Time:

2/1/2019

Confirm with:

Kongie

Email

Call

Payee 1:

SS

18,239.01

Name 1:

1st Autoworks Pte Ltd

Payee 2: (Strike if N.A.)

SS

-

Name 2:

1st

Payee 3: (Strike if N.A.)

SS

-

Name 3:

1st

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP \$400/-

 COPY SENT
 2/1/2019

(08/11/13) wof

ASS REC. BY: *marcus*

REF:

EQ

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

181

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

L7A56666

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

net 23334

P/P \$16,245.80 / -

(Red = \$6271.90 / 28.1.)

* 5 repair days + 1 Sunday + 2 pks = 8 days.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS, \$

) Photos

) Others

TOTAL

Veh No:

SJY521PD

Yr Regn:

6.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

OPEL ASTRA

c.c

1399

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp.Reading

33752

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WOLBE8ECXH8065805

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225 / 45 R 17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front:

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

27/1/19

D.O.I.

1/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R.

The U/C / Chassis frame / Body Structure affected due to collision.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (665) 62563561 FAX : (665) 62564315

Your ref: To Be Advised
Our ref: CC6/EQ119003864/Ufb3

Date: 04.03.2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJY5219D

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.03.2019 at the premises of M/s 1st Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	22,517.70
Revised Estimate Amount	: S\$	11,049.20
"Check" Items Amount	: S\$	2,981.70
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

FIRST AUTOWORKS

Repair Estimate

Date : 01/03/2019

To Whom It May Concern

Dear Sir,

RE: VEHICLE :: SJY 5219D

CHASSIS NO.: W0LBE8ECXH8065865

ENGINE NO.: B1170537JCVX0503

Name of insured :: Chan Yook Leng Caroline

Date of accident.: 27/02/2019

Reference:

Make: OPEL
ASTRA

not Alford
new
tel. 62583581
1/2 \$16245-80
5.2
1/3/19

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER	2,100.00
2	1	FRT BUMPER TOW COVER	130.00
3	1	FRT BUMPER LOW LIP RH	156.00
4	1	FRT BUMPER LOW LIP LH	156.00
5	15	FRT BUMPER CLIP SET	90.00
6	1	FRT BUMPER SIDE RETAINER LH - GUIDE	130.00
7	1	FRT BUMPER SIDE RETAINER LH - UPP	110.00
8	1	FRT BUMPER SIDE RETAINER RH - GUIDE	130.00
9	1	FRT BUMPER SIDE RETAINER RH - UPP	110.00
10	1	FRT BUMPER BRACKET LH	80.00
11	1	FRT BUMPER BRACKET RH	80.00
12	1	FRT BUMPER UNDER DUST COVER	220.00
13	1	FRT BUMPER BRACKET TOP CENTRE	180.00
14	1	FRT BRACE BRACKET CENTRE	229.00
15	1	FRT BRACE BRACKET RH	118.00
16	1	FRT BRACE BRACKET LH	118.00
17	1	FRT BUMPER SPONGE	190.00
18	1	FRT BUMPER REINFORCEMENT UPP (metal)	800.00
19	1	FRT BUMPER REINFORCEMENT LOW (firbe)	260.00
20	1	FRT BUMPER PARKING SENSOR SET	250.00
21	1	FRT BUMPER PARKING SENSOR SEAL SET	30.00
22	1	FRT BUMPER PARKING SENSOR WIRE HARNESS	400.00
23	1	FRT ENGINE DUST COVER RH	124.00
24	1	FRT ENGINE DUST COVER LH	124.00
25	1	FRT GRILLE ASSY	560.00
26	1	FRT GRILLE BASE	150.00
27	1	FRT GRILLE CHROME MOLDING RH	180.00
28	1	FRT GRILLE CHROME MOLDING LH	180.00
29	1	FRT GRILLE LOGO	160.00
30	1	FRT LOW CENTRE GRILLE	180.00
31	1	FRT LOW GRILLE LH	90.00
32	1	FRT LOW GRILLE RH	90.00
33	1	RH HEADLAMP(ilux)	3,500.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

<u>34</u>	1	LED CONTROL UNIT	1,300.00	?
<u>35</u>	1	LH HEADLAMP(ilux)	3,500.00	X
<u>36</u>	1	LH FOG LAMP	434.00	X
<u>37</u>	1	LH FOG LAMP COVER	120.00	X
<u>38</u>	1	RH FOG LAMP	434.00	—
<u>39</u>	1	RH FOG LAMP COVER	120.00	—
<u>40</u>	1	FENDER INNERSHIELD CLIP	8.00	✓
<u>41</u>	1	FRT FENDER RH	682.00	X
<u>42</u>	1	FRT FENDER INNERSHIELD RH	150.00	—

Lat Number plate Barfice 40

Parts Total: 18,153.00
Less 10%: 1,815.30
Total: 16,337.70

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. 650	3500.00 1950
2	Carry out spray painting on accident affected area. (frt Rh fender & Frt bumper other affected area) 510	2200.00 1800
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	160.00 50
4	To conduct 4 wheel alignment	160.00 X
5	To conduct head alignment	100.00 X
Labour Total :		6,120.00

Other

No.	Qty	Other Description	Price (SGD)
1	1	Tow Service	60.00 ✓
Other Total :			60.00

Total : \$22,517.70
Gst (7%) : \$1,576.24
GRAND TOTAL: \$24,093.94

25802-10A

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, Y WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Ronnie Tan
DID: 6844 1985 Fax: 6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey vehicle after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claims are on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

FIRST AUTOWORKS

Date: 15/4/2019

From: Firstautoworks Pte Ltd

Dear Sirs

RE: VEHICLE NO: SJY 5219D

CHASIS NO: W0LBE8ECXH8065865

Supplementary Items

Further to our estimate dated 01.03.2019, we append hereunder the additional Parts & labour required in respect of the repair as carried to the above vehicle for your kind attention.

Parts

<u>No.</u>	<u>Qty</u>	<u>Description</u>	<u>Amount</u>
1	1	AIR CON CONDENSER AIR GUIDE RH <i>Torn</i>	134.00 ✓
2	1	FRT RADIATOR <i>Widercore</i>	1424.00 ✓
3	1	FRT BONNET <i>Buc / Surf</i>	1758.00 ✓

Total: **3316.00**

Total: 3316.00


Less 10%: 331.60

7 % GST: 208.91

Grand Total: **3193.31**

This is only an estimate and should additional work be found necessary to be carried out in the course of repairs, extra materials and labour cost will be charged accordingly. You will be informed prior actions to be taken. **Parts prices are subjected to change.**

Yours faithfully



Service Advisor

Ronnie Tan

DID : 6844 1985 Fax: 68445185

CC :

Fax:

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

FIRST AUTOWORKS

Repair Estimate

Date : 01/03/2019

Reference:

To Whom It May Concern

Make: OPEL
ASTRA

Dear Sir,

RE: VEHICLE.: SJY 5219D
CHASSIS NO.: W0LBE8ECXH8065865
ENGINE NO.: B1170537JCVX0503

Name of insured.: Chan Yook Leng Caroline

Date of accident.: 27/02/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER	2,100.00
2	1	FRT BUMPER TOW COVER	130.00
3	1	FRT BUMPER LOW LIP RH	156.00
4	1	FRT BUMPER LOW LIP LH	156.00
5	15	FRT BUMPER CLIP SET	90.00
6	1	FRT BUMPER SIDE RETAINER LH - GUIDE	130.00
7	1	FRT BUMPER SIDE RETAINER LH - UPP	110.00
8	1	FRT BUMPER SIDE RETAINER RH - GUIDE	130.00
9	1	FRT BUMPER SIDE RETAINER RH - UPP	110.00
10	1	FRT BUMPER BRACKET LH	80.00
11	1	FRT BUMPER BRACKET RH	80.00
12	1	FRT BUMPER UNDER DUST COVER	220.00
13	1	FRT BUMPER BRACKET TOP CENTRE	180.00
14	1	FRT BRACE BRACKET CENTRE	229.00
15	1	FRT BRACE BRACKET RH	118.00
16	1	FRT BRACE BRACKET LH	118.00
17	1	FRT BUMPER SPONGE	190.00
18	1	FRT BUMPER REINFORCEMENT UPP (metal)	800.00
19	1	FRT BUMPER REINFORCEMENT LOW (firbe)	260.00
20	1	FRT BUMPER PARKING SENSOR SET	250.00
21	1	FRT BUMPER PARKING SENSOR SEAL SET	30.00
22	1	FRT BUMPER PARKING SENSOR WIRE HARNESS	400.00
23	1	FRT ENGINE DUST COVER RH	124.00
24	1	FRT ENGINE DUST COVER LH	124.00
25	1	FRT GRILLE ASSY	560.00
26	1	FRT GRILLE BASE	150.00
27	1	FRT GRILLE CHROME MOLDING RH	180.00
28	1	FRT GRILLE CHROME MOLDING LH	180.00
29	1	FRT GRILLE LOGO	160.00
30	1	FRT LOW CENTRE GRILLE	180.00
31	1	FRT LOW GRILLE LH	90.00
32	1	FRT LOW GRILLE RH	90.00
33	1	RH HEADLAMP(ilux)	3,500.00

not Afford
near
Tel: 62583581
P/P \$
527.
1/3/19

<u>34</u>	1	LED CONTROL UNIT	1,300.00	?
<u>35</u>	1	LH HEADLAMP(ilux)	3,500.00	X
<u>36</u>	1	LH FOG LAMP	434.00	X
<u>37</u>	1	LH FOG LAMP COVER	120.00	X
<u>38</u>	1	RH FOG LAMP	434.00	—
<u>39</u>	1	RH FOG LAMP COVER	120.00	—
<u>40</u>	1	FENDER INNERSHIELD CLIP	8.00	✓
<u>41</u>	1	FRT FENDER RH	682.00	X
<u>42</u>	1	FRT FENDER INNERSHIELD RH	150.00	✓

Parts Total: 18,153.00

Less 10%: 1,815.30

Total : 16,337.70

*Left number plate Bar/era 40
Bent. Bar/era
fit grille top car*

Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. <i>650</i>	3500.00 <i>1850</i>
2	Carry out spray painting on accident affected area. (frt Rh fender & Frt bumper other affected area) <i>510</i>	2200.00 <i>1800</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	160.00 <i>50</i>
4	To conduct 4 wheel alignment <i>11</i>	160.00 X
5	To conduct head alignment <i>11</i>	100.00 X

Labour Total : 6,120.00

Other

<u>No.</u>	<u>Qty</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	1	Tow Service	60.00 ✓

Other Total : 60.00

Total : \$22,517.70

Gst (7%) : \$1,576.24

GRAND TOTAL: \$24,093.94

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, Y WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Ronnie Tan

DID: 6844 1985 Fax: 6844 5185

LKK Auto Consultants hereby notify the Repairs of the following:

- To repair and/or spray painting
- To disassemble and/or parts during survey
- Parts or materials subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary claim must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4179E
Vehicle Details	
Vehicle No.:	SJY5219D
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Mar 2019
Vehicle Make:	OPEL
Vehicle Model:	ASTRA ST 1.4 AT (LED)
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	B1170537JCVX0503
Chassis No.:	WOLBE8ECXH8065865
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$23,630.00
Original Registration Date:	21 Jun 2017
First Registration Date:	21 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$20,082.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jun 2027
PARF Rebate Amount:	\$15,061.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jun 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$50,526.00
COE Rebate Amount:	\$41,605.00
Total Rebate Amount:	\$56,666.00

The information contained herein is correct as at 01 Mar 2019

OK

Letter of Authorisation & Indemnity

Accident Involving Vehicle no. SJY 5219D and YP 2890D On 27/2/2019.

At CAR PARK UBI AVE 1 LOT 413

1. I/We, the owner of vehicle no. SJY 5219D hereby instruct and authorize 1ST AUTO WORKS PTE LTD ("the workshop") to commence repairs to the said vehicle. Pending the outcome of my/our claim against the third party, I/we forthwith pay you the sum of \$_____ being refundable deposit of the repair to my/our said vehicle.
2. You are further authorized to appoint solicitors on my/our behalf and give the solicitors full instructions as if the appointment is made and instructions are given by me/us with respect to the conduct of my/our claim against the third party driver and/or his insurers including if necessary, to commence legal proceedings in court in my/our name against the third party.
3. You have my/our full authority to instruct my/our solicitors to negotiate a settlement with the third party and/or his insurers on such terms as you deem fit.
4. Upon resolving my/our claim, you are authorized to agree with my/our solicitors on the amount of their professional costs and disbursement for acting for me/us and to receive payment of the balance of the settlement sum on my/our behalf directly into your account. In the event that my/our claim or legal costs of the third party as well as the professional costs and disbursements of my/our solicitors notwithstanding that my/our solicitors were appointed by you on our behalf.
5. I/we also hereby instruct and authorise you deduct directly from the claim monies received from the third party all outstanding balances that are still owing to you, namely the balance of repair costs and rental of substitute vehicles.
6. In the event that I/we am/are required to attend at my/our solicitors office or to attend court in connection with my/our claim, I/we shall render full co-operation.
7. In the event that my/our claim against the third party and/or his insurers is not successful or cannot be proceeded with and/or if any Judgement or settlement is not honoured or satisfied by the third party, I/we authorise you to revert the claim against my/our own insurers for the cost of repairs and any other losses recoverable under my/our policy of insurance. In this respect, I/we understand and accept that the excess amount applicable under policy of insurance shall be borne by me/us.
8. If for whatever reasons, my/our insurers reject my/our claim for indemnity for the cost of repairs and/or any other losses recoverable under the policy of insurance or make an offer to pay less than the amount claimed by you, I/we agree and undertake to pay the full amount of your repair bill and survey fees and any other expenses reasonably incurred on my/our behalf or to pay you the difference in amount, as the case may be.
9. I/we shall keep you informed of any correspondences and/or summons that I may receive due to this action agreeing to pay or receive any monies due to this claim.

Dated this _____ day of _____ 20__

Signature of vehicle owner



Name - CHAN YOOK LENG CAROLINE

IC No : S 1104179E

(Company stamp, if applicable)

Address : BLK 331 UBI AVE 1

(S) 400131

Tel : 9121239

Witnessed by :

[Signature]

CHEAPEST CAR
INSURANCE RENEWAL



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!



Submit

Advanced
Search

Home » Used Cars » SG Car Consign Pte Ltd » Opel Astra 1.4A

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Rental

For Private &
Commercial Vehicles
Rental From
\$50/Day



① X

**Study
Abroad after
O/A/IB**

For Aust, NZ,
Swiss & UK Unis,
Uni Pathways &
Schs. Meet
@Suntec L3 Hall
331-2. Sun 3 Mar

OverseasEducation.sg/

Compare

Opel Astra 1.4A

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$80,900**

Depreciation \$8,830 /yr

View models with similar depreciation

Reg Date 08-Jun-2017

(8yrs 3mths 6days COE left)

Manufactured 2017

Mileage 43,000 km (24.9k /yr)

Transmission Auto

Engine Cap 1,399 cc

Road Tax \$626 /yr

Power 110.0 kW (147 bhp)
View specs of the Opel Astra (2016)

Curb Weight 1,233 kg

Features White Color,

Accessories As Per Factory Fittings.

Description Look No Further! Genuine Mileage With 1 Owner! Best Value For Your Money. Direct Owner's Beautiful White, Jun'2017 Opel Astra HB 1.4 AT(LED) With Grey Leather Upholstery. Selling Due To Upgrading To New Car. Low Fuel Consumption, Low Maintenance. Original Paintwork Condition And Well Kept. Trade In And Up To 80% Loan Available. Why Wait? No Obligation! Don't Miss, Must To Arrange For Viewing!

COE \$53,300

OMV \$20,500

ARF \$15,700

Dereg Value \$55,875 as of today (change)

No. of Owners 1

Type of Veh Hatchback

Category PARF Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 02-Feb-2019 | Last Updated on: 26-Feb-2019

Tags: Opel Astra, opel astra, 2017 Opel Astra, 2017 opel astra, Opel, Astra, astra, Used Opel

Upfront Payment

» more Financial Info



Seller Information

Company	SG Car Consign Pte Ltd » dealer's pricelist » 40 vehs sold 51 vehs available	
Address	170 Upper Bukit Timah Road #01-28 Search cars nearby this location	
Location	Bukit Timah Shopping Centre	
Office No	61000200	
Contact Person(s)	Andy Tay	94891030
	Danny Loh	97622873
	Eric Lim	94882822

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Shu Pei (LKKAUTO)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Tuesday, 5 March 2019 9:28 AM
To: Shu Pei (LKKAUTO)
Cc: Admin A; Poh Kin (LKKAUTO)
Subject: FW: Direct Settlement - Accident Involving YP2890D (OI : EQI - TBA) and SJY5219D (TP : LKK REF -CC6/EQI19003864/Ufb3) on 27.02.2019
Attachments: TP GIA REPORT.pdf; Preliminary_Advice.pdf; TP ESTIMATE- MARKED.pdf; SAS2562273.PDF

Dear Shu Pei

OI report as attached.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.


From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, March 4, 2019 7:15 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Poh Kin (LKKAUTO) <pohkin@lkkauto.com>
Subject: Direct Settlement - Accident Involving YP2890D (OI : EQI - TBA) and SJY5219D (TP : LKK REF - CC6/EQI19003864/Ufb3) on 27.02.2019

WITHOUT PREJUDICE

Dear Sir/ Madam,

We refer to the above matter.

We have inspected TP vehicle SJY 5219D at M/s 1st Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.



Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Poh Kin and he can be contacted at DID: 6841-2132.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Monday, 16 December 2019 3:37 PM
To: Janice Goh
Subject: YOUR REF: DMCPHQ18-007770 (OUR REF: CC6/EQI19003864/Ugb3s2) *** ACCIDENT INVOLVING YP 2890D & SJY 5219D ON 27/02/2019 ***
Attachments: ADJUSTMENT REPORT.pdf; INSPECTION REPORT.pdf; LKK RESURVEY PHOTO.pdf; LKK SURVEY PHOTO.pdf; LOD AND OTHER DOCUMENTS.pdf; PARF COE REBATE.pdf

EQ ref : **DMCPHQ18-007770**

LKK ref : CC6/EQI19003864/Ugb3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING YP 2890D(EQ-OI) AND SJY 5219D(TP) ON 27/02/2019

We refer to the above matter.

OI COLLIDED INTO PARKED VEHICLE.

A letter was sent out to the Insured to notify Third Party claim and NCD issues. No further feedback till to date.

We seek your approval to offer Third Party repairer "**FIRST AUTOWORKS PTE LTD**" at **18,239.01(all-in).**

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 25,502.10	\$ 17,383.01
2. Loss of Rental (10days x \$160.50) w/GST	\$ 1,605.00	\$ 856.00 (8days x \$107.00) w/GST
3. LTA/ GIA Search Fee	\$ -	\$ -
Total	\$ 27,107.10	<u>\$ 18,239.01</u>

**05days recommendation for repair + 1Sunday + 1Saturday + 1PRS = 8days

Market Value	: \$80,000.00 (est)
LTA Rebate	: <u>\$56,666.00 (est)</u>
Nett Value	: <u>\$23,334.00 (est)</u>

Enclosed here with all the relevant documents for your perusal.

Kindly let us have your approval/instruction.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,
Cecilia Chong | Case Handler

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Friday, 27 December 2019 3:21 PM
To: ronnie.tan@firstautoworks.com.sg
Cc: Suhaimi
Subject: RE: YOUR REF: SJY 5219D (OUR REF: CC6/EQI19003864/Ugb3s2) *** ACCIDENT INVOLVING YP 2590D & SJY 5219D ON 27/02/2019 ***

WITHOUT PREJUDICE

Dear Ronnie,

Thanks for your acceptance.

Please note that NO DV is required.

Thus, we shall proceed to submit and close off the case.

Thanks

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Ronnie Tan [mailto:ronnie.tan@firstautoworks.com.sg]

Sent: Friday, 27 December 2019 3:03 PM

To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

Cc: Suhaimi <suhaimi@firstautoworks.com.sg>

Subject: re: YOUR REF: SJY 5219D (OUR REF: CC6/EQI19003864/Ugb3s2) *** ACCIDENT INVOLVING YP 2590D & SJY 5219D ON 27/02/2019 ***

Hi Cecilia Chong

We are please to accept your offer at \$18 239.01

Accept Offer without Prejudice for any personal Injury claim

Thank You

Regard

Ronnie

From: "Cecilia Chong (LKK Auto)" <CeciliaChong@lkkauto.com>

Sent: Friday, 27 December, 2019 2:29 PM

To: "ronnie.tan@firstautoworks.com.sg" <ronnie.tan@firstautoworks.com.sg>

Subject: YOUR REF: SJY 5219D (OUR REF: CC6/EQI19003864/Ugb3s2) *** ACCIDENT INVOLVING YP 2590D & SJY 5219D ON 27/02/2019 ***

WITHOUT PREJUDICE

Dear Ronnie,

We are pleased to offer total amount of \$18,239.01 (all-in).

Kindly confirm acceptance.

Thanks

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQI19003864/Ugb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 09-01-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 2890D	Veh. Inspected	SJY 5219D
Policy No.	DMCPHQ18-007770	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	01/03/2019

2. Vehicle Particulars & Condition

Make & Model	OPEL ASTRA (A)	c.c	1399
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	W0LBE8ECXH8065865	Colour	GREY
Odometer	33752	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	DUNLOP	8 mm
L/H Front Tyre	225/45 R17	DUNLOP	8 mm
R/H Rear Tyre	225/45 R17	DUNLOP	8 mm
L/H Rear Tyre	225/45 R17	DUNLOP	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/02/2019	Inspection Date	01/03/2019
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 5219D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER	DISTORTED	2,100.00	2,100.00
1	FRT BUMPER TOW COVER	MISSING	130.00	130.00
1	FRT BUMPER LOW LIP RH	DISTORTED	156.00	156.00
1	FRT BUMPER OW LIP LH	NOT NECESSARY	156.00	-
15	FRT BUMPER CLIP SET	NECESSARY	90.00	90.00
1	FRT BUMPER SIDE RETAINER LH - GUIDE	NOT NECESSARY	130.00	-
1	FRT BUMPER SIDE RETAINER LH - UPP	NOT NECESSARY	110.00	-
1	FRT BUMPER SIDE RETAINER RH - GUIDE	BENT	130.00	130.00
1	FRT BUMPER SIDE RETAINER RH - UPP	BENT	110.00	110.00
1	FRT BUMPER BRACKET LH	NOT NECESSARY	80.00	-
1	FRT BUMPER BRACKET RH	MISSING	80.00	80.00
1	FRT BUMPER UNDER DUST COVER	TORN	220.00	220.00
1	FRT BUMPER BRACKET TOP CENTRE	BENT	180.00	180.00
1	FRT BRACE BRACKET CENTRE	NOT NECESSARY	229.00	-
1	FRT BRACE BRACKET RH	BENT	118.00	118.00
1	FRT BRACE BRACKET LH	NOT NECESSARY	118.00	-
1	FRT BUMPER SPONGE	TORN	190.00	190.00
1	FRT BUMPER REINFORCEMENT UPP (METAL)	NOT NECESSARY	800.00	-
1	FRT BUMPER REINFORCEMENT LOW (FIRBE)	CRACKED	260.00	260.00
1	SET FRT BUMPER PARKING SENSOR	SHORTED	250.00	250.00
1	SET FRT BUMPER PARKING SENSOR SEAL	NECESSARY	30.00	30.00
1	FRT BUMPER PARKING SENSOR WIRE HARNESS	NOT NECESSARY	400.00	-
1	FRT ENGINE DUST COVER RH	NOT NECESSARY	124.00	-
1	FRT ENGINE DUST COVER LH	NOT NECESSARY	124.00	-
1	FRT GRILLE ASSY	CRACKED	560.00	560.00
1	FRT GRILLE BASE	SCRATCHED	150.00	150.00
1	FRT GRILLE CHROME MOLDING RH	NOT NECESSARY	180.00	-
1	FRT GRILLE CHROME MOLDING LH	NOT NECESSARY	180.00	-
1	FRT GRILLE LOGO	NOT NECESSARY	160.00	-
1	FRT LOW CENTRE GRILLE	CRACKED	180.00	180.00
1	FRT LOW GRILLE LH	NOT NECESSARY	90.00	-

Report Ref No. CC6/EQI19003864/Ugb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT LOW GRILLE RH	NOT NECESSARY	90.00	-
1	RH HEADLAMP (ILUX)	BROKEN	3,500.00	3,500.00
1	LED CONTROL	SHORTED	1,300.00	1,300.00
1	LH HEADLAMP (ILUX)	NOT NECESSARY	3,500.00	-
1	LH FOG LAMP	NOT NECESSARY	434.00	-
1	LH FOG LAMP COVER	NOT NECESSARY	120.00	-
1	RH FOG LAMP	BROKEN	434.00	434.00
1	RH FOG LAMP COVER	BROKEN	120.00	120.00
1	FENDER INNER SHIELD CLIP	NECESSARY	8.00	8.00
1	FRT FENDER RH	TO REPAIR SEE LABOUR	682.00	-
1	FRT FENDER INNER SHIELD RH	TORN	150.00	150.00
1	AIR CON CONDENSER AIR GUIDE RH (ADDITIONAL)	TORN	134.00	134.00
1	FRT RADIATOR (ADDITIONAL)	HOLDER CRACKED	1,424.00	1,424.00
1	FRT BONNET (ADDITIONAL)	BUCKLED / BENT	1,758.00	1,758.00
	LESS 10% DISCOUNT		-2,146.90	-1,376.20
			19,322.10	12,385.80
	LABOUR			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRT FENDER RH.		3,500.00	1,950.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA. (FRT RH FENDER & FRT BUMPER OTHER AFFECTED AREA)		2,200.00	1,800.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		160.00	50.00
	TO CONDUCT 4 WHEEL ALIGNMENT.	NOT NECESSARY	160.00	-
	TO CONDUCT HEAD ALIGNMENT.	NOT NECESSARY	100.00	-
	TOW SERVICE.		60.00	60.00
			6,180.00	3,860.00
	GRAND TOTAL		25,502.10	16,245.80
	RECOMMENDED COST OF REPAIRS			16,245.80

Report Ref No. CC6/EQ19003864/Ugb3s2



Report Ref No. CC6/EQ119003864/Ugb3s2

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.