

FIRST AUTOWORKS

Repair Estimate

Date : 01/03/2019

Reference:

To Whom It May Concern

Make: OPEL
ASTRA

Dear Sir,

RE: VEHICLE : SJY 5219D
CHASSIS NO.: W0LBE8ECXH8065865
ENGINE NO.: B1170537JCVX0503

Name of insured : Chan Yook Leng Caroline
Date of accident.: 27/02/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

not Albert
near
tel. 62583581
p/p \$
52
11/3/19

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER	Dis 2,100.00
2	1	FRT BUMPER TOW COVER	Dis 130.00
3	1	FRT BUMPER LOW LIP RH	Dis 156.00
4	1	FRT BUMPER LOW LIP LH	Dis 156.00
5	15	FRT BUMPER CLIP SET	Dis 90.00
6	1	FRT BUMPER SIDE RETAINER LH - GUIDE	Dis 130.00
7	1	FRT BUMPER SIDE RETAINER LH - UPP	Dis 110.00
8	1	FRT BUMPER SIDE RETAINER RH - GUIDE	Dis 130.00
9	1	FRT BUMPER SIDE RETAINER RH - UPP	Dis 110.00
10	1	FRT BUMPER BRACKET LH	80.00
11	1	FRT BUMPER BRACKET RH	80.00
12	1	FRT BUMPER UNDER DUST COVER	220.00
13	1	FRT BUMPER BRACKET TOP CENTRE	180.00
14	1	FRT BRACE BRACKET CENTRE	229.00
15	1	FRT BRACE BRACKET RH	118.00
16	1	FRT BRACE BRACKET LH	118.00
17	1	FRT BUMPER SPONGE	Dis 190.00
18	1	FRT BUMPER REINFORCEMENT UPP (metal)	Dis 800.00
19	1	FRT BUMPER REINFORCEMENT LOW (firbe)	Dis 260.00
20	1	FRT BUMPER PARKING SENSOR SET	Dis 250.00
21	1	FRT BUMPER PARKING SENSOR SEAL SET	Dis 30.00
22	1	FRT BUMPER PARKING SENSOR WIRE HARNESS	Dis 400.00
23	1	FRT ENGINE DUST COVER RH	124.00
24	1	FRT ENGINE DUST COVER LH	124.00
25	1	FRT GRILLE ASSY	560.00
26	1	FRT GRILLE BASE	Dis 150.00
27	1	FRT GRILLE CHROME MOLDING RH	Dis 180.00
28	1	FRT GRILLE CHROME MOLDING LH	Dis 180.00
29	1	FRT GRILLE LOGO	Dis 160.00
30	1	FRT LOW CENTRE GRILLE	Dis 180.00
31	1	FRT LOW GRILLE LH	90.00
32	1	FRT LOW GRILLE RH	90.00
33	1	RH HEADLAMP(ilux)	3,500.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

<u>34</u>	1	LED CONTROL UNIT
<u>35</u>	1	LH HEADLAMP(ilux)
<u>36</u>	1	LH FOG LAMP
<u>37</u>	1	LH FOG LAMP COVER
<u>38</u>	1	RH FOG LAMP
<u>39</u>	1	RH FOG LAMP COVER
<u>40</u>	1	FENDER INNERSHIELD CLIP
<u>41</u>	1	FRT FENDER RH
<u>42</u>	1	FRT FENDER INNERSHIELD RH

	1,300.00	?
17	3,500.00	X
21	434.00	X
17	120.00	X
520	434.00	—
520	120.00	—
24	8.00	✓
2	682.00	X
75.17	150.00	—

Parts Total: 18,153.00
Less 10%: 1,815.30
Total : 16,337.70

Left Number plate Bar/era 40
 Band. Bar/era
 ftr grille to cur

Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. 650	3500.00 1850
2	Carry out spray painting on accident affected area. (ftr Rh fender & Frt bumper other affected area) 530	2200.00 1800
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	160.00 50
4	To conduct 4 wheel alignment	160.00 X
5	To conduct head alignment	100.00 X

Labour Total : 6,120.00

Other

<u>No.</u>	<u>Qty</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	1	Tow Service	60.00 ✓

Other Total : 60.00

Total : \$22,517.70
Gst (7%) : \$1,576.24
GRAND TOTAL: \$24,093.94

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, Y WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor
 Ronnie Tan
 DID: 6844 1985 Fax: 6844 5185



LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: