

FIRST AUTOWORKS

Repair Estimate

Date : 01/03/2019

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SJY 5219D

CHASSIS NO.: W0LBE8ECXH8065865

ENGINE NO.: B1170537JCVX0503

Name of insured : Chan Yook Leng Caroline

Date of accident.: 27/02/2019

Reference:

Make: OPEL
ASTRA

not Albert
new
Tel: 62583581
1/2 \$16245.80
5.2
1/3/19

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER	2,100.00
2	1	FRT BUMPER TOW COVER	130.00
3	1	FRT BUMPER LOW LIP RH	156.00
4	1	FRT BUMPER LOW LIP LH	156.00
5	15	FRT BUMPER CLIP SET	90.00
6	1	FRT BUMPER SIDE RETAINER LH - GUIDE	130.00
7	1	FRT BUMPER SIDE RETAINER LH - UPP	110.00
8	1	FRT BUMPER SIDE RETAINER RH - GUIDE	130.00
9	1	FRT BUMPER SIDE RETAINER RH - UPP	110.00
10	1	FRT BUMPER BRACKET LH	80.00
11	1	FRT BUMPER BRACKET RH	80.00
12	1	FRT BUMPER UNDER DUST COVER	220.00
13	1	FRT BUMPER BRACKET TOP CENTRE	180.00
14	1	FRT BRACE BRACKET CENTRE	229.00
15	1	FRT BRACE BRACKET RH	118.00
16	1	FRT BRACE BRACKET LH	118.00
17	1	FRT BUMPER SPONGE	190.00
18	1	FRT BUMPER REINFORCEMENT UPP (metal)	800.00
19	1	FRT BUMPER REINFORCEMENT LOW (firbe)	260.00
20	1	FRT BUMPER PARKING SENSOR SET	250.00
21	1	FRT BUMPER PARKING SENSOR SEAL SET	30.00
22	1	FRT BUMPER PARKING SENSOR WIRE HARNESS	400.00
23	1	FRT ENGINE DUST COVER RH	124.00
24	1	FRT ENGINE DUST COVER LH	124.00
25	1	FRT GRILLE ASSY	560.00
26	1	FRT GRILLE BASE	150.00
27	1	FRT GRILLE CHROME MOLDING RH	180.00
28	1	FRT GRILLE CHROME MOLDING LH	180.00
29	1	FRT GRILLE LOGO	160.00
30	1	FRT LOW CENTRE GRILLE	180.00
31	1	FRT LOW GRILLE LH	90.00
32	1	FRT LOW GRILLE RH	90.00
33	1	RH HEADLAMP(ilux)	3,500.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

34	1	LED CONTROL UNIT	1,300.00	?
35	1	LH HEADLAMP(ilux)	3,500.00	✓
36	1	LH FOG LAMP	434.00	✓
37	1	LH FOG LAMP COVER	120.00	✓
38	1	RH FOG LAMP	434.00	✓
39	1	RH FOG LAMP COVER	120.00	✓
40	1	FENDER INNERSHIELD CLIP	8.00	✓
41	1	FRT FENDER RH	682.00	✓
42	1	FRT FENDER INNERSHIELD RH	150.00	✓

Parts Total: 18,153.00
Less 10%: 1,815.30
Total: 16,337.70

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	3500.00
2	Carry out spray painting on accident affected area. (frt Rh fender & Frt bumper other affected area)	2200.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	160.00
4	To conduct 4 wheel alignment	160.00
5	To conduct head alignment	100.00
Labour Total :		6,120.00

Other

No.	Qty	Other Description	Price (SGD)
1	1	Tow Service	60.00
Other Total :			60.00

Total : \$22,517.70
Gst (7%) : \$1,576.24
GRAND TOTAL: \$24,093.94

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, I WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Ronnie Tan
DID: 6844 1985 Fax: 6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

TAX INVOICEEQ Insurance Company Limited
5 Maxwell Road
#17-00 Tower Block, MND Complex,
Singapore 069110

GST Ref. No: M2-0111811-5

Vehicle No: SJY 5219D
Chassis No : W0LBE8ECXH8065865
Engine No: B1170537JCVX0503

Invoice No:

Invoice Date:

DESCRIPTION**AMOUNT
SGD****Parts**

<u>No.</u>	<u>Qty.</u>	<u>Description</u>	<u>Price (SGD)</u>
1	1	FRT BUMPER	2,100.00
2	1	FRT BUMPER TOW COVER	130.00
3	1	FRT BUMPER LOW LIP RH	156.00
4	1	FRT BUMPER CLIP SET	90.00
5	1	FRT BUMPER SIDE RETAINER RH - GUIDE	130.00
6	1	FRT BUMPER SIDE RETAINER RH - UPP	110.00
7	1	FRT BUMPER BRACKET RH	80.00
8	1	FRT BUMPER UNDER DUST COVER	220.00
9	1	FRT BUMPER BRACKET TOP CENTRE	180.00
10	1	FRT BRACE BRACKET RH	118.00
11	1	FRT BUMPER SPONGE	190.00
12	1	FRT BUMPER REINFORCEMENT LOW (firbe)	260.00
13	1	FRT BUMPER PARKING SENSOR SET	250.00
14	1	FRT BUMPER PARKING SENSOR SEAL SET	30.00
15	1	FRT GRILLE ASSY	560.00
16	1	FRT GRILLE BASE	150.00
17	1	FRT LOW CENTRE GRILLE	180.00
18	1	RH HEADLAMP(ilux)	3,500.00
19	1	LED CONTROL UNIT	1,300.00
20	1	RH FOG LAMP	434.00
21	1	RH FOG LAMP COVER	120.00
22	1	FENDER INNERSHIELD CLIP	8.00
23	1	FRT FENDER INNERSHIELD RH	150.00

Supplementary Items

24	1	AIR CON CONDENSER AIR GUIDE RH	134.00
25	1	FRT RADIATOR	1,424.00
26	1	FRT BONNET	1,758.00

Total: 13762.00
Less 10%: 1376.20
Parts Total : 12385.80

Date: 15/4/2019

From: Firstautoworks Pte Ltd

Dear Sirs

RE: VEHICLE NO: SJY 5219D
CHASIS NO: W0LBE8ECXH8065865

Supplementary Items

Further to our estimate dated 01.03.2019, we append hereunder the additional Parts & labour required in respect of the repair as carried to the above vehicle for your kind attention.

Parts

<u>No.</u>	<u>Qty</u>	<u>Description</u>	<u>Amount</u>
1	1	AIR CON CONDENSER AIR GUIDE RH <i>Torn</i>	134.00 ✓
2	1	FRT RADIATOR <i>holder core</i>	1424.00 ✓
3	1	FRT BONNET <i>Buc / Surf</i>	1758.00 ✓

Total: **3316.00**

Total: 3316.00
Less 10%: 331.60
7 % GST: 208.91
Grand Total: **3193.31**

This is only an estimate and should additional work be found necessary to be carried out in the course of repairs, extra materials and labour cost will be charged accordingly. You will be informed prior actions to be taken. **Parts prices are subjected to change.**

Yours faithfully



Service Advisor

Ronnie Tan

DID : 6844 1985 Fax: 68445185

CC :

Fax:

Labour

<u>No.</u>	<u>Description</u>	<u>Price (SGD)</u>
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts	1,950.00
2	Carry out spray painting on affect area frt portion (frt Rh fender & Frt bumper other affected area)	1,800.00
3	To disconnect front wire harness of electrical component to facilitate repair, reconnect & check electrical function after repair	50.00

Labour Total : 3800.00

Other

<u>No.</u>	<u>Qty</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	1	Towing Service	60.00
Other Total :			60.00

Yours Faithfully,


Ronnie Tan
Service Advisor
Tel: 68441985 Fax:68445185

Total : 16245.80
GST (7%) 1137.21
Grand Total: 17383.01

E & O E

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1 ST AUTOWORKS PTE LTD".
PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.