

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 01 Mar 2019

Preliminary Advice

Vehicle No	: SLU9234E	Accident Date	: 02/02/2019
Make	: HONDA ACCORD	Policy No.	: 1201900003973
Assignment Date	: 01/03/2019	Excess	: S\$0.00
Date of Inspection	: 22/02/2019	Est. Duration of Repair	: 8 days
Inspection At	: Bw Workshop Services Pte Ltd (HQ) 30 UBI ROAD 4 Singapore 408615		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,693.40
Revised Amount	:S\$	4,777.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,777.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	46,718.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,282.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :