

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

26-Feb-19

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6281 E

1 pc	n/s headlamp	\$	1,028.00
1 pc	Bonnet grille	\$	385.00
1 pc	Front bumper	\$	531.00
1 pc	Front bumper emblem	\$	44.00
			<hr/>
			\$ 1,988.00
Less 10%			\$ 198.80
			<hr/>
			\$ 1,789.20

### S/NETT

1 pc	Front no. plate with casing	\$	50.00
1 pc	Front bumper clips	\$	48.00
			<hr/>
Sundry			\$ <del>50.00</del> <sup>20</sup>
To check for wiring and to focus head lamps			\$ <del>80.00</del> <sup>20</sup>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same			\$ <del>450.00</del> <sup>200</sup>
To putty and spray painting on front bumper			\$ <del>250.00</del> <sup>180</sup>
			<hr/>
			\$ 2,717.20

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Ka/ma 14/1/19  
1/3/19 1700h  
2 hrs.  
45  
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are to be identified on
- Temporary survey should be on "no prejudice" basis
- No illegal modification to be made
- Supplemental items to be replaced, if it is subject to final approve from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: