



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

27/02/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP FWD
Asker

WAUZZZ8R6CA003341

Accident date: 27/02/2019

Estimated repair cost for vehicle no: SLS2522E AUDI Q5 3.2 A FSI S-LINE '11

CHASSIS: WAUZZZ8R6CA003341

S/n	Qty	Items	U/price	Amount
1	1	Front L/H Head Lamp <i>cracked</i>		\$2,419.35 ✓
2	1	Front L/H Head Lamp Lower Bracket <i>new</i>		\$87.50 +
3	1	Front Bumper <i>Debond</i>		\$2,098.10 ✓
4	8	Front Bumper Clip <i>new</i>	\$6.50	\$52.00 30
5	2	Front Bumper Side Retainer <i>LH new</i>	\$36.55	\$73.10 36.55
6	1	Front L/H Bumper Fog Lamp <i>2nd</i>		\$194.10 ✓
7	1	Front L/H Bumper Fog Lamp Cover <i>new</i>		\$151.75 +
8	1	Front L/H Fender <i>Perished</i>		\$752.85 ✓
9	1	Front L/H Fender Cowling <i>Debond</i>		\$190.95 ✓
10	8	Front L/H Fender Cowling Clip <i>new</i>	\$6.50	\$52.00 30
11	1	Front L/H Rim <i>lt.</i>		\$3,140.25 1250/s
12	1	Front L/H Tyre <i>lt.</i>		\$450.00 350/s
13	1	Front L/H Lower Arm <i>Bent</i>		\$540.20 ✓
14	1	Front L/H Upper Arm <i>3 Bent</i>		\$540.80 285
15	1	Front L/H Trailing Arm		\$1,003.25 315
16	1	Front L/H Knuckle Arm <i>Bent</i>		\$1,020.55 ✓
17	1	Front L/H Knuckle Arm Bearing <i>new</i>		\$625.95 ✓
18	1	Front L/H Shock Absorber <i>Bent</i>		\$1,557.35 ✓
19	1	Front L/H Drive Shaft <i>?</i>		\$2,700.80 +
20	1	Front Stabilizer Bar <i>new</i>		\$422.95 +
21	1	Front Steering Rack <i>?</i>		\$5,440.10 +
22	1	Vinyl Wrap (Special Nett)		\$3,500.00 1200 (50)

Subtotal :- \$27,013.90

9811.85
8830.66

SW: 2800

Labour charges

To remove & refit front L/H undercarriage	\$100.00 ✓
To remove & refit front drive shaft & steering rack	x
To remove & refit vinyl wrap	\$450.00 300
To check wheel alignment	\$150.00 80
To check wiring	\$100.00 30
To reset computer	1610 \$280.00 100
Tuff kote	\$150.00 x
Towing fee	\$120.00 x
Panel beating	\$1,000.00 500
Spray painting	\$1,000.00 500

Subtotal :- \$3,350.00

Total:- \$30,363.90

total: 13240.66
L/S: 10.5k ✓
06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: