

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHB 4346X

DATE : 1.03.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

INDIA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>mostly broken</i>			\$ 251.00	✓
	Radiator Grille H Emblem <i>NW</i>			\$ 27.50	✓
	Front Bumper Cover <i>distorted</i>			\$ 544.50	✓
	Front Bumper Sponge <i>thin</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>BT</i>			\$ 402.10	✓
	Front Bumper Centre Grille <i>broken</i>			\$ 178.60	✓
	Front Bumper Bracket Top (LH/RH) <i>NW</i>	\$	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>NW</i>	\$	24.60	\$ 49.20	X
	Headlamp Support Top Cover <i>mostly cracked</i>			\$ 222.60	✓
	Headlamp Support Panel Assy <i>2 set / 1 side</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>mostly broken</i>	\$	1,388.00	\$ 2,776.00	✓
	Radiator <i>2 punctured / 1 set</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>NW</i>			\$ 792.95	X
	Radiator Bracket (RH/LH) <i>NW</i>	\$	6.50	\$ 13.00	X
	Radiator Guard <i>NW</i>	\$	20.00	\$ 40.00	X
	Horn Unit (LH/RH) <i>broken</i>	\$	73.80	\$ 147.60	✓
	Aircon Condenser <i>2 set</i>			\$ 927.50	✓
	Inter Cooler <i>BT</i>			\$ 1,032.50	✓
	Inter Cooler Mounting (2 PCS) <i>NW</i>			\$ 25.90	X
	SUB TOTAL			\$ 9,180.65	
	LESS 20%			\$ 1,836.13	
	DISCOUNTED TOTAL			\$ 7,344.52	
	Front Number Plate <i>broken</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>NW</i>			\$ 30.00	Nett X
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	500/-
	Spray Painting Charge			\$ 250.00	200/-
	Wiring Charge			\$ 50.00	30/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	NW
	TOTAL LABOUR			\$ 1,930.00	

SHB 4346X

[illegible]

SHB 4346X

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Exhaust Pipe			\$ 300.00
	TOTAL LABOUR			\$ 3,020.00
	ESTIMATE TOTAL			\$ 23,287.58
	05/03/2019 @ 1430m HA Antenna 2/5mm 9 dgs. 1 nja LKK Auto 8 <u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				