

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5584M

AAD1902-244

Not Authorized
21 Sep @ 11,250

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHC 5584M

VF1ABL15AUC279356

RENAULT

LATITUDE

28.2.2019

EQ

15/9/2014

	PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>B</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>B</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>CM</i> 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>S</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>S</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>S</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>D</i> 135.97	✓
8	1 BUMEP R RETAINER LH REAR	\$	<i>D</i> 44.99	✓
9	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>B</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>B</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 BOOT REAR	\$	<i>B</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>S</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>61.525W</i> 323.05	<i>508.52</i>
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>S</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>R</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>R</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>S</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>S</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>S</i> 586.45	
25	1 BOOT SWITCH	\$	<i>S</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>S</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>S</i> 221.81	

Trans-cab Auto Services Pte Ltd

AAD1902-244

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5584M

30	1 FENDER PANEL REAR LH	\$	Bu	3,299.13	✓
31	1 WHEELARCH REAR LH	\$	SL	543.47	X
32	1 FENDER PANEL INNER TRIM REAR LH	\$	Reform	671.45	✓
33	1 WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09	X
34	1 TAILLAMP LH	\$	CM	552.55	✓
35	1 TAILLAMP PANEL LH	\$	R	986.70	✓
36	1 TAILLAMP RH	\$	SL	552.55	X
37	1 TAILLAMP PANEL RH	\$	R	986.70	X
38	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	CM	404.56	✓
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
41	1 SPARE WHEEL PANEL TRIM	\$	SL	612.21	X
42	1 EXHAUST REAR	\$	R	7,489.05	X
43	1 EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	36,036.98
10%	\$	3,603.70
	\$	32,433.28

Special Nett

1	1SET PARKING AID	\$	Shan	700.00	Goosm
2	1SET REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	} X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	SL	17.82	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	X
12	1 REAR BOOT ADVERTISEMENT STICKER	\$	na	300.00	X
13	1 REAR BUMPER ADVERTISEMENT STICKER	\$	na	200.00	X

Trans-cab Auto Services Pte Ltd

AAD1902-244

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5584M

14	1SET FENDER WHEELARCH REAR RH CLIP	\$	na 35.00 X
15	1SET FENDER WHEELARCH REAR LH CLIP	\$	na 35.00 X
16	1 FENDER INNER TRIM CLIP LH	\$	na 28.00 ✓
17	1 FENDER INNER TRIM CLIP RH	\$	na 28.00 X
18	1 TAILLAMP CLIP RH	\$	na 5.00 X
19	1 TAILLAMP CLIP LH	\$	na 5.00 ✓
20	2 REAR WINDSCREEN SELANT	\$	na 80.00 405M
21	1 WINDSCREEN MOULDING	\$	na 100.00 ✓
22	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00 305M
23	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na 385.00 X
24	1 SPARE TYRE	\$	na 330.00 X

TOTAL \$ 2,620.02

TOTAL PARTS \$ 35,053.30

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 1100l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 1200l
To Rust-Proofing Of The Affected Areas.	\$	170.00 90l
To reinstall rear bumper parking sensor.	\$	170.00 60l
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 60l
To repair and realign rear exhaust pipe.	\$	na 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1902-244

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5584M

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 100/
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i> 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	120/
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	X
TOTAL	\$	14,340.00	

Over All Total \$ 49,393.30

(LUMP SUM)

Repair Days

~~20 DAYS~~

9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: