

Not Authorized  
LAL  
4/3/19  
2/5 ~~5000~~  
4dy.

FASTECT AUTO PTE LTD  
BLK1 KAKI BUKIT AVE 6  
#01-46/48/50 AUTOBAY  
SINGAPORE 417883

VEHICLE NO: GZ 4530R

QTY	PARTICULAR (NETT ITEM)			
1 PCS	TAILGATE	1105	20/Ref	\$1,250.00
1 PCS	TAILGATE OUTER HANDLE	295	CU	\$365.00
1 PCS	TAILGATE INNER LOCK		shuf	\$299.00
1 PCS	TAILGATE WEATHERSTRIP	286	1M	\$366.00
1 PCS	TAILGATE REAR WINDSCREEN RUBBER	299	nu	\$391.00
1 PCS	REAR BUMPER CENTRE		3ent	\$682.00
2 PCS	REAR BUMPER SIDES @\$350.00	315	MS de	\$700.00
2 PCS	REAR BUMPER SIDE HOLDERS @\$48.00		11	\$96.00
2 PCS	REAR BUMPER REFLECTORS @\$35.00		11	\$70.00
2 PCS	TAILLAMPS @\$285.00		11	\$570.00
1 PCS	REAR END PANEL	788	20/Ref	\$981.00
1 PCS	REAR END PANEL TOP PLATE		3ent	\$386.00
1 PCS	REAR SPARE TYRE BRACKET		11	\$345.00
1 PCS	REAR REFLECTOR		11	\$245.00
1 PCS	REAR REFLECTOR BRACKET		11	\$105.00
				\$6,851.00
	S.NETT			
1 SET	TAILGATE CORPORATE STICKER		nu	\$680.00
1 PCS	TAILGATE 70KM/H STICKER		nu	\$20.00
1 PCS	REAR LICENCE PLATE		3ent	\$20.00
1 SET	REAR BUMPER REVERSE SENSOR		shuf	\$280.00
1 PCS	REAR END PANEL SEALANT		nee	\$50.00
	LABOUR CHARGES:			
	TO CHECK WIRING			\$50.00
	TO DISMANTLE & REPLACING REVERSE SENOR			\$80.00
	TO TRANSFER TAILGATE COMPONENTS			\$120.00
	TO DISMANTLE & REFIX REAR WINDSCREEN			\$120.00
	TO SPRAY RUST PROOFING			\$100.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$900.00
	TO PUTTY & SPRAY PAINTING			\$900.00
			TO	\$10,171.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

4455  
102  
4009.5  
6273.5