SYLVAMAS _		ASSIGNI	MENT (Office)			63.73
From (Person)	Winnie Fan	of	A1G	Date/I	ime: 04/2	3/19
Estimated Cos	t:		Bill to:			17
OD/TP/WS	TP RES / OD RES / )	EVA/INV/MV	/ CS			
To Inspect Ve	hicle No:	SUK 4512	M	Insured:	SFB 87.	38ni
at Workshop	m/s_ Motor	Intalligen	ice Autrico	Tel:	6281008	7 100
of	13 Kaki Bukit A	Rd 4 #01	-20 Bartley	1 B/2 Cen	tre	
Policy No:	yati visan suu suusi sa		Claim No:	283910	14231SG	
Sum Insured:			Excess:			
Make of Veh: (Client's Record				D.O.A	. 73/0	49
CA / REV	REP. / REV 24 HRS			HO.	D. Endorsement:	
Date/Time:			d:		/\.	
Date/Time	Action/Instruction (	) Estinu	nto.			
AND THE PARTY OF T	54 451mm.					
	SKB 8238M)	c .				
	Dismartle: 5/2	15019				
1.8800 M. 11.000 A.	After apair: 810					
	THE PERSON AND THE PE	5 L-30 71 -1				

,

REF:

#### PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Fan, Winnie-LW

To:

Cc: Fong, Andy-SY, Chin, Lee-Ying

Sent: 4/3/2019 11:27:23 AM

Hi LKK,

Kindly assist to survey.

Please contact Ms.Ivy Pang of Motor Intelligence Automo Pte Ltd at tel no. 6281 0087 for a pre-repair survey of our client's vehicle located at 13 Kaki Bukit Road 4 #01-20 Bartley Biz Centre Singapore 417807.

Winnie Fan

AIG

Claims Service Associate Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



### Nivitha (LKK Auto)

From:

Fan, Winnie-LW <Winnie-LW.Fan@aig.com>

Sent:

Monday, 4 March 2019 11:27 AM

To:

'admin-a@lkkauto.com'; 'assignments@lkkauto.com'

Cc:

Fong, Andy-SY; Chin, Lee-Ying

Subject:

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE

SKB8238M AND SLK4512M ON 23/02/2019

Attachments:

SecureMessageAtt.html





This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息,请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

Click here by 2019-03-11 11:27 +08 to read your message. After that, open the attachment.

More Info

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint. Inc. All rights reserved.

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available.

ACCIDENT STATEMENT	
25/02/2019 11:02	
23/02/2019 10:45	
BISHAN STREET 11	
SINGAPORE	
	25/02/2019 11:02 23/02/2019 10:45 BISHAN STREET 11

Country Totale of E033	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLK4512M
Insured/Policyholder	
Name Of Registered Owner	TW PREMIUM AUTOMOBILE PTE LTD
Co Reg No	201320430G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90000000
Vehicle Particulars	

AZDA
Į

Model MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken Vehicle Category

THIRD PARTY PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 101549030

Cover Note Number

Driver

Name of Driver GOH AH HENG NRIC No S6944329Z Date Of Birth 06/11/1969 Occupation OUTDOOR Date Of Driving Pass 24/03/2017

Driving Experience 1 YEAR AND 10 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97480618

Fax Number Contact Number

EMail Address NOEMAIL Address

BLK 444 ANG MO KIO AVE 10 #11-1597

Postcode

560444

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: HWANG DONGSUP

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police? If Yes, Please state which Police Station

YES

Police Station Name

ANG MO KIO SOUTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 81 ANG MO KIO AVE 3, POSTCODE: 569929, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-4519999 - FAX NO: 65535679

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

AS PER POLICE REPORT No.T/20190223/2080:

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

SKB8238M

Vehicle Make/Model/Colour

JAGUAR XJ8 4.2 SOVEREIGN LWB (A) ABS A/B GAS/D

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1				
Name	GOH AH HENG			
Approximate Age	49			
Injuries Sustain				
njured person in which vehicle?	SLK4512M			
Were seat belts worn?	YES			
Was this injured conveyed to hospital by ambulance?				
Address	BLK 444 ANG MO KIO AVE 10 #11-1597			
Postcode	560444			

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Fleate report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the injuries; you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

Linderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident abali be collectively referred to as the "Insurers", the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (b) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Timo: Oliver's Signature (if driver is not the policyholder) Date & Time: 1DAC KAKI BUKIT(VAC) 23 KAKI BUKIT AVE 4

Reporting Centri-Singapore, 415937e Name: Tel: 67416697 NRIC/FIN No.: Fax: 67492305

Email: vackb@singnet.com.sg

SKETCH PLAN	152A		A SLK 4512M
Bishan STREET	(1)	1 /2	B SKB 8238M
	25 14 -> ID		
		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
DESCRIBE CIRCUMSTANCES OF			
	olice report		
DECLARATION /We declare the foreguing particular	s are true in every respect		TO THE PROPERTY OF THE PARTY OF
Policyholder's Signature	Oriver's Shature	Reporting Co	23 KAKI BUKIT (VAC) 23 KAKI BUKIT AVE 4 Singapore 415933
Tate & Time.	(If driver is not the policyholder) Date & Timer	Name:	Fax: 67492305





Police Station Of Origin: Ang Mo Kio South N.P.C 81 Ang Mo Kio Avenue 3 SINGAPORE 569929

Report No. T/20190223/2080

Tel No: 1800-4519999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/02/2019 14:23		Vide Report No.:	Station Diary No.: 149	
Informa	nt's Partic	ulars		
Name of GOH AF	Informant: HENG		Address: APT BLK 444 ANG MO H SINGAPORE 560444	KIO AVENUE 10 #11-1597
ID Type / ID No.: NRIC NO / S6944329Z		29Z	Contact No.: Home/Office:	Mobile: 97480618
Nationality: SINGAPORE CITIZEN		EN	Email:	
Sex: Male	Age: 49	Date of Birth: 06/11/1969	Type of Informant: Driver	int or
Race; Chinese			Language:	Institution / School Name:
Occupation; Grab driver			Driving Licence Informati Class: 3,4,5	on: Date of Expiry:

General Infor	mation of the Accide	nt	TIDKSE -	The Hall Market	GO HOW	
Type of Accident	Non-Injury Others		Orink Orive: No	Date/Time of Accident: 23/02/2019 10:45		Type of Location: Straight Road
BISHAN STR	EET 11					-
Weather: Clear		Road Su Dry	rface:		Road	Speed Limit:
Traffic Flow: One Way		Traffic Cont			Traffi	ic Volume:
Type of Collis Between Mov	sion: ring Vehicles - Head T	o Side				ne conveyed by ulance:

Details of V	ehicle Involve	ed .		B HEAT HEAT	(C = 4 8 2 2 2 2 1	
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SKB8238M	Car		JAGUAR		Slightly Damaged	0
SLK4512M	Car		MAZDA		Slightly Damaged	1



T/20190223/2080

Police Station Of Origin: Ang Mo Kio South N.P.C 81 Ang Mo Kio Avenue 3 SINGAPORE 569929 Tel No. 1800-4519999 2 of 3 Report No. T/20190223/2080

CONTINUATION OF REPORT

#### Brief Details.

On 23/02/2019 at about 1045hrs, I was driving a vehicle bearing registration number SLK4512M along Bishan Street 11. I am a Grab driver with a passenger namely Hwang DongSup, Fin: G1134273L, Hp: 84390150 in my vehicle. I was on the 2nd lane with 2 lane road, I was going straight and there is a vehicle bearing registration number SKB8238M at the opposite road turning into a carpark on my left. The vehicle SKB8238M didn't check and my vehicle collided with him. After the accident, we came out and exchange of particular. The driver is Huang Chang Yi S2508437C residing at 14 Gentle Road. After which, we took photo of the accident and left the location.

I have a stiff neck after the accident and my passenger was feeling unwell. As such, we decided to proceed to see a doctor at Blk 150 Bishan St 11 #01-151 (Bishan Grace Clinic). Both of us were given 4 days MC reference MC:0001019011 from 23/02/2019 to 26/02/2019.

I wish to state that I do have in car camera in my vehicle.





Police Station Of Origin: Ang Mo Kio South N P C 81 Ang Mo Kio Avenue 3 SINGAPORE 569929

3 of 3 Report No. T/20190223/2080

Tel No: 1800-4519999

CONTINUATION OF REPORT

#### Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

F / Sgt 2 TAN WEI REN	ing the Report.	Signature Of Informant:
Signature Of Interpreter: Not applicable		Date/Time. 23/02/2019 14:23
Officer In Charge Of Case. TP / GIA /		Classification Of Case:
Staff Sgt WONG SIEU LUI Contact No.: 65476151		SN.085
Authentication Stamp NP168	Sample per	a Force

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:	Company
Owner ID:	0430G
Vehicle Details	
Vehicle No.:	SLK4512M
Vehicle to be Exported:	No
ntended Deregistration Date:	05 Mar 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	P520420889
Chassis No.:	JM6BN22A8H0135636
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,777.00
Original Registration Date:	17 Jan 2017
First Registration Date:	17 Jan 2017
Transfer Count:	2
Actual ARF Paid:	\$9,777.00
ntended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jan 2027
PARF Rebate Amount:	\$7,332.00
ntended COE Rebate Details	
COE Expiry Date:	16 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,951.00
COE Rebate Amount:	\$40,062.00
Total Rebate Amount:	\$47,394.00

The information contained herein is correct as at 05 Mar 2019

ОК



## LKK Auto Consultants Pte Ltd

DAR - AlG.

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park , Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

SUK4512M

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SEM 7621B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
11	BONNET (CONSISTENT) -FL / BT	Buckled	1,068.00	1.068.00
20 19	BONNET HINGES (CONSISTENT) *FL	Bent	82.00	82.00
	BONNET OUTER WEATHERSTRIP (CONSISTENT) FL	Twisted	64.00	64.00
1	BONNET-INNER-WEATHERSTRIP (CONSISTENT) FL	Not Necessary	26.00	04.00
12	BONNET WEATHERSTRIP CLIP (CONSISTENT) FL	Not Necessary	51.60	
	BONNET LOGK (CONSISTENT) FC	Not Necessary	198.00	
	BONNET-LOCK-CABLE (CONSISTENT) *FL-	Not Necessary	53.00	
	FRONT SUPPORT PANEL (CONSISTENT) *FL	Cracked	470.00	470.00
1	N/S FRONT SUPPORT TOP COVER (CONSISTENT) *FL	cut - BR	91.00	91.00
	e/s front-support top cover (consistent) *FL	Not Necessary	91.00	01.00
	FRONT-SUPPORT AIR BAFFLE ASSY (CONSISTENT) *FL	Broken	168.00	168.00
			43.00	43.00
-	FRONT SUPPORT PANEL TOP COVER CLIPS / /C C	Necessary	43.00	1000
1	FRONT BUMPER (CONSISTENT) FL/ De	Deformed	826.00	826,00
11	FRONT BUMPER REINFORCEMENT (CONSISTENT) *FL-	Bent / BT	478.50	478.50
2	FRONT BUMPER AIR GUIDE (CONSISTENT) *FL	Deformed	112,00	112.00
	FRONT BUMPER CLIP (SONSISTENT)*FL / KC.	Necessary	43.00	43.00
1	O/S FRONT BUMPER INDICATION LAMPS (CONSISTENT)	Cracked / OPA	140.00	140.00
1	O/S FRONT BUMPER INDICATION LAMPS GARNISH	Deformed / MES	BR 25.00	25.00
1	FRONT BUMPER SIDE RETAINERS (CONSISTENT) FL	Necessary	19,00	19,00
1/2	FRONT BUMPER LOWER GRILLE SIDE COVER / MIS	Missing	70.00	70.00
1	FRONT BUMPER REINFORCEMENT INNER FRAME* (GONSISTENT) FL	Necessary	98.00	98.00
1	FRONT BUMPER LOWER SPLASHIELD COVER (CONSISTENT) *FL	Not Necessary	84.00	
1	FRONT BUMPER BOTTOM SUPPORT GARNISH (CONSISTENT) *FL	Not Necessary	96.00	
1	CVS FRONT BUMPER BOTTOM SUPPORT BRACKET (CONSISTENT) *FL	Not Necessary	55.00	
1	RADIATOR ASSY (CONSISTENT) FL	Bent	1,065.00	1,065.00
1	RADIATOR FAN COWLING (CONSISTENT) (NPA) *FL	Not Necessary		
1	RADIATOR FAN BLADE (CONSISTENT)(NPA) *FL	Not Necessary		
(1	RADIATOR GRILLE (CONSISTENT)*FL / CPA	Cracked	150.00	150.00
1	RADIATOR GRILLE CHROME GARNISH (GONSISTENT)	N/S Not Necessary / O/S Cut	366.00	183.00
1	RADIATOR GRILLE CHROME GARNISH HOSE (CONSISTENT) *FL	O/S Deformed /N/SNot Necessary	76.00	38.00
1	RADIATOR GRILLE SIDE BRACKET (CONSISTENT) FL	O/S Bent / N/S Not Necessary	26,00	13.00
9	BADIATOR GRILLE OUTER GARNISH (CONSISTENT)*FL	Cut	150.00	150.00
	RADIATOR GRILLE OUTER GARNISH INNER TRIM (CONSISTENT) *FL	Cracked	98.00	98.00
4	RADIATOR GRILLE OUTER GARNISH RIVETS— (CONSISTENT) *FL	Necessary	36.00	36.0
3	RADIATOR GRILLE OUTER GARNISH GLIP (CONSISTENT) *FL	Necessary	12.90	12.9
1	RADIATOR GRILLE SIDE EXTENSION COVER— (CONSISTENT) *FL	N/S Not Necessary / O/SMissing	96.00	48.0



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

SU( 45/2 M

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)	
1	RADIATOR BRACE PANEL (CONSISTENT) *FL	Not Necessary	39.00	100	
1	RADIATOR EMBLEM BADGE (CONSISTENT) FL	Necessary	59.00	59.00	
1 2	HEADLAMP (GONSISTENT) PL	Cracked	2,040.00	2,040.00	
2	HEADLAMP PANEL (CONSISTENT) FL Base	Buckled	298.00	298.00	
/ 1	FRONT LICENCE PLATE GARNISH (CONSISTENT) FL	Bent / CR	68.00	68.00	
2	FRONT-FENDER (CONSISTENT) *FL	Buckled	668.00	668.00	
1	FRONT FENDER-INNER COWLING (CONSISTENT) *FL	N/S Not Necessary /O/SDefor med	260.00	130.00	
12	FRONT FENDER INNER COWLING CLIP (CONSISTENT) *FL	Necessary	51.60	51.60	
1	WINDSHIELD WASHER TANK (CONSISTENT) *FL	Deformed	105.00	105.00	
1	WINDSHIELD WASHER TANK NECK (CONSISTENT) *FL	Deformed	129.80	129.80	
1	WINDSHIELD WASHER TANK CAP (CONSISTENT) *FL	Missing	25.00	25.00	
1	AIRCONLCONDENSOR (CONSISTENT) *FL	Bent	987.00	987.00	
1	AIRCON HOSE (CONDENSOR TO COMPRESSOR) (CONSISTENT) *FL	Not Necessary	75.00	0.0	
1	O/S FRONT-WHEEL RIM (CONSISTENT) *FL	Cut	412.00	412.00	
1	Q/S FRONT-WHEEL RIM HUB CAP (CONSISTENT) *FL	Missing	124.00	124.00	
1	Q/S FRONT SHOCK ABSORBER (CONSISTENT) *FL	Not Necessary	287.00		
1	O/S FRONT-LOWER ARM (CONSISTENT) *FL	Bent	484.70	484.70	
1	O(S-FRONT-KNUCKLE ARM (CONSISTENT) *FL	Bent	384.00	384.00	
1	O/S ERONT WHEEL BEARING WITH HUB (CONSISTENT)	Necessary	542.00	542.00	
	List Item Discount on L Items 20.00/20.00% (S\$)		-2,713.42	-2,419.90	
			10,853.68	9,679.60	
	SPECIAL NETT ITEMS				
11	FRONT LICENCE PLATE (CONSISTENT) PS /BT	Bent	50.00	50.00	
1	BLT RADIATOR COOLANT (CONSISTENT) *FS	Necessary	35.00	35.00	
	\$ 10	- ×	85.00	85.00	
	GRAND TOTAL		10,938.68	9,764.60	

Report Ref No.

, It Buper lower Grille / De.

Radiator Grille 1090 / MC. 14 support Radiator Brille Inner Garnish Base / CAS

M.MATAI, AMSAE-A / ht Burper Top Cover - le.

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk,

PHOTOGRAPHS FOR VEHICLE NO. SLM 7621B

INSPECTION

radioator Enville State

/ empport powered side Bracket / BR X Z

/ FA Fenders x Repair X Z

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRA	CKING			THE COMME SHOW				
Case I	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj S	ubmitted	Ins Auth'ed	Status	
05765W	22 Mar 2019 14:02 Edit Reg		04 Mar 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimat	S\$0.	OO v Rpt		Pending f Report Cancel Ca	or Survey
M	lain	Re	ference	C	laim Detail	· 1	Docume	nts	Show All
CLAIM SUB	FOLDER DE	TAILS	THE RESERVE AND ADDRESS.	And the sales of t	The second second	[Creat	ed by adjuster]	A STATE OF THE PARTY OF THE PAR	
Insured:	Huang Ch	ang Yi, ID: S25	08437C			1.000			
Main Claimant:	TWIN PRI	EMIUM AUTOMO	BILE PTE LTD,	Co. Reg. No	.: 20132043	0G			
Vehicle Reg. No.:	SLK451	2M			Date of Los		23/02/2019 10:00 - :59 [25 Months and 6 Days From LTA Reg Date (Man Yr)]		
Claim Type:	<b>TP</b> / 283	9194231SG			Policy/Cove Note No.:	ar I	2100242312 (Comprehensive)		
Vehicle Reg. No. (Insured):	SKB8238	м			Policy No. (Claimant)				
					Excess:				
Repairer:	Motor Int	elligence Autom	Pte Ltd (HQ)	13 KAKI BUK	T ROAD 4,	#01-20 BAR	RTLEY BIZ CENTRE	417807 Kaki	Bukit - Tel:
Handling Insurer:	AIG Asia	Pacific Insurance	e Pte. Ltd. (Exp	ress) - Tel: 6	5-6419-300	0 [Handl	led by Foo, Chit Y	an] Chityan.Fo	o@aig.com
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	. [Handled b	y XING GU	O QIANG] [Fi	nal Rpt due	02/04/2019
ASSOCIATI	ED MAIL RE								ompose Case Ma
AIG_SG (	25/03/2019):	Request To Uple	oad TP GIA Rep	oort			-		
ALL ASSOC	CIATED TAS	ve=				- Printerior		1	
ALL A5500	(Vertice and the second					View /	All Search Tasks	Create New	Task Complet
	Priority	Type Task	Group Subj	ect Hand	er Assi	gned By	Completed O	n Create	ed On Done
Due Date No results.									

## Claim Documents

\*SLK4512M (2839194231SG) [SKB8238M] TWIN PREMIUM AUTOMOBILE PTE LTD Feb 23 2019 10:00AM [Huang Chang Yi] Motor Intelligence Automo Pte Ltd

Up	load Documents Uplo	ad Photos   Compose New Letter   Upload Video   Upload Audio	View View in Bro	wser ¥
Ass	essment Reports		1 per page ▼	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnai	l Prin
1	25/03/19 09:40	Accident Statement From:OD - Reg. No: SKB8238M, Claimant: HUANG CHAN YI	1 Load HTM	
Pho	otos/Images		3 per page ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	l Prin
1	22/03/19 09:36	General View	Load JPG	•
2	22/03/19 09:36	General View	Load JPG	•
3	22/03/19 09:36	General View	Load JPG	•
4	22/03/19 09:36	General View	1 Load JPG	•
5	22/03/19 09:36	General View	1 Load JPG	•
6	22/03/19 09:36	General View	Load JPG	•
7	22/03/19 09:36	General View	Load JPG	•
8	22/03/19 09:36	General View	1 Load JPG	~
9	22/03/19 09:36	General View	● Load JPG	•
10	22/03/19 09:36	General View	Load JPG	•
11	22/03/19 09:36	General View	1 Load JPG	•
12	22/03/19 09:36	General View	Load JPG	•
13	22/03/19 09:36	General View	1 Load JPG	•
14	22/03/19 09:36	General View	1 Load JPG	•
15	22/03/19 09:36	General View	1 Load JPG	•
16	22/03/19 09:36	General View	● Load JPG	•
17	22/03/19 09:36	General View	1 Load JPG	•
18	22/03/19 09:36	General View	1 Load JPG	•
19	22/03/19 09:36	General View	■ Load JPG	•
20	22/03/19 09:36	General View	1 Load JPG	•
21	22/03/19 09:36	General View	1 Load JPG	•
22	22/03/19 09:36	General View	■ Load JPG	•
23	22/03/19 09:36	General View	1 Load JPG	•
24	22/03/19 09:36	Photographs of Damaged Parts	● Load JPG	•
25	22/03/19 09:36	Photographs of Damaged Parts	<b>●</b> Load JPG	•
26	22/03/19 09:36	Photographs of Damaged Parts	1 Load JPG	•
27	22/03/19 09:36	Photographs of Damaged Parts	① Load JPG	•
28	22/03/19 09:36	Photographs of Damaged Parts	1 Load JPG	•
29	22/03/19 09:36	Photographs of Damaged Parts	1 Load JPG	•
30	22/03/19 09:36	Photographs of Damaged Parts	1 Load JPG	•
31	22/03/19 09:36	Photographs of Damaged Parts	1 Load JPG	-

Assessment Reports			1 per	1 per page ▼		
No	No Finalized On AIG Asia Pacific Insurance Pte. Ltd. (SG)			Thumbnail	Print	
32	22/03/19 09:36	Photographs of Damaged Parts	0	Load JPG	•	
33	22/03/19 09:36	Photographs of Damaged Parts	0	Load JPG	•	
34	22/03/19 09:36	Photographs of Damaged Parts	0	Load JPG	•	
35	22/03/19 09:36	Photographs of Damaged Parts	0	Load JPG	€	
36	22/03/19 09:36	Photographs of Damaged Parts	0	Load JPG	•	
37	22/03/19 09:36	Photographs of Damaged Parts	0	Load JPG	•	
38	22/03/19 09:36	Photographs of Damaged Parts	0	Load JPG	•	
39	22/03/19 09:36	Photographs of Damaged Parts	0	Load JPG	•	
40	22/03/19 09:36	Photographs of Damaged Parts	0	Load JPG	•	
41	22/03/19 09:36	Photographs of Damaged Parts	0	Load JPG	•	
42	22/03/19 09:36	Photographs of Damaged Parts	0	Load JPG	•	
43	22/03/19 09:36	Photographs of Damaged Parts	0	Load JPG		
44	22/03/19 09:36	Photographs of Damaged Parts	0	Load JPG	•	
45	22/03/19 09:37	Photo After Spray	0	Load JPG	•	
46	22/03/19 09:37	Photo After Spray	0	Load JPG	•	
47	22/03/19 09:37	Photo After Spray	0	Load JPG	•	
48	22/03/19 09:37	Photo After Spray	0	Load JPG	•	
49	22/03/19 09:37	Photo After Spray	0	Load JPG	€	
50	22/03/19 09:37	Photo After Spray	0	Load JPG	•	
51	22/03/19 09:37	Photo After Spray	0	Load JPG	•	
52	22/03/19 09:37	Photo After Spray	0	Load JPG	•	
53	22/03/19 09:37	Photo After Spray	0	Load JPG	•	
54	22/03/19 09:37	Photo After Spray	0	Load JPG	2	
55	22/03/19 09:37	Photo After Spray	0	Load JPG	€	
56	22/03/19 09:37	Photo After Spray	0	Load JPG	•	
57	22/03/19 09:37	Photo After Spray	0	Load JPG	•	
58	22/03/19 09:37	Photo After Spray	0	Load JPG	•	
59	22/03/19 09:37	Photo After Spray	0	Load JPG	•	
60	22/03/19 09:37	Photo After Spray	0	Load JPG	•	

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.	

Adjuster Report

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG19003973/GCD3S2

Date:

28/03/2019

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100242312

Claimant Vehicle No:

SLK4512M

Insured Vehicle No:

SKB8238M

Date of Loss:

23/02/2019

Nature of Claim:

Claim No: 2839194231SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

**SLK4512M** 

Make & Model:

MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)

Engine No:

P520420889

Reg. Date:

Grey

17/01/2017 (Man. Year: 2016)

Chassis No: Odometer:

JM6BN22A8H0135636

Colour: Engine Capacity:

1496 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

99110 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/60R16

Rear Tyre Size:

205/60R16

Front Left Side:

CST 6 mm

Rear Left Side:

CST 6 mm

Front Right Side:

CST 6 mm

Rear Right Side:

CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

04/03/2019

Motor Intelligence Automo Pte Ltd (HQ)

Date Inspected:

04/03/2019 Inspected At:

13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ

CENTRE

Singapore 417807

Estimated Period of Repair:

4.0 days

XING GUO QIANG Adjuster:

Manager:

CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

	commende	리아() : [ TIN () :	0.000	Described.	
No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Bent	0.00 F	*- F
2	1	*FRONT SUPPORT TOP COVER	Broken	0.00 F	*-F
3	1	*FRONT SUPPORT PANEL TOP COVER CLIPS	Necessary	0.00 F	*-F
4	1	*FRONT BUMPER	Deformed	0.00 F	*-F
5	1	*FRONT BUMPER REINFORCEMENT	Bent	0.00 F	*-F
6	10	*FRONT BUMPER CLIP	Necessary	0.00 F	*- F
7	1	*O/S FRONT BUMPER INDICATION LAMPS	Cracked	0.00 F	*-F
8	1	*O/S FRONT BUMPER INDICATION LAMPS GARNISH	Broken	0.00 F	*- F
9	1	*FRONT BUMPER LOWER GRILLE SIDE COVER	Missing	0.00 F	*- F
10	1	*RADIATOR GRILLE	Cracked	0.00 F	*-F
11	1	*RADIATOR GRILLE CHROME GARNISH	Cut	0.00 F	*- F
12	2	*HEADLAMP	Cut	0.00 F	*-F
13	1	*FRONT LICENCE PLATE BASE	Deformed	0.00 F	*-F
14	1	*FRONT LICENCE PLATE	Bent	0.00 F	*- F
15	1	*FRT BUMPER LOWER GRILLE	Deformed	0.00 F	*-F
16	1	*RADIATOR GRILLE LOGO	Necessary	0.00 F	*-F
17	1	*RADIATOR GRILLE INNER GARNISH BASE	Cracked	0.00 F	*- F
18	2	*BONNET HINGE	Bent	0.00 F	*- F
19	1	*FRT BUMPER TOP COVER	Deformed	0.00 F	*- F
20	2	*SUPPORT PANEL SIDE BRACKET	Broken	0.00 F	*- F
21	2	*FRT FENDERS	Repair	0.00 F	*- F
F=Fr	anchise part.			univ.	
			Total Parts (S\$)	0.00	0.00

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >