

11/92110

INS. CASE OWNER:

CC 4/LPC1900

3983

U/K6352

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time: 08/03/19

Sent By: b3

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

SS

3,435.87

(3 days) Reduction:

74

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Cal

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 0%

Repair Cost:

(w/6M)

SS

3719.18

Loss of Rental (LOR):

(w/6M)

SS

321.00

(3 days) x \$100

Loss of Use (LOU):

SS

-

(\$ x days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

4042.18

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4042.18

Name 1:

Trans-Eurokars Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

-

Payee 3: (Strike if N.A.)

SS

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$450

REF:

UPC

ASSIGNMENT

From

Date:

02/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SMH 2767L

at Workshop m/s

Trans Eurokars

of

5 Unit Close, SL 408605

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 37928

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMH/2767L

Yr Regn:

1 / 19

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make:

made 3 hatchback 1496

Colour:

Grey

A/C. Insured / Std / NI / NA

Sp. Reading:

2245

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BN24A8K0251716

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/60218

DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

1/3/19

D.O.I.

7/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear A/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P \$3,475.87

(GAP: \$12,189.80/77%)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1) 5.00

2) 0.00

3) 0.00

4)

TOTAL

Report Format:

Lump Sum / LB: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Workshop (\$)



Auto
Consultants
Pte Ltd

Company Registration No: 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19003983/Uhb3

Date: 08.03.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SMH2767L

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 07.03.2019 at the premises of M/s Trans Eurokars Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	15,665.67
Revised Estimate Amount	: S\$	3,475.87
"Check" Items Amount	: S\$	96.03
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



TRANS EUROKARS PTE LTD

ESTIMATE COST OF REPAIRS

EUROKARS GROUP

LONPAC INSURANCE BHD
 100 BEACH ROAD
 #19-00 SHAW TOWER
 SINGAPORE 189702
 ATTN.: MOTOR CLAIMS
 FAX:

NAME: Ms Tan Chen Hoon
ADDRESS: 816 Jellicoe Road
 #15-06
 Singapore 200816
TEL: 90478290

WIP: 44869
EXCESS:
DATE: 1-Mar-19

VEH NO: SMH2767L
CHASSIS NO: JM6BN24A8K0251716
MODEL: MAZDA3

DATE IN:
MILEAGE:
DATE REG.: 17-Jan-19

CONTACT PERSON: Ronald 63957875
TYPE OF CLAIM: OWN DAMAGED CLAIM
POLICY NO.:

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES		
1	REAR BUMPER	1	MB63B-50-221ABB	2.5	\$ 949.20
2	RETAINER LHS	1	MBHN9-50-2J1C	3.4	\$ 35.60
3	BRACKET LHS	1	MBHN9-51-077B	1.1	\$ 45.60
4	BRACKET CENTER	1	MKD53-50-251	1.1	\$ 5.10
5	PROTECTOR CENTER, REAR BUMPER	1	MBHN9-50-369	1.1	\$ 56.00
6	COVER LOWER LHS, REAR BUMPER	1	MB63D-50-371	2.5	\$ 29.10
7	REAR REINFORCEMENT	1	MB45C-50-260	1.1	\$ 537.30
8	SHIELD SPLASH LHS	1	MBHN9-50-350C	1.1	\$ 77.60
9	REFLECTOR LHS	1	MD350-51-5LOE	5.0	\$ 50.40
10	GROMMET, REAR BUMPER	4	MBHN1-50-021A	2.0	\$ 10.00
11	RIVET, REAR BUMPER	10	MB8M4-50-355	2.0	\$ 42.00
12	RIVET, REAR BUMPER	2	MEA01-50-037	2.0	\$ 15.20
13	CLIP, REAR BUMPER	2	MBGV4-56-145	2.0	\$ 5.40
14	GROMMET, REAR BUMPER	2	M9991-00-501	2.0	\$ 5.60
15	REAR END PANEL	1	MB4YC-70-75ZA	1.1	\$ 624.70
16	PANEL LOWER LHS, REAR FENDER	1	MB4YC-71-40X	1.1	\$ 354.40
17	EXTRACTOR VENT LHS	1	MD350-51-920A	1.1	\$ 71.30
18	TRIM, END PANEL	1	MBHN9-68-89X	1.1	\$ 95.90
19	FASTENER, TRIM	5	MGJ21-68-885B02	1.1	\$ 14.00
20	TAILGATE	1	MBHY3-62-02XA	1.1	\$ 1,268.70
21	GROMMET, FINISHER TAILGATE	1	MBHN9-50-ES1	1.1	\$ 2.70
22	CLIP, FINISHER TAILGATE	4	MBHY1-51-0A6A	1.1	\$ 38.40
23	CLIP, FINISHER TAILGATE	1	MKD53-51-0B6B	1.1	\$ 2.50
24	CLIP, FINISHER TAILGATE	3	MKD53-51-0B6B	1.1	\$ 7.50
25	FASTENER, FINISHER TAILGATE	2	MBHN9-50-EA1	1.1	\$ 5.40
26	GASKET LHS, TAILGATE LAMP	1	MB45C-51-3J8	1.1	\$ 20.90
27	GASKET RHS, TAILGATE LAMP	1	MB45C-51-3H8	1.1	\$ 20.90
28	GASKET LHS, TAILLAMP	1	MBHP1-51-163	1.1	\$ 20.90
29	GASKET RHS, TAILLAMP	1	MBHP1-51-153	1.1	\$ 20.90
30	MASCOT, REAR	1	MBHN9-51-730	1.1	\$ 74.40

31	REAR WINDSCREEN MOULDING	1	MBHN9-50-614F	17	\$	47.50	X
32	SPACER, REAR WINDSCREEN	1	MGJ6A-50-897	17	\$	12.10	X
33	FASTENER, REAR WINDSCREEN	2	MD204-50-896A	17	\$	5.20	X
34	FASTENER, REAR WINDSCREEN	2	MBHS2-50-896	17	\$	17.40	X
35	GUARD STONE LHS	1	MBHS2-50-4R2	17	\$	16.50	X
					TOTAL PARTS	\$	4,606.30
					LESS 10%	\$	460.63
					TOTAL PARTS COST	\$	4,145.67
Labour Description							
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, PANEL LOWER LH AND TAILGATE. TO REPAIR REAR FENDER LH AND ALL AREAS AFFECTED BY THE ACCIDENT.			660	\$	4,290.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, PANEL LOWER LH, REAR FENDER LH AND TAILGATE.			1260	\$	3,150.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.			17	X	NETT \$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.			17	X	NETT \$ 120.00
5	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.			17	X	\$ 330.00
6	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)			200	NETT	\$ 330.00
7	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.			17	X	\$ 330.00
8	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.			17	X	\$ 990.00
9	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING			17	X	\$ 350.00
10	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			17	X	\$ 250.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			120		\$ 250.00
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			150		\$ 350.00
13	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.			17	X	NETT \$ 120.00
14	MZ-BR-SUNDRI	SUNDRIES.			all 20	NETT	\$ 100.00
					TOTAL LABOUR	\$ -	\$ 11,520.00
					TOTAL PARTS	\$ -	\$ 4,145.67
					TOTAL	\$ -	\$ 15,665.67
					LESS EXCESS	\$ -	\$ -

TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

Let's Agree! Consultants service notify the Repaired of the following:

- Temporary vehicle use spray painting
- Temporary damaged parts during recovery
- Photo record and subsequent information
- Temporary storage in a "No Loss/Prejudice" basis
- No other work should be allowed
- Suppliers only use - should be notified and is subject to approval from Insurance Company

Acknowledged by Repaired

Signature:

Date:



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

LONPAC INSURANCE BHD 100 BEACH ROAD #19-00 SHAW TOWER SINGAPORE 189702 ATTN : MOTOR CLAIMS FAX :		NAME : Ms Tan Chen Hoon ADDRESS : 816 Jellicoe Road #15-06 Singapore 200816 TEL : 90478290		WIP : 44869 EXCESS : DATE: 1-Mar-19	
VEH NO :	SMH2767L	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6BN24A8K0251716	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	17-Jan-19	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MB63B-50-221ABB	\$ 949.20	\$ 949.20
2	RETAINER LHS	1	MBHN9-50-2J1C	\$ 35.60	\$ 35.60
3	BRACKET LHS	1	MBHN9-51-077B		\$ 45.60
4	BRACKET CENTER	1	MKD53-50-251		\$ 5.10
5	PROTECTOR CENTER, REAR BUMPER	1	MBHN9-50-369		\$ 56.00
6	COVER LOWER LHS, REAR BUMPER	1	MB63D-50-371	\$ 29.10	\$ 29.10
7	REAR REINFORCEMENT	1	MB45C-50-260		\$ 537.30
8	SHIELD SPLASH LHS	1	MBHN9-50-350C		\$ 77.60
9	REFLECTOR LHS	1	MD350-51-5L0E	\$ 50.40	\$ 50.40
10	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ 10.00	\$ 10.00
11	RIVET, REAR BUMPER	10	MBBM4-50-355	\$ 42.00	\$ 42.00
12	RIVET, REAR BUMPER	2	MEA01-50-037	\$ 15.20	\$ 15.20
13	CLIP, REAR BUMPER	2	M8GV4-56-145	\$ 5.40	\$ 5.40
14	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 5.60	\$ 5.60
15	REAR END PANEL	1	MB4YC-70-75ZA		\$ 624.70
16	PANEL LOWER LHS, REAR FENDER	1	MB4YC-71-40X		\$ 354.40
17	EXTRACTOR VENT LHS	1	MD350-51-920A		\$ 71.30
18	TRIM, END PANEL	1	MBHN9-68-89X		\$ 95.90
19	FASTENER, TRIM	5	MGJ21-68-885B02		\$ 14.00
20	TAILGATE	1	MBHY3-62-02XA		\$ 1,268.70
21	GROMMET, FINISHER TAILGATE	1	MBHN9-50-ES1		\$ 2.70
22	CLIP, FINISHER TAILGATE	4	MBHY1-51-0A6A		\$ 38.40
23	CLIP, FINISHER TAILGATE	1	MKD53-51-0B6B		\$ 2.50
24	CLIP, FINISHER TAILGATE	3	MKD53-51-0B6B		\$ 7.50
25	FASTENER, FINISHER TAILGATE	2	MBHN9-50-EA1		\$ 5.40
26	GASKET LHS, TAILGATE LAMP	1	MB45C-51-3J8		\$ 20.90
27	GASKET RHS, TAILGATE LAMP	1	MB45C-51-3H8		\$ 20.90
28	GASKET LHS, TAILLAMP	1	MBHP1-51-163	\$ 20.90	\$ 20.90
29	GASKET RHS, TAILLAMP	1	MBHP1-51-153	\$ 20.90	\$ 20.90
30	MASCOT, REAR	1	MBHN9-51-730		\$ 74.40
31	REAR WINDSCREEN MOULDING	1	MBHN9-50-614F		\$ 47.50

32	SPACER, REAR WINDSCREEN	1	MGJ6A-50-897		\$	12.10
33	FASTENER, REAR WINDSCREEN	2	MD204-50-896A		\$	5.20
34	FASTENER, REAR WINDSCREEN	2	MBHS2-50-896		\$	17.40
35	GUARD STONE LHS	1	MBHS2-50-4R2		\$	16.50
			TOTAL PARTS	\$	1,184.30	\$ 4,606.30
			LESS 10%	\$	118.43	\$ 460.63
			TOTAL PARTS COST	\$	1,065.87	\$ 4,145.67

Labour Description

1	MZ-BR-REAR05	TO REPLACE REAR BUMPER. REPAIR AREAS AFFECTED BY THE ACCIDENT.	\$	660.00	\$	4,290.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR END PANEL AND TAILGATE.	\$	1,260.00	\$	3,150.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.			\$	560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.			\$	120.00
5	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.			\$	330.00
6	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	\$	200.00	\$	330.00
7	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.			\$	330.00
8	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.			\$	990.00
9	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING			\$	350.00
10	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$	250.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$	120.00	\$	250.00
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$	150.00	\$	350.00
13	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.			\$	120.00
14	MZ-BR-SUNDRI	SUNDRIES.	\$	20.00	\$	100.00

TOTAL LABOUR	\$	2,410.00	\$	11,520.00
TOTAL PARTS	\$	1,065.87	\$	4,145.67
TOTAL	\$	3,475.87	\$	15,665.67
LESS EXCESS	\$	-	\$	-
TOTAL AFTER EXCESS	\$	3,475.87		
GST 7%	\$	243.31	\$	-
GRAND TOTAL	\$	3,719.18	\$	-

REMARKS:

4 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



TRANS EUROKARS PTE LTD

ESTIMATE COST OF REPAIRS

Not Admit
 2hr notice.
 7/3/19
 3dy.
 7/3/19
 Eurokars Group

LONPAC INSURANCE BHD		NAME : Ms Tan Chen Hoon		WIP : 44869	
100 BEACH ROAD		ADDRESS : 816 Jellicoe Road		EXCESS :	
#19-00 SHAW TOWER		#15-06		DATE : 1-Mar-19	
SINGAPORE 189702		Singapore 200816			
ATTN. : MOTOR CLAIMS		TEL : 90478290			
FAX :					
VEH NO :	SMH2767L	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6BN24A8K0251716	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA3	DATE REG.:	17-Jan-19	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	REAR BUMPER	1	MB63B-50-221ABB	DS \$ 949.20
2	RETAINER LHS	1	MBHN9-50-2J1C	buy \$ 35.60
3	BRACKET LHS	1	MBHN9-51-077B	\$ 45.60
4	BRACKET CENTER	1	MKD53-50-251	\$ 5.10
5	PROTECTOR CENTER, REAR BUMPER	1	MBHN9-50-369	\$ 56.00
6	COVER LOWER LHS, REAR BUMPER	1	MB63D-50-371	m.s \$ 29.10
7	REAR REINFORCEMENT	1	MB45C-50-260	R \$ 537.30
8	SHIELD SPLASH LHS	1	MBHN9-50-350C	11 \$ 77.60
9	REFLECTOR LHS	1	MD350-51-5L0E	520 \$ 50.40
10	GROMMET, REAR BUMPER	4	MBHN1-50-021A	ru \$ 10.00
11	RIVET, REAR BUMPER	10	MBBM4-50-355	ru \$ 42.00
12	RIVET, REAR BUMPER	2	MEA01-50-037	ru \$ 15.20
13	CLIP, REAR BUMPER	2	MBGV4-56-145	ru \$ 5.40
14	GROMMET, REAR BUMPER	2	M9991-00-501	ru \$ 5.60
15	REAR END PANEL	1	MB4YC-70-75ZA	R \$ 624.70
16	PANEL LOWER LHS, REAR FENDER	1	MB4YC-71-40X	11 \$ 354.40
17	EXTRACTOR VENT LHS	1	MD350-51-920A	11 \$ 71.30
18	TRIM, END PANEL	1	MBHN9-68-89X	11 \$ 95.90
19	FASTENER, TRIM	5	MGJ21-68-885B02	11 \$ 14.00
20	TAILGATE	1	MBHY3-62-02XA	11 \$ 1,268.70
21	GROMMET, FINISHER TAILGATE	1	MBHN9-50-ES1	11 \$ 2.70
22	CLIP, FINISHER TAILGATE	4	MBHY1-51-0A6A	11 \$ 38.40
23	CLIP, FINISHER TAILGATE	1	MKD53-51-0B6B	11 \$ 2.50
24	CLIP, FINISHER TAILGATE	3	MKD53-51-0B6B	11 \$ 7.50
25	FASTENER, FINISHER TAILGATE	2	MBHN9-50-EA1	11 \$ 5.40
26	GASKET LHS, TAILGATE LAMP	1	MB45C-51-3J8	11 \$ 20.90
27	GASKET RHS, TAILGATE LAMP	1	MB45C-51-3H8	11 \$ 20.90
28	GASKET LHS, TAILLAMP	1	MBHP1-51-163	ru \$ 20.90
29	GASKET RHS, TAILLAMP	1	MBHP1-51-153	11 \$ 20.90
30	MASCOT, REAR	1	MBHN9-51-730	11 \$ 74.40

31	REAR WINDSCREEN MOULDING	1	MBHN9-50-614F	17	\$	47.50	X
32	SPACER, REAR WINDSCREEN	1	MGJ6A-50-897	17	\$	12.10	X
33	FASTENER, REAR WINDSCREEN	2	MD204-50-896A	17	\$	5.20	X
34	FASTENER, REAR WINDSCREEN	2	MBHS2-50-896	17	\$	17.40	X
35	GUARD STONE LHS	1	MBHS2-50-4R2	17	\$	16.50	X

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4953J
Vehicle Details	
Vehicle No.:	SMH2767L
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Mar 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 HATCHBACK 1.5 AT STANDARD EU6
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	P520551280
Chassis No.:	JM6BN24A8K0251716
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$16,506.00
Original Registration Date:	17 Jan 2019
First Registration Date:	17 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$16,506.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jan 2029
PARF Rebate Amount:	\$12,379.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jan 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,920.00
COE Rebate Amount:	\$25,550.00
Total Rebate Amount:	\$37,929.00

The information contained herein is correct as at 07 Mar 2019

OK

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 4 March 2019 11:33 AM
To: ronald.yap@eurokars.com.sg; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: jess.francis@eurokars.com.sg; samuel.ng@eurokars.com.sg; MT_Claim_SG
Subject: RE: Our Ref: 18/19/19/VP05/021474 ARRANGE FOR SURVEY / YOUR REF: SGT2947S
/ OUR REF: SMH2767L [External General]
Attachments: 1754_190301173205_001.pdf

Lonpac External - General

Without Prejudice

Dear Ronald


Please email to mt_claim@lonpac.com for all future cases.

Our Insured has not reported the accident to us.

If you still wish to pursue TP claims, please liaise with LKK Auto Consultants Pte Ltd for survey and assessment of liability.

Dear Catherine/Nivitha

Fya
Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: ronald.yap@eurokars.com.sg [mailto:ronald.yap@eurokars.com.sg]
Sent: Friday, 1 March, 2019 5:19 PM
To: ONG LI LI
Cc: jess.francis@eurokars.com.sg; samuel.ng@eurokars.com.sg
Subject: ARRANGE FOR SURVEY / YOUR REF: SGT2947S / OUR REF: SMH2767L

Dear Li Li,

As per subject / attached, let us have your appointed surveyor for arrangements.

Thank You,

*Ronald Yap
Insurance Claims*

Trans Eurokars Pte Ltd

5 Ubi Close, Singapore 408605

T: 6395 8899 H: 9127 7928

ronald.yap@eurokars.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg <transeurokars@eurokars.com.sg>

Sent: 01 March 2019 17:32

To: Ronald Yap <ronald.yap@eurokars.com.sg>

Subject: Attached Image

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19003983/Udb3s2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 04-02-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGT 2947S	Veh. Inspected	SMH 2767L
Policy No.	Z18VP05018053	Coverage (\$)	0.00
Claim No.	18/19/19/VP05/021474	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	04/03/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 HATCHBACK (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JM6BN24A8K0251716	Colour	GREY
Odometer	2245	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60R16	BRIDGESTONE	8 mm
L/H Front Tyre	205/60R16	BRIDGESTONE	8 mm
R/H Rear Tyre	205/60R16	BRIDGESTONE	8 mm
L/H Rear Tyre	205/60R16	BRIDGESTONE	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/03/2019	Inspection Date	07/03/2019
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 2767L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DISTORTED	949.20	949.20
1	RETAINER LHS	BENT	35.60	35.60
1	BRACKET LHS	NOT NECESSARY	45.60	-
1	PROTECTOR CENTER, REAR BUMPER	NOT NECESSARY	56.00	-
1	COVER LOWER LHS, REAR BUMPER	MISSING	29.10	29.10
1	REAR REINFORCEMENT	TO REPAIR SEE LABOUR	537.30	-
1	SHIELD SPLASH LHS	NOT NECESSARY	77.60	-
1	REFLECTOR LHS	BROKEN	50.40	50.40
4	GROMMET, REAR BUMPER	NECESSARY	10.00	10.00
10	RIVET, REAR BUMPER	NECESSARY	42.00	42.00
2	RIVET, REAR BUMPER	NECESSARY	15.20	15.20
2	CLIP, REAR BUMPER	NECESSARY	5.40	5.40
2	GROMMET, REAR BUMPER	NECESSARY	5.60	5.60
1	REAR END PANEL	TO REPAIR SEE LABOUR	624.70	-
1	PANEL LOWER LHS, REAR BUMPER	NOT NECESSARY	354.40	-
1	EXTRACTOR VENT LHS	NOT NECESSARY	71.30	-
1	TRIM, END PANEL	NOT NECESSARY	95.90	-
5	FASTENER, TRIM	NOT NECESSARY	14.00	-
1	TAILGATE	NOT NECESSARY	1,268.70	-
1	GROMMET, FINISHER TAILGATE	NOT NECESSARY	2.70	-
4	CLIP, FINISHER TAILGATE	NOT NECESSARY	38.40	-
1	CLIP, FINISHER TAILGATE	NOT NECESSARY	2.50	-
3	CLIP, FINISHER TAILGATE	NOT NECESSARY	7.50	-
2	FASTENER, FINISHER TAILGATE	NOT NECESSARY	5.40	-
1	GASKET LHS, TAILGATE LAMP	NOT NECESSARY	20.90	-
1	GASKET RHS, TAILGATE LAMP	NOT NECESSARY	20.90	-
1	GASKET LHS, TAILLAMP	NECESSARY	20.90	20.90
1	GASKET RHS, TAILLAMP	NECESSARY	20.90	20.90
1	MASCOT, REAR	NOT NECESSARY	74.40	-

Report Ref No. CC4/LPC19003983/Udb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	47.50	-
1	SPACER, REAR WINDSCREEN	NOT NECESSARY	12.10	-
2	FASTENER, REAR WINDSCREEN	NOT NECESSARY	5.20	-
2	FASTENER, REAR WINDSCREEN	NOT NECESSARY	17.40	-
1	GUARD STONE LHS	NOT NECESSARY	16.50	-
1	BRACKET CENTER	NOT NECESSARY	5.10	-
	LESS 10% DISCOUNT		-460.63	-118.43
			4,145.67	1,065.87
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, PANEL LOWER LH AND TAILGATE. TO REPAIR REAR FENDER LH AND ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR REINFORCEMENT AND REAR END PANEL.		4,290.00	660.00
	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, PANEL LOWER LH, REAR FENDER LH AND TAILGATE.		3,150.00	1,260.00
	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NOT NECESSARY	560.00	-
	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	TO TRANSFER TAILGATE MECHANISM.	NOT NECESSARY	330.00	-
	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)		330.00	200.00
	TO TRANSFER REVERSE CAMERA.	NOT NECESSARY	330.00	-
	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	NOT NECESSARY	990.00	-
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.	NOT NECESSARY	350.00	-
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	150.00

Report Ref No. CC4/LPC19003983/Udb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	NOT NECESSARY	120.00	-
			11,420.00	2,390.00
GRAND TOTAL			15,665.67	3,475.87
RECOMMENDED COST OF REPAIRS				3,475.87

Report Ref No. CC4/LPC19003983/Udb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.