

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5177A**AAD1902-242***Not Authen**Resumy Bk pain**8173P.50*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5177A

JTDKB3FU703078482

TOYOTA

PRIUS

28.2.2019

AXA

19/12/2018

PART**LIST**

1	1 REAR BUMPER	\$	<i>Bu</i>	458.60	<i>✓</i>
2	1 REAR BUMPER RE-INFORCEMENT	\$	<i>Bu</i>	318.80	<i>✓</i>
3	1 REAR BUMPER TOWING COVER	\$	<i>SL</i>	14.70	<i>X</i>
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	<i>Bu</i>	552.60	<i>✓</i>
5	1 REAR BUMPER SIDE RETAINER LH	\$	<i>SL</i>	112.70	<i>X</i>
6	1 REAR BUMPER SIDE RETAINER RH	\$	<i>SL</i>	112.70	
7	1 REAR TAILGATE	\$	<i>R</i>	1,547.27	
8	1 REAR TAILGATE OUTER GARNISH	\$	<i>SL</i>	905.10	
9	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>SL</i>	54.70	
10	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>SL</i>	54.70	
11	1 GARNISH, BACK DOOR SIDE, LH	\$	<i>SL</i>	93.60	
12	1 GARNISH, BACK DOOR SIDE, RH	\$	<i>SL</i>	93.60	
13	1 BOARD ASSY, BACK DOOR TRIM	\$	<i>SL</i>	254.40	
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>SL</i>	51.20	
15	1 REAR TAILGATE WEATHERSTRIP	\$	<i>SL</i>	365.20	<i>X</i>
16	1 REAR END PANEL	\$	<i>R</i>	602.10	
17	1 TAILLAMP LOWER RH	\$	<i>SL</i>	548.40	
18	1 TAILLAMP UPPER RH	\$	<i>SL</i>	557.90	
19	1 REAR BUMPER SIDE RH	\$	<i>SL</i>	232.00	
20	1 REAR BUMPER SIDE LH	\$	<i>SL</i>	232.00	
21	1 TAILLAMP LOWER LH	\$	<i>SL</i>	548.40	<i>X</i>
22	1 TAILLAMP UPPER LH	\$	<i>SL</i>	557.90	
		\$		8,268.57	
		25% \$		2,067.14	
		\$		6,201.43	

Special Nett

1 1SET PARKING AID

\$ *nd* 700.00 *2505m*

Trans-cab Auto Services Pte Ltd

AAD1902-242

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5177A

2	1SET REAR BUMPER CLIP	\$	22.00	
3	2 REAR WINDSCREEN SELANT	\$	80.00	
4	1 WINDSCREEN MOULDING	\$	100.00	
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
6	1 REAR TAILGATE TOYOTA LOGO	\$	47.00	
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	52.90	
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	53.50	
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	80.00	
10	1 REAR TAILGATE STICKER '6555-3333'	\$	80.00	
11	1 REAR BUMPER PROTECTOR	\$	100.00	

TOTAL \$ 1,315.40

TOTAL PARTS \$ 7,516.83

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To Rust-Proofing Of The Affected Areas.	\$	170.00	nn X
To reinstall rear bumper parking sensor.	\$	170.00	501
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	nn X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	nn X
To repair and realign rear exhaust pipe.	\$	170.00	nn X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	nn X

Trans-cab Auto Services Pte Ltd**AAD1902-242**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5177A

To transfer of rear end panel fittings, attachment and
perform water seepage test.

\$ *nn* 170.00 X

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *7* 170.00 X

To check steering geometry and computer wheel
alignment

\$ *7* 220.00 X**TOTAL \$ 7,580.00****Over All Total \$ 21,298.26****(PART-BY-PART) Repair Days***10 DAYS**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: