

LKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To identify damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TO:
Acknowledged by RepairerSignature: **ESTIMATE REPORT**

1ST Quotation

Date: **OWNER'S PARTICULARS**

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

FAX NO:

02/03/2019 15:55

JOB-NO: 50111449

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHA8262H

TRANS: AUTO

CHASSIS: KMHLB41UMGU080528

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDFU562235

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	
2 R&R RADIATOR & CONDENSER & TURBO INNER COOLER	1.00	250.00	0.00	250.00		Y	
3 TO ADJUST HEADLAMP & CHECK WATER LEAK	1.00	60.00	0.00	60.00	X	Y	
4 TO VACUUM & TOP UP AIRCON GAS R134A	1.00	200.00	0.00	200.00		Y	
5 TO RUST PROOFING ON ACCIDENT AFFECTED AREAS	1.00	80.00	0.00	80.00		Y	
6 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	
7 RESPRAY FRONT FENDER RH	1.00	250.00	0.00	250.00		Y	
8 RESPRAY FOG LAMP COVER RH	1.00	100.00	0.00	100.00	X	Y	
TOTAL:		2,190.00	0.00	2,190.00			
MATERIALS							
1 FRONT HEADLAMP RH / BR	1.00	1,808.08	361.62	1,446.46	L	Y	
2 FRONT BUMPER / BR	1.00	599.68	119.94	479.74	L	Y	
3 FRONT BUMPER SPONGE X NNI	1.00	99.68	19.94	79.74	L	Y	
4 FRONT BUMPER RETAINER RH / BR	1.00	42.32	8.46	33.86	L	Y	
5 FRONT BUMPER FOG LAMP COVER RH / CR4	1.00	178.55	35.71	142.84	L	Y	
6 FRONT FENDER RH X R	1.00	659.50	131.90	527.60	L	Y	
7 FRONT FENDER COWLING RH / CR4	1.00	185.12	37.02	148.10	L	Y	
8 FRONT WHEEL RIM COVER RH / CUT	1.00	265.20	53.04	212.16	L	Y	
9 FRONT BUMPER AIR DUCT RH X NNI	1.00	67.80	13.56	54.24	L	Y	
10 FRONT SUPPORT PANEL BRACKET RH X NNI	1.00	38.62	7.72	30.90	L	Y	
11 FRONT SUPPORT PANEL BRACKET LH X NNI	1.00	38.62	7.72	30.90	L	Y	
12 FRONT SUPPORT PANEL / BR	1.00	962.87	192.57	770.30	L	Y	
13 FRONT BUMPER CLIPS SET / MC	1.00	35.00	0.00	35.00	S	Y	
14 FRONT FENDER COWLING CLIPS SET / NEC	1.00	35.00	0.00	35.00	S	Y	
15 FRONT FENDER ADS STICKER RH / NEC	1.00	100.00	0.00	100.00	S	Y	
16 FRONT TYRE RH X NNI	1.00	180.00	0.00	180.00	S	Y	
17 COOLANT / NEC	1.00	60.00	0.00	60.00	S	Y	
TOTAL:		5,356.04	989.20	4,366.84			
TOTAL PARTS & LABOUR:		7,546.04	989.20	6,556.84			

EXCESS/LOADING:\$S 0.00

No. Of Day: _____

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: S\$ _____

DATE OF SURVEY: ____ / ____ / ____

SURVEYED BY: _____

CONTACT NO: _____ FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL: _____ FAX: _____