

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0269/2019/GW
Date	:	1-Mar-19

Vehicle IN workshop.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Ng Tze Kwok, Ben Jamin
Address	:	Blk 7 Tampines Avenue 8 #01 -09 Singapore 529597
Telephone	:	97762367
Type of Claim	:	Own Damage Claims
Policy No.	:	1800038355
Vehicle No	:	SLX 8692 G
Model Code	:	A3 SB 1.0 TFSI
Model / Year	:	14/4/2018
Engine No	:	CH2 678168
Chassis No	:	WAUZZZ8V3JA087063
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-Feb-19
Place of Accident	:	PIE Tuas 12.6KM L1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 8692 G

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To tow and recovery vehicle from scene of accident.	S/N	WAIVE	✓
2	To carry out first measurement test on car O-liner.	S/N \$	800.00	?
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	✓
4	To remove and transfer both front door's multi-lock system and power window devices. Inspect for damages and renew if necessary.	S/N \$	560.00	X
5	To remove and renew air condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	✓
6	To remove center console, instrument panels and clusters. Rene dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and knee airbag.	S/N \$	3,600.00	✓
SUB-TOTAL LABOUR CHARGES		:	\$ 6,520.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 8692 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
7	To renew front windscreen.	S/N \$ 480.00 ✓	
8	To remove and reinstall engine assy with gearbox assy to facillitate car -o-liner repairs.	S/N \$ 2,800.00 ?	
9	To remove and reinstall front suspension assy with subframe to facillitate car -oliner repairs. Inspect for damages and renew if necessary .	S/N \$ 2,400.00 ?	
10	To place vehicle on car- o-liner.	S/N \$1,800.00 ?	
11	To dismantle and renew front bumper, bonnet and both front fenders, both headlights and both front doors. Cut out and reweld lhs fender support and closing element. Align both front chassis frames to specification of origin. Renew front lock carrier and align to position. re-organise front crash management components. reinsall all parts removed.	\$10,200.00 3500.	Excluding Engine Bay.
12	✓ To respray front bumper, both front fenders, bonnet, hinges, both upper A-pillar, lhs fender top support, both front doors and engine compartment. To carry out joint sealant work and stone chip treatment.	\$7,700.00	
SUB-TOTAL LABOUR CHARGES		: \$ 25,380.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 8692 G

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
13	To carry out wheel alignment.	S/N	\$240.00	
14	To carry out diagnostic check.	S/N	\$384.00	
TOTAL LABOUR CHARGES		:	<u>\$32,524.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLX 8692 G**

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
1	FRONT BUMPER <i>Distorted</i>	\$	1,698.00 ✓	
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	170.00 ✗	
3	FRONT BUMPER GUIDE SECTION-LH/RH <i>new</i>	2 \$	70.00 ✗	/ MIS RH, LH
4	FRONT BUMPER GRILLE-CENTER	\$	146.00 ✗	
5	FRONT BUMPER CLOSING ELEMEN-LOWER CENTRE	\$	270.00 ✓	
6	FRONT BUMPER CLOSING ELEMEN-LH /RH	2 \$	540.00 ✗	LH - OR PH / MH
7	RADIATOR GRILLE <i>Smashed</i>	\$	1,301.00 ✓	
8	RADIATOR GRILLE CLOSING ELEMENT <i>smashed</i>	\$	174.00 ✓	
9	FRONT BUMPER AIR GUIDE GRILLE-LH/RH <i>new</i>	2 \$	342.00 ✗	
10	FOAM FILLER PIECE <i>old</i>	\$	172.00 ✓	
11	FRONT BUMPER SIDE REINFORCEMENT <i>but</i>	\$	670.00 ✓	
12	FRONT BUMPER COVER <i>smashed</i>	\$	111.00 ✓	
13	AIR CONDITIONER STICKER <i>new</i>	\$	7.00 ✓	
14	SIGN " CAUTION "	\$	13.00 ✓	
15	SIGNAL HORN "HIGH TONE"	\$	182.00 ✗	
16	SIGNAL HORN "LOW TONE"	\$	182.00 ✗	
17	BONNET <i>Distorted</i>	\$	2,501.00 ✓	
18	BONNET ATTACHMENT PARTS <i>new</i>	\$	149.00 ✓	
19	BONNET LIG HINGE-LH/RH <i>but</i>	2 \$	112.00 ✓	
20	BONNET GAS FILLED STRUT <i>Damaged</i>	\$	109.00 ?	
SUB TOTAL SPARE PARTS			\$ 8,919.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLX 8692 G**

S/N	Parts Description	<u>Damaged Parts & Prices</u>		Remark
		S/Nett		
21	BONNET EDGE PROTECTION- FRONT <i>Lt</i>	\$	25.00 ✓	
22	BONNET CATCH HOOK <i>Best</i>	\$	81.00 ✓	
23	BONNET STRIKER-LH/RH <i>Dmgd</i>	2 \$	200.00 ✓	
24	BONNET RUBBER SEAL <i>Lt</i>	\$	53.00 ✓	
25	FRONT ADAPTER-LH/RH ?	2 \$	24.00 ?	
26	BONNET CATCH HOOL ?	\$	58.00 ?	
27	BONNET LID LOCK WITH MICRO SWITCH <i>Dmgd</i>	2 \$	367.00 ✓	
28	BONNET LOCK LATCH COVER <i>me</i>	2 \$	7.00 ✓	
29	BONNET BOWDEN CABLE -CENTER ?	\$	53.00 ?	TN /
30	BONNET LOCK CABLE COVER ?	\$	9.00 ?	DR /
31	BONNET LID LOCK CABLE ?	\$	67.00 ?	TN /
32	BONNET SOUND ABSORBER <i>compbed</i>	\$	201.00 ✓	
33	PLENUM CHAMBER COVER ?	\$	164.00 ?	
34	FRONT WIPER COWL TRIM ?	\$	15.00 ✓	
35	FRONT FENDER-LH/RH <i>Buckled</i>	2 \$	1,556.00 ✓	
36	FRONT FENDER ATTACHMENT PARTS ?	2 \$	130.00 ?	
37	FRONT FENDER UPPER BRACKET-LH/RH } <i>new</i>	2 \$	50.00 x	
38	FRONT FENDER BRACKET-LH/RH	2 \$	86.00 x	RH- LH / OT
39	FRONT FENDER BRACE-LH/RH	2 \$	176.00 x	RH- LH / OT
40	FRONT FENDER CLOSING ELEMENT-LH/RH <i>new</i>	2 \$	112.00 x	LH- RH / OT
SUB TOTAL SPARE PARTS		\$	3,434.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 8692 G

S/N	Parts Description				Damaged Parts & Prices	
					S/Nett	Remark
41	FRONT FENDER SEAL STRIP-LH/RH	2	S	62.00	X	
42	FRONT WHEEL HOUSING LINER-LH/RH	2	S	316.00	X	
43	WHEEL HOUSING LINER ATTACHMENT PARTS	2	S	103.00	X	
44	FRONT FENDER CLOSING ELEMENT-LH		S	66.00	X	
45	LED HEADLIGHT-LH/RH	2	S	10,058.00	✓	
46	LED HEADLIGHT POWER MODULE	2	S	1,385.00	?	LH - RH / OK
47	LED WITH HEAT SINK-LH/RH	2	S	1,332.00	?	LH - RH / OK
48	LED HEADLIGHT CONTROL UNIT	2	S	1,015.00	?	RH / MIS LH / OK
49	LED HEADLIGHT LIFT CYLINDER-LH/RH	2	S	256.00	?	
50	WASH WATER RESERVOIR		S	186.00	X	
51	HOSE FOR LED HEADLIGHT WASHER SYSTEM		S	61.00	X	
52	LOCK CARRIER WITH MOUNTING FOR COOLANT RADIATOR		S	663.00	✓	
53	A/C CONDENSER WITH FLUID RESERVOIR		S	503.00	✓	
54	REFRIGERANT LINE FOR A/C CONDENSER		S	461.00	?	BT /
55	REFRIGERANT LINE FOR A/C CONDENSER CUT OFF POINT		S	601.00	?	
56	RADIATOR		S	878.00	✓	
57	ADDITIONAL RADIATOR		S	837.00	✓	
58	RADIATOR BUSH-LOWER	2	S	18.00	?	LH / MIS RH / MIS
59	RADIATOR BRACKET UPPER		S	77.00	?	LH - MIS RH / MIS
60	READY MIX COOLANT 1.5 LTR	4	S	84.00	✓	
SUB TOTAL SPARE PARTS				\$ 18,962.00		

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 8692 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	RADIATOR FAN WITH FAN RING ?	\$ 1,483.00	? OK /
62	AIR GUIDE-LH/RH <i>Combined</i>	2 \$ 44.00	✓
63	RADIATOR CORE SUPPORT SEAL <i>re</i>	\$ 8.00	✓
64	RADIATOR CORE SUPPORT AIR DUCT-UPPER CENTRE <i>re</i>	\$ 11.00	✓
65	AIR INTAKE AIR INLET <i>Combined</i>	\$ 53.00	✓
66	AIR INTAKE AIR BOX ?	\$ 62.00	?
67	INTERCOOLER GASKET ?	\$ 13.00	?
68	AIR FILTER ?	\$ 252.00	?
69	INTAKE MANIFOLD <i>How?</i>	\$ 129.00	Es ?
70	WATER DRAINAGE HOSE ?	\$ 31.00	?
71	PETROL ACTIVE CHARCOAL CONTAINER ?	\$ 294.00	?
72	FRONT DOOR-LH <i>Repair</i>	\$ 2,073.00	X
73	FRONT OUTER DOOR SEAL-LH <i>re re</i>	\$ 146.00	X
74	BONDING AGENT <i>3 same</i>	\$ 45.00	X
75	CLEANING SOLUTION	\$ 65.00	X
76	FRONT DOOR-RH <i>Repair</i>	\$ 2,073.00	X
77	FRONT OUTER DOOR SEAL-RH <i>2</i>	\$ 146.00	X
78	BONDING AGENT <i>3</i>	\$ 45.00	X
79	CLEANING SOLUTION <i>1st re</i>	\$ 65.00	X
80	APPLICATOR	\$ 7.00	X
SUB-TOTAL SPARE PARTS		\$ 7,045.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLX 8692 G**

S/N	Parts Description			Damaged Parts & Prices		Remark
				S/Nett		
81	FRONT DOOR ATTACHMENT PARTS-LH/RH	2	\$	436.00	✓	
82	FRONT DOOR CATCH	2	\$	191.00	✓	
83	FRONT DOOR CATCH COVER	2	\$	26.00	✓	
84	FRONT DOOR CHECK STRAP-LH/RH	2	\$	82.00	✓	
85	FRONT ROOF STRIP MOLDING-LH/RH	2	\$	1,074.00	✓	
86	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-LH/RH	2	\$	494.00	✓	
87	FRONT WINDSCREEN		\$	988.00	✓	
88	GEIL FOIL FOR RAIN SENSOR		\$	128.00	✓	
89	DATA PLATE FOR TYRE PRESSURE		\$	26.00	✓	
90	AIRBAG UNIT FOR STEERING WHEEL		\$	3,141.00	✓	
91	AIRBAG UNIT		\$	4,238.00	✓	
92	HEAD AIR BAG UNIT	2	\$	3,416.00	✓	
93	KNEE AIR BAG UNIT		\$	1,708.00	✓	
94	AIR BAG CONTROL UNIT		\$	1,606.00	✓	
95	AIR BAG CASH SENSOR		\$	1,145.00	✓	
96	SPORT STEERING WHEEL		\$	2,169.00		
97	DASH BOARD WITH AIR DUCT		\$	3,887.00	✓	
98	DASH BOARD PANEL UNDERTRAY -RH		\$	413.00	?	
99	HEADLINING		\$	1,809.00	✓	
100	FRONT A PILLAR COVER-LH/RH	2	\$	294.00	✓	
SUB- TOTAL SPARE PARTS				\$ 27,271.00		

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLX 8692 G**

S/N	Parts Description	<u>Damaged Parts & Prices</u>		Remark
		S/Nett		
101	FRONT GRAB HANDLE FOLDING-LH/RH <i>2</i>	2	\$ 258.00	<i>✓</i>
102	REAR GRAB HANDLE FOLDING-LH/RH <i>2</i>	2	\$ 258.00	<i>✓</i>
103	THREE POINT AUTOMATIC SEAT BELT-LH/RH <i>2</i>	2	\$ 2,010.00	<i>✓</i>
104	FRONT SEAT BELT HEIGHT ADJUSTER <i>?</i>	2	\$ 361.00	<i>?</i>
105	ACRYLIC SEALANT <i>?</i>	S/N	\$ 180.00	<i>✓</i>
106	CAVITY WAX <i>men</i>	S/N	\$ 140.00	<i>✓</i>
107	STONE CHIP	S/N	\$ 180.00	<i>✓</i>
108	FRONT WINDSCREEN SEALANT <i>men</i>	S/N	\$ 200.00	<i>✓</i>
109	FRONT CAR PLATE NO. <i>Best</i>	S/N	\$ 25.00	<i>✓</i>
110	SUNDRIES <i>?</i>		\$ 1,500.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 70,743.00	
TOTAL LABOUR CHARGES			\$ 32,524.00	
GRAND TOTAL			\$ 103,267.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim,
Surveyed Date : 04/03/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 21 Days.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/0D/0269/2019/GW

18-Mar-19

Kee Siang

1 of 1

SLX 8692 G

A3 SB 1.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	To dismantle both front door panel trims. To remove and reinstall both wing mirror assys to facilitate respraying for both front doors S/N	\$ 600.00	
2	To remove and renew intake manifold and other damaged engine components. S/N	\$ 900.00	
Parts			
1	External Temperature Sensor	\$ 54.00	
2	External Temperature Sensor Bracket	\$ 17.00	
3	Headlight Washer Hose	\$ 75.00	
4	Starter	\$ 1,443.00	
5	Flat Male Connector	\$ 43.00	
6	Butt Connector	\$ 48.00	
7	Return Hose	\$ 22.00	
8	Air Intake Duct Cover	\$ 27.00	
9	Air Duct	\$ 19.00	
10	Intake Manifold	\$ 588.00	
11	Turbo Intercooler	\$ 692.00	
12	Air Cond Bracket	\$ 25.00	
GRAND TOTAL :		\$ 4,553.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Raman (LKR)
Ru
18/03/19

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0269/2019/GW
Date : 1-Mar-19

Vehicle IN workshop.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

you recommended 21 days
We took 27 days exclude 5 Sundays
with additional repairs. Jb 13 Aug 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Ng Tze Kwok, Ben Jamin
Address : Blk 7 Tampines Avenue 8
#01 -09
Singapore 529597
Telephone : 97762367
Type of Claim : Own Damage Claims
Policy No. : 1800038355
Vehicle No : **SLX 8692 G**
Model Code : A3 SB 1.0 TFSI
Model / Year : 14/4/2018
Engine No : CHZ 678168
Chassis No : WAUZZZ8V3JA087063
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Feb-19
Place of Accident : PIE Tuas 12.6KM L1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 8692 G

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To tow and recovery vehicle from scene of accident.	S/N	WAIVE	na
2	To carry out first measurement test on car O-liner.	S/N \$	800.00	na
3	To remove, check and reinstall front wire harness for headlghs, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
4	To remove and transfer both front door's multi-lock system and power window devices. Inspect for damages and renew if necessary.	S/N \$	560.00	na
5	To remove and renew air condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	\$ 1,200.00
6	To remove center console, instrument panels and clusters. Rene dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and knee airbag.	S/N \$	3,600.00	\$ 3,600.00
SUB-TOTAL LABOUR CHARGES		:	\$ 6,520.00	\$ 5,160.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6641 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 8692 G

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 5,160.00
7	To renew front windscreen.	S/N	\$ 480.00	\$ 480.00
8	To remove and reinstall engine assy with gearbox assy to facilitate car -o-liner repairs.	S/N	\$ 2,800.00	na
9	To remove and reinstall front suspension assy with subframe to facilitate car -oliner repairs. Inspect for damages and renew if necessary .	S/N	\$ 2,400.00	na
10	To place vehicle on car- o-liner.	S/N	\$1,800.00	na
11	To dismantle and renew front bumper, bonnet and both front fenders, both headlights and both front doors. Cut out and reweld lhs fender support and closing element. Align both front chassis frames to specification of origin. Renew front lock carrier and align to position. re-organise front crash management components. reinsall all parts removed. (Add \$1000.00 for both headlamps, and checked items)		\$10,200.00	\$ 4,500.00
12	To respray front bumper, both front fenders, bonnet, hinges, both upper A-pillar, lhs fender top support, both front doors and engine compartment. To carry out joint sealant work and stone chip treatment.		\$7,700.00	\$ 4,875.00
SUB-TOTAL LABOUR CHARGES			\$ 25,380.00	\$ 15,015.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 8692 G

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 15,015.00
13	To carry out wheel alignment.	S/N	\$240.00	<i>na</i>
14	Added labour charges - see attached 18 Mar 19		\$1,500.00	\$ 1,500.00
15	Added labour charges - see attached 6 apr 19		\$400.00	\$ 400.00
16	To carry out diagnostic check.	S/N	\$384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	<u>\$34,424.00</u>	<u>\$ 17,299.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLX 8692 G**

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
1	FRONT BUMPER		\$ 1,698.00	\$ 1,358.40
2	FRONT BUMPER FIXING PARTS		\$ 170.00	
3	FRONT BUMPER GUIDE SECTION-LH/RH	2	\$ 70.00	\$ 55.04
4	FRONT BUMPER GRILLE-CENTER		\$ 146.00	
5	FRONT BUMPER CLOSING ELEMEN-LOWER CENTRE		\$ 270.00	\$ 216.00
6	FRONT BUMPER CLOSING ELEMEN-LH /RH	2	\$ 540.00	\$ 432.00
7	RADIATOR GRILLE		\$ 1,301.00	\$ 1,040.80
8	RADIATOR GRILLE CLOSING ELEMENT		\$ 174.00	\$ 138.80
9	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2	\$ 342.00	
10	FOAM FILLER PIECE		\$ 172.00	\$ 137.60
11	FRONT BUMPER SIDE REINFORCEMENT		\$ 670.00	\$ 527.60
12	FRONT BUMPER COVER		\$ 111.00	\$ 88.80
13	AIR CONDITIONER STICKER		\$ 7.00	\$ 5.12
14	SIGN " CAUTION "		\$ 13.00	\$ 9.76
15	SIGNAL HORN "HIGH TONE"		\$ 182.00	
16	SIGMAL HORN "LOW TONE"		\$ 182.00	\$ 145.60
17	BONNET		\$ 2,501.00	\$ 2,000.80
18	BONNET ATTACHMENT PARTS		\$ 149.00	\$ 119.20
19	BONNET LIG HINGE-LH/RH	2	\$ 112.00	\$ 88.48
20	BONNET GAS FILLED STRUT		\$ 109.00	
SUB TOTAL SPARE PARTS			\$ 8,919.00	\$ 6,364.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLX 8692 G**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 6,364.00
21	BONNET EDGE PROTECTION- FRONT		\$ 25.00	\$ 19.92
22	BONNET CATCH HOOK		\$ 81.00	\$ 64.72
23	BONNET STRIKER-LH/RH	2	\$ 200.00	\$ 159.04
24	BONNET RUBBER SEAL		\$ 53.00	\$ 41.92
25	FRONT ADAPTER-LH/RH	2	\$ 24.00	
26	BONNET CATCH HOOL		\$ 58.00	\$ 45.76
27	BONNET LID LOCK WITH MICRO SWITCH	2	\$ 367.00	\$ 293.60
28	BONNET LOCK LATCH COVER	2	\$ 7.00	\$ 5.12
29	BONNET BOWDEN CABLE -CENTER		\$ 53.00	\$ 41.68
30	BONNET LOCK CABLE COVER		\$ 9.00	\$ 7.12
31	BONNET LID LOCK CABLE		\$ 67.00	\$ 53.36
32	BONNET SOUND ABSORBER		\$ 201.00	\$ 160.80
33	PLENUM CHAMBER COVER		\$ 164.00	\$ 130.80
34	FRONT WIPER COWL TRIM		\$ 15.00	
35	FRONT FENDER-LH/RH	2	\$ 1,556.00	\$ 1,244.00
36	FRONT FENDER ATTACHMENT PARTS	2	\$ 130.00	
37	FRONT FENDER UPPER BRACKET-LH/RH	2	\$ 50.00	
38	FRONT FENDER BRACKET-LH/RH	2	\$ 86.00	\$ 68.16
39	FRONT FENDER BRACE-LH/RH	2	\$ 176.00	\$ 139.68
40	FRONT FENDER CLOSING ELEMENT-LH/RH	2	\$ 112.00	\$ 88.48
SUB TOTAL SPARE PARTS			\$ 3,434.00	\$ 8,928.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLX 8692 G**

S/N	Parts Description	c/f	<u>Damaged Parts & Prices</u>	
			<u>S/Nett</u>	<u>Remark</u>
				\$ 8,928.16
41	FORNT FENDER SEAL STRIP-LH/RH	2	\$ 62.00	
42	FRONT WHEEL HOUSING LINER-LH/RH	2	\$ 316.00	
43	WHEEL HOUSIN LINER ATTACHMENT PARTS	2	\$ 103.00	
44	FRONT FENDER CLOSING ELEMENT-LH		\$ 66.00	
45	LED HEADLIGHT-LH/RH	2	\$ 10,058.00	\$ 8,046.40
46	LED HEADLIGHT POWER MODULE	2	\$ 1,385.00	\$ 1,108.00
47	LED WITH HEAT SINK-LH/RH	2	\$ 1,332.00	\$ 1,064.80
48	LED HEADLIGHT CONTROL UNIT	2	\$ 1,015.00	\$ 812.00
49	LED HEADLIGHT LIFT CYLINDER-LH/RH	2	\$ 256.00	
50	WASH WATER RESERVOIR		\$ 186.00	\$ 148.40
51	HOSE FOR LED HEADLIGHT WASHER SYSTEM		\$ 61.00	
52	LOCK CARRIER WITH MOUNTING FOR COOLANT RADIATOR		\$ 663.00	\$ 530.40
53	A/C CONDENSER WITH FLUID RESERVOIR		\$ 503.00	\$ 402.00
54	REFRIGERANT LINE FOR A/C CONDENSER		\$ 461.00	\$ 368.80
55	REFRIGERANT LINE FOR A/C CONDENSER CUT OFF POINT		\$ 601.00	\$ 480.40
56	RADIATOR		\$ 878.00	\$ 702.40
57	ADDITIONAL RADIATOR		\$ 837.00	\$ 669.60
58	RADIATOR BUSH-LOWER	2	\$ 18.00	\$ 14.24
59	RADIATOR BRACKET UPPER		\$ 77.00	\$ 61.28
60	READY MIX COOLANT 1.5 LTR	4	\$ 84.00	\$ 67.20
SUB TOTAL SPARE PARTS		:	\$ 18,962.00	\$ 23,404.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLX 8692 G**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 23,404.08
61	RADIATOR FAN WITH FAN RING		\$ 1,483.00	\$ 1,186.40
62	AIR GUIDE-LH/RH	2	\$ 44.00	\$ 34.24
63	RADIATOR CORE SUPPORT SEAL		\$ 8.00	\$ 5.68
64	RADIATOR CORE SUPPORT AIR DUCT-UPPER CENTRE		\$ 11.00	\$ 8.32
65	AIR INTAKE AIR INLET		\$ 53.00	\$ 41.84
66	AIR INTAKE AIR BOX		\$ 62.00	
67	INTERCOOLER GASKET		\$ 13.00	
68	AIR FILTER		\$ 252.00	\$ 201.20
69	INTAKE MANIFOLD		\$ 129.00	
70	WATER DRAINAGE HOSE		\$ 31.00	\$ 24.48
71	PETROL ACTIVE CHARCOAL CONTAINER		\$ 294.00	
72	FRONT DOOR-LH		\$ 2,073.00	
73	FRONT OUTER DOOR SEAL-LH		\$ 146.00	
74	BONDING AGENT		\$ 45.00	
75	CLEANING SOLUTION		\$ 65.00	
76	FRONT DOOR-RH		\$ 2,073.00	
77	FRONT OUTER DOOR SEASL-RH		\$ 146.00	
78	BONDING AGENT		\$ 45.00	
79	CLEANING SOLUTION		\$ 65.00	
80	APPLICATOR		\$ 7.00	
SUB-TOTAL SPARE PARTS			\$ 7,045.00	\$ 24,906.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.