

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLX 8692 G**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 24,906.24
81	FRONT DOOR ATTACHMENT PARTS-LH/RH	2	\$ 436.00	
82	FRONT DOOR CATCH	2	\$ 191.00	
83	FRONT DOOR CATCH COVER	2	\$ 26.00	
84	FRONT DOOR CHECK STRAP-LH/RH	2	\$ 82.00	
85	FRONT ROOF STRIP MOLDING-LH/RH	2	\$ 1,074.00	
86	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-LH/RH	2	\$ 494.00	
87	FRONT WINDSCREEN		\$ 988.00	\$ 790.00
88	GEIL FOIL FOR RAIN SENSOR		\$ 128.00	\$ 102.40
89	DATA PLATE FOR TYRE PRESSURE		\$ 26.00	
90	AIRBAG UNIT FOR STEERING WHEEL		\$ 3,141.00	\$ 2,512.80
91	AIRBAG UNIT		\$ 4,238.00	\$ 3,390.40
92	HEAD AIR BAG UNIT	2	\$ 3,416.00	\$ 2,732.80
93	KNEE AIR BAG UNIT		\$ 1,708.00	\$ 1,366.40
94	AIR BAG CONTROL UNIT		\$ 1,606.00	\$ 1,284.80
95	AIR BAG CASH SENSOR		\$ 1,145.00	\$ 915.60
96	SPORT STEERING WHEEL		\$ 2,169.00	\$ 1,735.20
97	DASH BOARD WITH AIR DUCT		\$ 3,887.00	\$ 3,109.60
98	DASH BOARD PANEL UNDERTRAY -RH		\$ 413.00	
99	HEADLINING		\$ 1,809.00	\$ 1,447.20
100	FRONT A PILLAR COVER-LH/RH	2	\$ 294.00	\$ 234.40
SUB- TOTAL SPARE PARTS			\$ 27,271.00	\$ 44,527.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLX 8692 G**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 44,527.84
101	FRONT GRAB HANDLE FOLDING-LH/RH	2	\$ 258.00	\$ 206.40
102	REAR GRAB HANDLE FOLDING-LH/RH	2	\$ 258.00	\$ 206.40
103	THREE POINT AUTOMATIC SEAT BELT-LH/RH	2	\$ 2,010.00	\$ 1,608.00
104	FRONT SEAT BELT HEIGHT ADJUSTER	2	\$ 361.00	\$ 144.40
105	ACRYLIC SEALANT	S/N	\$ 180.00	
106	CAVITY WAX	S/N	\$ 140.00	
107	STONE CHIP	S/N	\$ 180.00	
108	FRONT WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
109	FRONT CAR PLATE NO.	S/N	\$ 25.00	\$ 25.00
110	Added parts - see atatched 18 Mar 19		\$ 888.00	\$ 190.40
111	Added parts - see atatched 26 Mar 19		\$ 3,053.00	\$ 2,438.88
112	SUNDRIES		\$ 1,500.00	\$ 148.32
	TOTAL SPARE PARTS	:	\$ 74,684.00	\$ 49,695.64
	TOTAL LABOUR CHARGES		\$ 34,424.00	\$ 17,299.00
	GRAND TOTAL		\$ 109,108.00	\$ 66,994.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0269/2019/GW 18-Mar-19 Kee Siang 1 of 1 SLX 8692 G A3 SB 1.0 TFSI	
Quantity	Description	Unit Price	Amount	
Labours				
1	To dismantle both front door panel trims. To remove and reinstall both wing mirror assys to facilitate respraying for both front doors S/N	\$ 600.00	\$ 600.00	
2	To remove and renew intake manifold and other damaged engine components. S/N	\$ 900.00	\$ 900.00	
		\$ 1,500.00	\$ 1,500.00	
Parts				
1	External Temperature Sensor	\$ 54.00	\$ 42.96	
2	External Temperature Sensor Bracket	\$ 17.00	\$ 13.04	
3	Headlight Washer Hose	\$ 75.00	\$ 59.92	
4	Starter	\$ 1,443.00	\$ 1,154.40	
5	Flat Male Connector	\$ 43.00	\$ 34.24	
6	Butt Connector	\$ 48.00	\$ 38.40	
7	Return Hose	\$ 22.00	\$ 17.28	
8	Air Intake Duct Cover	\$ 27.00	\$ 21.36	
9	Air Duct	\$ 19.00	\$ 14.48	
10	Intake Manifold	\$ 588.00	\$ 470.00	
11	Turbo Intercooler	\$ 692.00	\$ 553.20	
12	Air Cond Bracket	\$ 25.00	\$ 19.60	
Materials		\$ 3,053.00	\$ 2,438.88	
Labour		\$ 1,500.00	\$ 1,500.00	
Total :		\$ 4,553.00	\$ 3,938.88	

For Premium Automobiles Pte Ltd

 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0269/2019/GW 26-Mar-19 Kee Siang 2 of 2 SLX 8692 G A3 SB 1.0 TFSI
--	---	--

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Seat Headrest	\$ 648.00	
2	Dashboard Air Vent Centre	\$ 138.00	\$ 110.00
3	Loudspeaker Cover	\$ 86.00	\$ 68.16
4	Flat Connetor Housing	\$ 16.00	\$ 12.24
GRAND TOTAL :		\$ 888.00	\$ 190.40

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0269/2019/TF 6-Apr-19 Tony 1 of 1 SLX 8692 G A3 SB 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To replace front windscreen solar film <i>Alu</i>	\$ 400.00	\$ 400.00 ✓
		\$ 400.00	\$ 400.00

Adrian Ling
hls

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLX 8692 G

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0269/2019/NH

7 October 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SLX 8692 G, Audi A3 Sportsback 1.0 TFSI

With reference to the above-mentioned vehicle, no. **SLX 8692 G**, claimant, **Mr. Ng Tze Kwok, Benjamin**, please find the related document per attached.

1. A copy of the Original invoice no. 85014321 – S\$ 71,042.26
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLX 8692 G

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6386 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 1 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014321	Account: A0006 (T 0)		
		Date : 04/10/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
		Order : SLX8692G			
		Term : 30			
Regn No: SLX8692G (V 37114)		Regn Date: 14/04/2018	Mileage: 25002	WIP No.: 44425	
Model: A3 SPORTSBACK 1.0 TFSI 8VFANG		Chassis: WAUZZZ8V3JA087063	Engine: CHZ 678168	Dept: U	
You have been assisted by :- UB-Tony Foong (33)					
		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
S	SUBLET	M: TO REPLACE FRONT WINDSCREEN.	400.00	1.00	400.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER,RADIATOR AND ADDITIONAL RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	1200.00	1.00	1,200.00
S	BODYWORK	M: TO REMOVE CENTER CONSOLE,INSTRUMENT PANEL AND CLUSTER.RENEW DASHBOARD,BOTH FRONTAL AIRBAG, SLIP RING.TRANSFER OLD FITTINGS.RENEW SEAT BELTS AND CONTROL UNIT,PILLAR TRIMS,ROOF LINING, BOTH CURTAIN AIRBAG AND KNEE AIRBAG	3600.00	1.00	3,600.00
S	BODYWORK	M: TO RENEW FRONT WINDSCREEN	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND BOT FRONT FENDERS AND BOTH HEADLIGHT.CUT OUT AND WELD FENDER SUPPORT AND CLOSING ELEMENT.ALIGN BOTH FROM CHASSIS FRAMES TO SPECIFICATION OF ORIGIN.RENEW FR LOCK CARRIER TO POSITION.REORGANISE CRASH MANAGEME COMPONENTS.REINSTALL ALL PARTS REMOVED	4500.00	1.00	4,500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BOTH FRONT FENDERS, BONNET,HINGES,BOTH UPPER A PILLAR,LHS FENDER	4875.00	1.00	4,875.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 6828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 2 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014321	Account: A0006 (T Q)
	Date : 04/10/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SLX8692G	
	Term : 30	

Regn No: SLX8692G (V 37114) Regn Date: 14/04/2018 Mileage: 25002 WIP No.: 44425

Model: A3 SPORTSBACK 1.0 TFSI 8VFANG Chassis: WAUEZ28V3JA087063 Engine: CHZ 678168 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TOP SUPPORT AND BOTH FRONT DOORS.TO CARRY OUT JOINT SEALER WORK AND STONE CHIP TREATMENT M:	384.00	1.00	384.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	200.00	1.00	200.00
S	BODYWORK	TO SUPPLY FRONT WINDSCREEN SEALANT M:	600.00	1.00	600.00
S	BODYWORK	TO DISMANTLE BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAYING FOR BOTH FRONT DOOR M:	900.00	1.00	900.00
X	A8V0823723	(A) (G) SEAL 11/03/19 Less 020%	1.00	52.40	41.92
X	A04C129601G	(A) (SK) AIRCLEANER 18 Less 020%	1.00	251.50	201.20
X	A8V4867505B YX7	(A) (Ger) ROOFLINING 1 Less 020%	1.00	1809.00	1,447.20
X	A0AM911024A	(V) (Ger) STARTER 18/0 Less 020%	1.00	1443.00	1,154.40
X	A04C129709E	(V) (Ger) MANIFOLD 18/ Less 020%	1.00	587.50	470.00
X	A8V2819635D 6PS	(V) (Ger) AIR VENT 26/ Less 020%	1.00	137.50	110.00
X	A8V2857367B 6PS	(V) (Ger) COVER 26/3/1 Less 020%	1.00	85.20	68.16
X	A8P0971848D	HOLDER (V) 29/03/19 Less 020%	2.00	5.40	8.64
X	A8V3853651AA3FZ	GRILLE Less 020%	1.00	1301.00	1,040.80
X	A8V0867233 VU6	(V) (Ger) LINING 26/3/ Less 020%	1.00	146.50	117.20
X	A8V0867234 VU6	(V) (Ger) LINING 26/3/ Less 020%	1.00	146.50	117.20
X	A8V0941773D	HEADLIGHT Less 020%	1.00	5029.00	4,023.20
X	A8V0941774D	HEADLIGHT Less 020%	1.00	5029.00	4,023.20
X	A8V0821105L	FENDER Less 020%	1.00	777.50	622.00
X	A8V0821106L	FENDER Less 020%	1.00	777.50	622.00
X	A8V2819401 9B9	COVER Less 020%	1.00	163.50	130.80
X	A8V0863825	(A) (SK) SILENCER 11/0 Less 020%	1.00	201.00	160.80
X	A8V0880201DN6PS	(A) (G) AIRBAG 11/03/1 Less 020%	1.00	3141.00	2,512.80
X	A8V0880204J	(A) (SK) AIRBAG 11/03/ Less 020%	1.00	4238.00	3,390.40
X	A8V4880741F	(A) (G) AIRBAG 11/03/1 Less 020%	1.00	1708.00	1,366.40

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2223
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 3 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014321	Account: A0006 (T 0)		AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120	
		Date : 04/10/2019				
		Order : SLX8692G				
		Term : 30				
Regn No: SLX8692G (V 37114)		Regn Date: 14/04/2018	Mileage: 25002		WIP No.: 44425	
Model: A3 SPORTSBACK 1.0 TFSI 8VFANG		Chassis: WAUZZZ8V3JA087063	Engine: CHZ 678168		Dept: U	
You have been assisted by :- UB-Tony Foong (33)						
		Details		Qty	Unit Price	Amount
X	A8V4880742F	(A) (G) AIRBAG 11/03/1	Less 020%	1.00	1708.00	1,366.40
X	A8V2880841D	(A) (SK) AIRBAG 11/03/	Less 020%	1.00	1708.00	1,366.40
X	A5Q0816411AS	(V) (G) CONDENSER 11/0	Less 020%	1.00	502.50	402.00
X	A5Q0121251GD	RADIATOR	Less 020%	1.00	878.00	702.40
X	A5Q0121251HS	RADIATOR	Less 020%	1.00	837.00	669.60
X	A8V3807233B	PLATE	Less 020%	1.00	270.00	216.00
X	A8V0805588A	(A) (SK) CARRIER 11/03	Less 020%	1.00	663.00	530.40
X	A5Q0121203DA	ELECTRIC F	Less 020%	1.00	1483.00	1,186.40
X	A8V0807550A	FOAM INSER	Less 020%	1.00	172.00	137.60
X	A8V4807109E	BEAM	Less 020%	1.00	659.50	527.60
X	AG A13040M2	PREMIX-COOLANT	Less 020%	4.00	21.00	84.00
X	A8V3845099S NVE	(A) (SK) WINDSHIELD 11	Less 020%	1.00	987.50	790.00
X	A8V0807065R GRU	COVER	Less 020%	1.00	1698.00	1,358.40
X	A8V0823029D	HOOD	Less 020%	1.00	2501.00	2,000.80
X	A8V2857001J 24A	(A) (SK) DASHBOARD 11/	Less 020%	1.00	3887.00	3,109.60
X	A4G0063511L	UTR ADHESIVE PADS	Less 020%	1.00	26.00	20.80
X	A8V0098615	ATT. PARTS	Less 020%	1.00	149.00	119.20
X	A04E145757	GASKET	Less 020%	1.00	12.60	10.08
X	A5Q0121367F	(A) (SK) BRACKET 18/03	Less 020%	2.00	38.30	61.28
X	A8V0121285A	AIR DUCT	Less 020%	1.00	10.40	8.32
X	A04C145749A	(A) (SK-Last) COOLER 1	Less 020%	1.00	691.50	553.20
X	A8V0823126B	EDGING	Less 020%	1.00	24.90	19.92
X	A8V0807217A	COVER	Less 020%	1.00	111.00	88.80
X	A8V3807319	PLATE	Less 020%	1.00	270.00	216.00
X	A8V3807320	PLATE	Less 020%	1.00	270.00	216.00
X	A5Q0820769	(A) (SK) BRACKET 18/03	Less 020%	1.00	24.50	19.60
X	A8V0821092C	PLATE	Less 020%	1.00	55.30	44.24
X	A8V0821468E	BRACKET	Less 020%	1.00	42.60	34.08
X	A8V0821135A	SUPPORT	Less 020%	1.00	87.30	69.84
X	A8V0821136A	SUPPORT	Less 020%	1.00	87.30	69.84
X	A8V3807183B	GUIDE	Less 020%	1.00	34.40	27.52
X	A8V3807184B	GUIDE	Less 020%	1.00	34.40	27.52
X	A8V0823301G	HINGE	Less 020%	1.00	55.30	44.24
X	A8V0823302G	(SK) HINGE	Less 020%	1.00	55.30	44.24

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9826 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 4 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014321	Account: A0006 (T 0)
	Date : 04/10/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SLX8692G	
	Term : 30	

Regn No: SLX8692G (V 37114) Regn Date: 14/04/2018 Mileage: 25002 WIP No.: 44425

Model: A3 SPORTSBACK 1.0 TFSI 8VFANG Chassis: WAUZZZ8V3JA087063 Engine: CHZ 678168 Dept: U

You have been assisted by :- US-Tony Foong (33)

		Details		Qty	Unit Price	Amount
X	A5Q0122291BD	(A) (SK) COUPLER 18	Less 020%	1.00	21.60	17.28
X	A5Q0129621B	AIR DUCT	Less 020%	1.00	18.10	14.48
X	A5Q0129637B	(A) (SK) HOSE 18/03/19	Less 020%	1.00	30.60	24.48
X	A8V0121230	SEAL	Less 020%	1.00	7.10	5.68
X	A1K0121367F	MOUNTING	Less 020%	2.00	8.90	14.24
X	A8V0820536	BRACKET	Less 020%	1.00	16.30	13.04
X	A8V0823185C	CATCH	Less 020%	1.00	99.40	79.52
X	A8V0857819	ADJUSTER	Less 020%	1.00	180.50	144.40
X	A8V0823186C	CATCH	Less 020%	1.00	99.40	79.52
X	A8V0821467E	BRACKET	Less 020%	1.00	42.60	34.08
X	A4H0823543	COVER	Less 020%	1.00	8.90	7.12
X	A8V0821091C	PLATE	Less 020%	1.00	55.30	44.24
X	A820820535A	TEMP. SENS.	Less 020%	1.00	53.70	42.96
X	A8V4823485C	HOOK	Less 020%	1.00	57.20	45.76
X	A4D0260749B	WASHER	Less 020%	1.00	3.00	2.40
X	A3D0260749C	WASHER	Less 020%	1.00	4.00	3.20
X	A5Q0820741B	(V) (SK) COOLANT PIP 25	Less 020%	1.00	600.50	480.40
X	A8V0823480A	HOOK	Less 020%	1.00	80.90	64.72
X	A4H0823188	(A) (G) COVER 11/03/19	Less 020%	2.00	3.20	5.12
X	A8V0823509A	LOCK	Less 020%	2.00	183.50	293.60
X	A8V0419091CHINU	(V) (Ger) STEERING WH 2	Less 020%	1.00	2169.00	1,735.20
X	A8V0857608 MGE	(V) (Ger) HANDLE 26/3/	Less 020%	1.00	129.00	103.20
X	A8V0857607A MGE	(V) (Ger) HANDLE 26/3/	Less 020%	1.00	129.00	103.20
X	A8V5857705E V04	(A) (SK) SEAT BELT 11/	Less 020%	1.00	1005.00	804.00
X	A8V5857706E V04	(A) (SK) SEAT BELT 11/	Less 020%	1.00	1005.00	804.00
X	A8V0857607 MGE	(A) (SK) HANDLE 26/3/1	Less 020%	2.00	129.00	206.40
X	A8V2823535B	CABLE	Less 020%	1.00	66.70	53.36
X	A8V0823531A	BOWD CABLE	Less 020%	1.00	52.10	41.68
X	A5Q0820743K	(V) (Ger) COOLANT PIP 1	Less 020%	1.00	461.00	368.80
X	A8U0955609	FILM	Less 020%	1.00	128.00	102.40
X	A7L0973812	(A) (SK) HOUSING 26/3/	Less 020%	1.00	15.30	12.24
X	A5Q0959651B	(A) (SK) SENSOR 11/03/	Less 020%	3.00	381.50	915.60
X	A1J0955751D	TUBING	Less 020%	1.00	74.90	59.92
X	A431955465A	GASKET	Less 020%	1.00	6.90	5.52

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159936
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408999
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 5 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014321	Account: A0006 (T 0)
	Date : 04/10/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SLX8692G	
	Term : 30	

Regn No: SLX8692G (V 37114) Regn Date: 14/04/2018 Mileage: 25002 WIP No.: 44425

Model: A3 SPORTSBACK 1.0 TFSI 8V FANG Chassis: WAUZZZ8V3JA087063 Engine: CHZ 678168 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
X	A443955465	GASKET	Less 020%	1.00	2.90
X	A000979940	CONNECTOR (WHITE)	Less 020%	5.00	9.60
X	A000979020EA	WIRES	Less 020%	2.00	21.40
X	A8K0010520A	PLATE	Less 020%	1.00	12.20
X	A8V0010515A	STICKER	Less 020%	1.00	6.40
X	AD 00920002	PRIMER (DG)	Less 020%	1.00	18.60
X	A5Q0959655BJ	(A) (SK)MODULE 11/03/	Less 020%	1.00	1606.00
X	A8V0951210D	HORN	Less 020%	1.00	182.00
X	A5Q0129254B	AIR DUCT	Less 020%	1.00	52.30
X	A8V0121284E	AIR DUCT	Less 020%	1.00	21.40
X	A8V0121283K	AIR DUCT	Less 020%	1.00	21.40
X	A8V3853949	(A) (SK) PLATE 11/03/1	Less 020%	1.00	173.50
X	A5Q0955453R	WATER RES.	Less 020%	1.00	185.50
X	A8V0998474A	LED	Less 020%	1.00	665.50
X	A7FP941572AC	POWER MOD	Less 020%	2.00	692.50
X	A880907397D	CTRL UNIT	Less 020%	2.00	507.50
X	A8V0998473A	LED	Less 020%	1.00	665.50
X	AN 0161857	POP-RIVET	Less 020%	16.00	3.00
X	AN 10721501	BOLT	Less 020%	1.00	7.40
X	AN 90653901	(A) (SK) CLIP 18/03/19	Less 020%	1.00	1.30
X	AWHT005551A	BOLT	Less 020%	8.00	2.10
X	AN 90827102	BOLT	Less 020%	1.00	23.10
X	AN 10507201	SCREW	Less 020%	2.00	0.90
X	AN 91141501	RIVET	Less 020%	1.00	2.20
X	A5Q0129954	COVER	Less 020%	1.00	26.70

Parts 49,470.64
Labour 0.00
Sublet 17,524.00
Menus 0.00
Lubricant 0.00

Sub-Total 66,394.64

7% GST 4,647.62

Grand Total 71,042.26



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLX8692G

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0269/2019/TF
6th April 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SPORTSBACK 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V3JA087063
Vehicle Regn No. : **SLX8692G**
Vehicle Mileage : 18803KM
Vehicle Owner : Mr. Ng Tze Kwok, Benjamin
Certificate No : 1800038355
Own Damage Excess : \$642.00 (Inclusive 7%GST)
Accident Date : 28 February 2019
Place : PIE Tuas 12.6km L1
Repair Cost : \$ 71,042.26
WIP No. : 44425
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 8/4/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Mar 2019		05 Mar 2019 11:27 Edit Adj Rpt	S\$66,994.64 Edit Estimates	S\$66,994.64 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: NG TZE KWOK, BENJAMIN , ID: S8219634Z, Tel: +6597762367									
Vehicle Reg. No.: SLX8692G		Date of Loss: 28/02/2019 07:00 - :59 [10 Months and 14 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 1774505617SG		Policy/Cover Note No.: 1800038355 (Comprehensive)							
		Excess: S\$600.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Md Ishak, Mohd Imran] Imran.Ishak@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/03/2019]									
Driver/Custodian: ANG SHI TING, CECILIA (35 / Female), NRIC: S8404603E, Tel: +6591138130 Email: CECILANG@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (11/09/2019): Alert - Adj Mandate Approved (S\$66994.64) - SLX8692G - Claim Handler: Md Ishak, ... - AIG_SG (01/04/2019): Alert - Adj Mandate Approved (S\$66000.00) - SLX8692G - Claim Handler: Md Ishak, ... - AIG_SG (25/03/2019): Alert - Adj Mandate Maintained - SLX8692G - Claim Handler: Md Ishak, Mohd Imran - AIG_SG (21/03/2019): Alert - Adj Mandate Maintained - SLX8692G - Claim Handler: Md Ishak, Mohd Imran - AIG_SG (07/03/2019): Alert - Adj Mandate Approved (S\$61237.00) - SLX8692G - Claim Handler: Md Ishak, ... - AIG_SG (06/03/2019): SLX8692G / OD / 28/02/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX8692G (1774505617SG)
 OD
 Feb 28 2019 7:00AM
 [NG TZE KWOK, BENJAMIN]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Assessment Reports														1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	06/03/19 10:02	Adjuster Immediate Advice											Load HTM	☒			
2	19/03/19 17:06	Adjuster Immediate Advice											Load HTM	☒			
3	21/03/19 13:59	Adjuster Immediate Advice											Load HTM	☒			
4	28/03/19 17:25	Adjuster Immediate Advice											Load HTM	☒			
5	03/09/19 16:22	Adjuster Immediate Advice											Load HTM	☒			
Photos/Images														3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	06/03/19 09:46	General View											Load JPG	☒			
2	06/03/19 09:46	General View											Load JPG	☒			
3	06/03/19 09:46	General View											Load JPG	☒			
4	06/03/19 09:46	General View											Load JPG	☒			
5	06/03/19 09:46	General View											Load JPG	☒			
6	06/03/19 09:46	General View											Load JPG	☒			
7	06/03/19 09:46	General View											Load JPG	☒			
8	06/03/19 09:46	General View											Load JPG	☒			
9	06/03/19 09:46	General View											Load JPG	☒			
10	06/03/19 09:46	General View											Load JPG	☒			
11	06/03/19 09:46	General View											Load JPG	☒			
12	06/03/19 09:46	General View											Load JPG	☒			
13	06/03/19 09:46	General View											Load JPG	☒			
14	06/03/19 09:46	General View											Load JPG	☒			
15	06/03/19 09:46	General View											Load JPG	☒			
16	06/03/19 09:46	General View											Load JPG	☒			
17	06/03/19 09:46	General View											Load JPG	☒			
18	06/03/19 09:46	General View											Load JPG	☒			
19	06/03/19 09:46	General View											Load JPG	☒			
20	06/03/19 09:46	General View											Load JPG	☒			
21	06/03/19 09:46	General View											Load JPG	☒			
22	06/03/19 09:46	General View											Load JPG	☒			
23	06/03/19 09:46	General View											Load JPG	☒			
24	06/03/19 09:46	General View											Load JPG	☒			
25	06/03/19 09:46	General View											Load JPG	☒			
26	06/03/19 09:46	General View											Load JPG	☒			
27	06/03/19 09:46	General View											Load JPG	☒			
28	06/03/19 09:46	General View											Load JPG	☒			
29	06/03/19 09:46	General View											Load JPG	☒			
30	06/03/19 09:46	General View											Load JPG	☒			
31	06/03/19 09:46	General View											Load JPG	☒			
32	06/03/19 09:46	General View											Load JPG	☒			
33	06/03/19 09:46	General View											Load JPG	☒			
34	06/03/19 09:46	General View											Load JPG	☒			
35	06/03/19 09:46	General View											Load JPG	☒			
36	06/03/19 09:46	General View											Load JPG	☒			
37	06/03/19 09:46	General View											Load JPG	☒			
38	06/03/19 09:46	General View											Load JPG	☒			

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
39	06/03/19 09:46	General View	 Load JPG	☒
40	06/03/19 09:46	General View	 Load JPG	☒
41	06/03/19 09:46	General View	 Load JPG	☒
42	06/03/19 09:46	General View	 Load JPG	☒
43	06/03/19 09:46	General View	 Load JPG	☒
44	06/03/19 09:46	General View	 Load JPG	☒
45	06/03/19 09:46	General View	 Load JPG	☒
46	06/03/19 09:46	General View	 Load JPG	☒
47	06/03/19 09:46	General View	 Load JPG	☒
48	06/03/19 09:46	General View	 Load JPG	☒
49	06/03/19 09:46	General View	 Load JPG	☒
50	06/03/19 09:46	General View	 Load JPG	☒
51	06/03/19 09:46	General View	 Load JPG	☒
52	06/03/19 09:46	General View	 Load JPG	☒
53	06/03/19 09:46	General View	 Load JPG	☒
54	06/03/19 09:46	General View	 Load JPG	☒
55	06/03/19 09:46	General View	 Load JPG	☒
56	06/03/19 09:46	General View	 Load JPG	☒
57	06/03/19 09:46	General View	 Load JPG	☒
58	06/03/19 09:46	General View	 Load JPG	☒
59	06/03/19 09:46	General View	 Load JPG	☒
60	06/03/19 09:46	General View	 Load JPG	☒
61	06/03/19 09:46	General View	 Load JPG	☒
62	06/03/19 09:46	General View	 Load JPG	☒
63	06/03/19 09:46	General View	 Load JPG	☒
64	06/03/19 09:46	General View	 Load JPG	☒
65	06/03/19 09:46	General View	 Load JPG	☒
66	06/03/19 09:46	General View	 Load JPG	☒
67	06/03/19 09:46	General View	 Load JPG	☒
68	06/03/19 09:46	General View	 Load JPG	☒
69	06/03/19 09:46	General View	 Load JPG	☒
70	06/03/19 09:46	General View	 Load JPG	☒
71	06/03/19 09:46	General View	 Load JPG	☒
72	06/03/19 09:46	General View	 Load JPG	☒
73	06/03/19 09:46	General View	 Load JPG	☒
74	06/03/19 09:46	General View	 Load JPG	☒
75	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
76	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
77	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
78	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
79	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
80	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
81	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
82	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
83	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
84	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
85	22/03/19 11:42	Reinspection Photo	Load JPG	☒
86	22/03/19 11:42	Reinspection Photo	Load JPG	☒
87	22/03/19 11:42	Reinspection Photo	Load JPG	☒
88	22/03/19 11:42	Reinspection Photo	Load JPG	☒
89	22/03/19 11:42	Reinspection Photo	Load JPG	☒
90	22/03/19 11:42	Reinspection Photo	Load JPG	☒
91	22/03/19 11:42	Reinspection Photo	Load JPG	☒
92	22/03/19 11:42	Reinspection Photo	Load JPG	☒
93	22/03/19 11:42	Reinspection Photo	Load JPG	☒
94	22/03/19 11:42	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
95	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
96	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
97	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
98	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
99	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
100	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
101	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
102	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
103	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
104	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
105	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
106	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
107	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
108	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
109	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
110	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
111	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
112	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
113	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
114	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
115	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
116	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
117	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
118	22/03/19 11:42	Reinspection Photo	 Load JPG	☒
119	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
120	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
121	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
122	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
123	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
124	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
125	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
126	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
127	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
128	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
129	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
130	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
131	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
132	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
133	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
134	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
135	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
136	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
137	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
138	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
139	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
140	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
141	26/03/19 08:56	Reinspection Photo	Load JPG	☒
142	26/03/19 08:56	Reinspection Photo	Load JPG	☒
143	26/03/19 08:56	Reinspection Photo	Load JPG	☒
144	26/03/19 08:56	Reinspection Photo	Load JPG	☒
145	26/03/19 08:56	Reinspection Photo	Load JPG	☒
146	26/03/19 08:56	Reinspection Photo	Load JPG	☒
147	26/03/19 08:56	Reinspection Photo	Load JPG	☒
148	26/03/19 08:56	Reinspection Photo	Load JPG	☒
149	26/03/19 08:56	Reinspection Photo	Load JPG	☒
150	26/03/19 08:56	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
151	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
152	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
153	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
154	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
155	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
156	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
157	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
158	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
159	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
160	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
161	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
162	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
163	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
164	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
165	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
166	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
167	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
168	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
169	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
170	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
171	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
172	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
173	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
174	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
175	26/03/19 08:56	Reinspection Photo	 Load JPG	☒
176	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
177	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
178	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
179	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
180	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
181	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
182	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
183	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
184	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
185	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
186	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
187	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
188	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
189	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
190	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
191	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
192	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
193	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
194	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
195	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
196	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
197	09/04/19 15:51	Reinspection Photo	Load JPG	☒
198	09/04/19 15:51	Reinspection Photo	Load JPG	☒
199	09/04/19 15:51	Reinspection Photo	Load JPG	☒
200	09/04/19 15:51	Reinspection Photo	Load JPG	☒
201	09/04/19 15:51	Reinspection Photo	Load JPG	☒
202	09/04/19 15:51	Reinspection Photo	Load JPG	☒
203	09/04/19 15:51	Reinspection Photo	Load JPG	☒
204	09/04/19 15:51	Reinspection Photo	Load JPG	☒
205	09/04/19 15:51	Reinspection Photo	Load JPG	☒
206	09/04/19 15:51	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
207	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
208	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
209	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
210	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
211	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
212	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
213	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
214	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
215	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
216	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
217	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
218	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
219	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
220	09/04/19 15:51	Reinspection Photo	 Load JPG	☒
221	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
222	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
223	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
224	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
225	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
226	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
227	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
228	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
229	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
230	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
231	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
232	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
233	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
234	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
235	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
236	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
237	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
238	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
239	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
240	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
241	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
242	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
243	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
244	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
245	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
246	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
247	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
248	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
249	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
250	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
251	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
252	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
253	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
254	02/09/19 11:31	Reinspection Photo	Load JPG	☒
255	02/09/19 11:31	Reinspection Photo	Load JPG	☒
256	02/09/19 11:31	Reinspection Photo	Load JPG	☒
257	02/09/19 11:31	Reinspection Photo	Load JPG	☒
258	02/09/19 11:31	Reinspection Photo	Load JPG	☒
259	02/09/19 11:31	Reinspection Photo	Load JPG	☒
260	02/09/19 11:31	Reinspection Photo	Load JPG	☒
261	02/09/19 11:31	Reinspection Photo	Load JPG	☒
262	02/09/19 11:31	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
263	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
264	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
265	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
266	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
267	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
268	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
269	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
270	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
271	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
272	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
273	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
274	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
275	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
276	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
277	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
278	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
279	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
280	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
281	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
282	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
283	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
284	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
285	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
286	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
287	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
288	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
289	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
290	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
291	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
292	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
293	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
294	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
295	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
296	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
297	02/09/19 11:31	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/03/19 09:44	Singapore Accident Statement	 Load PDF	
2	06/03/19 09:44	NEW CAR PRICES	 Load PDF	
3	06/03/19 09:44	Certificate of Insurance	 Load PDF	
4	06/03/19 09:44	Driver's Driving License	 Load PDF	
5	06/03/19 09:44	ESTIMATE	 Load PDF	
6	19/03/19 14:59	SUPPLEMENTARY LIST	 Load PDF	
7	21/03/19 14:00	SUPPLEMENTARY LIST	 Load PDF	
8	28/03/19 17:17	SUPPLEMENTARY LIST 2	 Load PDF	
9	03/09/19 16:12	SUPPLEMENTARY LIST 3	 Load PDF	
10	21/10/19 09:48	Workshop Invoice	 Load PDF	
11	21/10/19 09:48	Discharge Voucher	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/02/19 18:45	Accident Statement	 Load HTM	
Photos/Images			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print

Assessment Reports					1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print	
1	28/02/19 14:46	Accident Photo		Load JPG	☒	
2	28/02/19 14:46	Accident Photo		Load JPG	☒	
3	28/02/19 14:46	Accident Photo		Load JPG	☒	
4	28/02/19 14:46	Accident Photo		Load JPG	☒	
5	28/02/19 14:46	Accident Photo		Load JPG	☒	
6	28/02/19 14:46	Accident Photo		Load JPG	☒	
7	28/02/19 14:46	Accident Photo		Load JPG	☒	
8	28/02/19 14:46	Accident Photo		Load JPG	☒	
9	28/02/19 14:46	Accident Photo		Load JPG	☒	
10	28/02/19 14:46	Accident Photo		Load JPG	☒	
11	28/02/19 14:46	Accident Photo		Load JPG	☒	
12	28/02/19 14:46	Accident Photo		Load JPG	☒	
13	28/02/19 14:46	Accident Photo		Load JPG	☒	
14	28/02/19 14:46	Accident Photo		Load JPG	☒	
15	28/02/19 14:46	Accident Photo		Load JPG	☒	
Documentation					1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print	
1	28/02/19 14:42	Sketch Plan		Load JPG	☒	
2	28/02/19 14:42	Sketch Plan #2		Load JPG	☒	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19004008/AQD3E2

Date: 21/10/2019

REFERENCE

Insured/Claimant: NG TZE KWOK, BENJAMIN

Policy No: 1800038355

Date of Loss: 28/02/2019

Nature of Claim: OD

Claim No: 1774505617SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX8692G

Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A)

Engine No: CHZ678168

Reg. Date: 14/04/2018 (Man. Year: 2018)

Chassis No: WAUZZZ8V3JA087063

Colour: Grey

Odometer: 18803 km

Engine Capacity: 999 cc

Market Value/New Car Price: S\$113,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	74,020.28	49,695.64	24,324.64	32.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	34,424.00	17,299.00	17,125.00	49.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	108,444.28	66,994.64	41,449.64	38.22
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	107,844.28	66,394.64	41,449.64	38.43
+ GST 7.00/7.00% (S\$)	7,549.10	4,647.62	2,901.48	38.43
Nett Amount (S\$)	115,393.38	71,042.26	44,351.12	38.43

INSPECTION

Date of Assignment: 05/03/2019

Date Inspected: 04/03/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 27.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,698.00 FS	*1,358.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Damaged	70.00 FS	*55.04 FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	146.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	270.00 FS	*216.00 FS
6	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Damaged	540.00 FS	*432.00 FS
7	1		*RADIATOR GRILLE	Smashed	1,301.00 FS	*1,040.80 FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Smashed	174.00 FS	*138.80 FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	342.00 FS	*- FS
10	1		*FOAM FILLER PIECE	Deformed	172.00 FS	*137.60 FS
11	1		*FRONT BUMPER SIDE REINFORCEMENT	Bent	670.00 FS	*527.60 FS
12	1		*FRONT BUMPER COVER	Smashed	111.00 FS	*88.80 FS
13	1		*AIR CONDITIONER STICKER	Necessary	7.00 FS	*5.12 FS
14	1		*SIGN CAUTION	Necessary	13.00 FS	*9.76 FS
15	1		*SIGNAL HORN HIGH TONE	Not Necessary	182.00 FS	*- FS
16	1		*SIGNAL HORN LOW TONE	Damaged	182.00 FS	*145.60 FS
17	1		*BONNET	Distorted	2,501.00 FS	*2,000.80 FS
18	1		*BONNET ATTACHMENT PARTS	Necessary	149.00 FS	*119.20 FS
19	2		*BONNET LIG HINGE - LH / RH	Bent	112.00 FS	*88.48 FS
20	1		*BONNET GAS FILLED STRUT	Not Necessary	109.00 FS	*- FS
21	1		*BONNET EDGE PROTECTION - FRONT	Cut	25.00 FS	*19.92 FS
22	1		*BONNET CATCH HOOK	Bent	81.00 FS	*64.72 FS
23	2		*BONNET STRIKER - LH / RH	Damaged	200.00 FS	*159.04 FS
24	1		*BONNET RUBBER SEAL	Cut	53.00 FS	*41.92 FS
25	2		*FRONT ADAPTER - LH / RH	Not Necessary	24.00 FS	*- FS
26	1		*BONNET CATCH HOOL	Bent	58.00 FS	*45.76 FS
27	2		*BONNET LID LOCK WITH MICRO SWITCH	Damaged	367.00 FS	*293.60 FS
28	2		*BONNET LOCK LATCH COVER	Necessary	7.00 FS	*5.12 FS
29	1		*BONNET BOWDEN CABLE - CENTER	Damaged	53.00 FS	*41.68 FS
30	1		*BONNET LOCK CABLE COVER	Damaged	9.00 FS	*7.12 FS
31	1		*BONNET LID LOCK CABLE	Damaged	67.00 FS	*53.36 FS
32	1		*BONNET SOUND ABSORBER	Crumpled	201.00 FS	*160.80 FS
33	1		*PLENUM CHAMBER COVER	Deformed	164.00 FS	*130.80 FS
34	1		*FRONT WIPER COWL TRIM	Not Necessary	15.00 FS	*- FS
35	2		*FRONT FENDER - LH / RH	Buckled	1,556.00 FS	*1,244.00 FS
36	2		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	130.00 FS	*- FS
37	2		*FRONT FENDER UPPER BRACKET - LH / RH	Not Necessary	50.00 FS	*- FS
38	2		*FRONT FENDER BRACKET - LH / RH	Bent	86.00 FS	*68.16 FS
39	2		*FRONT FENDER BRACE - LH / RH	Bent	176.00 FS	*139.68 FS
40	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Damaged	112.00 FS	*88.48 FS
41	2		*FRONT FENDER SEAL STRIP - LH / RH	Not Necessary	62.00 FS	*- FS
42	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	316.00 FS	*- FS
43	2		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	103.00 FS	*- FS
44	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	66.00 FS	*- FS
45	2		*LED HEADLIGHT - LH / RH	Smashed	10,058.00 FS	*8,046.40 FS
46	2		*LED HEADLIGHT POWER MODULE	Damaged	1,385.00 FS	*1,108.00 FS
47	2		*LED WITH HEAT SINK - LH / RH	Damaged	1,332.00 FS	*1,064.80 FS
48	2		*LED HEADLIGHT CONTROL UNIT	Damaged	1,015.00 FS	*812.00 FS
49	2		*LED HEADLIGHT LIFT CYLINDER - LH / RH	Not Necessary	256.00 FS	*- FS
50	1		*WASH WATER RESERVOIR	Deformed	186.00 FS	*148.40 FS
51	1		*HOSE FOR LED HEADLIGHT WASHER SYSTEM	Not Necessary	61.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*LOCK CARRIER WITH MOUNTING FOR COOLANT RADIATOR	Cracked	663.00 FS	*530.40 FS
53	1		*A/C CONDENSER WITH FLUID RESERVOIR	Bent	503.00 FS	*402.00 FS
54	1		*REFRIGERANT LINE FOR A/C CONDENSER	Bent	461.00 FS	*368.80 FS
55	1		*REFRIGERANT LINE FOR A/C CONDENSER CUT OFF POINT	Bent	601.00 FS	*480.40 FS
56	1		*RADIATOR	Bent	878.00 FS	*702.40 FS
57	1		*ADDITIONAL RADIATOR	Bent	837.00 FS	*669.60 FS
58	2		*RADIATOR BUSH - LOWER	Damaged	18.00 FS	*14.24 FS
59	1		*RADIATOR BRACKET UPPER	Damaged	77.00 FS	*61.28 FS
60	4		*READY MIX COOLANT 1.5 LTR	Necessary	84.00 FS	*67.20 FS
61	1		*RADIATOR FAN WITH FAN RING	Cracked	1,483.00 FS	*1,186.40 FS
62	2		*AIR GUIDE - LH / RH	Cracked	44.00 FS	*34.24 FS
63	1		*RADIATOR CORE SUPPORT SEAL	Necessary	8.00 FS	*5.68 FS
64	1		*RADIATOR CORE SUPPORT AIR DUCT - UPPER CENTRE	Necessary	11.00 FS	*8.32 FS
65	1		*AIR INTAKE AIR INLET	Cracked	53.00 FS	*41.84 FS
66	1		*AIR INTAKE AIR BOX	Not Necessary	62.00 FS	*- FS
67	1		*INTERCOOLER GASKET	Not Necessary	13.00 FS	*- FS
68	1		*AIR FILTER	Cracked	252.00 FS	*201.20 FS
69	1		*INTAKE MANIFOLD	Not Necessary	129.00 FS	*- FS
70	1		*WATER DRAINAGE HOSE	Damaged	31.00 FS	*24.48 FS
71	1		*PETROL ACTIVE CHARCOAL CONTAINER	Not Necessary	294.00 FS	*- FS
72	1		*FRONT DOOR - LH	Repair	2,073.00 FS	*- FS
73	1		*FRONT OUTER DOOR SEAL - LH	Not Necessary	146.00 FS	*- FS
74	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
75	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
76	1		*FRONT DOOR - RH	Repair	2,073.00 FS	*- FS
77	1		*FRONT OUTER DOOR SEAL - RH	Not Necessary	146.00 FS	*- FS
78	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
79	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
80	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
81	2		*FRONT DOOR ATTACHMENT PARTS - LH / RH	Not Necessary	436.00 FS	*- FS
82	2		*FRONT DOOR CATCH	Not Necessary	191.00 FS	*- FS
83	2		*FRONT DOOR CATCH COVER	Not Necessary	26.00 FS	*- FS
84	2		*FRONT DOOR CHECK STRAP - LH / RH	Not Necessary	82.00 FS	*- FS
85	2		*FRONT ROOF STRIP MOLDING - LH / RH	Not Necessary	1,074.00 FS	*- FS
86	2		*FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH / RH	Not Necessary	494.00 FS	*- FS
87	1		*FRONT WINDSCREEN	Cut	988.00 FS	*790.00 FS
88	1		*GEIL FOIL FOR RAIN SENSOR	Necessary	128.00 FS	*102.40 FS
89	1		*DATA PLATE FOR TYRE PRESSURE	Not Necessary	26.00 FS	*- FS
90	1		*AIRBAG UNIT FOR STEERING WHEEL	Activated	3,141.00 FS	*2,512.80 FS
91	1		*AIRBAG UNIT	Activated	4,238.00 FS	*3,390.40 FS
92	2		*HEAD AIR BAG UNIT	Activated	3,416.00 FS	*2,732.80 FS
93	1		*KNEE AIR BAG UNIT	Activated	1,708.00 FS	*1,366.40 FS
94	1		*AIR BAG CONTROL UNIT	Activated	1,606.00 FS	*1,284.80 FS
95	1		*AIR BAG CASH SENSOR	Activated	1,145.00 FS	*915.60 FS
96	1		*SPORT STEERING WHEEL	Cut	2,169.00 FS	*1,735.20 FS
97	1		*DASH BOARD WITH AIR DUCT	Torn	3,887.00 FS	*3,109.60 FS
98	1		*DASH BOARD PANEL UNDERTRAY - RH	Not Necessary	413.00 FS	*- FS
99	1		*HEADLINING	Crumpled	1,809.00 FS	*1,447.20 FS
100	2		*FRONT A PILLAR COVER - LH / RH	Cut	294.00 FS	*234.40 FS
101	2		*FRONT GRAB HANDLE FOLDING - LH / RH	Damaged	258.00 FS	*206.40 FS
102	2		*REAR GRAB HANDLE FOLDING - LH / RH	Damaged	258.00 FS	*206.40 FS
103	2		*THREE POINT AUTOMATIC SEAT BELT - LH / RH	Activated	2,010.00 FS	*1,608.00 FS
104	1				361.00 FS	*144.40 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRONT SEAT BELT HEIGHT ADJUSTER (2PCS)	Damaged (1Pc Only)		
105	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
106	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
107	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
108	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
109	1		*FRONT CAR PLATE NO.	Bent	25.00 FS	*25.00 FS
110	1		*SUNDRIES	Necessary	1,500.00 FS	*148.32 FS
111	1		*SEAT HEADREST	Repair	648.00 FS	*- FS
112	1		*DASHBOARD AIR VENT CENTRE	Cracked	110.00 FS	*110.00 FS
113	1		*LOUDSPEAKER COVER	Cracked	68.16 FS	*68.16 FS
114	1		*FLAT CONNETOR HOUSING	Broken	12.24 FS	*12.24 FS
115	1		*EXTERNAL TEMPERATURE SENSOR BRACKET	Broken	13.04 FS	*13.04 FS
116	1		*HEADLIGHT WASHER HOSE	Cut	59.92 FS	*59.92 FS
117	1		*STARTER	Cracked	1,154.40 FS	*1,154.40 FS
118	1		*FLAT MALE CONNECTOR	Necessary	34.24 FS	*34.24 FS
119	1		*BUTT CONNECTOR	Necessary	38.40 FS	*38.40 FS
120	1		*RETURN HOSE	Broken	17.28 FS	*17.28 FS
121	1		*AIR INTAKE DUCT COVER	Missing	21.36 FS	*21.36 FS
122	1		*AIR DUCT	Cracked	14.48 FS	*14.48 FS
123	1		*INTAKE MANIFOLD	Cracked	470.00 FS	*470.00 FS
124	1		*TURBO INTERCOOLER	Dented	553.20 FS	*553.20 FS
125	1		*AIR COND BRACKET	Broken	19.60 FS	*19.60 FS
126	1		*EXTERNAL TEMPERATURE SENSOR	Crumpled	42.96 FS	*42.96 FS
F=Franchise part. S=SpcNett.					Total Parts (\$\$)	74,020.28 49,695.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER	New	800.00	0.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
3	TO REMOVE AND TRANSFER BOTH FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	560.00	0.00
4	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENE DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAGS AND KNEE AIRBAG	New	3,600.00	3,600.00
5	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
6	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR-O-LINER REPAIRS	New	2,800.00	0.00
7	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR-OLINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	2,400.00	0.00
8	TO PLACE VEHICLE ON CAR-O-LINER	New	1,800.00	0.00
9	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH FRONT FENDERS, BOTH HEADLIGHTS AND BOTH FRONT DOORS. CUT OUT AND REWELD LHS FENDER SUPPORT AND CLOSING ELEMENT. ALIGN BOTH FRONT CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. RENEW FRONT LOCK CARRER AND ALIGN TO POSITION. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	10,200.00	4,500.00
10	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH UPPER A-PILLAR, LHS FENDER TOP SUPPORT, BOTH FRONT DOORS AND ENGINE COMPARTMENT. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT	New	7,700.00	4,875.00
11	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	0.00
12	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
13	TO DISMANTLE BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSYS TO FACILITATE RESPRAYING FOR BOTH FRONT DOORS	New	600.00	600.00
14	TO REMOVE AND RENEW INTAKE MANIFOLD AND OTHER DAMAGED ENGINE COMPONENTS	New	900.00	900.00
15	TO REPLACE FRONT WINDSCREEN SOLAR FILM	New	400.00	400.00
16	TO REMOVE AND RENEW AIR CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
Gross Labour Cost (\$\$)			34,424.00	17,299.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >