

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5989Z**AAD1902-238***Not Authorised**Recovery B4 pain**81P74.53*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5989Z

JTDKB3FU603075699

TOYOTA

PRIUS

27.2.2019

AIG

1/11/2018

PART**LIST**

- | | |
|----|-------------------------------------|
| 1 | 1 REAR BUMPER |
| 2 | 1 REAR BUMPER RE-INFORCEMENT |
| 3 | 1 REAR BUMPER TOWING COVER |
| 4 | 1 REAR BUMPER UNDER COVER (BLACK) |
| 5 | 1 REAR BUMPER SIDE RETAINER LH |
| 6 | 1 REAR BUMPER SIDE RETAINER RH |
| 7 | 1 REAR TAILGATE |
| 8 | 1 REAR TAILGATE OUTER GARNISH |
| 9 | 1 COVER, REAR COMBINATION LAMP, RH |
| 10 | 1 COVER, REAR COMBINATION LAMP, RH |
| 11 | 1 GARNISH, BACK DOOR SIDE, LH |
| 12 | 1 GARNISH, BACK DOOR SIDE, RH |
| 13 | 1 BOARD ASSY, BACK DOOR TRIM |
| 14 | 1 PANEL ASSY, BACK DOOR TRIM, UPPER |
| 15 | 1 REAR TAILGATE WEATHERSTRIP |
| 16 | 1 REAR END PANEL |
| 17 | 1 TAILLAMP LOWER RH |
| 18 | 1 TAILLAMP UPPER RH |
| 19 | 1 REAR BUMPER SIDE RH |
| 20 | 1 REAR BUMPER SIDE LH |
| 21 | 1 TAILLAMP LOWER LH |
| 22 | 1 TAILLAMP UPPER LH |

\$	<i>B</i>	458.60	✓
\$	<i>B</i>	318.80	✓
\$	<i>mi</i>	14.70	✓
\$	<i>nd/um</i>	552.60	✓
\$	<i>sn</i>	112.70	✓
\$	<i>ni</i>	112.70	✓
\$	<i>n</i>	1,547.27	} X
\$	<i>sn</i>	905.10	
\$	<i>sn</i>	54.70	
\$	<i>sn</i>	54.70	
\$	<i>sn</i>	93.60	
\$	<i>sn</i>	93.60	
\$	<i>sn</i>	254.40	
\$	<i>sn</i>	51.20	
\$	<i>sn</i>	365.20	
\$	<i>n</i>	602.10	
\$	<i>sn</i>	548.40	} X
\$	<i>sn</i>	557.90	
\$	<i>ng/ni</i>	232.00	
\$	<i>sn</i>	232.00	X
\$	<i>sn</i>	548.40	X
\$	<i>sn</i>	557.90	X
\$		8,268.57	
25% \$		2,067.14	
\$		6,201.43	

Special Nett

1 1SET PARKING AID

\$ *Short* 700.00 *250.00*

Trans-cab Auto Services Pte Ltd**AAD1902-238**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5989Z

2 1SET REAR BUMPER CLIP	\$	nn 22.00 ✓
3 2 REAR WINDSCREEN SELANT	\$	nn 80.00
4 1 WINDSCREEN MOULDING	\$	nn 100.00
5 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00
6 1 REAR TAILGATE TOYOTA LOGO	\$	nn 47.00
7 1 REAR TAILGATE WORDING 'PRIUS'	\$	nn 52.90
8 1 REAR TAILGATE WORDING 'HYBRID'	\$	nn 53.50
9 1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn 80.00
10 1 REAR TAILGATE STICKER '6555-3333'	\$	nn 80.00
11 1 REAR BUMPER PROTECTOR	\$	nn 100.00 5051

TOTAL \$ 1,315.40**TOTAL PARTS \$ 7,516.83****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 2001
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 2201
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 501
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn 170.00 X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00 X
To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1902-238**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5989Z

To transfer of rear end panel fittings, attachment and
perform water seepage test.

\$ *nn* 170.00 *X*

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 *X*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 *X***TOTAL \$ 7,580.00****Over All Total \$ 21,298.26****(PART-BY-PART) Repair Days***10 DAYS**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: