

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H**AAD1902-198***Not Authorized**Reserve B4 paint**82841-16*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 339H

VF1ABL15AUC282743

RENAULT

LATITUDE

22.2.2019

FCIL

22/3/2016

PART

1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER INSULATOR RH
1	DOOR PANEL FRT RH
1	WIPER RESERVOIR
1	WIPER RESERVOIR NECK
1	WIPER RESERVOIR MOTOR
1	RADIATOR GRILL

LIST

\$	<i>Bu 1/2</i> 1,259.42	✓
\$	<i>Sn</i> 181.75	X
\$	<i>Sn</i> 394.68	X
\$	<i>Di</i> 150.77	✓
\$	<i>Sn</i> 123.88	X
\$	<i>Sn</i> 472.83	X
\$	<i>Sn</i> 266.80	X
\$	<i>Sn</i> 207.21	X
\$	<i>R</i> 914.08	X
\$	<i>Argenta</i> 1,184.43	✓
\$	<i>R</i> 152.15	} X
\$	<i>R</i> 783.83	
\$	<i>Sn</i> 278.84	
\$	<i>Sn</i> 15.79	
\$	<i>Sn</i> 130.84	
\$	<i>R</i> 2,844.66	
\$	<i>Sn</i> 348.25	
\$	<i>Sn</i> 136.11	
\$	<i>Sn</i> 270.06	
\$	<i>Sn</i> 1,707.78	
TOTAL \$	11,824.17	
10% \$	1,182.42	
\$	10,641.75	

Special Nett

1SET	BUMPER CLIP FRT	\$
1	BUMPER BRACKET CLIP FRT RH	\$
1	BUMPER SUPPORT CLIP FRT RH	\$
1SET	BUMPER GRILLE LOWER CLIP	\$

<i>Net</i> 66.00	✓
<i>nn</i> 12.00	X
<i>nn</i> 10.50	X
<i>nn</i> 69.00	X

Trans-cab Auto Services Pte Ltd

AAD1902-198

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	<i>nn</i> 80.00	X
1	FRONT RIGHT DOOR STICKER 'CHASSIS'	\$	<i>nn</i> 50.00	X

\$	157.50
----	--------

TOTAL	\$	10,799.25
--------------	----	------------------

TOTAL PARTS**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	<i>2200</i>
Putty and spray painting of the affected portion.	\$	3,000.00	<i>2000</i>
To rust-proofing of the affected areas.	\$	<i>nn</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>200</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00	X
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1902-198**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

To vacuum, replace, refix and recharge Air
Intercooler

\$ *~ 170.00* X

TOTAL	\$	8,210.00
--------------	-----------	-----------------

Over All Total	\$	19,009.25
-----------------------	-----------	------------------

PART-BY-PART(REPAIR DAY)*10 DAYS**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before repairs are pointing
- To display damaged parts during resurvey
- Parts prices must be confirmed
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplimentary charges must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: