

ASS. REC. BY:

REF:

CS/FCI19004019/KW3

02

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

05/3/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 339H

Insured:

SHC 861SE

at Workshop m/s

Trans - Cab

Tel:

of

Amul

Policy No:

Claim No:

D19001417MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/2/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (

) Estimate

SHD 339H x

SHC 861SE x

ASS. REC. BY:

REF: 10021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 33914

Yr Regn:

03.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c

1985

Colour:

W.4 / R.1

A/C: Insured / Std / NI / NA

Sp. Reading

324828

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1 ABL15AUC 282743

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S / Rim / STD A / Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

22/2/19

D.O.I.

8/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File pass to

7/3/19

82841-16

(Red 16,168.09, 859)

RECEIVED 07 MAR 2019

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

7/3 - typist

Report Format:

Lump Sum / I.B.I. (\$)

CWS

2841.16

Days Of Repair:

2

Resurvey No. of Trip:

-

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - R.S. \$

Fees

Others

TOTAL

390

MOTOR SURVEY ASSIGNMENT

Date	26-02-2019	Our Ref No. D19001417MFSH
Accident Date	22-02-2019	Claim Type. Third Party
Insured Vehicle	SHC8618E	Third Party Vehicle. SHD339H
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

Kenneth
FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 7 March 2019 2:50 PM
To: Ng Wai Yin; calvin.er@transcab.com.sg
Cc: SUR; jasminetan@transcab.com.sg
Subject: FW: SHD 339H-DOA: 22/2/2019
Attachments: MARK EST.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Finalize amount \$2841.16 before GST @ 2 days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

2/25/2019

PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD339H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Feb 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002938
Chassis No.:	VF1ABL15AUC282743
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	22 Mar 2016
First Registration Date:	22 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Mar 2024
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	21 Mar 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$39,633.00
COE Rebate Amount:	\$25,107.00
Total Rebate Amount:	\$40,105.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Feb 2019

OK

Trans-cab Auto Services Pte Ltd

AAD1902-198

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H*Not Notified**Assess by paint**82841-16*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 339H

VF1ABL15AUC282743

RENAULT

LATITUDE

22.2.2019

FCIL

22/3/2016

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER INSULATOR RH
1	DOOR PANEL FRT RH
1	WIPER RESERVOIR
1	WIPER RESERVOIR NECK
1	WIPER RESERVOIR MOTOR
1	RADIATOR GRILL

	LIST
\$	<i>Bul</i> 1,259.42 ✓
\$	<i>Sn</i> 181.75 X
\$	<i>Sn</i> 394.68 X
\$	<i>Di</i> 150.77 ✓
\$	<i>Sn</i> 123.88 X
\$	<i>Sn</i> 472.83 X
\$	<i>Sn</i> 266.80 X
\$	<i>Sn</i> 207.21 X
\$	<i>N</i> 914.08 X
\$	<i>Ng</i> 1,184.43 ✓
\$	<i>N</i> 152.15
\$	<i>N</i> 783.83
\$	<i>Sn</i> 278.84
\$	<i>Sn</i> 15.79
\$	<i>Sn</i> 130.84
\$	<i>N</i> 2,844.66 } X
\$	<i>Sn</i> 348.25
\$	<i>Sn</i> 136.11
\$	<i>Sn</i> 270.06
\$	<i>Sn</i> 1,707.78
TOTAL	\$ 11,824.17
10%	\$ 1,182.42
	\$ 10,641.75

Special Nett

1SET	BUMPER CLIP FRT	\$	<i>N</i> 66.00 ✓
1	BUMPER BRACKET CLIP FRT RH	\$	<i>N</i> 12.00 X
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>N</i> 10.50 X
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>N</i> 69.00 X

Trans-cab Auto Services Pte Ltd

AAD1902-198

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	80.00	X
1	FRONT RIGHT DOOR STICKER 'CHASSIS'	\$	50.00	X

\$	157.50
----	--------

TOTAL \$	10,799.25
----------	-----------

TOTAL PARTS**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	3,000.00	2201
----	----------	------

Putty and spray painting of the affected portion.

\$	3,000.00	2001
----	----------	------

To rust-proofing of the affected areas.

\$	170.00	X
----	--------	---

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$	380.00	X
----	--------	---

To check steering geometry and computer wheel alignment

\$	220.00	X
----	--------	---

To transfer of tire, rim and on wheel balancing.

\$	170.00	X
----	--------	---

To Check Electrical Lighting Concerned.

\$	170.00	201
----	--------	-----

To transfer of front fender fittings, attachment and perform water seepage test.

\$	380.00	X
----	--------	---

To vacuum, replace, refix and recharge air condenser

\$	380.00	X
----	--------	---

To replace, refix and top up coolant for radiator

\$	170.00	X
----	--------	---

Trans-cab Auto Services Pte Ltd

AAD1902-198

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

To vacuum, replace, refix and recharge Air
Intercooler

\$ ~ 170.00 X

TOTAL \$ 8,210.00

Over All Total \$ 19,009.25

PART-BY-PART(REPAIR DAY)

10 DAYS

2 days

19139.24

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before start of repair
- To display damaged car in survey
- Parts prices are on "no prejudice" basis
- Third party work is on "no prejudice" basis
- No illegal modification is allowed
- Supply emergency repair must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19004019/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-03-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8618E		Veh. Inspected	SHD 339H
Policy No.			Coverage (\$)	0.00
Claim No.	D19001417MFSH		Excess (\$)	0.00
Assign From	EILEEN		Assign Date	05/03/2019
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)		c.c	1995
Engine No.	HIDDEN		Year of Reg.	2016
Chassis No.	VF1ABL15AUC282743		Colour	WHITE / RED
Odometer	324926		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	9 mm	
L/H Front Tyre	215/60 R16	GITI	9 mm	
R/H Rear Tyre	215/60 R16	GITI	9 mm	
L/H Rear Tyre	215/60 R16	GITI	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/02/2019		Inspection Date	06/03/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 339H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER FRT	BUCKLED / DENTED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT RH	DISTORTED	150.77	150.77
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	HEADLAMP RH	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	RADIATOR GRILL	SERVICEABLE	1,707.78	-
	LESS 10% DISCOUNT		-1,182.42	-259.46
			10,641.74	2,335.16
SPECIAL NETT ITEMS				
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-

Report Ref No. CS/FCI19004019/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RIGHT DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	FRONT RIGHT DOOR STICKER "CHASSIS" (SN)	NOT NECESSARY	50.00	-
			287.50	66.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,HEADLAMP PANEL FRT RH,FENDER PANEL FRT RH AND DOOR PANEL FRT RH.		3,000.00	220.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
			8,210.00	440.00
GRAND TOTAL			19,139.24	2,841.16
RECOMMENDED COST OF REPAIRS				2,841.16

Report Ref No. CS/FCI19004019/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.