

INSURER

INS. CASE OWNER:

CC 6 /AIG1900

LICK

IDAC:

Surveyor:

Ardian

DOI:

ASSIGNMENT

04/11/19

Date / Time:

4/12/19

Registered in Merimen:

5/12/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGP 7883E

Claim No.:

757624661154

Name of Insured:

UTMAY SHARMINI D/O SUPKURNAMAH

Policy No.:

1506161133

Insured Tel No.:

HP:

Make / Model:

Subaru

Excess Sec II :SS

D.O.A.:

Place of Accident:

Mamori Rd.

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SW 955T



INSRS:

WSP:

Tel:

Liability:

RMKS:

SW WERKZ



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

6/1/2020
klondike

SW 955T - 6

SGP 7883E - 4

File pass to me to close

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OT:

After call 1st to OT:

2/9/19 klondike

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OT:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / CIA:

Medical Bill:

PTR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

US \$5 5,000

(6 days) Reduction:

65 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

5/12/19 Confirm with: Chris

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

77

If NO or B 28, Ass. Lio:

Repair Cost:

\$5 5,000

(01 REAR END (P))

Loss of Rental (LOR):

\$5 800

(8 days) X \$100

Loss of Use (LOU):

\$5 -

(8 days)

Loss of Income (LOI):

\$5 -

(8 days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GLA/LTA Search:

\$5 -

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/Independent)

Legal Cost:

\$5 -

Total:

\$5 5,800

Global Sum \$5:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee:

\$320

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

\$5 5,800

Name 1:

SW WERKZ PTE LTD

Payee 2: (Strike if N.A.)

\$5 -

Name 2:

Payee 3: (Strike if N.A.)

\$5 -

Name 3:

Adrian

ASSIGNMENT

Frpt: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLD955ST Yr Regn: 2008, JuneType: MC / MCycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish CC 1794Colour: Grey A/C: Insured / Std / Nil / NASp. Reading 224513 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JTDER 12W 903000063Gen. Cond: Good / Fair / Poor / BurntSteering: Ins / Jammed / Leaked / Burnt orBrake: Ins / Jammed / Leaked / Burnt orModi: Nil / SR / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 04/03/19Survey held at SW WorkzDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG.

WE Expiry: 24/06/23.

CL/S \$5,000 / Red \$9,108.62 / 65%.

MV: 28k

PV: 16.3k

Nett: 11.7k.

6 days + 1 Sunday + 1 PRS = 8 days.

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report

Final Report

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, \$

Photos

Others

TOTAL

Date:

Sheet1

SW WERKZ PTE LTD

BLOCK 25 KAKI BUKIT ROAD 4 #03-65/67/68 SYNERGY @ KB Singapore 417800
 HP: 92712214 TEL: (65) 63844844 FAX: (65) 63834944

01st MARCH 2019

RS CAR LEASING PTE LTD
 25 KAKI BUKIT ROAD 54
 # 03-65/67/68 SYNERGY @KB
 Singapore 417800

TP A167

JTDER12W903000063

Khanchana

Accident date: 28th JANUAR 2019
 Estimated repair cost for vehicle no: SLD9555T Toyota Wish 1.8 A

S/n	Qty	Items	U/price	Amount
				\$1,250.00
1	1	Rear Boot Lid <i>Distorted</i>		\$375.40
2	2	Rear Boot Lid Hinges <i>Not new</i>	\$187.70	\$74.10
3	1	Rear boot lid emble logo <i>New</i>		\$549.10 389
4	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$276.10
5	1	Rear boot lid inner rubber <i>At</i>		\$513.80 238
6	1	Rear Boot Lid center moulding <i>Cracked</i>		\$17.00
7	2	Rear Boot Lid center moulding side clips <i>New</i>	\$8.50	\$50.00 X
8	1	Rear Boot Lid Number Plate <i>Not new</i>		\$270.20 X
9	2	Rear Boot Lid Number Plate Lamp <i>Not new</i>	\$135.10	\$680.80 485
10	1	Rear Boot Lid Inner Trim board <i>Cracked</i>		\$68.00 X
11	1	Rear Boot Lid Inner lock side cover <i>Not new</i>		\$310.10 246
12	1	Rear boot lid windscreen seal <i>New</i>		\$1,280.20 819.
13	2	Rear tail lamp <i>Cracked</i>	\$840.10	\$34.00 10.
14	4	Rear tail lamp clips <i>New</i>	\$8.50	\$640.00 X
15	2	Rear tail lamp panel <i>Repair</i>	\$320.00	\$740.00 578
16	1	Rear End Panel outer <i>Dented</i>		\$580.00 X
17	1	Rear End Panel inner <i>Repair</i>		\$402.40 295
18	1	Rear End Panel Top Garnish <i>Deformed</i>		\$536.10 X
19	1	Rear spare tire lock <i>Not new</i>		\$536.77 X
20	1	Rear floor panel top cover <i>Not new</i>		\$120.00 X
21	1	Rear floor panel sealant <i>Not new</i>		\$1,072.00 545
22	1	Rear Bumper <i>Deformed</i>		\$166.20 X
23	2	Rear Bumper side reflector <i>Not new</i>	\$83.10	\$111.20
24	2	Rear Bumper Side Bracket <i>New</i>	\$55.60	\$350.00 200/200
25	1	Rear Bumper reverse sensor <i>Damaged</i>	\$68.40	\$136.80
26	2	Rear Bumper Bracket <i>Dented</i>	\$6.50	\$52.00 30
27	8	Rear bumper clips <i>New</i>		\$212.16 X
28	1	rear exhaust aluminium cover <i>Not new</i>		

Subtotal :- \$11,508.62

Page 361

5500-20

S.N.200

751 = 412515

labour charges

To Check Wiring System
Tuff Kote
To Remove & refix cushion
To Remove & refix rear windscreen
Gum
To Remove & refix reverse Sensor
Panel beating
Spray painting

1970

~~\$80.00~~ 30

~~\$150.00~~ 60

~~\$120.00~~ 60

~~\$120.00~~ ✓

~~\$50.00~~ ✓

~~\$100.00~~ 50

~~\$1,000.00~~ 820

~~\$1,000.00~~ 820

Subtotal :- \$2,600.00

Total:- \$14,108.82

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 625515

l/s: SK

06/07/20

Sheet1

SW WERKZ PTE LTD

BLOCK 25 KAKI BUKIT ROAD 4 #03-65/67/68 SYNERGY @ KB Singapore 417800
 HP: 92712214 TEL: (65) 63844844 FAX: (65) 63834944

01st MARCH 2019

RS CAR LEASING PTE LTD
 25 KAKI BUKIT ROAD 54
 # 03-65/67/68 SYNERGY @KB
 Singapore 417800

TPA19

JTDER12W903000063

Khanchana

Accident date: 28th JANUAR 2019
 Estimated repair cost for vehicle no: SLD9555T Toyota Wish 1.8 A

S/n	Qty	Items	U/price	Amount
				\$1,250.00
1	1	Rear Boot Lid <i>Distorted</i>	\$187.70	\$375.40
2	2	Rear Boot Lid Hinges <i>Not new</i>		\$74.10
3	1	Rear boot lid emble logo <i>new</i>		\$549.10
4	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$276.10
5	1	Rear boot lid inner rubber <i>lt</i>		\$613.80
6	1	Rear Boot Lid center moulding <i>cracked</i>		\$17.00
7	2	Rear Boot Lid center moulding side clips <i>new</i>	\$8.50	\$50.00
8	1	Rear Boot Lid Number Plate <i>Not new</i>		\$270.20
9	2	Rear Boot Lid Number Plate Lamp <i>Not new</i>	\$135.10	\$680.00
10	1	Rear Boot Lid Inner Trim board <i>cracked</i>		\$68.00
11	1	Rear Boot Lid Inner lock side cover <i>Not new</i>		\$310.10
12	1	Rear boot lid windscreen seal <i>Not</i>		\$1,280.20
13	2	Rear tail lamp <i>cracked</i>	\$640.10	\$34.00
14	4	Rear tail lamp clips <i>new</i>	\$8.50	\$640.00
15	2	Rear tail lamp panel <i>Repair</i>	\$320.00	\$740.00
16	1	Rear End Panel outer <i>Dented</i>		\$580.00
17	1	Rear End Panel inner <i>Repair</i>		\$403.40
18	1	Rear End Panel Top Garnish <i>Deformed</i>		\$536.10
19	1	Rear spare tire lock <i>Not new</i>		\$535.77
20	1	Rear floor panel top cover <i>Not</i>		\$120.00
21	1	Rear floor panel sealant <i>Not</i>		\$1,077.00
22	1	Rear Bumper <i>Deformed</i>		\$166.20
23	2	Rear Bumper side reflector <i>Not new</i>	\$83.10	\$111.20
24	2	Rear Bumper Side Bracket <i>new</i>	\$55.60	\$350.00
25	1	Rear Bumper reverse sensor <i>Damaged</i>	\$68.40	\$136.80
26	2	Rear Bumper Bracket <i>Dented</i>	\$6.50	\$52.00
27	8	Rear bumper clips <i>Not</i>		\$212.15
28	1	rear exhaust aluminium cover <i>Not new</i>		

Subtotal :- \$11,508.62

6500.20

412515

S.N:200

labour charges

To Check Wiring System

Tuff Kote

To Remove & refix cushion

To Remove & refix rear windscreen

Gum

To Remove & refix reverse Sensor

Panel beating

Spray painting

~~\$60.00~~ 30

~~\$150.00~~ 60

~~\$120.00~~ 60

~~\$120.00~~ ✓

~~\$50.00~~ ✓

~~\$100.00~~ 50

~~\$1,000.00~~ 800

~~\$1,000.00~~ 800

Subtotal :- \$2,600.00

Total:- \$14,108.62

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6255.15
c/s: SK
06/11/15

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3098R
Vehicle Details	
Vehicle No.:	SLD9555T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 AUTO
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	1ZZ3111565
Chassis No.:	JTDER12W903000063
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,803.00
Original Registration Date:	25 Jun 2008
First Registration Date:	25 Jun 2008
Transfer Count:	3
Actual ARF Paid:	\$18,803.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jun 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$18,953.00
COE Rebate Amount:	\$16,320.00
Total Rebate Amount:	\$16,320.00
Miscellaneous	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Mar 2019

OK



New Arrival, Good For Short Term Ride, Low Monthly From \$600, So Call To View Before Is Gone.

☆ Posted: 04-Mar-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



☐ Toyota Wish 1.8A (COE till 10/2021) \$22,500 \$8,700 /yr 04-Oct-2006 1,794 cc 216,000 km MPV Available

Replacements Since Purchase In Dec 2016: 1. New Leather Upholstery 2. New 17" Alloy Rims 3. New 17" Tyres (latest Change May 18) 4. New Windscreen (01/17) 5. Rear Brake Shoes And Front Brake Pads (01/...

Carro

☆ Posted: 02-Mar-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



☐ Toyota Wish 1.8A (COE till 08/2021) \$21,800 \$8,730 /yr 27-Oct-2006 1,794 cc - MPV Available

Superb Condition, Very Well Taken Care, Don't Miss It. Up To 100% Flexible Loan. We Provide Lowest Interest Rate, Flexible Loan And High Trade In. Are Available. Package With Unrivaled Warranty Complete W...

Classic Credit Pte Ltd

☆ Posted: 11-Feb-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



☐ Toyota Wish 1.8A (COE till 12/2021) \$20,800 \$7,420 /yr 22-Dec-2006 1,794 cc - MPV Available

New Arrival! Well Maintained By Previous Owner. Low Mileage At 15,000km/Yr. Most Sought After MPV, 120 Points Check By Our In House Workshop. In House Loan Available. Call Us For Viewing Right Now.

☆ Posted: 28-Feb-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Insurance renewal at cheaper price!

We'll find you the cheapest car insurance quotes from over 10 insurers. Make your choice on zero excess and own workshop. Everything done at the comfort of your own home. Roadside assistance & claims support completely free.

Find out more!



☐ Toyota Wish 1.8A Sunroof (COE till 01/2027) \$49,800 \$6,290 /yr 30-Jan-2007 1,794 cc 172,664 km MPV Available

Rare Wish 1.8A With Sunroof/Rear Air-Con Of Low \$6,300 Depreciation Yet Price Negotiable! Road Tax Till Jan 20! Low Mileage Clocked Of 14500km Annually. Superb Condition. 100% Accident Free. Call Now!

Lake View Credit Pte Ltd

☆ Posted: 02-Mar-2019 Tags: 2007 Toyota Wish, 2007 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



☐ Toyota Wish 1.8A (COE till 03/2027) \$52,555 \$6,550 /yr 12-Mar-2007 1,794 cc - MPV Available

100% Loan Available! Minimum Losses! Easy Maintained And Reliable! Guaranteed 100% Loan Approval, Free 1 Year Warranty, Free Servicing, Free Polishing. Highest Trade In For Your Used Car. Hurry Buy No...

Cars Inn Credit Pte Ltd

☆ Posted: 07-Jan-2019 Tags: 2007 Toyota Wish, 2007 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



☐ Toyota Wish 1.8A Aero Tourer (COE till 07/2023) \$31,500 \$7,150 /yr 31-Jul-2008 1,794 cc 136,000 km MPV Available

Great MPV Choice Of Toyota Wish 1.8A With New 5 Years COE! Low Mileage Clocked Of 17500km Annually. No Other Repairs Needed. New Tyres. 100% Accident-Free. Trade In Welcome!

☆ Posted: 21-Feb-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



☐ Toyota Wish 1.8A (COE till 09/2023) \$30,888 \$6,810 /yr 15-Sep-2008 1,794 cc - MPV Available

One Owner, Very Well Taken Care, Service With The Agent Up To Now. Don't Miss, Lowest Price In Town. Warranty On Engine And Gearbox. Please Call.

☆ Posted: 26-Feb-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



☐ Toyota Wish 1.8A (COE till 10/2028) \$52,000 \$5,400 /yr 16-Oct-2008 1,794 cc - MPV Available

Most Part Change And No Repair Needed. Well Maintain By Seller. New Tyre And Battery. Call Now For Details.

☆ Posted: 11-Feb-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



☐ Toyota Wish 1.8A (COE till 10/2023) \$32,838 \$7,090 /yr 30-Oct-2008 1,794 cc - MPV Available

High Trade In Most Welcome! Flexible Bank/In-House Loan Available! 100% Loan At 2.98%. Can Be Arranged! View To Believe! Don't Miss, Call Now To Arrange A Test Drive Today!

☆ Posted: 23-Jan-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

SHORTLISTED RECENT

Compare

☐ Toyota Wish 1.8A (COE till 04-Dec-2008) \$36,000 \$7,570 /yr 04-Dec-2008 1,794 cc 138,000 km MPV Available

Dear Khanchna ,

Accept _DV please . Thanks

Get [Outlook for iOS](#)

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Sent: Thursday, December 5, 2019 5:33:47 PM
To: chris_chanbebe@hotmail.com <chris_chanbebe@hotmail.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: SLD9555T & SLD9555T DOA 28.1.19

Without Prejudice

Dear Sirs/Mdm,
We refer to the above matter.

We propose settlement as follows:

1. Cost of Repair	\$ 5,000.00
2. Loss of Rental (8 days x \$100)	\$ 800.00
Total	\$ 5,800.00

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Thursday, 7 November 2019 9:50 AM
To: chris_chanbebe@hotmail.com
Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Khanchna (LKK Auto)

Khanchna (LKK Auto)

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Thursday, 19 December 2019 9:42 PM
To: Khanchna (LKK Auto)
Subject: Re: SLD9555T & SLD9555T DOA 28.1.19
Attachments: DV.jpg

Dear Khanchna ,

Enclosed is the DV .
Please let us have payment soon . Thanks

Regards,
Chris Chan Pick Yuen

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Sent: Thursday, December 5, 2019 5:57 PM
To: chan pick yuen <chris_chanbebe@hotmail.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: SLD9555T & SLD9555T DOA 28.1.19

Without Prejudice
Dear Chris,
Thank you for the acceptance.

We attach herewith a copy of the DV for your further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.
In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Thursday, 5 December 2019 5:35 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: Re: SLD9555T & SLD9555T DOA 28.1.19

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2019 Edit Reg		04 Mar 2019 00:00 Edit Adj Rpt	S\$5,000.00 Edit Estimates	S\$5,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Vithya Sharmini D/O Supramaniam, ID: S88205831									
Main Claimant: RS CAR LEASING PTE LTD, Co. Reg. No.: 201843098R									
Vehicle Reg. No.: SLD9555T		Date of Loss: 28/01/2019 08:00 - :59 [127 Months and 3 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7536746611SG		Policy/Cover Note No.: 1800101133 (Comprehensive)							
Vehicle Reg. No. (Insured): SGP7883E		Policy No. (Claimant): 5106982526							
		Excess:							
Repairer: Sw Werkz Pte Ltd (HQ) BLK 25 KAKI BUKIT ROAD 4, #03-67/68 SYNERGY @ KAKI BUKIT, 417800 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/03/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLD9555T (7536746611SG)**
[SGP7883E]
TP
RS CAR LEASING PTE LTD
Jan 28 2019 8:00AM
[Vithya Sharmini D/O Supramaniam]
Sw Werkz Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Letters/Correspondences														1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown											1	Edit			
Assessment Reports														1 per page		☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail		Print		
1	06/03/19 16:54	Accident Statement From:OD - Reg. No: SGP7883E, Claimant: VITHYA SHARMINI D/O SUPRAMANIAM											1	Load HTM			
Photos/Images														3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	27/09/19 18:06	General View											1	Load JPG	☒		
2	27/09/19 18:06	General View											1	Load JPG	☒		
3	27/09/19 18:06	General View											1	Load JPG	☒		
4	27/09/19 18:06	General View											1	Load JPG	☒		
5	27/09/19 18:06	General View											1	Load JPG	☒		
6	27/09/19 18:06	General View											1	Load JPG	☒		
7	27/09/19 18:06	General View											1	Load JPG	☒		
8	27/09/19 18:06	General View											1	Load JPG	☒		
9	27/09/19 18:06	General View											1	Load JPG	☒		
10	27/09/19 18:06	General View											1	Load JPG	☒		
11	27/09/19 18:06	General View											1	Load JPG	☒		
12	27/09/19 18:06	General View											1	Load JPG	☒		
13	27/09/19 18:06	General View											1	Load JPG	☒		
14	27/09/19 18:06	General View											1	Load JPG	☒		
15	27/09/19 18:06	General View											1	Load JPG	☒		
16	27/09/19 18:06	General View											1	Load JPG	☒		
17	27/09/19 18:06	General View											1	Load JPG	☒		
18	27/09/19 18:06	General View											1	Load JPG	☒		
19	27/09/19 18:06	General View											1	Load JPG	☒		
20	27/09/19 18:06	General View											1	Load JPG	☒		
21	27/09/19 18:06	General View											1	Load JPG	☒		
22	27/09/19 18:06	General View											1	Load JPG	☒		
23	27/09/19 18:06	General View											1	Load JPG	☒		
24	27/09/19 18:06	General View											1	Load JPG	☒		
25	27/09/19 18:06	General View											1	Load JPG	☒		
26	27/09/19 18:06	General View											1	Load JPG	☒		
27	27/09/19 18:06	General View											1	Load JPG	☒		
28	27/09/19 18:06	General View											1	Load JPG	☒		
29	27/09/19 18:06	General View											1	Load JPG	☒		
30	27/09/19 18:06	General View											1	Load JPG	☒		
31	27/09/19 18:07	Reinspection Photo											1	Load JPG	☒		
32	27/09/19 18:07	Reinspection Photo											1	Load JPG	☒		
33	27/09/19 18:07	Reinspection Photo											1	Load JPG	☒		
34	27/09/19 18:07	Reinspection Photo											1	Load JPG	☒		
35	27/09/19 18:07	Reinspection Photo											1	Load JPG	☒		
36	27/09/19 18:07	Reinspection Photo											1	Load JPG	☒		

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					☒
37	27/09/19 18:07	Reinspection Photo		Load JPG	☒
38	27/09/19 18:07	Reinspection Photo		Load JPG	☒
39	27/09/19 18:07	Reinspection Photo		Load JPG	☒
40	27/09/19 18:07	Reinspection Photo		Load JPG	☒
41	27/09/19 18:07	Reinspection Photo		Load JPG	☒
42	27/09/19 18:07	Reinspection Photo		Load JPG	☒
43	27/09/19 18:07	Reinspection Photo		Load JPG	☒
44	27/09/19 18:07	Reinspection Photo		Load JPG	☒
45	27/09/19 18:07	Reinspection Photo		Load JPG	☒
46	27/09/19 18:07	Reinspection Photo		Load JPG	☒
47	27/09/19 18:07	Reinspection Photo		Load JPG	☒
48	27/09/19 18:07	Reinspection Photo		Load JPG	☒
49	27/09/19 18:07	Reinspection Photo		Load JPG	☒
50	27/09/19 18:07	Reinspection Photo		Load JPG	☒
51	27/09/19 18:07	Reinspection Photo		Load JPG	☒
52	27/09/19 18:07	Reinspection Photo		Load JPG	☒
53	27/09/19 18:07	Reinspection Photo		Load JPG	☒
54	27/09/19 18:07	Reinspection Photo		Load JPG	☒
55	27/09/19 18:07	Reinspection Photo		Load JPG	☒
56	27/09/19 18:07	Reinspection Photo		Load JPG	☒
57	27/09/19 18:07	Reinspection Photo		Load JPG	☒
58	27/09/19 18:07	Reinspection Photo		Load JPG	☒
59	27/09/19 18:07	Reinspection Photo		Load JPG	☒
60	27/09/19 18:07	Reinspection Photo		Load JPG	☒
61	27/09/19 18:07	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/03/19 18:52	TP GIA REPORT		Load PDF	
2	02/09/19 17:22	OI GIA REPORT		Load PDF	
3	02/09/19 17:27	LETTER TO OI		Load PDF	
4	10/01/20 08:43	WORKSHOP INVOICE		Load PDF	
5	10/01/20 08:43	AUTHORISATION TO ACT FORM		Load PDF	
6	10/01/20 08:43	Release Voucher		Load PDF	
7	10/01/20 08:43	RENTAL RECEIPT		Load PDF	
8	10/01/20 08:43	LOD		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGP7883E (Insd veh)	Model:	TOYOTA WISH 1.8 (A)
	SLD9555T (TP veh)		
Date of Accident:	28/01/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	14,108.62
Final Repair Cost	:	\$	5,000.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	800.00 8 days
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	5,800.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	SW Werkz Pte Ltd	:	\$ 5,800.00
2)		:	\$

JOANNE LEE KHANG MIN

10 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19004020/AKA3Q2

Date: 10/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800101133
 Claimant: SLD9555T Insured Vehicle No: SGP7883E
 Vehicle No: SLD9555T Nature of Claim: TP Claim No: 7536746611SG
 Date of Loss: 28/01/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD9555T Engine No: 1ZZ3111565
 Make & Model: TOYOTA WISH, 1.8 (A) Chassis No: JTDER12W903000063
 Reg. Date: 25/06/2008 (Man. Year: 2008) Odometer: 224573 km
 Colour: Grey
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,508.62	4,325.15	7,183.47	62.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,970.00	630.00	24.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,108.62	6,295.15	7,813.47	55.38
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	14,108.62	5,000.00	9,108.62	64.56
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
Nett Liability (S\$)		5,800.00		

INSPECTION

Date of Assignment: 04/03/2019
 Date Inspected: 04/03/2019 Inspected At: Sw Werkz Pte Ltd (HQ)
 BLK 25 KAKI BUKIT ROAD 4, #03-67/68 SYNERGY @ KAKI BUKIT
 Singapore 417800
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Distorted	1,250.00 F	*1,250.00 FL
2	2	*REAR BOOT LID HINGES	Not Necessary	375.40 F	*- FL
3	1	*REAR BOOT LID EMBLE LOGO	Necessary	74.10 F	*74.10 FL
4	1	*REAR BOOT LID INNER LOCK	Damaged	549.10 F	*389.00 FL
5	1	*REAR BOOT LID INNER RUBBER	Cut	276.10 F	*276.10 FL
6	1	*REAR BOOT LID CENTER MOULDING	Cracked	613.80 F	*238.00 FL
7	2	*REAR BOOT LID CENTER MOULDING SIDE CLIPS	Necessary	17.00 F	*17.00 FL
8	1	*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	2	*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	270.20 F	*- FL
10	1	*REAR BOOT LID INNER TRIM BOARD	Cracked	680.00 F	*485.00 FL
11	1	*REAR BOOT LID INNER LOCK SIDE COVER	Not Necessary	68.00 F	*- FL
12	1	*REAR BOOT LID WINDSCREEN SEAL	Necessary	310.10 F	*246.00 FL
13	2	*REAR TAIL LAMP	Cracked	1,280.20 F	*819.00 FL
14	4	*REAR TAIL LAMP CLIPS	Necessary	34.00 F	*10.00 FL
15	2	*REAR TAIL LAMP PANEL	Repair	640.00 F	*- FL
16	1	*REAR END PANEL OUTER	Dented	740.00 F	*578.00 FL
17	1	*REAR END PANEL INNER	Repair	580.00 F	*- FL
18	1	*REAR END PANEL TOP GARNISH	Deformed	403.40 F	*295.00 FL
19	1	*REAR SPARE TIRE LOCK	Not Necessary	536.10 F	*- FL
20	1	*REAR FLOOR PANEL TOP COVER	Not Necessary	535.77 F	*- FL
21	1	*REAR FLOOR PANEL SEALANT	Not Necessary	120.00 F	*- FL
22	1	*REAR BUMPER	Deformed	1,077.00 F	*545.00 FL
23	2	*REAR BUMPER SIDE REFLECTOR	Not Necessary	166.20 F	*- FL
24	2	*REAR BUMPER SIDE BRACKET	Necessary	111.20 F	*111.20 FL
25	1	*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
26	2	*REAR BUMPER BRACKET	Dented	136.80 F	*136.80 FL
27	8	*REAR BUMPER CLIPS	Necessary	52.00 F	*30.00 FL
28	1	*REAR EXHAUST ALUMINIUM COVER	Not Necessary	212.15 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,508.62	5,700.20
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,375.05
Total Parts (\$\$)	11,508.62	4,325.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING SYSTEM	New	60.00	30.00
2	TUFF KOTE	New	150.00	60.00
3	TO REMOVE & REFIX CUSHION	New	120.00	60.00
4	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
5	GUM	New	50.00	50.00
6	TO REMOVE & REFIX REVERSE SENSOR	New	100.00	50.00
7	PANEL BEATING	New	1,000.00	800.00
8	SPRAY PAINTING	New	1,000.00	800.00
Gross Labour Cost (S\$)			2,600.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >