

Sheet1

SW WERKZ PTE LTD

BLOCK 25 KAKI BUKIT ROAD 4 #03-65/67/68 SYNERGY @ KB Singapore 417800
 HP: 92712214 TEL: (65) 63844844 FAX: (65) 63834944

01st MARCH 2019

RS CAR LEASING PTE LTD
 25 KAKI BUKIT ROAD 54
 # 03-65/67/68 SYNERGY @KB
 Singapore 417800

TP AIG

JTDER12W903000063

Khanchana

Accident date: 28th JANUAR 2019

Estimated repair cost for vehicle no: SLD9555T Toyota Wish 1.8 A

S/n	Qty	Items	U/price	Amount
				\$1,250.00 ✓
1	1	Rear Boot Lid <i>Distorted</i>	\$187.70	\$375.40 x
2	2	Rear Boot Lid Hinges <i>Neu</i>		\$74.10 ✓
3	1	Rear boot lid emble logo <i>neu</i>		\$549.10 389
4	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$276.10 ✓
5	1	Rear boot lid inner rubber <i>at</i>		\$613.80 238
6	1	Rear Boot Lid center moulding <i>cracked</i>		\$17.00 ✓
7	2	Rear Boot Lid center moulding side clips <i>neu</i>	\$8.50	\$50.00 x
8	1	Rear Boot Lid Number Plate <i>Neu neu</i>		\$270.20 x
9	2	Rear Boot Lid Number Plate Lamp <i>Neu neu</i>	\$135.10	\$680.00 485
10	1	Rear Boot Lid Inner Trim board <i>cracked</i>		\$68.00 x
11	1	Rear Boot Lid Inner lock side cover <i>Neu neu</i>		\$310.10 246
12	1	Rear boot lid windscreen seal <i>Noc</i>		\$1,280.20 819
13	2	Rear tail lamp <i>cracked</i>	\$640.10	\$34.00 10
14	4	Rear tail lamp clips <i>neu</i>	\$8.50	\$640.00 x
15	2	Rear tail lamp panel <i>Repair</i>	\$320.00	\$740.00 578
16	1	Rear End Panel outer <i>Dented</i>		\$580.00 x
17	1	Rear End Panel inner <i>Repair</i>		\$403.40 285
18	1	Rear End Panel Top Garnish <i>Deformed</i>		\$536.10 x
19	1	Rear spare tire lock <i>Neu neu</i>		\$536.77 x
20	1	Rear floor panel top cover <i>neu</i>		\$120.00 x
21	1	Rear floor panel sealant <i>neu</i>		\$1,077.00 545
22	1	Rear Bumper <i>Deformed</i>		\$166.20 x
23	2	Rear Bumper side reflector <i>Neu neu</i>	\$83.10	\$111.20 ✓
24	2	Rear Bumper Side Bracket <i>neu</i>	\$55.60	\$350.00 200(SN)
25	1	Rear Bumper reverse sensor <i>Damaged</i>	\$68.40	\$136.80 ✓
26	2	Rear Bumper Bracket <i>Dented</i>	\$6.50	\$52.00 30
27	8	Rear bumper clips <i>Noc</i>		\$212.15 x
28	1	rear exhaust aluminium cover <i>Neu neu</i>		

Subtotal :- \$11,508.62

5500.20

412515

S.N:200

labour charges

To Check Wiring System

Tuff Kote

To Remove & refix cushion

To Remove & refix rear windscreen

Gum

To Remove & refix reverse Sensor

Panel beating

Spray painting

~~\$60.00~~ 30

~~\$150.00~~ 60

~~\$120.00~~ 60

\$120.00 ✓

\$50.00 ✓

~~\$100.00~~ 50

~~\$1,000.00~~ 800

~~\$1,000.00~~ 800

1970

Subtotal :- \$2,600.00

Total:- \$14,108.62

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6255.15

4/s: SK

06 days.