

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorized
Money After Party
2 days

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: _____ Third Party

Date: **04.03.2019**

Accident Date : 01.03.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Daihatsu Copen" Reg. No. SJF7621 Claiming Against Your Insured Reg. No. SLR931B		
1pc	Rear Bumper		
10pcs	Rear Bumper Clips		
1pc	Rear Bumper Lamp LH <i>Scr ✓</i>		
1pc	Boot <i>R x</i>		
	Less 15%		
1pc	Rear Bumper Sticker		
1pc	Rear Number Plate (3D)	<i>CM</i>	<i>un</i> 50.00 SN <i>30sn</i>
1pc	Rear Boot Carbon Spoiler		<i>45sn</i> 145.00 SN
1pc	Rear Boot Logo "Audi"		<i>un</i> 480.00 SN <i>✓</i>
1pc	Rear Bumper Reverse Sensor		<i>un</i> 105.00 SN <i>x</i>
1pc	Rear Bumper Reverse Camera		180.00 SN <i>?</i>
			380.00 SN <i>?</i>
	To Conduct Rear Electrical Check, Locking System, Adjust, Tail Lamp etc		30.00 <i>15</i>
	To Repair / Replace & Align Muffler/Exhaust System and Conduct Carbon Monoxide Leakage Test		<i>un</i> 80.00 <i>x</i>
	Labour Charge - Panel Beating, Repairing Of End Panel and Parts Replacement		450.00 <i>250</i>
	To Reseal Paint Protection (Diamondbrite) to Spray Paint Areas		150.00 <i>?</i>
	To Respray Affected Areas		600.00 <i>220</i>
	Total :		2,650.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: