

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 400M**AAD1903-001***Not Notarized
Presumy B4 point*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 400M

VF1ABL15AUC283283

RENAULT

LATITUDE

1.3.2019

AXA

17/10/2016

PART**LIST**

1	BUMPER COVER FRT	\$	<i>N</i>	1,259.42	X
1	HEADLAMP LH	\$	<i>Sn</i>	1,184.43	X
1	HEADLAMP HARNESS	\$	<i>Sn</i>	928.29	X
1	FENDER PANEL FRT LH	\$	<i>B</i>	783.83	✓
1	WHEELARCH FRT LH	\$	<i>Sn</i>	278.84	X
1	FENDER BRACKET LOWER LH	\$	<i>Sn</i>	15.79	X
1	FENDER INSULATOR LH	\$	<i>Sn</i>	130.84	X
1	DOOR PANEL FRT LH	\$	<i>B</i>	2,844.66	✓
1	DOOR HINGE UPPER LH	\$	<i>N</i>	261.28	✓
1	DOOR HINGE LOWER LH	\$	<i>N</i>	300.55	X
1	DOOR CHECK FRT LH	\$	<i>Sn</i>	194.77	X
1	DOOR LOCK FRT LH	\$	<i>N</i>	908.75	X
1	DOOR CATCH FRT LH	\$	<i>Sn</i>	131.23	X
1	DOOR HANDLE OUTER FRT LH	\$	<i>CM</i>	477.76	✓
1	DOOR HANDLE COVER FRT LH	\$	<i>N</i>	13.22	✓
1	DOOR HANDLE MODULE FRT LH	\$	<i>Sn</i>	133.60	X
1	DOOR REGULATOR FRT LH	\$	<i>Sn</i>	505.19	X
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>Sn</i>	796.46	X
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>Sn</i>	120.97	X
1	DOOR PANEL REAR LH	\$	<i>B</i>	2,844.66	✓
1	DOOR GUIDE REAR LH	\$	<i>Sn</i>	176.82	} X
1	DOOR HINGE UPPER LH	\$	<i>Sn</i>	274.50	
1	DOOR HINGE LOWER LH	\$	<i>N</i>	300.55	
1	DOOR CHECK REAR LH	\$	<i>Sn</i>	203.06	
1	DOOR LOCK REAR LH	\$	<i>N</i>	908.75	
1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i>	126.49	
1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i>	35.52	
1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i>	7.89	
1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i>	13.22	}
1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i>	133.60	
1	DOOR REGULATOR REAR LH	\$	<i>N</i>	1,135.10	

Trans-cab Auto Services Pte Ltd**AAD1903-001**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 400M

1	DOOR REGUALTOR MOTOR REAR LH	\$	893.75	}	X
1	DOOR REGULATOR NUT REAR LH	\$	12.43		
1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	6.31		
1	DOOR FINISHER REAR LH	\$	423.10		
1	DOOR MOULDING REAR LH	\$	176.82		
1	DOOR MOULDING CLIP L70Y	\$	5.92		
1	DOOR MOULDING SCREW L70Y	\$	6.91		
1	DOOR CASING REAR LH	\$	1,509.06		
1	DOOR WATER SHIELD REAR LH	\$	30.39		
1	DOOR CASING CLIP	\$	12.63		
1	DOOR CASING LIGHT L70Y	\$	48.74		
1	DOOR FINISHER INNER REAR LH	\$	323.44		
1	DOOR FINISHER BRACKET INNER REAR LH	\$	46.97		
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33		
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33		
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33		
1	DOOR GRAB HANDLE REAR LH	\$	210.96		
1	DOOR BLIND REAR LH	\$	741.80		
1	DOOR WHEATHESTRIIP REAR LH	\$	410.66		
1	DOOR SEAL REAR LH	\$	162.02		
1	DOOR GLASS RUNNER SEAL REAR LH	\$	229.31		
1	DOOR WAIST SEAL OUTER REAR LH	\$	334.69		
1	DOOR WAIST SEAL INNER REAR LH	\$	115.64		
1	FENDER PANEL REAR LH	\$	3,299.13	}	X
1	FENDER PANEL INNER TRIM REAR	\$	671.45		
1	WHEELARCH REAR LH	\$	543.47		
1	BUMPER COVER REAR	\$	1,108.46		
1	BUMPER LOWER REAR	\$	768.84		
1	BUMPER BRACKET CTR REAR	\$	113.47		
1	BUMPER RETAINER LH REAR	\$	44.99		
1	BUMPER BEAM REAR	\$	777.52		
1	BUMPER BEAM BRACKET LH REAR	\$	225.95		
1	DOOR MIRROR ASSY LH	\$	1,483.40		
1	TAILLAMP LH	\$	552.55		
1	ROCKER PANEL INNER GARNISH LH	\$	466.51		
1	ROCKER PANEL INNER LH	\$	1,024.79		
1	ROCKER PANEL CENTER LH	\$	990.25		
1	KUCKLE ARM REAR LH L70Y	\$	736.67		
1	BRAKE DISC REAR L70Y	\$	525.91		
1	ABS SENSOR REAR LH L70Y	\$	375.93		

Trans-cab Auto Services Pte Ltd

AAD1903-001

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 400M

1	REAR AXLE L70Y	\$	Sn 4,167.03	X
1	LOWER ARM REAR LH L70Y	\$	Sn 905.99	X
2	ABSORBER REAR	\$	Sn 389.75	X
1	STABILIZER BAR REAR L70Y	\$	Sn 604.65	X

	\$	42,969.30
10%	\$	4,296.93
	\$	38,672.37

Special Nett

1SET	BUMPER CLIP FRT	\$	nn 66.00	
1	BUMPER BRACKET CLIP FRT LH	\$	nn 12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	nn 10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	nn 69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn 70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	nn 20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	nn 30.00	
1SET	WHEELARCH CLIP FRT LH	\$	nn 30.50	
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn 80.00	605m
1	FRONT DOOR STICKER 'Chassis'	\$	nn 50.00	155m
1	REAR DOOR STICKER '6555 3333'	\$	nn 80.00	605m
1	DOOR CHECK BOLT	\$	nn 22.69	
1	DOOR GUIDE SCREW	\$	nn 10.85	
1	DOOR HINGE BOLT	\$	nn 10.85	
1	DOOR HINGE NUT RH	\$	nn 14.60	
1	DOOR CHECK BOLT	\$	nn 22.69	
1	DOOR CHECK NUT	\$	nn 3.75	
1	DOOR LOCK SCREW L70Y	\$	nn 6.12	
1	DOOR CATCH SCREW L70Y	\$	nn 10.06	
1	FRONT LEFT TYRE RIM	\$	nn 380.00	
1	FRONT LEFT TYRE	\$	Sn 330.00	X

TOTAL	\$	1,329.63
--------------	----	-----------------

TOTAL PARTS	\$	40,002.00
--------------------	----	------------------

LABOUR

Trans-cab Auto Services Pte Ltd**AAD1903-001**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 400M

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00 <i>900/</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	4,200.00 <i>1320/</i>
To rust-proofing of the affected areas.	\$	170.00 <i>120/</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 <i>100/</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>60/</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00 <i>20/</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>30/</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
To lift-up engine with gear box and refit.	\$	<i>nn</i> 440.00 <i>X</i>
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>nn</i> 440.00 <i>X</i>
To remove and refit air bag system and reset.	\$	<i>nn</i> 480.00 <i>X</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00 <i>60/</i>

Trans-cab Auto Services Pte Ltd**AAD1903-001**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 400M

To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00	<i>X</i>
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00	<i>X</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>nn</i> 170.00	<i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00	<i>X</i>

TOTAL	\$	13,280.00
--------------	-----------	------------------

Over All Total	\$	53,282.00
-----------------------	-----------	------------------

PART-BY-PART(REPAIR DAY)**20 DAYS***8 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: