

ASS. REC. BY:

REF:

CS/EQI 19004032

RIT

Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Joel Goh

of

EQ

Date/Time:

4/3/2019

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 3411S

Insured:

at Workshop m/s

Borneo motor > Pandan crescent

Tel:

of

Policy No:

Claim No:

Dm19H000370-J6

Sum Insured:

Excess:

500

Make of Veh:

(Client's Record)

D.O.A.

11/1/2019

CA / REV / REP. / REV 24 HRS

owner waiting
06/3/19 @ 10.00-3.00am

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

GBG 3411S b

7/3 @ 1:35pm revert via email.

7/3 @ 2:06pm authorise repair by Joel

7/3 @ 2:33pm inform by email authorise repair to Thomas
excess \$500/-

REF:

0172W

ASSIGNMENT

From:

Date:

Veh No.

GBG34115

Yr Regn:

2017 / July

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Truck / Taxi / Prime Mover /OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: GBG34115

Make:

TOYOTA HILUX SDR

C.C. 2582

at Workshop m/s Borneo Motor

Colour:

GREY

A/C

Insured / Std / NI / NA

of 2, Borneo Cars

Sp. Reading:

38605

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.:

C/No:

JTBM TO2P600217919

Claims No.:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

500

Steering: Order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: MR / S/Rim / STD A/Rim or10am - 1030am

Tyre Size:


F:

ASRISC

(Policy Condition)

R:

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

64k

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

06/02/19

D.O.I.

06/03/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

BORNEO MOTORCA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Part by Part \$10,612.70 (Red. 3039.30/22%)

RECEIVED 19 MAR 2019

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

6

1) 19/3 Typist



Final Report

Resurvey No. of Trip:

1

Survey Fee:

230

Date/Time, File Return to?

Transportation

2)

Add Fee:



Site Insp. (\$)

) 12 x 1000



Interview (\$)

) Phone



Tech Insp (\$)

) Other



Weekend (\$)

) Other

Report Format:

OP

Lump Sum / I.B.T. (\$ 10,612.70)

TOTAL

230

Nivitha (LKK Auto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Monday, 4 March 2019 4:09 PM
To: assignments
Cc: Thomas Pang PTCBC
Subject: RE: Own Damaged Claim for GBG3411S (DM19HO00370-JG)
Attachments: 25022019140537-0001.pdf; GBG3411S.pdf

Dear LKK

Please assist on this OD survey.

Excess: S\$500.00 (no waiver)
Survey and revert.


Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Thomas Pang PTCBC [mailto:Thomas.Pang@borneomotors.com.sg]
Sent: Friday, March 1, 2019 2:50 PM
To: Joel Goh
Subject: RE: Own Damaged Claim for GBG3411S (DM19HO00370-JG)

Dear Joel,

Customer only come down to submit the report to us on 25/02/2019. So we submit the estimate on 25/02/2019.

Thank you

Regards

thomas

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]
Sent: Friday, March 1, 2019 2:20 PM
To: Thomas Pang PTCBC
Subject: RE: Own Damaged Claim for GBG3411S (DM19HO00370-JG)

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 7 March 2019 1:35 PM
To: Admin-D (LKKAUTO); 'Joel Goh'
Cc: SUR; assignments
Subject: RE: Own Damaged Claim for GBG3411S (DM19HO00370-JG)
Attachments: PRELI ADVISED GBG 3411S.pdf; estimate gbg 3411s.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBG 3411S**
We did not authorise repair

Kindly let us have your authorization

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 5 March 2019 10:27 AM
To: 'Joel Goh' <joel.goh@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Thomas Pang PTCBC' <Thomas.Pang@borneomotors.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: Own Damaged Claim for GBG3411S (DM19HO00370-JG)

Dear Joel,

Thank you for the assignment.

Please be informed that the vehicle currently not in the workshop and repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh [<mailto:joel.goh@eqinsurance.com.sg>]
Sent: Monday, 4 March 2019 4:09 PM
To: assignments <assignments@lkkauto.com>
Cc: Thomas Pang PTCBC <Thomas.Pang@borneomotors.com.sg>
Subject: RE: Own Damaged Claim for GBG3411S (DM19HO00370-JG)

Dear LKK

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 7 March 2019 2:33 PM
To: Thomas.Pang@borneomotors.com.sg
Cc: Wally Tan TCBC; SUR
Subject: GBG 3411S / OD / EQ

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBG 3411S (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAuto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Thursday, 7 March 2019 2:06 PM
To: Denise Tay (LKKAuto); Admin-D (LKKAuto)
Cc: SUR; assignments
Subject: RE: Own Damaged Claim for GBG3411S (DM19HO00370-JG)

Dear Denise

Please proceed to authorize OD claim up to S\$10,788.30


Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Thursday, March 7, 2019 1:35 PM
To: Admin-D (LKKAuto); Joel Goh
Cc: SUR; assignments
Subject: RE: Own Damaged Claim for GBG3411S (DM19HO00370-JG)

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBG 3411S**
We did not authorise repair

Kindly let us have your authorization

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DM19HO00370-JG

Date: 7/3/2018

Our Ref: CS/EQI19004032/R1td3

The Motor Claims Department
EQ INSURANCE COMPANY LTD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. GBG 3411S

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 06/03/2019 at the premises of M/s Borneo Motor and have the following to report: -

Workshop Estimate Amount	: S\$ 13,652.00
Revised Estimate Amount	: S\$ 10,485.50
"Check" Items Amount	: S\$ 302.80
Market Value	: S\$ 64,000.00
LTA Reimbursement Value	: S\$ 25,590.00
Nett Value	: S\$ 38,410.00

Description of Damage:

The vehicle sustained damages
at the front o/s portion



Comments/ Present Status:

Damages Consistent.
We have not authorized repair.

Yours faithfully

Rasul
Automotive Assessor

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	0172W
Vehicle Details	
Vehicle No.:	GBG3411S
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2691586
Chassis No.:	JTFHT02P600217919
Maximum Power Output:	-
Open Market Value:	\$28,138.00
Original Registration Date:	19 Jul 2017
First Registration Date:	19 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,600.00
COE Rebate Amount:	\$25,590.00
Total Rebate Amount:	\$25,590.00

The information contained herein is correct as at 07 Mar 2019

OK

CAUTION: This email originated from outside of the organisation. Do not click links or open attachments unless you recognise the sender and know the content is safe.

Dear Thomas

The timeline to submit an OD claim against the policy is 14 days from date of accident.
We received your incoming OD claim on 25/02/2019, 25 days after the accident.

Please assist to advise on the reason for the delay in order for us to review and consider this matter.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Thomas Pang PTCBC [<mailto:Thomas.Pang@borneomotors.com.sg>]
Sent: Wednesday, February 27, 2019 2:09 PM
To: EQI PRS; Tan Wei Yin
Subject: FW: Own Damaged Claim for GBG3411S

Hi,

Attach document for your perusal. This is own damaged claim.

Thank you

Regards

Thomas
Borneo Motors
DID:6631 1860 HP: 9847 6171 FAX:6773 3094

From: Thomas Pang PTCBC
Sent: Monday, February 25, 2019 2:35 PM
To: 'janet.tan@eqinsurance.com.sg'; 'weiyin.tan@eqinsurance.com.sg'
Subject: Own Damaged Claim for GBG3411S

Hi,

Attach document for your perusal. This is own damaged claim.

Thank you

Regards

Thomas

Borneo Motors

DID:6631 1860 HP: 9847 6171 FAX:6773 3094

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	01/02/2019 19:06
Date Of Accident	01/02/2019 08:55
Exact Location Of Accident	HOUGANG AVE 2 TOWARDS HOUGANG AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBG3411S
Insured/Policyholder	
Name Of Registered Owner	HAI TANG AIR-CON SERVICE
Co Reg No	52940172W
Email Address	HAITANGAIRCON@LIVE.COM
Mobile Phone No	
Alternative Phone No	OFFICE-98895797
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE VAN TURBO 5DR MT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-004318
Cover Note Number	
Driver	
Name of Driver	LEE THENG SENG
NRIC No	S1491028Z
Date Of Birth	26/04/1961
Occupation	OUTDOOR
Date Of Driving Pass	30/10/1984
Driving Experience	34 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96825797
Fax Number	
Contact Number	
EMail Address	HAITANGAIRCON@LIVE.COM

Address NIL

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES

Foreign Vehicle Registration Number JSJ433 (MOTORCYCLE)

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : PASSENGER 1
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] PUNGGOL NPC

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20190201/2079 LODGED AT PUNGGOL NPC. ON 01/02/2019 AT AROUND 0855HRS, I WAS TRAVELLING ALONG HOUGANG AVENUE 2 TOWARDS HOUGANG AVENUE 3 AND AT THAT POINT OF TIME, I WAS IN THE SECOND LANE. THE LANE ON MY LEFT IS A BUS LANE. WHILE APPROACHING THE TRAFFIC JUNCTION, IN BETWEEN LAMP POST NUMBER 34 AND 36, MY VEHICLE CAME TO A STOP AS THE TRAFFIC LIGHT IS IN RED IN MY FAVOUR AND THE VEHICLES IN FRONT OF ME HAS STOPPED. AFTER MY VEHICLE HAS STOPPED, I HEARD A LOUD SOUND FROM THE BACK OF MY VEHICLE. I ALIGHTED FROM MY VEHICLE TO MAKE A CHECK AND DISCOVERED THAT THERE IS A MOTORCYCLE BEARING THE REGISTRATION NUMBER JSJ433 LYING ON THE GROUND BEHIND MY VEHICLE. THE RIDER AND PILLION WAS ALSO ON THE GROUND. I WENT TO ASSIST THEM AND SUBSEQUENTLY TRAFFIC POLICE AND AMBULANCE CAME TO THE SCENE. THE RIDER AND PILLION OF JSJ433 WERE CONVEYED BY AMBULANCE. I WISHED TO INFORM THAT I HAVE A PASSENGER WHO IS MY SON'S DOMESTIC HELPER WHEN THE ACCIDENT HAPPENED. I DO HAVE IN-BUILT CAR CAMERA; HOWEVER, IT IS NOT WORKING. I WISHED TO INFORM THAT THE LORRY GBF20L WHICH WAS ON THE FIRST LANE WAS NOT INVOLVED IN THE ACCIDENT. I WAS GIVEN A POLICE CASE CARD AND THE REPORT NUMBER IS E/20190201/0070 AND THE TRAFFIC POLICE INVESTIGATION OFFICER IS ADELINA, TEL: 65476066.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number JSJ433

Vehicle Make/Model/Colour UNKNOWN
Details Of Properties
Vehicle Category MOTORCYCLE
Name of Driver HARRYCHANDER A/L PUSHPANATHAN
NRIC/Passport Number 960521045617
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 2
Passenger 1
NAME: : PILLION
GENDER: :

DETAILS OF INJURED PERSON 1

Name HARRYCHANDER A/L PUSHPANATHAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? JSJ433
Were seat belts worn? NO
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 2

Name PILLION
Approximate Age
Injuries Sustain
Injured person in which vehicle? JSJ433
Were seat belts worn? NO
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode



SINGAPORE POLICE FORCE



T/20190201/2079

1 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20190201/2079

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/02/2019 13:37	Vide Report No.: E/20190201/0070	Station Diary No.: 48
--	-------------------------------------	--------------------------

Informant's Particulars			
Name of Informant: LEE THENG SENG		Address: APT BLK 193 RIVERVALE DRIVE #05-797 SINGAPORE 540193	
ID Type / ID No.: NRIC NO / S1491028Z		Contact No.: Home/Office: Mobile: 96825797	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 57	Date of Birth: 26/04/1961	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: AIR-CON SERVICER		Driving Licence Information: Class: 2B,2A,2,3,4 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 01/02/2019 08:55	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 HOUGANG AVENUE 2 HOUGANG AVENUE 3 Between lamp post number 34 and 36				
Weather: Sunny		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF20L	Lorry					1
GBG3411S	Van					1
JSJ433	Motorcycle					1



SINGAPORE POLICE FORCE



T/20190201/2079

2 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20190201/2079

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	PERIYASAMY THIRUMURTHY	ID No.	G2908675W
Related Vehicle	GBF20L (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LEE THENG SENG	ID No.	S1491028Z
Related Vehicle	GBG3411S (Van)	Contact No.	96825797
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Rider			
Name	HARRYCHANDER A/L PUSHPANATHAN	ID No.	960521045617
Related Vehicle	JSJ433 (Motorcycle)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 01/02/2019 at around 0855hours, I was travelling along Hougang Avenue 2 towards Hougang Avenue 3 and at that point of time, I was in the second lane. The lane on my left is a bus lane.

While approaching the traffic junction, in between lamp post number 34 and 36, my vehicle came to a stop as the traffic light is in red in my favour and the vehicles in front of me has stopped. After my vehicle has stopped, I heard a loud sound from the back of my vehicle. I alighted from my vehicle to make a check and discovered that there is a motorcycle bearing the registration number JSJ 433 lying on the ground behind my vehicle. The rider and pillion was also on the ground.



**SINGAPORE
POLICE FORCE**



T/20190201/2079

3 of 4

Report No. T/20190201/2079

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

CONTINUATION OF REPORT

I went to assist them and subsequently traffic police and ambulance came to the scene. The rider and pillion of JSJ 433 were conveyed by ambulance. I wished to inform that I have a passenger who is my son's domestic helper when the accident happened. I do have in-built car camera; however, it is not working. I wished to inform that the lorry GBF20L which was on the first lane was not involved in the accident.

I was given a police case card and the report number is E/20190201/0070 and the traffic police investigation officer is Adelina, Tel: 65476066.



**SINGAPORE
POLICE FORCE**



T/20190201/2079

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

4 of 4

Report No. T/20190201/2079

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Staff Sgt TAY HUEI JING

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sgt 2 PHUA TIAK YEE

Contact No.: 65472077

Signature Of Informant:

Date/Time:

01/02/2019 13:37

Classification Of Case:

Authentication Stamp

NP168

COMMERCIAL VEHICLE PRIVATE (SCH I) SCHEDULE

Page 1 of 7

Agency	A000137	Class of Policy	COMMERCIAL VEHICLE PRIVATE (SCH I)	Policy Number	DMCPHQ18-004318
Account	A000137	Issued on	05/07/2018 in Singapore		
Client	0147841	Acceptance Date	05/07/2018		

Period of Insurance from 19/07/2018 to 18/07/2019 , both dates inclusive

Insured's Name HAI TANG AIR-CON SERVICE
 Address BLK/HOUSE NO. 8 #01-522
 DEFU LANE 10
 SINGAPORE 539189

Business/Occupn Others
 Hire Purchase Hong Leong Finance Ltd

Premium	Basic Annual Premium	SGD1,144.03		
	Premium after NCD	SGD1,144.03	Premium Due	SGD1,144.03
			Premium GST	SGD80.08
			Total Due	SGD1,224.11

Risk No. 001	COMMERCIAL VEHICLE PRIVATE (SCH I)				
1. Registration	GBG3411S	Make/Model	TOYOTA		
Type of Cover	Comprehensive	No. of seats	2	Body Type	Van
Engine No.	1KD2691586	Capacity cc	0	Yr of Manuf/Regn	2017/2017
Chassis No.	JTFHT02P600217919			NCB%	20.00
		Tonnage	1.08	Certificate Ref.	LCVP1
Sum Insured: Market Value at the time of loss			SGD0.00		
Section 1			SGD500.00		
YEID-All Claims	Additional		SGD3,000.00		

COMMERCIAL VEHICLE COMPREHENSIVE (Ver. 7)

For information on Motor Claims Framework (MCF), please visit GIA websites
 (www.gia.org.sg /pdfs /Industry /Motor /MCF2010_Brochure.pdf)

The Policy is subject to the following Clauses, Warranties, Memo, Endorsement,
 Exclusions as printed herein and/or attached hereto:-

EXCESS - OWN DAMAGE CLAIMS

We will not pay for the Excess specified in the Policy Schedule or the
 Certificate of Insurance. You will have to pay the Excess for every claim made
 against us for own damage claims to your vehicle under Section 1.

If we have made any payment under Section 1 which includes this Excess, you have
 to refund us the amount of the Excess.

This Excess is in addition to any other excess applicable under this Policy.

Continued on page 2





**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 4900
www.police.gov.sg

Our Ref : TP/IP/06473/2019
Date : 12 February 2019

**Lee Theng Seng
Apt Blk 193 Rivervale Drive
#05-797
Singapore 540193**

Dear Sir,

**TRAFFIC ACCIDENT INVOLVING GBC3411S / JSJ433 / GBF20L ALONG HOUGANG AVENUE
2 ON 1 FEBRUARY 2019 AT ABOUT 08.57 A.M.**

I refer to the above accident.

2 We have completed our investigations into this case and Traffic Police will take no further action in the matter against you.

3 Please be informed that our decision does not preclude you from pursuing civil claims. Should you have any further enquiries, please contact investigation officer Nur Adelina at DID: 6547 6066 or via email at Nur_Adelina_Mohammad_Fuat@spf.gov.sg . Thank you.

Yours Faithfully,

**NUR ADELINA
INVESTIGATION OFFICER
TRAFFIC POLICE DEPARTMENT**



SINGAPORE POLICE FORCE

Traffic Police
Singapore Police Force
10, Ubi Avenue 3
Singapore 408865
Tel : 6547 0000
Fax : 6547 6259

Date : 02 Feb 2019

Your Ref :
Our Ref : TP/IP/06473/2019

000055

LEE THENG SENG
APT BLK 193 RIVERVALE DRIVE
#05-797
SINGAPORE 540193



Dear Sir / Madam,

**CASE OF TRAFFIC ACCIDENT INVOLVING GBG3411S ALONG HOUGANG AVENUE 2 ON 01 FEB
2019 @ 8.57 AM**

Please be informed that Traffic Police is investigating into the above matter and will update you the status in due course.

2 IF you have not lodged a Police Report of a Traffic Accident (NP168) in respect of the said accident which is now required for police investigation, please do so as soon as possible at the nearest police station, Neighbourhood Police Centre (NPC), Neighbourhood Police Post (NPP) or online via Singapore Police Force Electronic Police Centre (<http://www.police.gov.sg/epc>).

3 Please note that the information given by you in the Police Report of a Traffic Accident (NP168) will be carefully considered. You may not be called upon for an interview if the information in the Police Report is sufficient for our investigation. However, if you have any further information or other evidence (such as CCTV footages) which you have not stated in your report and which you think will assist in the investigation, you are advised to contact the Investigation Officer within 2 weeks of this letter to arrange for an appointment.

4 You may contact the Investigation Officer NUR ADELINA BINTE MOHAMMAD FUAT at his / her office number: 65476066 or the supervisor MOHD JAMAL BIN MARZUKI at 65476354 if you have any further queries.

5 Thank you.

Yours faithfully,

TAN CHEE SING (ASP)
CHIEF INVESTIGATION OFFICER
INVESTIGATION BRANCH
TRAFFIC POLICE

This is computer generated and does not require a signature.

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S1491028Z**

Name

LEE THENG SENG

Birth Date **26 Apr 1961**

Issue Date **29 Apr 2003**



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S1491028Z**



Name

LEE THENG SENG

Race

CHINESE

Date of Birth

26-04-1961

Sex

M

Country of Birth

SINGAPORE



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

	PASS DATE
Class 2B Motorcycles not exceeding 200 cc	30 Apr 1980
Class 2A Motorcycles between 201 cc and 400 cc	30 Apr 1980
Class 2 Motorcycles exceeding 400 cc	30 Apr 1980
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	30 Oct 1984
Class 4 Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	06 Dec 1984



Licence No: **S1491028Z**



1598143

NRIC No: **S1491028Z**



Blood Group

A+

Date of issue

17-01-1994

**APT BLK 193 RIVERVALE DRIVE #05-797
SINGAPORE 540193**

NRIC No: **S1491028Z**

Date: **21/07/2014**



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQI1	M/S Hai Tang Air-Con Service 8 Defu Lane 10 #01-522 Singapore 539189 Mobile: 98895797
	Document No 0	
	Document Date 25/02/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY	S5	KDH201R	19/07/2017	GBG3411S	0	41652 72/OD/GBG3411S
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTFHT02P600217919	1KD2691586	30	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMCPHQ18-004318 ACC DATE:01.02.2019 TOW/DRIVE IN:25.02.2019 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	S	BP-SUBLET SUPPLY SEALANT (NETT)				100 200.00
3	S	BP-SUBLET DRILL HOLE AND INSTALL REAR REVERSE SENS OR (NETT)				180.00
4	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST (NET T)				122.40
5	S	BP-SUBLET REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE (NETT)				360 720.00
6	S	BP-SUBLET REPLACE TAILGATE GLASS (NETT)				462.00
7	S	BP-SUBLET REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				1800 2880.00
8	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS				2360 2360.00
9	C	BP-ECU2 TO RESET ECU AND REPROGRAMME (NETT)				180.00
10	Z	BP-SUNDRY SUPPLY 70KM/H STICKER				50.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

Person
Hp 9000000
6 days
PIP
06/03/19 @ 1020
Respry by paint
EXCESS: 500
REPAIR

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3825449

TO SECURITY GUARD

3825449

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 25/02/2019
TIME 13:52

VEHICLE NO GBG3411S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQI1 Document No 0 Document Date 25/02/2019	M/S Hai Tang Air-Con Service 8 Defu Lane 10 #01-522 Singapore 539189 Mobile: 98895797

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY	S5	KDH201R	19/07/2017	GBG3411S	0	41652 72/OD/GBG3411S
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTFHT02P600217919	1KD2691586	30	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	-----------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	Z	BP-SUNDRY				25 50.00
12	L	BP-LPO				200.00
13	1	T52159-26470				448.10
14	2	T52157-26010				23.10
15	3	T52158-26010				23.10
16	4	T58385-26070				102.80
17	5	T52165-26030				91.70
18	6	T52155-26150				39.90
19	7	T90467-09185				24.00
20	8	T57069-26120				338.00
21	9	T67005-26G62				2006.80
22	0	T67881-26073				402.60
23	1	T68105-26150				1297.20
24	2	T69350-26122				272.60
25	3	T75441-26281				47.90
26	4	T90975-02064				72.20
27	5	T81551-26202				367.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 5,557.60 Labour 380.00 Materials 7,714.40 Lubrication/Fluid 0.00 Others 0.00	13,652.00 GST 7.00% 955.64 Less 0.00 Amount Due 14,607.64

PLEASE TEAR ALONG PERFORATED LINE

3825450

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 25/02/2019
TIME 13:52

13/7/19.20

3825450

VEHICLE NO GBG3411S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQI1	M/S Hai Tang Air-Con Service 8 Defu Lane 10 #01-522 Singapore 539189 Mobile: 98895797
	Document No 0	
	Document Date 18/03/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY	S5	KDH201R	19/07/2017	GBG3411S	38835	41652 72/OD/GBG3411S
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFHT02P600217919	1KD2691586	30	Thomas Pang W T	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMCPHQ18-004318 ACC DATE:01.02.2019 TOW/DRIVE IN:25.02.2019 EXCESS:\$500 DATE-IN:11.03.2019 DATE SURVEY:06.03.2019 NO OF REPAIR DAYS:06 WORKING DAYS BY:LKK-RASUL AUTHORIZED ON:07.03.201				50.00
2	S	BP-SUBLET SUPPLY SEALANT (NETT) PO:21125 A45				100.00
3	S	BP-SUBLET DRILL HOLE AND INSTALL REAR REVERSE SENS A45 OR (NETT)				180.00
4	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST (NET A45 T)				122.40
5	S	BP-SUBLET REMOVE AND TRANSFER TAILGATE COMPONENTS A45 ONTO NEW TAILGATE (NETT) PO:21126				360.00
6	S	BP-SUBLET REPLACE TAILGATE GLASS (NETT) PO:21125 A45				462.00
7	S	BP-SUBLET REPLACE ACC DAMAGED PARTS A45 AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS PO:21125				1800.00
8	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS PO:21125 A45				2360.00
9	C	BP-ECU2 TO RESET ECU AND REPROGRAMME (NETT) 18				180.00
10	Z	BP-SUNDRY SUPPLY 70KM/H STICKER				25.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3943236

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 18/03/2019
TIME 09:07

3943236

VEHICLE NO GBG3411S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail		Account No S1000021 / ICEQI1		Customer Detail				
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110		Document No 0		M/S Hai Tang Air-Con Service 8 Defu Lane 10 #01-522 Singapore 539189 Mobile: 98895797				
Document Date 18/03/2019								
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
17	SBMDY S5	KDH201R	19/07/2017	GBG3411S	38835	41652	72/OD/GBG3411S	
Chassis No		Engine No		Terms	Service Engineer	Vehicle In	Collected On	
JTFHT02P600217919		1KD2691586		30	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
11	Z	BP-SUNDRY SUPPLY 8 PAX STICKER						25.00
12	V	EXC Excess element of insurance repair to be 88						-500.00
		paid by the insured party						
13	1	T52159-26470	COVER, RR BUMPER		1.00	448.10		448.10
14	2	T52157-26010	SUPPORT, RR BUMPER		1.00	23.10		23.10
15	3	T52165-26030	COVER, RR BUMPER		1.00	91.70		91.70
16	4	T52155-26150	SUPPORT, RR BUMPER RH		1.00	39.90		39.90
17	5	T90467-09185	CLIP		10.00	2.40		24.00
18	6	T67881-26073	WEATHERSTRIP, BACK DR		1.00	402.60		402.60
19	7	T68105-26150	REAR BACK DOOR GLASS (W/WIPER)		1.00	1297.20		1297.20
20	8	T75441-26281	PLATE, LUGGAGE		1.00	47.90		47.90
21	9	T90975-02064	EMBLEM, SYMBOL		1.00	72.20		72.20
22	0	T81551-26202	LENS, RR COMB RH		1.00	367.60		367.60
23	1	T67005-26150	BACK DOOR PANEL W/CAMERA		1.00	2134.00		2134.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.								
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total 10,112.70		
		Please acknowledge receipt of vehicle		Parts	4,948.30	GST 7.00%	707.89	
				Labour	280.00	Less	0.00	
				Materials	5,384.40			
				Lubrication/Fluid	0.00			
				Others	0.00			
						Amount Due	10,820.59	

PLEASE TEAR ALONG PERFORATED LINE

3943237

TO SECURITY GUARD

3943237

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 18/03/2019
TIME 09:07

VEHICLE NO GBG3411S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CS/EQ19004032/R1td3e2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 20-03-2019	
		Code : EQI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	GBG 3411S
Policy No.	DMCPHQ18-004318	Coverage (\$)	0.00
Claim No.	DM19HO00370/JG	Excess (\$)	500.00
Assign From		Assign Date	04/03/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTFHT02P600217919	Colour	GREY
Odometer	38605	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/02/2019	Inspection Date	06/03/2019
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks			
A)THE MARKET VALUE IS S\$64,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 3411S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	70 KM/H STICKER (SN)	NECESSARY	50.00	25.00
1	8 PAX STICKER (SN)	NECESSARY	50.00	25.00
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
1	REAR BUMPER COVER (SN)	SCRATCHED	448.10	448.10
1	R/R SIDE BPR RETAINER (SN)	NECESSARY	23.10	23.10
1	L/R SIDE BPR RETAINER (SN)	NOT NECESSARY	23.10	-
4	REAR BUMPER BRACKET (SN)	SERVICEABLE	102.80	-
1	R/F TOP BUMPER COVER (SN)	SCRATCHED	91.70	91.70
1	R/RR BUMPER SUPPORT (SN)	NECESSARY	39.90	39.90
10	CLIP @\$2.40 (SN)	NECESSARY	24.00	24.00
1	REAR OUTER FLR MEMBER (SN)	TO REPAIR SEE LABOUR	338.00	-
1	PANEL SUB-ASSY, BACK (SN)	BENT	2,134.00	2,134.00
1	RR BACK DOOR W/STRIP (SN)	NECESSARY	402.60	402.60
1	REAR BACK DOOR GLASS (W/WIPER) (SN)	NECESSARY	1,297.20	1,297.20
1	REAR BACK DOOR LOCK ASSY (SN)	SERVICEABLE	272.60	-
1	"TOYOTA HIACE" EMBLEM (SN)	NECESSARY	47.90	47.90
1	EMBLEM, SYMBOL (SN)	NECESSARY	72.20	72.20
1	R/R COMBINATION LENS (SN)	BROKEN	367.60	367.60
			6,084.80	5,048.30
LABOUR				
	SUPPLY SEALANT.		200.00	100.00
	DRILL HOLE AND INSTALL REAR REVERSE SENSOR.		180.00	180.00
	CHECK WIRING AND CONDUCT WATER TEST.		122.40	122.40
	REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE.		720.00	360.00
	REPLACE TAILGATE GLASS.		462.00	462.00
	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN / REALIGN.		2,880.00	1,800.00
	ACC AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR OUTER FLR MEMBER.			

Report Ref No. CS/EQ19004032/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESPRAY ACC AFFECTED AREAS. TO RESET ECU AND REPROGRAMME.		2,950.00	2,360.00
			180.00	180.00
			7,694.40	5,564.40
GRAND TOTAL			13,779.20	10,612.70
RECOMMENDED COST OF REPAIRS				10,612.70
LESS EXCESS				-500.00
NETT LIABILITY				10,112.70

Report Ref No. CS/EQ119004032/R1td3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.