

Ref: CS/AWA 19004033 | Title: Titled

Surveyor

ASSIGNMENT (Office)

From (Person): Ben Tang

at AWA

Date/Time: 04/3/19

Estimated Cost:

Billing:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SGR 9900R

Insured:

at Workshop no: Comfort delgro Engineering Pte Ltd
of Pandan

Tel: 68676919 Chae Krong

Policy No: BvFPSB 0006781907

Claim No:

Sum Insured:

Excess: 500

Make of Veh:
(Client's Record)

D.O.A. 25/21 2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction () Estimate

SGR 9900R X

06/03/19 @ 11.45am revert to Ben Tang by email.

8/3/19 @ 9:24am inform authorise by Ben Tang.

8/3/19 @ 10:18am - email to comfort authorise repair excess \$500/-

Confirm final figure @ \$7011.40. 4days (Red: 573840; 4%)

150

Shiau Chan (LKKAUTO)

From: Tang, Ben <Ben.Tang@awac.com> on behalf of Motorsurvey
<Motorsurvey@awac.com>
Sent: Monday, 4 March 2019 4:03 PM
To: assignments
Cc: SUR; CDGE Pandan Private Cars Crash Repair Counter
(pandan_cr@sparkcarcare.com)
Subject: OD survey assignment for SGR 9900R - DOA : 25/02/2019 Our Ref: TBA

The above captioned accident refers. Please conduct an "OWN DAMAGE" survey on the following:

Insured Vehicle	:	SGR 9900 R		
Policy Number	:	BVFPSB0006781907	Account Code:	B900SD5
Policy Excess	:	\$500.00	(Insured to pay)	
Sum Insured	:	Market Value with COE & PARF		
Make / Model	:	Mercedes Benz C200 A/T		
Name of Workshop	:	Comfortdelgro Engineering Pte Ltd (Pandan)		
Contact Number	:	68676919		
Person to Contact	:	Chen Chee Kiong		
Estimated Cost of repairs	:	\$12,347.80		
(x)	Please take photographs of the front windscreen area from inside to ascertain whether the insured vehicle is equipped with a car camera. (Compulsory)			
()	Please authorize repair			
()	Please authorize repair on lump sum basis			
(x)	Please revert with your preliminary survey report with photographs			
()	Our policy has Car Rental Extension benefit. Please fax a copy of your preliminary report to Mr Kenneth Tan of BKW Automobile Pte Ltd at 67386666 stating the estimated number of days for the repair works and copy us in your fax			
Remarks				

Regards,

Claims Division

Tan Fitch

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 6 March 2019 11:44 AM
To: 'Motorsurvey'; assignments
Cc: SUR; 'CDGE Pandan Private Cars Crash Repair Counter'
Subject: RE: OD survey assignment for SGR 9900R - DOA : 25/02/2019 Our Ref: TBA
Attachments: CSAWA19004033T1td3.pdf, SGR9900 Photo.pdf

Dear Ben,

Enclosed herewith preliminary advice of SGR 9900R.
Repair cost economical.
We have not authorise repair.

Kindly advice on the authorisation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 5 March 2019 10:26 AM
To: 'Motorsurvey' <Motorsurvey@awac.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'CDGE Pandan Private Cars Crash Repair Counter' <pandan_cr@sparkcarcare.com>
Subject: RE: OD survey assignment for SGR 9900R - DOA : 25/02/2019 Our Ref: TBA

Dear Ben,

Thank you for the assignment.

Shiau Chan on behalf of G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tang, Ben [<mailto:Ben.Tang@awac.com>] **On Behalf Of** Motorsurvey
Sent: Monday, 4 March 2019 4:03 PM
To: LKK (assignments@lkkauto.com) <assignments@lkkauto.com>
Cc: SUR (sur@lkkauto.com) (sur@lkkauto.com) <sur@lkkauto.com>; CDGE Pandan Private Cars Crash Repair Counter (pandan_cr@sparkcarcare.com) <pandan_cr@sparkcarcare.com>
Subject: OD survey assignment for SGR 9900R - DOA : 25/02/2019 Our Ref: TBA

The above captioned accident refers. Please conduct an "OWN DAMAGE" survey on the following:



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Policy No.: BVFPSB0006781907

Date: 06 March 2019

Our Ref: CS/AWA19004033/T1td3

The Motor Claims Department
Allied World Assurance Company Ltd

Attn: Ben Tang

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SGR 9900R

We thank you for the instruction on 04/03/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/03/2018 at the premises of M/s COMFORTDELGRO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>12,347.80</u>
Revised Estimate Amount	: S\$ <u>6,195.20</u>
"Check" Items Amount	: S\$ <u>1,554.90</u>
Market Value	: S\$ <u>140,000.00</u>
Salvage Value	: S\$ <u>78,161.00</u>
Nett Value	: S\$ <u>61,839.00</u>

Description of Damage:
The vehicle sustained damages at the front o/s portion.



Comments/ Present Status:
Damages consistent.
Repair cost economical.
Days of repair: 4 days.
We have NOT authorise repair.

Yours faithfully

MOHD TAUFIKH
Automotive Assessor

Denise Tay (LKKAUTO)

From: Tang, Ben <Ben.Tang@awac.com> on behalf of Motorsurvey
<Motorsurvey@awac.com>
Sent: Friday, 8 March 2019 9:24 AM
To: Shiau Chan (LKKAUTO); Motorsurvey; assignments
Cc: SUR; 'CDGE Pandan Private Cars Crash Repair Counter'
Subject: RE: OD survey assignment for SGR 9900R - DOA : 25/02/2019 Our Ref: NSV1900113

Dear Shiau Chan

We refer to above matter.

Please proceed to authorize repair \$6,195.20 and check items \$1,554.90 subject to verification.

Thank you.

Best Regards
Ben Tang
Claims Analyst
Claims Group
Global Markets

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 6423 0816
F: +65 6423 0864
E: ben.tang@awac.com
W: www.awac.com

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Wednesday, 6 March 2019 11:44 AM
To: Motorsurvey <Motorsurvey@awac.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'CDGE Pandan Private Cars Crash Repair Counter' <pandan_cr@sparkcarcare.com>
Subject: RE: OD survey assignment for SGR 9900R - DOA : 25/02/2019 Our Ref: TBA

Dear Ben,

Enclosed herewith preliminary advice of SGR 9900R.
Repair cost economical.
We have not authorise repair.

Kindly advice on the authorisation.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 8 March 2019 10:18 AM
To: 'pandan_cr@sparkcarcare.com'
Cc: SUR
Subject: SGR 9900R / OD / AWAC

Importance: High

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGR 9900R (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: BVFPSB0006781907

Our Ref: CS/AWA19004033/T1td3

Date:15/3/2019

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir,

PRELIMINARY ADVICE OF VEHICLE NO SGR 9900R


We thank you for the instruction on 04/3/2019

Please be informed that we had conducted the inspection of the abovementioned vehicle 5/3/2019 at the premises of m/s: Comfort Delgro and have the following to report:-

Workshop Estimate Amount	: S\$ <u>12,749.80 inclusive supp \$442.20</u>
Revised Estimate Amount	: S\$ <u>7,332.40 (inclusive confirm check item and supp)</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u>140,000.00</u>
LTA Reimbursement Value	: S\$ <u>78,161.00</u>
Nett Value	: S\$ <u>61,839.00</u>

Description of Damage:

The vehicle sustained damages due to
Front o/s portion



Comments/ Present Status:

Damage consistent
Repair Cost economical
Days of repair: 4

Yours faithfully

Taufikh

Automotive Assessor

 [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2272W

Vehicle Details

Vehicle No.: SGR9900R

Vehicle to be Exported: No

Intended Deregistration Date: 06 Mar 2019

Deregistration Date:

Vehicle Make: MERCEDES BENZ

Vehicle Model: C200 A/T ABS

D/AIRBAG 2WD 4DR

Primary Colour: Blue

Manufacturing Year: 2017

Engine No.: 27492030958955

Chassis No.: WDD2050422R277287

Maximum Power Output: 135.0 kW (181 bhp)

Open Market Value:

\$45,783.00

Original Registration Date: 27 Jul 2017

First Registration Date:

27 Jul 2017

Transfer Count: 0

Actual ARF Paid: \$51,097.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Jul 2027

PARF Rebate Amount:

\$38,322.00

Intended COE Rebate Details

COE Expiry Date: 26 Jul 2027

COE Category: B - Car above 1600cc
or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$47,501.00

COE Rebate Amount: \$39,839.00

Total Rebate Amount: \$78,161.00

The information contained herein is correct as at 06 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2019 16:27
Date Of Accident	25/02/2019 08:30
Exact Location Of Accident	BUKIT BATOK STREET 25 TURNING LEFT TO BUKIT BATOK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGR9900R
Insured/Policyholder	
Name Of Registered Owner	PEPPERL + FUCHS ASIA PTE LTD
Co Reg No	197902272W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81397194

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	BVFPSB0006781907
Cover Note Number	

Driver

Name of Driver	LEK BAK KHIM
NRIC No	S1461806F
Date Of Birth	05/09/1961
Occupation	INDOOR
Date Of Driving Pass	04/06/1979
Driving Experience	39 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81397194
Fax Number	
Contact Number	
Email Address	TONYLEK@SG.PEPPERL-FUCHS.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

Passenger 1	NAME: : IRENE
	GENDER: : FEMALE
Passenger 2	NAME: : JOANNE
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I (SGR9900R) was at the slip road turning left to Bukit Batok Ave 3, from Bukit Batok street 25, looking to my right, giving way to oncoming traffic when I accidentally let go of my brake pedal. My car moved forward slowly and as a result the front right side of my car make contact with the rear left side of a bus (SMB3056E) who was going straight along Bukit Batok east ave 3. No injuries involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMB3056E
Vehicle Make/Model/Colour	MAN / NL320F
Details Of Properties	
Vehicle Category	BUS
Name of Driver	SAW ENG HENG
NRIC/Passport Number	S7480735F
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report accurately the details of the accident to speed up the claims process.
2. This form must be completed by the **Policyholder** and/or the **Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any untrue information or withholding of material facts may give rise to and constitute an **insurance policy violation**.
4. The intent and consequences of this form by insurance companies is not an admission of being liable on the part of insurance companies.
5. **Any later reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the Risk Reports Management Centre established by the General Insurance Association of Singapore (GIAS) for archiving and the copies of this report will be a full and complete disclosure of the accident to the relevant parties.
7. By the completion of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to release of the report being made available (if needed).
8. **Consent under the Personal Data Protection Act (PDPA):**
 - (i) I understand, acknowledge, agree and affirm that:
 - (ii) My Insurer, my Insurers and the General Insurance Association of Singapore (GIAS) may be permitted to collect, use, disclose and/or process my personal data/personal information as set out in this form, and any other personal information provided by me or processed by my Insurer collectively the "Personal Information", and disclose and/or transfer such Personal Information to all Insurers, who have insured vehicles involved in the accident (all Insurers) who have insured vehicles involved in the accident and be collectively referred to as the "Insurers", the Insurers' representative firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or replies to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes".
 - (b) all Insurers who have insured vehicles involved in the accident and the Insurers' representative firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may also be disclosed by any of the Insurers and/or GIAS to their third party service providers or agents (including their representative firms), which may be also outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHAMMAD SULHANI BIN
MOHD AFFANDI

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I (SGR9900R) was at the slip road turning left to Bukit Batok Ave 3, from Bukit Batok street 25, looking to my right, giving way to oncoming traffic when I accidentally let go of my brake pedal. My car moved forward slowly and as a result the front right side of my car make contact with the rear left side of a bus (SMB3056E) who was going straight along Bukit Batok east ave 3. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD SULHANDI BIN MOH AFFANDI

MARS Officer:



Registered Owner or Driver's Signature

Job Complete Date/Time:

25 February 2019 at 3:23 PM

Date/Time:

25 February 2019 at 3:23 PM

Accident Photo



ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ☒ Own Damage
☐ 3rd Party
☐ Windscreen

Vehicle No. : **SGR9900R**
Make & Model : **MERCEDES BENZ / 2WD 4DF**
Year of Manufacture : _____
Chassis No. : **WDD2050422R277287**
Engine No. : **27492030958955**
Policy No. : **BVFPSB0006781907**
Time of Accident : **08:30**

Ins Company : **AWAC**
Excess : _____
Date of Accident : **25/02/2019**
Suggested Days of Repair : **10day**

In-house Vehicle Assessor

Repair Estimates

Name : **Wong Chee Wei**
Signature : _____
Contact No : **68676919**
HP : 97239882

Parts (a) Cost / List Price Items	\$6,648.00
Plus/Less 10 %	\$664.80
(b) Nett Price Items	_____
Less _____ %	_____
(c) Special Nett Items	\$115.00 195
Total Parts Cost (Appendix A)	\$7,427.80
Labour (Appendix B)	\$4,920.00
Total Repair Cost	\$12,347.80

The above total will be subjected to 7% G.S.T.

Name of Surveyor : **Tan Jiah 97495749**
Company : **LKM**
Survey conducted on : **5/3/19** at **355pm**

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice. **Revert**
(b) Recommended Days of Repair : **4** day(s) **+ Repair before part**
(c) Resurvey : **Required / Not Required** **sure Mianta.com**
(d) Excess : \$ **500**
(e) Signature of surveyor : **[Signature]** Date: **5/3/19**

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandna Road S (609286)

Tel: 68676919 Fax: 62626950

Appendix A

Spare Parts

Vehicle No. : SGR9900R Submit By : Wong Chee Wei
 Make & Model : MERCEDES BENZ C200 A/T ABS D/AIRBAG 2WD 4DR Year Manufacture : 2017
 Chassis No. : WDD2050422R277287 Engine No. : 27492030958955

OD

S/Order :

S/No.	Part Description	Qty	Cost	Nett	List	S- Nett
			Price	Price	Price	Price
1	BONNET	1 ✓	\$1,040.00	bt ✓	✓	
2	L/BONNET HINGE	1	\$99.00	Rx	x	
3	R/BONNET HINGE	1	\$99.00	Rx	x	
4	L/BONNET LOCK	1	\$35.00	x nm	x	
5	R/BONNET LOCK	1	\$35.00	x nm	x	
6	LOGO - BONNET	1 ✓	\$42.00	nc	✓	
7	INSULATOR BONNET	1	\$132.00	x nm	x	
8	INSULATOR CLIP BONNET	20	\$80.00	x nm	x	
9	FR GRILLE	1	\$72.00	am	✓	
10	FR GRILLE MOULDING BASE	1 ✓	\$105.00	am	✓	
11	L/CHROME MOULDING GRILLE	1	\$42.00	am	x	
12	R/CHROME MOULDING GRILLE	1	\$42.00	am	✓	
13	EMBLEM - STAR	1	\$72.00	nm	x	
14	FR BUMPER	1 ✓	\$940.00	de	✓	
15	FR BUMPER CLIP	10	\$40.00	ne	✓	
16	R/ OUTER GUIDE RAIL	1 ✓	\$35.00	de	✓	
17	R/BUMPER CARRIER	1	\$48.00 ✓	bt	✓	
18	R/SIDE SENSOR BUMPER	1	\$93.00	nm	✓	
19	R/OUT SENSOR BUMPER	1	\$93.00 ✓	nm	✓	
20	R/ INN SENSOR BUMPER	1	\$93.00	x nm	x	
21	R/ GRILLE	1	\$38.00 ✓	am	✓	
22	R/LOWER CHROME MOULDING	1	\$85.00	x nm	✓	
23	CENTER LOWER CHROME MOULDING	1	\$160.00	x nm	x	
24	RIGHT HEAD LAMP	1 ✓	\$1,580.00	am	✓	
25	R/INNER CROSSMEMBER BRACKET	1 ✓	\$48.00	bt	✓	
26	R/BRACKET HEAD LAMP	1	\$385.00	am	x	
27	FR REINFORCEMENT	1	\$225.00	x nm	x	
28	R/ FR SPONGE ✓	1	\$110.00	de	✓	
29	CTR FR SPONGE	1	\$88.00	x nm	x	
30	L/ FR SPONGE	1	\$62.00	x nm	x	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SGR9900R**
 Make & Model : **MERCEDES BENZ C200 A/T ABS D/AIRBAG 2WD 4DR**
 Chassis No. : **JTFAT35YX0K209513**

Submit By : **Wong Chee Wei**
 Year Manufacture : **2017**
 Engine No. : **27492030958955**

Pages 2

S/No.	Part Description	Qty	Cost Price	Nett Price	List Price	S- Nett Price
31	R/ FR FENDER	1	\$460.00	K2	X	
32	R / FENDER LINER FR	✓ 1	\$65.00	de	✓	
33	R / FENDER LINER REAR	1	\$65.00	X112	X	
34	R / FENDER CLIPS	10	\$40.00	X11	X	
35	BODY SEALANT				neu	40 60
36	A/C GAS				nn X	? 60
37	FRONT NUMBER PLATE					6t 35
38						
39						
40						
41						
42						
43						
44						
45						
46						
47						
48						
49						
50						
51						
52						
53						
54						
55						
56						
57						
58						
59						
60						
61						
62						
63						
64						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 68676919 Fax: 62626950,68676903

Labour

Year of Manufacture : 0

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandan Road S (609286)

Tel:68676919 Fax: 62626950

Appendix A

Spare PartsVehicle No. : **SGR9900R** Submit By : **Wong Chee Wei**Make & Model : **MERCEDES D/AIRBAG 2WD**
BENZ 4DR Year Manufacture : **0**Chassis No. : **WDD2050422R277287** Engine No. : **Supplementary****Cost / List**

S/No.	Part Description	Qty	Unit Price	COST Price	Disposition by Surveyor
1	UPPER GARNISH INNER BUMPER A205 886 11 65 ✓	1	de ✓	\$42.00 ✓	
2	FR GRILLE INNER GARNISH A205 505 18 3D ✓	1	de ✓	\$72.00 ✓	
3	TUBE ✓	1	dis ✓	\$105.00 ✓	
4	UPPER CTR BRACKET A205 620 41 01 ✓	1	dis ✓	\$115.00 ✓	
5	R / GRILLE INNER GARNISH A205 885 41 23 ✓	1	de ✓	\$38.00 ✓	
6	Rivet ✓	10	no ✓	\$20.00	400
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		1			
21		1			
22		1			
23		1			
24		1			
25		1			
26		1			
27		1			
28		1			
29		1			
30		1			

Steve
11/3/19

Spare PartsVehicle No. : **SGR9900R**Submit By : **Wong Chee Wei**Make & Model : **MERCEDES BENZ C200 A/T ABS D/AIRBAG 2WD 4DR**Year Manufacture : **2017**Chassis No. : **WDD2050422R277287**Engine No. : **27492030958955****OD****S/Order**

S/No.	Part Description	Qty	Cost	Nett	List	S- Nett
			Price	Price	Price	Price
1	BONNET	1	\$1,040.00	66		
2	L/BONNET HINGE	1	\$99.00	Rp		
3	R/BONNET HINGE	1	\$99.00	Rp		
4	L/BONNET LOCK	1	\$35.00	X		
5	R/BONNET LOCK	1	\$35.00	?	X 117	
6	LOGO - BONNET	1	\$42.00	net		
7	INSULATOR BONNET	1	\$132.00	X		
8	INSULATOR CLIP BONNET	20	\$80.00	X		
9	FR GRILLE ✓	1	\$72.00	?	net	
10	FR GRILLE MOULDING BASE ✓	1	\$105.00	?	net	
11	L/CHROME MOULDING GRILLE	1	\$42.00	?	X	
12	R/CHROME MOULDING GRILLE	1	\$42.00	net		
13	EMBLEM - STAR	1	\$72.00	?	X 117	
14	FR BUMPER	1	\$940.00	net		
15	FR BUMPER CLIP	10	\$40.00	net		
16	R/ OUTER GUIDE RAIL ✓	1	\$35.00	?	net	
17	R/BUMPER CARRIER ✓	1	\$48.00	?	net	
18	R/SIDE SENSOR BUMPER ✓	1	\$93.00	?	dis	
19	R/OUT SENSOR BUMPER ✓	1	\$93.00	?	dis	
20	R / INN SENSOR BUMPER	1	\$93.00	?	X 117	
21	R/ GRILLE	1	\$38.00	net		
22	R/LOWER CHROME MOULDING	1	\$85.00	?	X 117	
23	CENTER LOWER CHROME MOULDING	1	\$160.00	?	X 117	
24	RIGHT HEAD LAMP	1	\$1,580.00	net		
25	R/INNER CROSSMEMBER BRACKET	1	\$48.00	?	net	
26	R/BRACKET HEAD LAMP	1	\$385.00	net	X 117	
27	FR REINFORCEMENT	1	\$225.00	?	X 117	
28	R / FR SPONGE	1	\$110.00	net		
29	CTR FR SPONGE	1	\$88.00	?	X 117	
30	L / FR SPONGE	1	\$62.00	X	117	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Steve Ren A before Spring
11/3/19

Spare Parts

Vehicle No. : SGR9900R Submit By : Wong Chee Wei
Make & Model : MERCEDES BENZ C200 AT ABS D/AIRBAG 2WD 4DR Year Manufacture : 2017
Chassis No. : WDD2060422R277287 Engine No. : 27492030958955

OD

S/Order :

S/No.	Part Description	Qty	Cost Price	Nett Price	List Price	S-Nett Price
1	BONNET	1	\$1,040.00	66		
2	L/BONNET HINGE	1	\$99.00	10		
3	R/BONNET HINGE	1	\$99.00	10		
4	L/BONNET LOCK	1	\$39.00	X		
5	R/BONNET LOCK	1	\$39.00	2	16	
6	LOGO - BONNET	1	\$42.00	10		
7	INSULATOR BONNET	1	\$132.00	X		
8	INSULATOR CLIP BONNET	20	\$80.00	X		
9	FR GRILLE	1	\$72.00	2		
10	FR GRILLE MOULDING BASE	1	\$105.00	2	16	
11	L/CHROME MOULDING GRILLE	1	\$42.00		X	
12	R /CHROME MOULDING GRILLE	1	\$42.00	2		
13	EMBLEM-STAR	1	\$72.00	X		
14	FR BUMPER	1	\$940.00	10		
15	FR BUMPER CLIP	10	\$40.00	10		
16	R/ OUTER GUIDE RAIL	1	\$35.00	2		
17	R/BUMPER CARRIER	1	\$48.00	2		
18	R/SIDE SENSOR BUMPER	1	\$93.00	2		
19	R/OUT SENSOR BUMPER	1	\$93.00	2		
20	R/INN SENSOR BUMPER	1	\$93.00	2	X	
21	R/ GRILLE	1	\$38.00	2		
22	R/LOWER CHROME MOULDING	1	\$85.00	2	X	
23	CENTER LOWER CHROME MOULDING	1	\$160.00	2	X	
24	RIGHT HEAD LAMP	1	\$1,580.00	10		
25	R/INNER CROSSMEMBER BRACKET	1	\$48.00	2		
26	R/BRACKET HEAD LAMP	1	\$385.00	10	X	
27	FR REINFORCEMENT	1	\$225.00	2	X	
28	R / FR SPONGE	1	\$110.00	10		
29	CTR FR SPONGE	1	\$88.00	2	X	
30	L/ FR SPONGE	1	\$82.00	2		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Steve Re. d bar spray
11/3/19

129

201 504

61

Vehicle No. : **SGR9900R**
 Make & Model : **MERCEDES BENZ C200 A/T ABS D/AIRBAG 2WD 4DR**
 Chassis No. : **JTFAT35YX0K209513**

Submit By : **Wong Chee Wei**
 Year Manufacture : **2017**
 Engine No. : **27492030958955**

Pages 2

S/No.	Part Description	Qty	Cost Price	Nett Price	List Price	S- Nett Price
31	R/FR FENDER	1	\$460.00	17		
32	R / FENDER LINER FR	1	\$65.00	de		
33	R / FENDER LINER REAR	1	\$65.00	?		
34	R / FENDER CLIPS	10	\$40.00	2		
35	BODY SEALANT					40 60
36	W/ O/S					2 00
37	FRONT NUMBER PLATE					65 35
38						
39						
40						
41						
42						
43						
44						
45						
46						
47						
48						
49						
50						
51						
52						
53						
54						
55						
56						
57						
58						
59						
60						
61						
62						
63						
64						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 68676919 Fax: 62626950, 68676903

Year of Manufacture : 0

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

COMFORTDELGRO ENGINEERING PTE LTD

Appendix A

45 Pandan Road S (609286)

Tel:68676919 Fax: 62626950

Spare Parts

Vehicle No. : SGR9900R Submit By : Wong Chee Wei

Make & Model : MERCEDES D/AIRBAG 2WD
BENZ 4DR Year Manufacture : 0

Chassis No. : WDD2050422R277287 Engine No. :

Supplementary**Cost / List**

S/No.	Part Description	Qty	Unit Price	COST Price	Disposition by Surveyor
1	UPPER GARNISH INNER BUMPER A205 886 11 85 ✓	1		\$42.00	
2	FR GRILLE INNER GARNISH A205 505 18 30 ✓	1		\$72.00	
3	TUBE ✓	1		\$105.00	
4	UPPER CTR BRACKET A205 620 41 01 ✓	1		\$115.00	
5	R / GRILLE INNER GARNISH A205 885 41 23 ✓	1		\$38.00	
6	Rivet ✓	10		\$20.00	
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		1			
21		1			
22		1			
23		1			
24		1			
25		1			
26		1			
27		1			
28		1			
29		1			
30		1			

Steve
11/3/19



平治汽车零部件供应商私人有限公司

AUTOMEXIM SUPPLIES & PARTS HOUSE PTE LTD

580, SERANGOON ROAD SINGAPORE 218194
 TEL : 6295 5593 (4 LINES) FAX : 6295 8503
 GST REG NO : M2-0125450-7 RCB Reg No : I99404347N
 Email : automexi@singnet.com.sg

DELIVERY ORDER

COMFORTDELGRO ENG PTE LTD(PDN) DELIVER TO :
 BLK C 45 PANDAN ROAD
 SINGAPORE 579701 SINGAPORE 609286
 NETTY
 REMARK : 4500807507 /

D/O NO : D617652
 DATE : 09/03/2019
 PAGE : 1 OF 1

ITEM	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL AMT.
1 205-880-0357DB /	F BONET	1	PC	1,040.00 /	1,040.00 ✓
2 000-817-1701DB /	205-213 BONET BAGE	1	PC	42.00 /	42.00 ✓
3 205-880-1840DB /	F BUMPER	1	PC	940.00 /	940.00 ✓
4 124-990-0492DB /	EXPANSION RIVET	10	PC	4.00	40.00 ✓
5 205-885-0921DB /	RAIL RH	1	PC	35.00	35.00 ✓
6 205-885-3265DB /	BASIC MOUNTING FOR BUMPER	1	PC	48.00	48.00 ✓
7 205-885-2623DB /	COVER BUMPER AREA RH	1	PC	38.00	38.00 ✓
8 205-906-7603DB /	HEAD LAMP RH	1	PC	1,580.00	1,580.00 ✓
9 205-620-3501DB /	REINFORCEMENT SIDE BRACKET RH	1	PC	48.00	48.00 ✓
10 205-885-1037DB /	F BUMPER IMPACT ABSORBER	1	PC	110.00	110.00 ✓
11 205-690-3401DB /	F FENDER INNER COVER FRT PART RI	1	PC	65.00	65.00 ✓
12 205-885-1165DB /	BASIC MOUNTING FOR BUMPER	1	PC	42.00	42.00 ✓
13 205-620-4101DB /	CONSOLE	1	PC	115.00	115.00 ✓
14 205-885-4123DB /	COVER BUMPER AREA	1	PC	38.00	38.00 ✓
15 205-505-1830DB /	AIR DUCT SEGMENT	1	PC	72.00	72.00 ✓
16 205-905-9000DB /	PRESSURE SENSOR	1	PC	105.00	105.00 ✓

COMFORTDELGRO ENGINE:	
Items issued to external business and defects. Expenses 1-1	
Issued by:	Recd by:
Name _____	Name _____
Sign/Date _____	Sign/Date 09/09/19
SCM, CPD _____	Crash Repair _____

ISSUED BY : BERNARD

SUB-TOTAL : S\$ 4,358.00
 ADD. 7% GST : S\$ 305.06
 TOTAL : S\$ 4,663.06



平治汽车零部件供应商私人有限公司

AUTOMEXIM SUPPLIES & PARTS HOUSE PTE LTD

580, SERANGOON ROAD SINGAPORE 218194

TEL : 6295 5593 (4 LINES) FAX : 6295 8503

GST REG NO : M2-0125450-7 RCB Reg No : 199404347N

Email : automexi@singnet.com.sg

DELIVERY ORDER

COMFORTDELGRO ENG PTE LTD(PDN) DELIVER TO :

BLK C

SINGAPORE 579701

45 PANDAN ROAD

SINGAPORE 609286

NETTY SGR9900R

D/O NO : D617678

DATE : 11/03/2019

PAGE : 1 OF 1

REMARK : 4500807584 /

ITEM	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL AMT.
1 000-905-5504DB /	DISTANCE SENSOR ✓	1	PC	93.00	93.00
2 003-990-9497DB /	BLIND RIVET	10	PC	3.00	30.00 ✓

COMFORTDELGRO ENG PTE LTD

Items issued in accordance with the order

Issued by: _____

Name _____

Sign/Date _____

SCM, CPD _____

Name _____

Sign/Date 11/03/19

Crash Repair _____

501013290

ISSUED BY : BERNARD

SUB-TOTAL : S\$ 123.00

ADD. 7% GST : S\$ 8.61

TOTAL : S\$ 131.61



平治汽车零部件供应商私人有限公司

AUTOMEXIM SUPPLIES & PARTS HOUSE PTE LTD

580, SERANGOON ROAD SINGAPORE 218194

TEL : 6295 5593 (4 LINES) FAX : 6295 8503

GST REG NO : M2-0125450-7 RCB Reg No : 199404347N

Email : automexi@singnet.com.sg

DELIVERY ORDER

COMFORTDELGRO ENG PTE LTD(PDN) DELIVER TO :
BLK C 45 PANDAN ROAD
SINGAPORE 579701 SINGAPORE 609286
NETTY

D/O NO : D617683
DATE : 11/03/2019
PAGE : 1 OF 1

REMARK : 4500807611 /

ITEM	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL AMT.
1 000-905-5504DB /	DISTANCE SENSOR /	1	PC	93.00	93.00

COMFORTDELGRO ENGINEERING PTE LTD	
Items issued to external business, with no warranty, for and defects. Estimated by:	
Issued by:	Received by:
Name	Name
Sign/Date	Sign/Date 12/03/19
SCM, CPD	Crash Repair

5001013420

ISSUED BY : BERNARD

SUB-TOTAL : S\$ 93.00
ADD. 7% GST : S\$ 6.51
TOTAL : S\$ 99.51

VINCAR

Tax Invoice

Bill To :

COMFORTDELGRO ENGINEERING PTE LTD
45 PANDAN ROAD
SINGAPORE 609286


Invoice No :	MS19040
Date :	14/03/2019
Page :	1
Terms :	C.O.D.

Attn : WONG CHEE WEI**Phone :** 68676919**Fax :** 6624113

Description	Amount (SGD)	Tax Code
MERCEDES BENZ C200 DIAMOND GRILLE REF_NO: YST-W213-1005 REMARK: PART IS OEM	S\$450.00	N7 ✓
Total		S\$450.00
Add: GST @ 7%		S\$31.50
Total Inc GST		S\$481.50
Less: Deposit		S\$0.00
Balance Due		S\$481.50

NOTE : Cheques should be crossed & made payable to
VINCAR PTE LTD
Account No : 208-315-1023 (UOB LTD)

VINCAR PTE LTD


Authorised Signature

VINCAR PRIVATE LIMITED

www.vincar.com.sg

GST REG. NO. 20-0312900-K
CO. REG. NO. 200312900K

ADMIN OFFICE

1 Chang Chuan Road 05-02/03 OC Building Singapore 169630 T 6474 1119 F 6479 1911

RETAIL SHOWROOMS

24 Leng Kee Road 01-02 Leng Kee Autopoint Singapore 159096 T 6473 1119

61 Ubi Avenue 2 02-16/17 Automobile Megamall Singapore 408898 T 6749 1119 F 6842 1911

SPAREPARTS OFFICE

237 Alexandra Road 01-10 to 16 The Arcade Singapore 159929 T 6472 1119 F 6473 1911

Finalize form

ComfortDelgro Engineering Pte Ltd

45 Pandan Road S (609286)

Tel : 68676919 Fax : 62626950

Amended
Finalization Form

Bill To :	AWAC	Vehicle No. :	SGR9900R
-----------	------	---------------	----------

Attention : Mr Dreck DOA @ 19.07.2017

A.Spare parts		
Cost Price	: \$	5,024.00

10% Discount / Plus	:	\$	502.40
			5.526.40

B. Nett Price : \$ _____

Discount / Plus : \$ -

C. Special Nett	: \$	75.00
-----------------	------	-------

D. Labour	: \$	1,410.00
-----------	------	----------

Finalized Total : : \$ 7,011.40

E. Lump Sum (less _____ %)	\$
----------------------------	----

\$

F. Less Excess	\$ -500.00
----------------	------------

Total Amount : : \$ **6,511.40**

N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm & revert by fax. Thanks

Submitted By / Date : Wong Chee Wei / 21.08.2017

Confirmed By / Date :



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA19004033/T1td3e2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 12-04-2019



Code : AWA

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SGR 9900R
Policy No. BVFPSB0006781907	Coverage (\$)	0.00
Claim No.	Excess (\$)	500.00
Assign From BEN TANG	Assign Date	04/03/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C200	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2050422R277287	Colour	BLUE
Odometer	38971	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	PIRELLI	6 mm
L/H Front Tyre	225/45 R18	PIRELLI	6 mm
R/H Rear Tyre	225/45 R18	PIRELLI	6 mm
L/H Rear Tyre	225/45 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/02/2019	Inspection Date	05/03/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 45 PANDAN ROAD SINGAPORE 609286		

5a. Remarks

A)THE MARKET VALUE IS S\$140,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 9900R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (WCP)	BENT	1,040.00	1,040.00
1	L/BONNET HINGE (WCP)	TO REPAIR SEE LABOUR	99.00	-
1	R/BONNET HINGE (WCP)	TO REPAIR SEE LABOUR	99.00	-
1	L/BONNET LOCK (WCP)	NOT NECESSARY	35.00	-
1	R/BONNET LOCK (WCP)	NOT NECESSARY	35.00	-
1	LOGO - BONNET (WCP)	NECESSARY	42.00	42.00
1	INSULATOR BONNET (WCP)	NOT NECESSARY	132.00	-
20	INSULATOR CLIP BONNET (WCP)	NOT NECESSARY	80.00	-
1	FR GRILLE (WCP) }	DAMAGED	72.00	450.00
1	FR GRILLE MOULDING BASE (WCP) }	CRACKED	105.00	-
1	R/CHROME MOULDING GRILLE (WCP) }	CUT	42.00	-
1	L/CHROME MOULDING GRILLE (WCP)	NOT NECESSARY	42.00	-
1	EMBLEM-STAR (WCP)	NOT NECESSARY	72.00	-
1	FR BUMPER (WCP)	DEFORMED	940.00	940.00
10	FR BUMPER CLIP (WCP)	NECESSARY	40.00	40.00
1	R/OUTER GUIDE RAIL (WCP)	DEFORMED	35.00	35.00
1	R/BUMPER CARRIER (WCP)	BENT	48.00	48.00
1	R/SIDE SENSOR BUMPER (WCP)	DISTORTED	93.00	93.00
1	R/OUT SENSOR BUMPER (WCP)	DISTORTED	93.00	93.00
1	R/INN SENSOR BUMPER (WCP)	NOT NECESSARY	93.00	-
1	R/GRILLE (WCP)	CUT	38.00	38.00
1	R/LOWER CHROME MOULDING (WCP)	NOT NECESSARY	85.00	-
1	CENTER LOWER CHROME MOUDING (WCP)	NOT NECESSARY	160.00	-
1	RIGHT HEAD LAMP	CRACKED	1,580.00	1,580.00
1	R/INNER CROSSMEMBER BRACKET (WCP)	BENT	48.00	48.00
1	R/BRACKET HEAD LAMP (WCP)	NOT NECESSARY	385.00	-
1	FR REINFORCEMENT (WCP)	NOT NECESSARY	225.00	-
1	R/FR SPONGE (WCP)	DEFORMED	110.00	110.00
1	CTR FR SPONGE (WCP)	NOT NECESSARY	88.00	-
1	L/ FR SPONGE (WCP)	NOT NECESSARY	62.00	-
1	R/FR FENDER (WCP)	TO REPAIR SEE LABOUR	460.00	-
1	R/FENDER LINER FR (WCP)	DEFORMED	65.00	65.00

Report Ref No. CS/AWA19004033/T1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	R/FENDER LINER REAR (WCP)	NOT NECESSARY	65.00	-
10	R/FENDER CLIPS (WCP)	NOT NECESSARY	40.00	-
1	UPPER GARNISH INNER BUMPER A205 886 11 65 (ADDITIONAL) (WCP)	DEFORMED	42.00	42.00
1	FR GRILLE INNER GARNISH A205 505 18 30 (ADDITIONAL) (WCP)	DEFORMED	72.00	72.00
1	TUBE (ADDITIONAL) (WCP)	DISTORTED	105.00	105.00
1	UPPER CTR BRACKET A205 620 41 01 (ADDITIONAL) (WCP)	DISTORTED	115.00	115.00
1	R/GRILLE INNER GARNISH A205 885 41 23 (ADDITIONAL) (WCP)	DEFORMED	38.00	38.00
10	RIVERT (ADDITIONAL) (WCP)	NECESSARY	30.00	30.00
	COST PLUS 10%		705.00	502.40
			7,755.00	5,526.40
	SPECIAL NETT ITEMS			
1	BODY SEALANT (SN)	NECESSARY	60.00	40.00
1	A/C GAS (SN)	NOT NECESSARY	60.00	-
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
			155.00	75.00
	LABOUR			
	TO REMOVE AND REPLACE ALL DAMAGE PARTS, FRT RHS FENDER, BONNET, BUMPER, AND OTHER BY PANEL BEATING. INCLUSIVE OF THE REPAIR OF L/BONNET HINGE, R/BONNET HINGE AND R/FR FENDER.		2,500.00	600.00
	TO SPRAY PAINTING DAMAGE PARTS AND SURFACE FRT DOOR AND PILLER.		2,200.00	750.00
	TO CHECK WIRING SYSTEM.		80.00	30.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
	APPLY ANTI RUST COATING.		80.00	30.00
			-	-
			-	-
			-	-
			-	-
			-	-
			4,920.00	1,410.00
	GRAND TOTAL		12,830.00	7,011.40
	RECOMMENDED COST OF REPAIRS			7,011.40

Report Ref No. CS/AWA19004033/T1td3e2



LESS EXCESS			-500.00
NETT LIABILITY			6,511.40

Report Ref No. CS/AWA19004033/T1td3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.