

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 9073E

DATE 4/3/2019 15:47

MAKE :

MODEL : HYUNDAI i40

AKA-JU
L8um

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Bracket		\$ 35.60	\$ 71.20
	Rear Bumper Sponge			\$ 103.50
	SUB TOTAL			\$ 749.70
	LESS 20%			\$ 149.94
	DISCOUNTED TOTAL			\$ 599.76
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Bumper Reverse Sensor			\$ 135.70
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Wiring Charge			\$ 30.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 1,595.46
<p>NAZ LK1C</p> <p>5/3/19 1550</p> <p>LIS</p> <p>2 DAY</p> <p>CHECK ITEMS PHOTOS</p> <p>AFTER REPAIR PHOTOS</p>				
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

CRK

OWN

?

?

Nett / NCC

Nett /

Not working

200

200

OWN

30