

19/5/2018

INS. CASE OWNER:

RA

CC 4/AXA1900

4038, A 263^{SR}

LKK:

IDAC:

Surveyor:

Admin

DOI:

ASSIGNMENT

4/1/18

Date / Time:

4/1/18

Registered in Merlimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SIX 2444

Name of Insured:

PRIMEERSEVANSLO K GOVINDASWAMY

Claim No.:

SAMPLE 08/10/16

Policy No.:

PA/POKER

Insured Tel No.:

HP:

Make / Model:

HYUNDAI

Excess Sec II : \$5

D.O.A.:

1/1/18

Place of Accident:

PIE TMS BKE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SIX 2444

SIX 4245P

SIX 8138T

INSRS:
WSP:
Tel:
Liability:
RMKS:

01

INSRS:
WSP:
Tel:
Liability:
RMKS:New motor
TPINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SIX 4245P - X

SIX 2444 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

Email 09.05.19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: LOP

Repair Cost:

43 \$513,000

(14 days) Reduction:

64 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 23-07-19

Confirm with SURVEY

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 100%

Repair Cost:

nil

3 VEH CL OI LAST

Loss of Rental (LOR):

\$5 -

(days)

Loss of Use (LOU):

\$5 1400.00

(5100) x 1/2 days

Loss of Income (LOI):

\$5 -

(S x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

\$57.45

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

4350

Total:

\$515,571.45

Global Sum \$5: 15,000

FINAL PAYMENT

Date/Time: 23-07-19

Confirm with: SURVEY

Email ☒ Call ☐

Payee 1:

\$515,000

Name 1:

HEAT MOTOR PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJE 424SP Yr Regn: 2008 AprilType: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c. 1598Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 250875 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0S3ZEE106104073Gen. Cond: Good Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kapsen kapsen

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 04/03/19Survey held at Chew Motor.Des. of Damages: Frt Rear O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TPAXA.COE Expiry : 24/04/23.45: 113,000 (RED: 113,019.25 6.9%)MV: 29K 29,300PV: 16K 16,000Nett: 13K 13,480

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

EZ-SWIFT CAR RENTAL & LEASING PTE LTD

04/03/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP AxA.

Asher.

MR053ZEE106104073

Accident date: 01/03/2019

Estimated repair cost for vehicle no: SJE4245P TOYOTA ALTIS 1.6 A '08

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Buckled</i>		\$1,217.45 <i>+ 906</i>
2	2	Front Bonnet Hinge <i>new</i>	\$121.35	\$242.70 <i>+</i>
3	1	Front Bonnet Lock <i>new</i>		\$182.10 <i>+</i>
4	1	Front Bonnet Inner Rubber <i>new</i>		\$174.70 <i>+</i>
5	1	Front Bonnet Insulator <i>new</i>		\$374.50 <i>+</i>
7	2	Front Head Lamp <i>cracked</i>	\$445.10	\$890.20 <i>✓</i>
8	2	Front Head Lamp Lower Bracket <i>new</i>	\$174.80	\$349.60 <i>+</i>
9	1	Front Bumper <i>delid</i>		\$371.45 <i>✓</i>
10	16	Front Bumper Clip <i>new</i>	\$6.50	\$104.00 <i>✓</i>
11	2	Front Bumper Side Retainer <i>new</i>	\$122.10	\$244.20 <i>95</i>
12	2	Front Bumper Fog Lamp <i>LH cracked</i>	\$374.10	\$748.20 <i>374.10</i>
13	2	Front Bumper Fog Lamp Cover <i>new</i>	\$174.40	\$348.80 <i>+</i>
14	1	Front Bumper Emblem Logo <i>new</i>		\$121.10 <i>✓</i>
15	1	Front Bumper Number Plate <i>Best</i>		\$50.00 <i>✓</i>
16	1	Front Bumper Top Rubber <i>new</i>		\$134.45 <i>+</i>
17	1	Front Bumper Centre Lower Garnish <i>delid</i>		\$182.20 <i>✓</i>
18	1	Front Bumper Reinforcement <i>Best</i>		\$374.40 <i>✓</i>
19	1	Front Grille <i>cracked</i>		\$381.45 <i>✓</i>
20	1	Front Grille Inner <i>new</i>		\$281.75 <i>+</i>
21	1	Front Support Panel <i>Buckled</i>		\$972.40 <i>✓</i>
22	1	Front Air-Con Condenser <i>Best</i>		\$1,217.85 <i>✓</i>
23	1	Front Air-Con Fan Motor Assy <i>new</i>		\$371.10 <i>+</i>
24	1	Front Radiator <i>Best</i>		\$974.45 <i>✓</i>
25	1	Front Radiator Fan Motor Assy <i>new</i>		\$378.85 <i>+</i>
26	1	Rear Boot Lid <i>Buckled</i>		\$781.45 <i>✓</i>
27	2	Rear Boot Lid Hinge <i>new</i>	\$182.25	\$364.50 <i>+</i>
28	1	Rear Boot Lid Emblem Logo <i>new</i>		\$30.75 <i>✓</i>

29	1	Rear Boot Lid Corolla Logo		\$28.90	✓
30	1	Rear Boot Lid Altis Logo	new	\$31.20	✓
31	1	Rear Boot Lid 1.6 Logo		\$28.85	✓
32	1	Rear Boot Lid Centre Chrome Moulding	new	\$374.10	+
34	2	Rear Boot Lid Side Reflector	cut	\$274.10	\$548.20 ✓
35	1	Rear Boot Lid Number Plate	Not free	\$50.00	+
36	2	Rear Boot Lid Number Plate Lamp		\$83.10	\$166.20 +
37	1	Rear Boot Lid Inner Lock	changed		\$136.60 ✓
38	1	Rear Boot Lid Inner Rubber	cut		\$231.35 ✓
39	1	Rear Boot Lid Inner Trim Board	3M		\$371.25 +
40	8	Rear Boot Lid Inner Trim Board Clip	3M	\$6.50	\$52.00 +
41	2	Rear Tail Lamp	could	\$371.85	\$743.70 ✓
43	2	Rear Tail Lamp Panel	Ry's	\$271.85	\$543.70 +
44	1	Rear Bumper	Debond		\$561.60 ✓
45	8	Rear Bumper Clip	new	\$6.50	\$52.00 30
46	2	Rear Bumper Side Retainer Outer	new	\$107.00	\$214.00 85
47	2	Rear Bumper Side Retainer Inner	new	\$92.90	\$185.80 +
48	1	Rear Bumper Reverse Sensor (Special Nett)	Debd		\$350.00 200/sw
49	2	Rear Bumper Side Reflector	cracked	\$171.45	\$342.90 78
50	1	Rear Bumper Inner Foam	could		\$180.90 ✓
51	1	Rear Bumper Reinforcement	Bent		\$295.90 105
52	2	Rear Bumper Reinforcement Bracket	Bent	\$61.80	\$123.60 ✓
53	2	Rear Bumper Mud Shield	3M	\$81.10	\$162.20 +
54	12	Rear Bumper Mud Shield Clip	3M	\$6.50	\$78.00 +
55	2	Rear Fender	Ry's	\$971.45	\$1,942.90 +
56	2	Rear Fender Inner Trim Board	3M new	\$381.90	\$763.80 +
57	16	Rear Fender Inner Trim Board Clip		\$6.50	\$104.00 +
58	2	Rear Fender Air Duct Cover	LH Debd	\$95.40	\$190.80 95%
59	1	Rear End Panel	Distorted		\$731.45 ✓
60	1	Rear End Panel Top Garnish	Debd		\$371.45 ✓
61	1	Rear Spare Tyre Panel	Buckled		\$972.85 ✓
62	2	Rear Spare Tyre Side Panel	new	\$181.90	\$363.80 +
63	1	Rear Spare Tyre Panel Top Cover	tom		\$371.25 ✓
64	1	Rear Spare Tyre Panel Top Sponge	new		\$381.90 +
65	1	Rear Spare Tyre Panel & End Panel Sealant	new		\$450.00 200/sw
66	1	Rear Spare Tyre Lock	could		\$172.10 35
67	1	Rear L/H Chassis	Ry's		\$741.35 +
68	1	Rear Windscreen Seal	3M new		\$172.45 +
69	1	Rear Windscreen Moulding			\$181.90 +
70	1	Rear Exhaust	Bent		\$792.90 ✓
71	2	Rear Exhaust Mounting	3M	\$61.10	\$122.20 +
72	1	Rear Exhaust Aluminium Cover			\$182.10 +
73	1	Rear Centre Exhaust			\$972.50 +

14292-10 SN 400

1071907

Subtotal :- \$27,699.25

Labour charges

To remove & refit cushion & trim board	\$280.00 200
To remove & refit roof lining	\$380.00 X
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & centre exhaust	\$380.00 80
To remove & refit rear windscreen	\$120.00 X
Gum	\$50.00 X
To remove & refit petrol tank	\$280.00 X
To remove & refit air-con condenser, radiator, fan motor & top up gas	\$380.00 120
To check wheel alignment	\$150.00 X
To check wiring	\$100.00 60
Tuff kote	\$150.00 60
Towing fee	\$150.00 X
Panel beating	\$3,000.00 2400
Spray painting	\$2,800.00 2200

Subtotal :- \$8,320.00

Total:- \$36,019.25

total 16289.07

4/5: 13K

14 days

131C 14 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 09/05/2019

Survey Details:

Date of loss	1-Mar-19
Date of appointment	4-Mar-19
Date of survey	4-Mar-19
Location of survey	CHEW MOTOR PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SJE 4245P
Make and Model	TOYOTA COROLLA ALTIS 1.6 AUTO
Date of registration	25/4/2008
Excess	
Market Value	\$29,500
Parf Rebate	\$16,020
Nett Loss	\$13,480

Repair details:

Initial Estimate	\$ 36,019.25
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 11,119.08
Check items (estimate)	\$ -
Labour	\$ 5,170.00
Total	\$ 16,289.08
Lump Sum(if applicable)	\$ 13,000.00

Number of days for repair	<u>14days</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Remarks:

Liability: Insured involved in 3 vehicle chain collision insured was the last vehicle. Inform insured that his NCD may affected and AXA to settle at best.

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	13,910.00
Loss of use	\$	1,600.00
Loss of rental	\$	-
Loss of income	\$	-
LTA search fees	\$	7.45
Others	\$	-
Proposed Total	\$	15,517.45

*Third party vehicle is rental vehicle

veh. in
- when motor



Service Request Details

Claim

S9M01FO8

Reference

None

Loss Date

1 March 2019

Report Date

2 Mar 2019 12:00:00 AM

Request Date

4 March 2019

Due Date

11 March 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJE4245P

Make

TPVD TOYOTA

Model

ALTIS

Primary Contact/Insured

K GOVINDASAMY PANNEERSELVAN S/O
BLK 22 MARSILING DRIVE, #11-131, 730022, Singapore
98414158
GPSELVAN@SP.EDU.SG

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



MANDATE IA (S9M01FO8 / SJE 4245P)

Type

Question

Message

Liability: Insured involved in 3 vehicle chain collision insured was the last vehicle. Inform insured that his NCD may affected and AXA to settle at best. Settlement: Repair Cost : \$13,910.00 (w/GST) Loss of Use : \$1,600.00 (16days x \$100) LTA Search: \$7.45 Total: \$15,517.45 Revised Immediate Advice with Mandate and relevant document uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (09/05/2019)

Reply

5/27/2019

Claim Portal

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu



Re:MANDATE IA (S9M01FO8 / SJE 4245P)

Type

🔍 Question

Message

Hi, pls propose global sum at \$12,400 (all-in). TY.

Reply



RE: Re:MANDATE IA (S9M01FO8 / SJE 4245P)

Type

🔗 Question

Message

Hi Sir, Third party disagreed with our offer and counter propose G/S \$15,000 (all in). Please refer to third party email dated 27/05/2019. Thank you (14.06.19)

Reply



Re:RE: Re:MANDATE IA (S9M01FO8 / SJE 4245P)

Type

🔍 Question

Message

Pls proceed to accept global sum of \$15k. TY.

Reply

Assignment

To: Chew Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. SJE424P and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 02 day of 03 2019.

Signature : 
Name : EZ-SWIFT CAR RENTAL & LEASING PTE LTD
ID No. : Reg No.: 201724540N
Address : 1 Kaki Bukit Avenue 6
Block A #01-11 Autobay@Kaki Bukit
Singapore 417883

Witness Signature : 
Witness Name : CHEW MOTOR PTE. LTD.
Witness ID : 1 Kaki Bukit Avenue 6 Blk C #01-41
Witness Address : Autobay@Kaki Bukit Singapore 417883
Tel: 6509 5545 Fax: 6509 5567
Email: claims@chewmotor.com
UEN: 201718369R

OK
Asher

Our Reference : CM1904-0058 / SJE4245P
Your Reference : SLX2944U

23 April 2019

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#B1-01,
Singapore 068811



CHEW MOTOR PTE. LTD

WITHOUT PREJUDICE

Dear Sir/Madam

ACCIDENT INVOLVING SJE4245P & SLX2944U ON 01.03.2019 ALONG PIE(JURONG) BEFORE BKE EXIT AT 21:50HRS

We are instructed by **EZ-SWIFT CAR RENTAL & LEASING PTE LTD** to claim damages and losses against you in connection with the above-captioned road traffic accident which our client's vehicle **SJE4245P** damaged by vehicle **SLX2944U** driven by your insured at the material time.

We are informed that the said accident was caused by your insured's negligence. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows: -


➤ Repair Costs (7% GST)	\$ 13,910.00
➤ Loss of Use for 16 days (14 + 2 Weekends) (Rental Vehicle)	\$ 1,920.00
➤ LTA Search Fees	\$ 7.45
➤ Total	<u>\$ 15,837.45</u>

A copy of each supporting documents are enclosed for your perusal.

- GIA Report
- Invoice
- LTA Search Receipt

Please let us have your cheque for the sum of **\$15,837.45** made payable to us, **CHEW MOTOR PTE. LTD.** within the next 14 days.

Yours Sincerely,


CHEW MOTOR PTE. LTD.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19004038/Aeb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 30-07-2019



ATTN: RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 2944U	Veh. Inspected	SJE 4245P
Policy No.	VPA/P2114822	Coverage (\$)	0.00
Claim No.	S9M01FO8	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	04/03/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053ZEE106104073	Colour	SILVER
Odometer	250875	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	KAPSEN	6 mm
L/H Front Tyre	195/65R15	KAPSEN	6 mm
R/H Rear Tyre	195/65R15	KAPSEN	6 mm
L/H Rear Tyre	195/65R15	KAPSEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/03/2019	Inspection Date	04/03/2019
Survey held at	CHEW MOTOR PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **14 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 4245P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET (CONSISTENT)	BUCKLED	1,217.45	906.00
2	FRONT BONNET HINGE @ \$121.35 (CONSISTENT)	NOT NECESSARY	242.70	-
1	FRONT BONNET LOCK (CONSISTENT)	DAMAGED	182.10	182.10
1	FRONT BONNET INNER RUBBER (CONSISTENT)	NOT NECESSARY	174.70	-
1	FRONT BONNET INSULATOR (CONSISTENT)	NOT NECESSARY	374.50	-
2	FRONT HEAD LAMP @ \$445.10 (CONSISTENT)	CRACKED	890.20	890.20
2	FRONT HEAD LAMP LOWER BRACKET @ \$174.80 (CONSISTENT)	NOT NECESSARY	349.60	-
1	FRONT BUMPER (CONSISTENT)	DEFORMED	371.45	371.45
16	FRONT BUMPER CLIP @ \$6.50 (CONSISTENT)	NECESSARY	104.00	104.00
2	FRONT BUMPER SIDE RETAINER @ \$122.10 (CONSISTENT)	NECESSARY	244.20	95.00
2	FRONT BUMPER FOG LAMP @ \$374.10 (CONSISTENT)	N/S CRACKED	748.20	374.10
2	FRONT BUMPER FOG LAMP COVER @ \$174.40 (CONSISTENT)	NOT NECESSARY	348.80	-
1	FRONT BUMPER EMBLEM LOGO (CONSISTENT)	NECESSARY	121.10	121.10
1	FRONT BUMPER NUMBER PLATE (CONSISTENT)	BENT	50.00	50.00
1	FRONT BUMPER TOP RUBBER (CONSISTENT)	NOT NECESSARY	134.45	-
1	FRONT BUMPER CENTRE LOWER GARNISH (CONSISTENT)	DEFORMED	182.20	182.20
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	374.40	374.40
1	FRONT GRILLE (CONSISTENT)	CRACKED	381.45	381.45
1	FRONT GRILLE INNER (CONSISTENT)	NOT NECESSARY	281.75	-
1	FRONT SUPPORT PANEL (CONSISTENT)	BUCKLED	972.40	972.40
1	FRONT AIR-CON CONDENSER (CONSISTENT)	BENT	1,217.85	1,217.85
1	FRONT AIR-CON FAN MOTOR ASSY (CONSISTENT)	NOT NECESSARY	371.10	-
1	FRONT RADIATOR (CONSISTENT)	BENT	974.45	974.45
1	FRONT RADIATOR FAN MOTOR ASSY (CONSISTENT)	NOT NECESSARY	378.85	-
1	REAR BOOT LID (CONSISTENT)	BUCKLED	781.45	781.45
2	REAR BOOT LID HINGE @ \$182.25 (CONSISTENT)	NOT NECESSARY	364.50	-
1	REAR BOOT LID EMBLEM LOGO (CONSISTENT)	NECESSARY	30.75	30.75
1	REAR BOT LID COROLLA LOGO (CONSISTENT)	NECESSARY	28.90	28.90

Report Ref No. CC4/ASM19004038/Aeb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT LID ALTIS LOGO (CONSISTENT)	NECESSARY	31.20	31.20
1	REAR BOOT LID 1.6 LOGO (CONSISTENT)	NECESSARY	28.85	28.85
1	REAR BOOT LID CENTRE CHROME MOULDING (CONSISTENT)	NOT NECESSARY	374.10	-
2	REAR BOOT LID SIDE REFLECTOR @ \$274.10 (CONSISTENT)	CUT	548.20	548.20
1	REAR BOOT LID NUMBER PLATE (CONSISTENT)	NOT NECESSARY	50.00	-
2	REAR BOOT LID NUMEBR PLATE LAMP @ \$83.10 (CONSISTENT)	NOT NECESSARY	166.20	-
1	REAR BOOT LID INNER LOCK (CONSISTENT)	DAMAGED	136.60	136.60
1	REAR BOOT LID INNER RUBBER (CONSISTENT)	CUT	231.35	231.35
1	REAR BOOT LID INNER TRIM BOARD (CONSISTENT)	NOT NECESSARY	371.25	-
8	REAR BOOT LID INNER TRIM BOARD CLIP @ \$6.50 (CONSISTENT)	NOT NECESSARY	52.00	-
2	REAR TAIL LAMP @ \$371.85 (CONSISTENT)	CRACKED	743.70	743.70
2	REAR TAIL LAMP PANEL @ \$271.85 (CONSISTENT)	TO REPAIR SEE LABOUR	543.70	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	561.60	561.60
8	REAR BUMPER CLIP @ \$6.50 (CONSISTENT)	NECESSARY	52.00	30.00
2	REAR BUMPER SIDE RETAINER OUTER @ \$107.00 (CONSISTENT)	NECESSARY	214.00	85.00
2	REAR BUMPER SIDE RETAINER INNER @ \$92.90 (CONSISTENT)	NOT NECESSARY	185.80	-
2	REAR BUMPER SIDE REFLECTOR @ \$171.45 (CONSISTENT)	CRACKED	342.90	78.00
1	REAR BUMPER INNER FOAM (CONSISTENT)	CRACKED	180.90	180.90
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	295.90	105.00
2	REAR BUMPER REINFORCEMENT BRACKET @ \$61.80 (CONSISTENT)	BENT	123.60	123.60
2	REAR BUMPER MUD SHIELD @ \$81.10 (CONSISTENT)	NOT NECESSARY	162.20	-
12	REAR BUMPER MUD SHIELD CLIP @ \$6.50 (CONSISTENT)	NOT NECESSARY	78.00	-
2	REAR FENDER @ \$971.45 (CONSISTENT)	TO REPAIR SEE LABOUR	1,942.90	-
2	REAR FENDER INNER TRIM BOARD @ \$381.90 (CONSISTENT)	NOT NECESSARY	763.80	-
16	REAR FENDER INNER TRIM BOARD CLIP @ \$6.50 (CONSISTENT)	NOT NECESSARY	104.00	-

Report Ref No. CC4/ASM19004038/Aeb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER AIR DUCT COVER @ \$95.40 (CONSISTENT)	N/S DEFORMED	190.80	95.40
1	REAR END PANEL (CONSISTENT)	DISTORTED	731.45	731.45
1	REAR END PANEL TOP GARNISH (CONSISTENT)	DEFORMED	371.45	371.45
1	REAR SPARE TYRE PANEL (CONSISTENT)	BUCKLED	972.85	972.85
2	REAR SPARE TYRE SIDE PANEL @ \$181.90 (CONSISTENT)	NOT NECESSARY	363.80	-
1	REAR SPARE TYRE PANEL TOP COVER (CONSISTENT)	TORN	371.25	371.25
1	REAR SPARE TYRE PANEL TOP SPONGE (CONSISTENT)	NOT NECESSARY	381.90	-
1	REAR SPARE TYRE LOCK (CONSISTENT)	CRACKED	172.10	35.00
1	REAR L/H CHASSIS (CONSISTENT)	TO REPAIR SEE LABOUR	741.35	-
1	REAR WINDSCREEN SEAL (CONSISTENT)	NOT NECESSARY	172.45	-
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NOT NECESSARY	181.90	-
1	REAR EXHAUST (CONSISTENT)	BENT	792.90	792.90
2	REAR EXHAUST MOUNTING @ \$61.10 (CONSISTENT)	NOT NECESSARY	122.20	-
1	REAR EXHAUST ALUMINIUM COVER (CONSISTENT)	NOT NECESSARY	182.10	-
1	REAR CENTRE EXHAUST (CONSISTENT)	NOT NECESSARY	972.50	-
	LESS 25% DISCOUNT		-	-3,573.02
			26,899.25	10,719.08
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	350.00	200.00
1	REAR SPARE TYRE PANEL & END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	450.00	200.00
1	GUM (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			850.00	400.00
	LABOUR			
	TO REMOVE & REFIT CUSHION & TRIM BOARD.		280.00	200.00
	TO REMOVE & REFIT ROOF LINING.	NOT NECESSARY	380.00	-
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
	TO REMOVE & REFIT REAR & CENTRE EXHAUST.		380.00	80.00
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT PETROL TANK.	NOT NECESSARY	280.00	-

Report Ref No. CC4/ASM19004038/Aeb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT AIR-CON CONDENSER, RADIATOR, FAN MOTOR & TOP UP GAS.		380.00	120.00
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	TO CHECK WIRING.		100.00	60.00
	TUFF KOTE.		150.00	60.00
	TOWING FEE.	NOT NECESSARY	150.00	-
	PANEL BEATING, INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL, REAR FENDER AND REAR L/H CHASSIS.		3,000.00	2,400.00
	SPRAY PAINTING.		2,800.00	2,200.00
			8,270.00	5,170.00
GRAND TOTAL			36,019.25	16,289.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,000.00

Report Ref No. CC4/ASM19004038/Aeb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.