



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

EZ-SWIFT CAR RENTAL & LEASING PTE LTD

04/03/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP AxA.

Asher.

MR053ZEE106104073

Accident date: 01/03/2019

Estimated repair cost for vehicle no: SJE4245P TOYOTA ALTIS 1.6 A '08

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Buckled</i>		\$1,217.45 <i>+ 906</i>
2	2	Front Bonnet Hinge <i>new</i>	\$121.35	\$242.70 <i>+</i>
3	1	Front Bonnet Lock <i>new</i>		\$182.10 <i>✓</i>
4	1	Front Bonnet Inner Rubber <i>new</i>		\$174.70 <i>+</i>
5	1	Front Bonnet Insulator <i>new</i>		\$374.50 <i>+</i>
7	2	Front Head Lamp <i>cracked</i>	\$445.10	\$890.20 <i>✓</i>
8	2	Front Head Lamp Lower Bracket <i>new</i>	\$174.80	\$349.60 <i>+</i>
9	1	Front Bumper <i>delid</i>		\$371.45 <i>✓</i>
10	16	Front Bumper Clip <i>new</i>	\$6.50	\$104.00 <i>✓</i>
11	2	Front Bumper Side Retainer <i>new</i>	\$122.10	\$244.20 <i>- 95</i>
12	2	Front Bumper Fog Lamp <i>new</i>	\$374.10	\$748.20 <i>- 374.10</i>
13	2	Front Bumper Fog Lamp Cover <i>new</i>	\$174.40	\$348.80 <i>+</i>
14	1	Front Bumper Emblem Logo <i>new</i>		\$121.10 <i>✓</i>
15	1	Front Bumper Number Plate <i>new</i>		\$50.00 <i>✓</i>
16	1	Front Bumper Top Rubber <i>new</i>		\$134.45 <i>+</i>
17	1	Front Bumper Centre Lower Garnish <i>delid</i>		\$182.20 <i>✓</i>
18	1	Front Bumper Reinforcement <i>new</i>		\$374.40 <i>✓</i>
19	1	Front Grille <i>new</i>		\$381.45 <i>✓</i>
20	1	Front Grille Inner <i>new</i>		\$281.75 <i>+</i>
21	1	Front Support Panel <i>Buckled</i>		\$972.40 <i>✓</i>
22	1	Front Air-Con Condenser <i>new</i>		\$1,217.85 <i>✓</i>
23	1	Front Air-Con Fan Motor Assy <i>new</i>		\$371.10 <i>+</i>
24	1	Front Radiator <i>new</i>		\$974.45 <i>✓</i>
25	1	Front Radiator Fan Motor Assy <i>new</i>		\$378.85 <i>+</i>
26	1	Rear Boot Lid <i>Buckled</i>		\$781.45 <i>✓</i>
27	2	Rear Boot Lid Hinge <i>new</i>	\$182.25	\$364.50 <i>+</i>
28	1	Rear Boot Lid Emblem Logo <i>new</i>		\$30.75 <i>✓</i>

29	1	Rear Boot Lid Corolla Logo	2		\$28.90	✓
30	1	Rear Boot Lid Altis Logo	1		\$31.20	✓
31	1	Rear Boot Lid 1.6 Logo	1		\$28.85	✓
32	1	Rear Boot Lid Centre Chrome Moulding	new		\$374.10	+
34	2	Rear Boot Lid Side Reflector	lit	\$274.10	\$548.20	✓
35	1	Rear Boot Lid Number Plate	3M		\$50.00	+
36	2	Rear Boot Lid Number Plate Lamp	3M	\$83.10	\$166.20	+
37	1	Rear Boot Lid Inner Lock	Deaged		\$136.60	✓
38	1	Rear Boot Lid Inner Rubber	lit		\$231.35	✓
39	1	Rear Boot Lid Inner Trim Board	3M		\$371.25	+
40	8	Rear Boot Lid Inner Trim Board Clip	3M	\$6.50	\$52.00	+
41	2	Rear Tail Lamp	could	\$371.85	\$743.70	✓
43	2	Rear Tail Lamp Panel	Pyris	\$271.85	\$543.70	+
44	1	Rear Bumper	Deformed		\$561.60	✓
45	8	Rear Bumper Clip	new	\$6.50	\$52.00	30
46	2	Rear Bumper Side Retainer Outer	new	\$107.00	\$214.00	85
47	2	Rear Bumper Side Retainer Inner	new	\$92.90	\$185.80	+
48	1	Rear Bumper Reverse Sensor (Special Nett)	Deagd		\$350.00	2nd SW
49	2	Rear Bumper Side Reflector	cracked	\$171.45	\$342.90	78
50	1	Rear Bumper Inner Foam	could		\$180.90	✓
51	1	Rear Bumper Reinforcement	Bent		\$295.90	105
52	2	Rear Bumper Reinforcement Bracket	Bent	\$61.80	\$123.60	✓
53	2	Rear Bumper Mud Shield	3M	\$81.10	\$162.20	+
54	12	Rear Bumper Mud Shield Clip	3M	\$6.50	\$78.00	+
55	2	Rear Fender	Pyris	\$971.45	\$1,942.90	+
56	2	Rear Fender Inner Trim Board	3M	\$381.90	\$763.80	+
57	16	Rear Fender Inner Trim Board Clip		\$6.50	\$104.00	+
58	2	Rear Fender Air Duct Cover	LH Dehd	\$95.40	\$190.80	9540
59	1	Rear End Panel	Disltd		\$731.45	✓
60	1	Rear End Panel Top Garnish	Dehd		\$371.45	✓
61	1	Rear Spare Tyre Panel	Buckled		\$972.85	✓
62	2	Rear Spare Tyre Side Panel	new	\$181.90	\$363.80	+
63	1	Rear Spare Tyre Panel Top Cover	tom		\$371.25	✓
64	1	Rear Spare Tyre Panel Top Sponge	new		\$381.90	+
65	1	Rear Spare Tyre Panel & End Panel Sealant	new		\$450.00	2nd SW
66	1	Rear Spare Tyre Lock	could		\$172.10	35
67	1	Rear L/H Chassis	Pyris		\$741.35	+
68	1	Rear Windscreen Seal	3M		\$172.45	+
69	1	Rear Windscreen Moulding			\$181.90	+
70	1	Rear Exhaust	Bent		\$792.90	✓
71	2	Rear Exhaust Mounting	3M	\$61.10	\$122.20	+
72	1	Rear Exhaust Aluminium Cover			\$182.10	+
73	1	Rear Centre Exhaust			\$972.50	+

14292-10

SN: 400

1071907

Subtotal :- \$27,699.25

Labour charges

To remove & refit cushion & trim board	\$280.00 200
To remove & refit roof lining	\$380.00 X
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & centre exhaust	\$380.00 80
To remove & refit rear windscreen	\$120.00 X
Gum	\$50.00 X
To remove & refit petrol tank	\$280.00 X
To remove & refit air-con condenser, radiator, fan motor & top up gas	\$380.00 120
To check wheel alignment	\$150.00 X
To check wiring	\$100.00 60
Tuff kote	\$150.00 60
Towing fee	\$150.00 X
Panel beating	\$3,000.00 2400
Spray painting	\$2,800.00 2200

Subtotal :- \$8,320.00

Total:- \$36,019.25

Total: 16289.07

4/5: 13K (not vide)

14 Days

131C 14 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: