

INS CASE OWNER:

Bernard

CC 6, ALG 1900

4042, Afo3/2

LKK:  
IDAC:

Surveyor:

Adrian

DOI:

4/3/19

Date / Time:

4/3/19

Registered in Merimen:

7/3/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLX 7821 H

Name of Insured:

HIS MOTORING PTE

Insured Tel No.:

HP:

D.O.A.:

4/3/19

Excess Sec II :SS

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Yu wongjun

Driver Tel No.:

(V/L: YES / NO )

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Flying High



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

11/3

cpl

8/4/2019

SLX 7821 H. 25/04/2019/16/01/18

File review, BOLA 27, Rental company, send letter to OI

KLU LOB ✓

After better paint photo ✓

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 16/5/2019

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 4,700.00

( 5 days)

Reduction:

54.78

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Zack

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

S\$ 4,700.00

Loss of Rental (LOR):

S\$ -

( days)

Loss of Use (LOU):

S\$ 300.00

(\$ 60.00 x 5 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$310.00

Total:

S\$ 5,000.00

Global Sum S\$ 5,000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 5,000.00

Name 1:

Flying High spray painting

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY:

REF:

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Vehicle: IN / OUT

Person Contacted: \_\_\_\_\_

Veh No: SKW8080P Yr Regn: 1Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Verel c.c. 1496Colour: White A/C: Insured / Std / NI / NASp. Reading: 84827 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16R: 215/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 04/03/19.Survey held at Flying HighDes. of Damages: Frt / rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAIG.10393U.S. \$4,700.00 (Nett 5,693.00 / 54.78%)

mv:

pv:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Pref. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic &amp; Add.

S + RS. \$1

Photos

Others

TOTAL

Subject: SKW8080P

Date:

Honda Vezel

Ru11103164

Rear Bumper Distorted	880 ✓
Rear Bumper Clips m	30 ✓
Rear Bumper Side Holder x 02 m	32 x 2 = 64 ✓
Rear Bumper Lower Spoiler Distorted	1200(SN) 900(SN)
Rear Bumper Reflector x 02 Cracked	151 x 2 = 302 ✓
Rear Bumper Top Chrome Plate Bent	380(SN) 300(SN)
Rear End Panel Repair	580 X
Rear End Panel Top Garnish Behind	105 ✓
Rear End Panel Sealant NE m	60(SN) X
Reverse Sensor Dmgd	280(SN) 200(SN)
Taillamp x 02 LH cut	460 x 2 = 920 460
Taillamp Lower Garnish x 02 LH Behind	195 x 2 = 390 195
Tailgate Distorted	1100 ✓
Tailgate Lock Dmgd	182 ✓
Tailgate Weatherstripe, NE m	165 X
Tailgate Buzzer Dmgd	605 ✓
Tailgate <del>Weatherstripe</del> Moulding m	125 ✓
Tailgate Glass Sealant m	60(SN) ✓
Vezel Emblem m	65 ✓
Spore Tyre Panel Top Cover NE m	305 X
Spore Tyre Panel Tools Sponge Behind	215 ✓

3828

S/V 1400

3061.40

Subject: SKW8080P.

Date:

Panel Beating  
Spray Painting  
Wiring -

To underseal

To remove reverse sensor

To remove upholstery.

To transfer tailgate fitting.

To remove tailgate glass

~~1200~~ 600

~~1200~~ 600

~~50~~ 30

150 x

~~100~~ 50

~~150~~ 50

~~150~~ 80

~~180~~ 120

1530

3180

total: 5592.4

h/s: A.7k

05 Day.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

**.Poh Kin (LKKAUTO)**

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Thursday, 23 May 2019 2:46 PM  
**To:** OHMYCAR  
**Cc:** Admin A  
**Subject:** RTA involving vehicle nos, SKW8080P and SLX 7821H on 02.03.2019 \*\*\* LKK REF: CC6/AIG19004042/Afa3  
**Attachments:** DV SKW 8080P.pdf  
**Importance:** High

**WITHOUT PREJUDICE**  
**SAVE AS TO COSTS**

**Our Ref:** CC6/AIG19004042/Afa3  
**Your Ref:** SKW 8080P

Dear Zack,

We refer to the above matter and our tele conversation on even date.

We hereby confirmed settlement at global sum of **\$ 5,000.00** (all in) on this matter.

Please duly sign the DV attached and return with **Authorization to ACT** to us (LKK) for payment processing.

In the meantime, we appreciate if you could furnish us a copy of the **after paint photo** for our file record.

Your prompt action will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr) | Case Handler**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK  
Auto Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAuto)

---

**Subject:** FW: Final Repair Bill & Claim Loss Of Use (SKW8080P) \*\*\* LKK REF: CC6/AIG19004042/Afa3  
**Attachments:** Final Repair Bill (SKW 8080P Honda Vezel).odt

**From:** OHMYCAR <[info@ohmycar.sg](mailto:info@ohmycar.sg)>  
**Sent:** Thursday, 9 May, 2019 11:26 AM  
**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** Final Repair Bill & Claim Loss Of Use (SKW8080P)

Hi, this is Zack from FLYING HIGH SPRAY PAINTING.  
We will be using this email ([info@ohmycar.sg](mailto:info@ohmycar.sg)) for future inquiries, updates and paper works.

Attached is the Final Repair Bill for vehicle SKW8080P.

We would like to request to claim for **Loss Of Use**.  
Surveyor (Adrian) quoted us 5 days.

Thank you.

Best regards,  
Zack  
[www.ohmycar.sg](http://www.ohmycar.sg)  
[info@ohmycar.sg](mailto:info@ohmycar.sg)  
+65 92303750



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC6/AIG19004042/Afa3**

16 MAY 2019

**BIS MOTORING PTE LTD  
20 BENDEMEER ROAD  
#03-13/14 BS BENDEMEER CENTRE  
SINGAPORE 339914**

Dear Sir/Madam,

**ACCIDENT INVOLVING SLX 7821H AND SKW 8080P ALONG/AT LORONG 27  
GEYLANG TURNING RIGHT TO SIMS AVENUE ON 02/03/2019**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third-Party claim. However, if your policy has an NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Poh Kin, Chong  
Case Handler  
DID: 6841 2132  
FAX: 6741 4108  
Email: pohkin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

**AUTHORISATION TO ACT**  
**(AIG Express Third Party Claim)**

I, GOH CHOON HEE (the third party claimant) of Blk 324D  
SENGKANG EAST WAY #03-617 <sup>SINGAPORE 544324</sup> (address), owner of Skw 8080P (vehicle no.)  
hereby authorize FLYING HIGH SPRAY PAINTING ("the workshop") to act for me  
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle  
no. Skw 8080P that was damaged pursuant to the accident which occurred on 02/03/19  
(date) along LORONG 27 GEYLANG SIMS AVE (location) involving vehicle no/s  
SLX 7821 H ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit  
and the workshop is further authorized to receive payment further to settlement of my claim with  
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without  
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 04 (day) of 03 (month) 20 19 (year)

  
Signed by "the third party claimant"  
(with chop if applicable)

 **FLYING HIGH SPRAY PAINTING**  
BLK 1 KAKI BUKIT AVE 6  
#01-29 SINGAPORE 417883  
(AUTO BAY @ KAKI BUKIT)  
TEL: 6749 2997 FAX: 6744 2942  
  
Signed by "the workshop"  
(with chop)

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, FLYING HIGH SPRAY PAINTING ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$5,000.00 (Global Sum) for vehicle no. SKW 8080P that was damaged pursuant to the accident which occurred on 02/03/2019 (date) along LORONG 27 GEYLANG (location) involving vehicle no/s SLX 7821H. This is pursuant to the inspection conducted on 04/03/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GOH CHOON HEE ("the third party claimant") of vehicle no. SKW 8080P make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKW 8080P (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 23 (day) of 05 (month) 20 19 (year)

 LW

Signed by appointed surveyor

**FLYING HIGH SPRAY PAINTING**  
BLK 1 KAKI BUKIT AVE 6  
#01-29 SINGAPORE 417883  
(AUTO BAY @ KAKI BUKIT)  
TEL: 6749 2997 FAX: 6744 2942

24

Signed by "the workshop" (with chop)

高 飛 汽 車 噴 漆 廠  
**FLYING HIGH SPRAY PAINTING**

Blk 1, Kaki Bukit Ave 6, #01-29 Singapore 417883 (AutoBay@Kaki Bukit)  
Tel: 6749 2997 Fax: 6744 2942 Email: info@ohmycar.sg  
Business Reg. No. 42523200

INVOICE

Vehicle no: SKW 8080 P  
Model: HONDA VEZEL  
Name: GOH CHOON HEE  
Date of accident: 02/03/2019  
Address: C/O No 1 kaki bukit ave 6  
          #01-29 AutoBay@kaki bukit  
          S (417883)

FINAL REPAIR BILL FOR VEHICLE NO SKW 8080 P

QTY	ITEM	AMOUNT
1	LUMP SUM REPAIR COST	\$4,700.00
	Total	\$4,700.00
Dollars	FOUR THOUSAND SEVEN HUNDRED ONLY	

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING


















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Mar 2019 <a href="#">Edit Reg</a>		04 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,700.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,700.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>BIS MOTORING PTE LTD</b> , Co. Reg. No.: 2017935055D									
Main Claimant: <b>GOH CHOON HEE</b> , ID: S15871221									
Vehicle Reg. No.: <b>SKW8080P</b>		Date of Loss: 02/03/2019 20:00 - :59							
Claim Type: <b>TP / 8237542109SG</b>		Policy/Cover Note No.: 0999994322 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SLX7821H</b>		Policy No. (Claimant): GA131949							
		Excess:							
Repairer: <b>Flying High Spray Painting (HQ)</b> BLK 1 Kaki Bukit Ave 6, #01-29 Auto Bay, 417883 Kaki Bukit - Tel: 67492997									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ] Bernard.JIQian.Ler@aig.com									
Claimant's Insurer: <b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 18/03/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKW8080P (8237542109SG)  
[SLX7821H]  
TP  
GOH CHOON HEE  
Mar 2 2019 8:00PM  
[BIS MOTORING PTE LTD]  
Flying High Spray Painting

<a href="#">Upload Documents</a>			<a href="#">Upload Photos</a>			<a href="#">Compose New Letter</a>			<a href="#">Upload Video</a>			<a href="#">Upload Audio</a>			<a href="#">View</a>			<a href="#">View in Browser</a>		
<b>Letters/Correspondences</b>															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown															Edit		
<b>Photos/Images</b>															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
2	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
3	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
4	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
5	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
6	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
7	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
8	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
9	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
10	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
11	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
12	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
13	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
14	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
15	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
16	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
17	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
18	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
19	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
20	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
21	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
22	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
23	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
24	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
25	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
26	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
27	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
28	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
29	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
30	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
31	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
32	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
33	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
34	14/05/19 18:39		General View															Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	14/05/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/05/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/05/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/05/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/05/19 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
41	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
42	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
43	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
44	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
45	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
46	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
47	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
48	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
49	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
50	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
51	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
52	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
53	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
54	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
55	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
56	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
57	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
58	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
59	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
60	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
61	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
62	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
63	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
64	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
65	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
66	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
67	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
68	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
69	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
70	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
71	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
72	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
73	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
74	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
75	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
76	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
77	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
78	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
79	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
80	14/05/19 18:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
81	23/05/19 16:09	Reinspection Photo-after paint photo	 Load JPG	<input checked="" type="checkbox"/>
82	23/05/19 16:09	Reinspection Photo-after paint photo	 Load JPG	<input checked="" type="checkbox"/>
83	23/05/19 16:09	Reinspection Photo-after paint photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/03/19 19:04	TP GIA REPORT	Load PDF	
2	15/05/19 08:38	TP ESTIMATE	Load PDF	
3	23/05/19 16:04	Letter to OI	Load PDF	
4	06/06/19 10:17	WORKSHOP INVOICE	Load PDF	
5	06/06/19 10:17	AUTHORISATION TO ACT FORM	Load PDF	
6	06/06/19 10:17	Release Voucher	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	08/03/19 11:41	OI GIA REPORT	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLX7821H (Insd veh)	Model:	HONDA VEZEL 1.5 X CVT (A)
	SKW8080P (TP veh)		
Date of Accident:	02/03/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	:	\$		10,943.00
Final Repair Cost	:	\$		5,000.00
Loss of Use	:	\$		5.00 days at \$60.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		5,000.00

**Is Third Party Workshop GIA Registered?**    ☐ YES    ☒ NO    (Kindly indicate below)

**A) For Non GIA Registered Workshop:**    Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

**B) For GIA Registered Workshop:**    BOLA Applicable: Yes/ No    BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%)    Assessed Liability (\*): \_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Flying High Spray Painting	: \$	5,000.00
2)		: \$	

JOANNE LEE KHANG MIN

06 Jun  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19004042/AFA3Q2

Date: 06/06/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994322  
**Claimant Vehicle No :** SKW8080P **Insured Vehicle No :** SLX7821H  
 Date of Loss: 02/03/2019 Nature of Claim: TP Claim No: 8237542109SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SKW8080P**  
 Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: HIDDEN  
 Reg. Date: (Man. Year: 1900) Chassis No: RU11103164  
 Colour: White Odometer: 84827 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm  
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,763.00	4,722.40	3,040.60	39.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,530.00	1,650.00	51.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,943.00</b>	<b>6,252.40</b>	<b>4,690.60</b>	<b>42.86</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,943.00</b>	<b>4,700.00</b>	<b>6,243.00</b>	<b>57.05</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		300.00		
<b>Nett Liability (S\$)</b>		<b>5,000.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,000.00</b>		

## INSPECTION

Date of Assignment: 04/03/2019  
 Date Inspected: 04/03/2019 Inspected At: Flying High Spray Painting (HQ)  
 BLK 1 Kaki Bukit Ave 6, #01-29 Auto Bay  
 Singapore 417883  
 Estimated Period of Repair: 5.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** Chong Poh Kin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	880.00 F	*880.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Necessary	64.00 F	*64.00 FL
4	1		*REAR BUMPER LOWER SPOILER	Distorted	1,200.00 FS	*900.00 FS
5	2		*REAR BUMPER REFLECTOR	Cracked	302.00 F	*302.00 FL
6	1		*REAR BUMPER TOP CHROME PLATE	Bent	380.00 FS	*300.00 FS
7	1		*REAR END PANEL	Repair	580.00 F	*- FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	105.00 F	*105.00 FL
9	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
10	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
11	1		*TAILLAMP	N/S Cut	920.00 F	*460.00 FL
12	1		*TAILLAMP LOWER GARNISH	N/S Deformed	390.00 F	*195.00 FL
13	1		*TAILGATE	Dented	1,100.00 F	*1,100.00 FL
14	1		*TAILGATE LOCK	Damaged	182.00 F	*182.00 FL
15	1		*TAILGATE WEATHERSTRIPE	Not Necessary	165.00 F	*- FL
16	1		*TAILGATE BUZZER	Damaged	105.00 F	*105.00 FL
17	1		*TAILGATE GLASS MOULDING	Necessary	125.00 F	*125.00 FL
18	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
19	1		*VEZEL EMBLEM	Necessary	65.00 F	*65.00 FL
20	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	305.00 F	*- FL
21	1		*SPARE TYRE PANEL TOOLS SPONGE	Deformed	215.00 F	*215.00 FL
22	1		*TAILGATE SOUND INSULATOR	Necessary	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,763.00	5,488.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	765.60
Total Parts (S\$)	7,763.00	4,722.40

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,200.00	600.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	0.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	50.00
7	TO TRANSFER TAILGATE FITTING	New	150.00	80.00
8	TO REMOVE TAILGATE GLASS	New	180.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>3,180.00</b>	<b>1,530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >