

TP AIG
Poh kin

Flying High

Subject: SKW80SOP

Date:

Honda Vezel
Ru11103164

Rees Bumper Distorted	880 ✓
Rees Bumper Clips m	30 ✓
Rees Bumper Side Holder x02 m	32x2=64 ✓
Rees Bumper Lower Spoiler Distorted	1200(SN) 900(SN)
Rees Bumper Reflector x02 Cracked	151x2=302 ✓
Rees Bumper Top Chrome Plate Bent	380(SN) 300(SN)
Rees End Panel Repair	580 X
Rees End Panel Top Garnish Rehd	105 ✓
Rees End Panel Sealed N/A m	60(SN) X
Reverse Sensor Dmgd	280(SN) 200(SN)
Taillamp x02 LH at	460x2=920 460
Taillamp Lower Garnish x02 LH Rehd	195x2=390 195
Tailgate Distorted	100 ✓
Tailgate Lock Dmgd	182 ✓
Tailgate Weatherstripe N/A m	165 X
Tailgate Buzzer Dmgd	105 ✓
Tailgate Weatherstripe Moulding m	125 ✓
Tailgate G(411) Sealed m	60(SN) ✓
Vezel Emblem m	65 ✓
Spare Tyre Panel Top Cover N/A m	305 X
Spare Tyre Panel Tools Sponge Rehd	215 ✓

Accepted by Repairer
Signature: _____
Date: _____

is subject to approval from insurance Company
• Supplementary repairs must be authorised and
• No body work (repairs) is allowed
• This body survey is on a "No Fault" principle, pass
• To display damaged parts (body) clearly
• To display damaged parts (body) clearly
the Repairer of the following:
(Please do not sign this form until you have read the terms and conditions on the back of this form)

Tailgate
Wind
Insulator
250(SN)

N/A 200(SN)

3828

S/N: 1400

3061.40

Subject: SKW 8080P

Date:

Panel Beating
Spray Painting
Wiring -
To undercut
To remove reverse sensor
To remove upholstery.
To transfer tailgate fitting.
To remove tailgate glass

1200	600	
1200	600	
50	30	
150	x	
100	50	
150	50	
150	80	1530
180	120	

total: 5592.4

h/s: A-Tk

05 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: