

ASS. REC. BY:

REF:

CS/FCL 9004047 / RHT 3

Special Instruction:

Surveyor:

RASH

ASSIGNMENT (Office)

From (Person):

Serene Lee

of

FCL

Date/Time:

05/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDR 200C

Insured:

SHC 2169Z

at Workshop m/s

PML

Tel:

6319074

of

Alexandra

Policy No:

Claim No:

D19000926 MESH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04/2/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SHC 2169Z / SDR 200C

NBA/INC 19002214/Y DOR: 04/2/19

SHC 200C

20/3@4:

58pm - revised via email preli advise

Part by Part \$9337.90, 4 days. Confirm.

Cred. 2835.10 (23%)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000926MFSH

Date: 20/3/2019

Our Ref: CS/FCI19004047/R1td3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGO 200C

Please be informed that we had conducted the inspection of the abovementioned vehicle
18/3/2019 at the premises of M/s Performance have the following to report: -

Workshop Estimate Amount	: S\$ <u>12,173.00</u>
Revised Estimate Amount	: S\$ <u>10,788.00</u>
"Check" Items Amount	: S\$ <u>268.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:
The vehicle sustained damages at the
N/S front portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	09-02-2019	Our Ref No. D19000926MFSH
Accident Date	04-02-2019	Claim Type. Third Party
Insured Vehicle	SHC2169Z	Third Party Vehicle. SGQ200C
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. COR - \$13,025.11) *NOTE: IV HAD ANOTHER ACCIDENT ON S	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

OUT

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 20 March 2019 4:58 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000926MFSH/1
Attachments: PRELI ADVISED SGQ 200C.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SGQ 200C**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 5 March 2019 11:15 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000926MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that the vehicle currently not in the workshop and repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 5 March 2019 8:55 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000926MFSH/1

Dear Sir/Mdm,

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190133 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

01 MAR 2019

Estimate No. : b1 50353
Date Estimated : 01/03/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Loo Lip Ping
235 Jalan Kampong Chantek

Singapore 587925

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDQ200C	D333571	27/09/2013	520iA	0

DESCRIPTION

Replacing front bumper panel and attachments, left front side panel, etc to knock out dents caused by the accident

Spray front bumper and left front side panel

To replace left headlight

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

To carry out body cavity preservation.
(Per panel).

Sundries

VALUE

2,550.00

1,823.00

481.00

177.00

118.00

150.00

Total Labour 1:

5,399.00

DESCRIPTION

FRT LH FENDER

FRT BUMPER LH SPACER

FRT BUMPER PANEL PRIMED (M/PDC)

EMBLEM GROMMET

BMW EMBLEM

LH HEADLIGHT LED TECHNOLOGY

QTY

PRIC

1 884.90

1 10.05

1 1,602.50

2 0.80

1 71.25

1 4,203.70

VALUE

884.90

10.05

1,602.50

1.60

71.25

4,203.70

Total Parts :

6,774.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796501 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50353
Date Estimated : 01/03/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDQ200C	D333571	27/09/2013	520iA	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claim No. _____
Excess S\$ _____
Sign _____
Authorised Yes / No _____
Time _____
RESURVEY Yes / No _____
PML Yes / No _____
Surveyor's E-mail _____
No. of Working Days _____

18/03/19 @ 1140
Raul
90010068

4-5 days

20/3/19



Labour 1	:	5,399.00
Parts	:	6,774.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	852.11
Grand Total	:	13,025.11

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 50353
Date Estimated : 01/03/2019
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -
Loo Lip Ping
235 Jalan Kampong Chantek

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 587925

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	MILEAGE
SDQ200C	D333571	27/09/2013	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper LH spacer and attachment, front LH fender include making good the front bumper and knocking out dents caused by the accident	1700.00		1,700.00
To spray paint front bumper and front LH fender	1730.00		1,730.00
* To replace LH LED technology headlight include programming and conducting tests for proper function	408.00		408.00
To check electrical wiring systems at the front section for proper function	150.00		150.00
* To carry out body cavity preservation (Per panel)	100.00		100.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT LH FENDER	884.90	1.00		884.90
FRT BUMPER LH SPACER	10.05	1.00		10.05
BMW EMBLEM	71.25	1.00		71.25
LH HEADLIGHT LED TECHNOLOGY	4,203.70	1.00		4,203.70

SUPPLEMENTARY ITEMS

Total Labour :	4,168.00
Total Parts :	5,169.90
Total Labour & Parts :	9,337.90
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,337.90
GST @7%:	653.65
Grand Total :	9,991.55



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19004047/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2169Z	Veh. Inspected	SDQ 200C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000926MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	05/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	BMW 520I AT	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WBA5A32080D333571	Colour	WHITE	
Odometer	75124	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R18	CONTINENTAL	6 mm	
L/H Front Tyre	245/45 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	245/45 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	245/45 R18	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/02/2019	Inspection Date	18/03/2019	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDQ 200C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT LH FENDER (SN)	BENT	884.90	884.90
1	FRT BUMPER LH SPACER (SN)	NECESSARY	10.05	10.05
1	FRT BUMPER PANEL PRIMED (M/PDC)(SN)	TO REPAIR SEE LABOUR	1,602.50	-
2	EMBLEM GROMMET (SN)	NOT NECESSARY	1.60	-
1	BMW EMBLEM (SN)	NECESSARY	71.25	71.25
1	LH HEADLIGHT LED TECHNOLOGY (SN)	CRACKED	4,203.70	4,203.70
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
			6,924.00	5,249.90
LABOUR				
	REPLACING FRONT BUMPER PANEL AND ATTACHMENTS, LEFT FRONT SIDE PANEL, ETC TO KNOCK OUT DENTS CAUSED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRT BUMPER PANEL PRIMED (M/PDC).		2,550.00	1,700.00
	SPRAY FRONT BUMPER AND LEFT FRONT SIDE PANEL.		1,923.00	1,730.00
	TO REPLACE LEFT HEADLIGHT.		481.00	408.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.		177.00	150.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	100.00
			5,249.00	4,088.00
GRAND TOTAL			12,173.00	9,337.90
RECOMMENDED COST OF REPAIRS				9,337.90

Report Ref No. CS/FCI19004047/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.